

Alachua County

License Number: 1102115

TATU

License Type: Permanent Food Service

1702 W UNIVERSITY AVE STE J, GAINESVILLE 32603

Inspection Date: 07/08/2009

Inspection Number: 1869977

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: FULTON, DANIEL

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. SUSHI AREA.For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1103024

I LOVE NY PIZZA

License Type: Permanent Food Service

1702 W UNIVERSITY AVE, STE A-2, GAINESVILLE 32603

Inspection Date: 07/08/2009

Inspection Number: 1880194

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: FULTON, DANIEL

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1101555

GATOR CITY SPORTS GRILL

License Type: Permanent Food Service

1728 W UNIVERSITY AVE, GAINESVILLE 326031839

Inspection Date: 07/07/2009

Inspection Number: 1678223

Inspection Type: Routine - Food

Inspection Disposition: Call Back - Complied

Inspector Name: FULTON, DANIEL

Violation CodeObservationViolation Citation

15-39-2

Violation: 15-39-2

Hood drip tray not pitched to drain into metal container. For reporting purposes only.

NFPA 96, 6.2.4.3 Grease drip trays shall be pitched to drain into an enclosed metal container having a capacity not exceeding 1 gallon. FOR REPORTING PURPOSES ONLY

46-05-2

Violation: 46-05-2

Observed obstructed exits, stairs, hallways or egress. HASP ON WIC.For reporting purposes only.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

Alachua County

License Number: 1101713		SALTY DOG SALOON	
License Type: Permanent Food Service		1712 W UNIVERSITY AVE, GAINESVILLE 326031839	
Inspection Date: 07/07/2009	Inspection Number: 1719151	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Admin. complaint recommended
Inspector Name: FULTON, DANIEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Violation: 46-05-2 Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.HASP ON WIC.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	
License Number: 1102491		SWAMP	
License Type: Permanent Food Service		1642 W UNIVERSITY AVE, GAINESVILLE 326031840	
Inspection Date: 07/06/2009	Inspection Number: 1900695	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: FULTON, DANIEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-08-2	Exit signs not visible from any direction. For reporting purposes only.PARTILY BLOCKED BY T V. (UPSTAIRS)	NFPA 101, 7.10.1.2 Exits, other than main exterior exit doors that obviously and clearly are identifiable as exits, shall be marked by an approved sign readily visible from any direction of exit access. FOR REPORTING PURPOSES ONLY.	
License Number: 1101372		EL INDIO 34 ST	
License Type: Permanent Food Service		5011 NW 34 ST, GAINESVILLE 32605	
Inspection Date: 07/06/2009	Inspection Number: 1859824	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: HENTGES, JUDY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. Gap between filters For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
47-08-2	Observed electrical wiring in disrepair. For reporting purposes only. Reachin cooler power cord is spliced together.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
47-08-2	Observed electrical wiring in disrepair. For reporting purposes only. Chip warmer power cord is spliced together.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Alachua County

License Number: 1103047		KAYS CAFE	
License Type: Permanent Food Service		5240 NW 34 ST, GAINESVILLE 32605	
Inspection Date: 07/06/2009	Inspection Number: 1859850	Inspection Type: Quality Assurance	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: HENTGES, JUDY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
39-03-2	Exhaust system off during the operation of cooking equipment. For reporting purposes only.	NFPA 96, 11.1.1 Exhaust systems shall be operated whenever cooking equipment is turned on. For reporting purposes only.	
License Number: 1102704		BEEF O'BRADY'S	
License Type: Permanent Food Service		1999 NW 43 ST, GAINESVILLE 326053403	
Inspection Date: 06/29/2009	Inspection Number: 1647771	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Complied
Inspector Name: BROWNING, JULIANNE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair	
License Number: 1102892		KRYSTAL	
License Type: Permanent Food Service		7700 W NEWBERRY RD, GAINESVILLE 32606	
Inspection Date: 07/07/2009	Inspection Number: 1910975	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: BROWNING, JULIANNE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-25-2	Hood filters not equipped with a drip tray. For reporting purposes only.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY	
License Number: 1102713		MILDRED'S BIG CITY FOOD	
License Type: Permanent Food Service		3445 W UNIVERSITY AVE, GAINESVILLE 32607	
Inspection Date: 07/01/2009	Inspection Number: 1890603	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WRENNE, LILYANN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient	
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair	
License Number: 1102862		FIVE STAR PIZZA	
License Type: Permanent Food Service		600 NW 75 ST STE D, GAINESVILLE 32607	
Inspection Date: 07/07/2009	Inspection Number: 1911119	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: WRENNE, LILYANN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
47-16-2	Electrical outlet missing cover plate in hallway. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

Alachua County

License Number: 1102973		GATOR'S DOCKSIDE	
License Type: Permanent Food Service		3842 NEWBERRY ROAD 1-A, GAINESVILLE 32607	
Inspection Date: 07/01/2009	Inspection Number: 1859762	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: WRENNE, LILYANN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair	
License Number: 1103161		PEACH VALLEY CAFE	
License Type: Permanent Food Service		3275 SW 34 ST, GAINESVILLE 32607	
Inspection Date: 06/25/2009	Inspection Number: 1915095	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: WRENNE, LILYANN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair	
License Number: 1102838		BEEF O'BRADY'S	
License Type: Permanent Food Service		6500 SW ARCHER RD SUITE E, GAINESVILLE 32608	
Inspection Date: 07/09/2009	Inspection Number: 1839332	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WRENNE, LILYANN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-05-2	Observed a splitter/multi-plug adapter in use by slicer. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 1103088		BACKYARD BURGERS #1245	
License Type: Permanent Food Service		3400 SW 34 ST, GAINESVILLE 32608	
Inspection Date: 06/29/2009	Inspection Number: 1914752	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: WRENNE, LILYANN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair	
License Number: 1101942		PIZZA HUT STORE # 24426	
License Type: Permanent Food Service		15947 NW US HWY 441, ALACHUA 32615	
Inspection Date: 07/06/2009	Inspection Number: 1839378	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: HENTGES, JUDY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-07-2	Exit signs missing. For reporting purposes only. Dining Area	NFPA 101, 7.10.1.2 Exits, other than main exterior exit doors that obviously and clearly are identifiable as exits, shall be marked by an approved sign readily visible from any direction of exit access. FOR REPORTING PURPOSES ONLY.	
46-09-2	Exit signs not properly illuminated. For reporting purposes only. Rear area	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	

Bay County

License Number: 1301775 JIMMY'S
 License Type: Permanent Food Service 533 E 6 ST, PANAMA CITY 324013047

Inspection Date: 07/06/2009 Inspection Number: 1912475 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended
 Inspector Name: DURGIN, JANIE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-26-2	Observed exhaust system operated with filters removed. For reporting purposes only.	NFPA 96, 11.1.2 Filter-equipped exhaust systems shall not be operated with filters removed. For reporting purposes only.

License Number: 1301551 JOHN BOY'S SHOPPE
 License Type: Permanent Food Service 325 S TYNDALL PKWY, CALLAWAY 324046725

Inspection Date: 07/06/2009 Inspection Number: 1902248 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DURGIN, JANIE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only.	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

License Number: 1305264 MELLOW MUSHROOM
 License Type: Permanent Food Service 8746 THOMAS DRIVE, PANAMA CITY 32408

Inspection Date: 07/08/2009 Inspection Number: 1902178 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DESHAZIER, ERNEST

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. Observed by the backdoor.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Bradford County

License Number: 1400205

PIT STOP CAFE

License Type: Permanent Food Service

1706 MADISON ST, LAWTEY 32058

Inspection Date: 07/09/2009

Inspection Number: 1870987

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: DOHERTY, BRENDEN

Violation CodeObservationViolation Citation

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only. NEAR
BACK DOOR

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1400092

WENDY'S OLD FASHION HAMBURGERS

License Type: Permanent Food Service

631 S WALNUT ST, STARKE 320913948

Inspection Date: 07/07/2009

Inspection Number: 1860727

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: DOHERTY, BRENDEN

Violation CodeObservationViolation Citation

15-40-2

No metal container installed for catching grease from hood drip tray. For reporting
purposes only.

NFPA 96, 6.2.4.3 Grease drip trays shall be pitched to drain into an enclosed metal container having a capacity not exceeding 1 gallon. FOR REPORTING PURPOSES ONLY

Brevard County

License Number: 1506080		WILLIS DELI	
License Type: Permanent Food Service		4450 DIXIE HWY, PALM BAY 32905	
Inspection Date: 07/06/2009	Inspection Number: 1910641	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SCHOENLY, BARBARA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor./by kitchen door For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
License Number: 1504055		CREATIVE CATERING BY THE FARIN	
License Type: Permanent Food Service		333 N BABCOCK ST, MELBOURNE 329356733	
Inspection Date: 07/10/2009	Inspection Number: 1898925	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WOODS, CRYSTAL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-07-2	Observed misalignment of hood suppression system nozzles. For reporting purposes only.extra fryer not under hood.	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.	
License Number: 1504463		HULA GIRL CAFE LLC	
License Type: Permanent Food Service		6300 N WICKHAM RD STE# 119, MELBOURNE 32940	
Inspection Date: 07/09/2009	Inspection Number: 1908866	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WOODS, CRYSTAL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.for lights in kitchen	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
47-06-2	Observed brown extension cord in use light. For reporting purposes only.waitstaff	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Brevard County

License Number: 1504802

MALIBU'S SPORTS GRILL

License Type: Permanent Food Service

165 BARTON BLVD, ROCKLEDGE 32955

Inspection Date: 07/10/2009

Inspection Number: 1898585

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: MAYNARD, DIANE

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.outside lights

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1506127

7 STAR DINER

License Type: Permanent Food Service

563 BARTON BLVD STE 13, ROCKLEDGE 32955

Inspection Date: 07/10/2009

Inspection Number: 1857634

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: MAYNARD, DIANE

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Broward County

License Number: 1612036 CHURCHS CHICKEN #1377
 License Type: Permanent Food Service 141 S FEDERAL HWY, DANIA 33004

Inspection Date: 07/07/2009 Inspection Number: 1884847 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GRAY, ANTHONY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 1608853 SHENANIGANS EAST SIDE PUB
 License Type: Permanent Food Service 1300 S FEDERAL HWY, DANIA BEACH 33004

Inspection Date: 07/07/2009 Inspection Number: 1843891 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GRAY, ANTHONY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-11-2	Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only.	NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

Broward County

License Number: 1618759 HEMISPHERE GRILL
 License Type: Permanent Food Service 1960 S OCEAN SIDE DR, HALLANDALE 33009

Inspection Date: 07/08/2009 Inspection Number: 1884873 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CONSIGLIO, CAMILLE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
48-23-1	Carbon monoxide sensor device located in a gas boiler room in a building which also contains sleeping rooms is not integrated with the building's fire detection system. Boiler Information: Boiler Jurisdiction Number: fl121656, Boiler Expiration Date:	509.211(5) FS Every enclosed space or room that contains a boiler regulated under chapter 554 which is fired by the direct application of energy from the combustion of fuels and that is located in any portion of a public lodging establishment that also contains sleeping rooms shall be equipped with one or more carbon monoxide sensor devices. Such devices shall be integrated with the public lodging establishment's fire detection system.

Broward County

License Number: 1622237

JASMINE ON THE OCEAN

License Type: Permanent Food Service

1960 S OCEAN DR, HALLANDALE 33009

Inspection Date: 07/08/2009

Inspection Number: 1914670

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CONSIGLIO, CAMILLE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-08-2	Observed electrical wiring in disrepair. For reporting purposes only.near mop sink	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
48-23-1	Carbon monoxide sensor device located in a gas boiler room in a building which also contains sleeping rooms is not integrated with the building's fire detection system. Boiler Information: Boiler Jurisdiction Number: fl21656, Boiler Expiration Date: 3	509.211(5) FS Every enclosed space or room that contains a boiler regulated under chapter 554 which is fired by the direct application of energy from the combustion of fuels and that is located in any portion of a public lodging establishment that also contains sleeping rooms shall be equipped with one or more carbon monoxide sensor devices. Such devices shall be integrated with the public lodging establishment's fire detection system.

Broward County

License Number: 1600606 EDDIE HILLS REST
 License Type: Permanent Food Service 134 N FEDERAL HWY, HALLANDALE 330094353

Inspection Date: 07/08/2009 Inspection Number: 1895052 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CONSIGLIO, CAMILLE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-40-2	Portable fire extinguisher with no approved inspection tag. For reporting purposes only.bc	61C-1.004(9)(b) FAC and NFPA 10, 6.3.4 A standard state approved service tag shall be attached to each extinguisher and a person holding a valid state permit issued by the State Fire Marshal shall recharge or inspect the extinguisher and shall prepare the tag to include the information required by rule 4A-21.241, FAC, herein adopted by reference. Maintenance Recordkeeping. Each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was performed and that identifies the person performing the service. FOR REPORTING PURPOSES ONLY.

License Number: 1615135 WONTON GARDEN CHINESE RESTAURANT
 License Type: Permanent Food Service 709 W HALLANDALE BEACH BLVD, HALLANDALE 33009-5332

Inspection Date: 07/07/2009 Inspection Number: 1874622 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CONSIGLIO, CAMILLE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
49-07-2	Observed flammable material stored card board next to open flame on gas stove Corrected On Site.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

License Number: 1620162 HOLLYWOOD PRIME
 License Type: Permanent Food Service 3555 S OCEAN DR, HOLLYWOOD 33019

Inspection Date: 07/06/2009 Inspection Number: 1884881 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CONSIGLIO, CAMILLE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.blocked by trash can Corrected On Site.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 1619467 MCDONALDS #4400
 License Type: Permanent Food Service 6204 MIRAMAR PKWY, MIRAMAR 33023

Inspection Date: 07/02/2009 Inspection Number: 1864408 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended
 Inspector Name: QUINONES, JOSE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. front counter.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Broward County

License Number: 1620387 POWER FUSIONZ CAFE
 License Type: Permanent Food Service 12165 PEMBROKE RD, PEMBROKE PINES 33025

Inspection Date: 07/08/2009 Inspection Number: 1812907 Inspection Type: Routine - Food Inspection Disposition: Call Back - Complied
 Inspector Name: VASQUEZ, JANNETH

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-41-2	Violation: 45-41-2 Portable fire extinguisher tag with double date punched. For reporting purposes only.	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

License Number: 1613640 TIEN TIEN CHINESE FOOD
 License Type: Permanent Food Service 9975 MIRAMAR PKWY, MIRAMAR 330252398

Inspection Date: 07/08/2009 Inspection Number: 1884747 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: VASQUEZ, JANNETH

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-2	Exit signs not properly illuminated. For reporting purposes only. Repeat Violation.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 1617134 COOL RUNNINGS CAFE
 License Type: Permanent Food Service 9977 MIRAMAR PKWY, MIRAMAR 330252398

Inspection Date: 07/08/2009 Inspection Number: 1833422 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: VASQUEZ, JANNETH

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 1616931 ASAIN GRILL
 License Type: Permanent Food Service 7462 ROYAL PALM BLVD, MARGATE 33063-6881

Inspection Date: 07/07/2009 Inspection Number: 1906205 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DIEHL, TERRENCE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. SOUTHWEST DINING ROOM.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

Broward County

License Number: 1607038 CHIFA TAYPA CHINESE RESTAURANT
 License Type: Permanent Food Service 213 S SR 7, MARGATE 33068

Inspection Date: 07/06/2009 Inspection Number: 1854500 Inspection Type: Routine - Food
 Inspector Name: WILLIAMS, NOVELETTE

Inspection Disposition: Inspection Completed - No Further Action

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-25-2	Hood filters not equipped with a drip tray. For reporting purposes only.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY
47-06-2	Observed extension cord in use for non-temporary period, with reachin freezer in kitchen area. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1620349 ROYAL CARIBBEAN RESTAURANT
 License Type: Permanent Food Service 181 S SR 7, MARGATE 33068

Inspection Date: 07/06/2009 Inspection Number: 1833960 Inspection Type: Routine - Food
 Inspector Name: WILLIAMS, NOVELETTE

Inspection Disposition: Inspection Completed - No Further Action

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-42-2	Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.	NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY
39-05-2	Ventilation inadequate as evidenced by smoke stained walls in kitchen area. For reporting purposes only.	NFPA 96, 4.1.1 Cooking equipment used in processes producing smoke or grease-laden vapors shall be equipped with an exhaust system that complies with all the equipment and performance requirements of this standard; and NFPA 96, 8.2.2 Air Volume. NFPA 96, 8.2.2.1: Exhaust air volumes for hoods shall be of a sufficient level to provide for capture and removal of grease-laden cooking vapors. FOR REPORTING PURPOSES ONLY

License Number: 1621177 Q RICURAS
 License Type: Permanent Food Service 197 SR 7, MARGATE 33068

Inspection Date: 07/06/2009 Inspection Number: 1874968 Inspection Type: Routine - Food
 Inspector Name: WILLIAMS, NOVELETTE

Inspection Disposition: Inspection Completed - No Further Action

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed over fryers. Notified Fire AHJ. For reporting purposes only.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

Broward County

License Number: 1621273		A TODO TACO	
License Type: Permanent Food Service		336 S SR7, MARGATE 33068	
Inspection Date: 07/06/2009	Inspection Number: 1833938	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WILLIAMS, NOVELETTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 1619296		CALIENTE RESTAURANT & GRILL	
License Type: Permanent Food Service		996 - 998 SW 81 AVE, NORTH LAUDERDALE 33068	
Inspection Date: 07/09/2009	Inspection Number: 1809247	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Admin. complaint recommended
Inspector Name: WILLIAMS, NOVELETTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 1621090		KFC/ LONG JOHN SILVERS	
License Type: Permanent Food Service		2150 W ATLANTIC BLVD, POMPANO BEACH 33069	
Inspection Date: 07/08/2009	Inspection Number: 1854712	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: NUTTALL, JOHN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-15-2	Observed an uncovered electrical box. For reporting purposes only. Inside walk in freezer	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 1617701		BERNIES	
License Type: Permanent Food Service		1420 CORAL RIDGE DR, CORAL SPGS 330715433	
Inspection Date: 07/07/2009	Inspection Number: 1906049	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BECKER, ROBERT			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

Broward County

License Number: 1613419

DOCKSIDERS RESTAURANT

License Type: Permanent Food Service

2670 E SUNRISE BLVD, FORT LAUDERDALE 33304

Inspection Date: 07/02/2009

Inspection Number: 1683224

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Complied

Inspector Name: TORRES, LARRY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-15-2	Violation: 47-15-2 Observed an uncovered electrical box. For reporting purposes only. by plate storage shelving	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.
48-12-2	Violation: 48-12-2 No current boiler certification provided/available. boiler certicate posted on boiler room expired. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

Broward County

License Number: 1621071		DOUBLETREE SUITES BANQUET ROOM	
License Type: Permanent Food Service		2670 E SUNRISE BLVD, FORT LAUDERDALE 33304	
Inspection Date: 07/02/2009	Inspection Number: 1703711	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Complied
Inspector Name: TORRES, LARRY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
48-12-2	Violation: 48-12-2 No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.	

License Number: 1618562		GEORGIE'S ALIBI	
License Type: Permanent Food Service		2266 WILTON DR, WILTON MANOR 33305	
Inspection Date: 07/08/2009	Inspection Number: 1895522	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: TORRES, LARRY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

License Number: 1620393		GALANGA THAI KITCHEN & SUSHI BAR	
License Type: Permanent Food Service		2389 WILTON DR, WILTON MANORS 33305	
Inspection Date: 07/09/2009	Inspection Number: 1854566	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: TORRES, LARRY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

License Number: 1601258		BONA ITALIAN RESTAURANT	
License Type: Permanent Food Service		2468 WILTON DR, WILTON MANORS 333051251	
Inspection Date: 07/09/2009	Inspection Number: 1864862	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: TORRES, LARRY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

Broward County

License Number: 1610710		RUTHS CHRIS STEAK HOUSE	
License Type: Permanent Food Service		2525 N FEDERAL HWY, FT LAUDERDALE 333051620	
Inspection Date: 07/08/2009	Inspection Number: 1652680	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Complied
Inspector Name: TORRES, LARRY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 1619787		MILLERS FORT LAUDERDALE ALE HOUSE	
License Type: Permanent Food Service		2861 N FEDERAL HWY, FORT LAUDERDALE 33306	
Inspection Date: 07/08/2009	Inspection Number: 1895564	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: MERNO, RAHLIBA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 1615793		MICKEY'S 19 HOLE	
License Type: Permanent Food Service		2739 E OAKLAND PARK BLVD, FT LAUDERDALE 333061604	
Inspection Date: 07/02/2009	Inspection Number: 1875082	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: MERNO, RAHLIBA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	

Broward County

License Number: 1619578 CARLS SEAFOOD REST TAKE OUT
 License Type: Permanent Food Service 2934 N SR 7, LAUDERDALE LAKES 33313

Inspection Date: 07/09/2009 Inspection Number: 1864814 Inspection Type: Routine - Food Inspection Disposition: Call Back - Extension given, pending
 Inspector Name: WILLIAMS, NOVELETTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-07-2	Violation: 45-07-2 Observed misalignment of hood suppression system nozzles. For reporting purposes only.	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.
45-07-2	Observed misalignment of hood suppression system nozzles. For reporting purposes only.	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

License Number: 1620461 COMFORT SUITES
 License Type: Permanent Food Service 1800 S FEDERAL HWY, FORT LAUDERDALE 33316

Inspection Date: 07/06/2009 Inspection Number: 1833798 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CHERY, JOCELYNE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-21-1	No carbon monoxide sensor device located in a gas boiler room in a building which also contains sleeping rooms. Boiler Information: Boiler Jurisdiction Number: FI053370, Boiler Expiration Date: 1/15/2010 Boiler Jurisdiction Number: FI053372, Boiler E	509.211(5) FS Every enclosed space or room that contains a boiler regulated under chapter 554 which is fired by the direct application of energy from the combustion of fuels and that is located in any portion of a public lodging establishment that also contains sleeping rooms shall be equipped with one or more carbon monoxide sensor devices that bear the label of a nationally recognized testing laboratory and have been tested and listed as complying with the most recent Underwriters Laboratories, Inc., Standard 2034, or its equivalent, unless it is determined that carbon monoxide hazards have otherwise been adequately mitigated as determined by the division.

License Number: 1608746 PIZZA HUT 630062
 License Type: Permanent Food Service 1239 S FEDERAL HWY, FT LAUDERDALE 333162068

Inspection Date: 07/09/2009 Inspection Number: 1885087 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CHERY, JOCELYNE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Broward County

License Number: 1619420		DUTCH POT JAMAICAN REST	
License Type: Permanent Food Service		111 N SR 7, PLANTATION 33317	
Inspection Date: 07/02/2009	Inspection Number: 1884998	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WILLIAMS, FERNANDO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair	
License Number: 1621517		LATIN BOHEMIA GRILL	
License Type: Permanent Food Service		6903 W BROWARD BLVD, PLANTATION 33317	
Inspection Date: 07/07/2009	Inspection Number: 1874788	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WILLIAMS, FERNANDO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 1620068		CHURCHS CHICKEN #5393	
License Type: Permanent Food Service		3450 N SR 7, LAUDERDALE LAKES 33319	
Inspection Date: 07/08/2009	Inspection Number: 1905927	Inspection Type: Routine - Food	Inspection Disposition: Emergency order recommended
Inspector Name: WILLIAMS, NOVELETTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
39-05-2	Ventilation inadequate as evidenced by smoke stained walls in kitchen area, above oven. For reporting purposes only.	NFPA 96, 4.1.1 Cooking equipment used in processes producing smoke or grease-laden vapors shall be equipped with an exhaust system that complies with all the equipment and performance requirements of this standard; and NFPA 96, 8.2.2 Air Volume. NFPA 96, 8.2.2.1: Exhaust air volumes for hoods shall be of a sufficient level to provide for capture and removal of grease-laden cooking vapors. FOR REPORTING PURPOSES ONLY	
39-05-2	Violation: 39-05-2 Ventilation inadequate as evidenced by smoke stained walls in kitchen area, above oven. For reporting purposes only.	NFPA 96, 4.1.1 Cooking equipment used in processes producing smoke or grease-laden vapors shall be equipped with an exhaust system that complies with all the equipment and performance requirements of this standard; and NFPA 96, 8.2.2 Air Volume. NFPA 96, 8.2.2.1: Exhaust air volumes for hoods shall be of a sufficient level to provide for capture and removal of grease-laden cooking vapors. FOR REPORTING PURPOSES ONLY	
License Number: 1621798		HURRICANE GRILL AND WINGS	
License Type: Permanent Food Service		1905 N PINE ISLAND RD, PLANTATION 33322	
Inspection Date: 07/07/2009	Inspection Number: 1854440	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WILLIAMS, ALECIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

Broward County

License Number: 1621810

NUTRITION ZONE CAFE

License Type: Permanent Food Service

13999 W SUNRISE BLVD, SUNRISE 33323

Inspection Date: 07/08/2009

Inspection Number: 1854482

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: WILLIAMS, ALECIA

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 1612616

CLASSICS DELI

License Type: Permanent Food Service

5602 FLAMINGO RD, COOPER CITY 33330

Inspection Date: 07/08/2009

Inspection Number: 1807557

Inspection Type: Routine - Food

Inspection Disposition: Call Back - Complied

Inspector Name: VASQUEZ, JANNETH

Violation CodeObservationViolation Citation

47-08-2

Violation: 47-08-2

Observed electrical wiring in disrepair. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1619979

ORIGINAL PANCAKE HOUSE

License Type: Permanent Food Service

6650 DYKES RD, SOUTHWEST RANCHES 33331

Inspection Date: 07/07/2009

Inspection Number: 1907056

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DURDEN, VICKIE

Violation CodeObservationViolation Citation

47-16-2

Electrical outlet missing cover plate. For reporting purposes only.cracked

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Broward County

License Number: 1600896		BUCK & MARY'S OWLS NEST BAR	
License Type: Permanent Food Service		3301 NE 3 AVE, OAKLAND PARK 33334	
Inspection Date: 07/08/2009	Inspection Number: 1866034	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SCHNEIDER, MICHELE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.	
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only.	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.	
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	
47-03-2	Observed unused opening in panel box unprotected. For reporting purposes only.	NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

License Number: 1618870		DOWNTOWN PIZZA GRILL	
License Type: Permanent Food Service		906 NE 62 ST, OAKLAND PARK 33334	
Inspection Date: 07/09/2009	Inspection Number: 1907086	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SCHNEIDER, MICHELE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.	

License Number: 1607756		OVER EASY CAFE	
License Type: Permanent Food Service		318 E OAKLAND PK BLVD, WILTON MANORS 33334	
Inspection Date: 07/07/2009	Inspection Number: 1835239	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SCHNEIDER, MICHELE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only 11/08.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.	

Broward County

License Number: 1609691

DOMINO'S PIZZA

License Type: Permanent Food Service

400 E OAKLAND PARK BLVD, WILTON MANORS 333342150

Inspection Date: 07/07/2009

Inspection Number: 1896683

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: SCHNEIDER, MICHELE

Violation CodeObservationViolation Citation

37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 1617630

TACO BELL #17677

License Type: Permanent Food Service

593 E OAKLAND PARK BLVD, OAKLAND PARK 333342151

Inspection Date: 07/07/2009

Inspection Number: 1866028

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: SCHNEIDER, MICHELE

Violation CodeObservationViolation Citation

37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only section of filters.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

Citrus County

License Number: 1900792

GRANNIE'S RESTAURANT

License Type: Permanent Food Service

1712 US HIGHWAY 19, CRYSTAL RIVER 34429

Inspection Date: 07/09/2009

Inspection Number: 1867406

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: CRAIG, JILL

Violation CodeObservationViolation Citation

47-16-2

Electrical outlet missing cover plate in waitstation. For reporting purposes only.
Repeat Violation.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 1900723

CINNAMON STICKS REST & BAKERY

License Type: Permanent Food Service

2120 W GULF TO LAKE HWY, INVERNESS 34453

Inspection Date: 07/06/2009

Inspection Number: 1857190

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: CRAIG, JILL

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Repeat Violation.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

Clay County

License Number: 2001064 O'CHARLEY'S #369
 License Type: Permanent Food Service 1609 CR 220, ORANGE PARK 32003

Inspection Date: 07/08/2009 Inspection Number: 1859916 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DOHERTY, BRENDEN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 2000953 POMPEII COAL FIRED PIZZA
 License Type: Permanent Food Service 2134 PARK AVE, ORANGE PARK 32073

Inspection Date: 07/08/2009 Inspection Number: 1821841 Inspection Type: Routine - Food Inspection Disposition: Call Back - Admin. complaint recommended
 Inspector Name: DOHERTY, BRENDEN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Violation: 47-06-2 Observed extension cord in use for non-temporary period to buffet. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Collier County

License Number: 2102841

MISS SAIGON GOURMET INC

License Type: Permanent Food Service

3106 N TAMIAMI TRL, NAPLES 34103

Inspection Date: 07/10/2009

Inspection Number: 1872769

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: MORRIS, CHARLES

Violation Code

Observation

Violation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only. front door

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

Columbia County

License Number: 2200358	WAFFLE HOUSE #719		
License Type: Permanent Food Service	3639 W HWY 90, LAKE CITY 32055		
Inspection Date: 07/02/2009	Inspection Number: 1859561	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: FULTON, DANIEL			

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

License Number: 2200370	INTERNATIONAL HOUSE OF PANCAKE		
License Type: Permanent Food Service	3322 US HIGHWAY 90, LAKE CITY 32055		
Inspection Date: 07/09/2009	Inspection Number: 1859552	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: FULTON, DANIEL			

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. MICROWAVE .For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2355715 ALFONSO
 License Type: Mobile Food Dispensing Vehicle 2151 NW 13 ST, MIAMI 33002

Inspection Date: 07/09/2009 Inspection Number: 1135151 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: NUNEZ, ANDRES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-16-2	Observed mobile food dispensing vehicle equipped with LP-gas operating indoors. For reporting purposes only.	61C-4.0161(10) FAC Installation of liquefied petroleum gas appliances, equipment, apparatus or containers on theme park food carts is to be performed in accordance with the provisions of National Fire Protection Association Standard Number 58, Liquefied Petroleum Gases Handbook, and Chapters 69A-3 and 5F-11, FAC, herein adopted by reference. The following requirements must also be met: (a) Gas appliances shall be installed in accordance with manufacturer's specifications. (b) The gas supply shall be shut off at the tank when equipment is not in use; (c) No unit utilizing LP-gas shall park in a building during the operation of its vending business. FOR REPORTING PURPOSES ONLY.

License Number: 2356415 FUTURO CAFETERIA
 License Type: Mobile Food Dispensing Vehicle 553 E 13 ST, HIALEAH 33010

Inspection Date: 07/08/2009 Inspection Number: 1133127 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: NUNEZ, ANDRES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

License Number: 2324859 LA DELICIOSA CAFETERIA
 License Type: Permanent Food Service 1002 E 24 STREET, HIALEAH 33013

Inspection Date: 07/02/2009 Inspection Number: 1853234 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DE LOS SANTOS, JUAN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 2317476 MAVY CAFETERIA
 License Type: Permanent Food Service 3501 E 10 CT, HIALEAH 330132915

Inspection Date: 07/01/2009 Inspection Number: 1832687 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DE LOS SANTOS, JUAN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 2327768 CAFE TROPICAL
 License Type: Permanent Food Service 12535 W OKEECHOBEE RD, HIALEAH GDNS 330166026

Inspection Date: 07/09/2009 Inspection Number: 1681787 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended
 Inspector Name: SIMANEK, MICHELLE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-16-2	Electrical outlet missing cover plate. For reporting purposes only. (MOP SINK RM)	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2325819		CASITA TEJAS MEXICAN REST	
License Type: Permanent Food Service		27 N KROME AVE, HOMESTEAD 330306014	
Inspection Date: 07/06/2009	Inspection Number: 1864046	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: ALFONSO, ARELYS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 2319565		LA QUEBRADITA	
License Type: Permanent Food Service		702 N KROME AVE, HOMESTEAD 330306045	
Inspection Date: 07/08/2009	Inspection Number: 1843483	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: ALFONSO, ARELYS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 2325932		CASA LEOS KITCHEN INC	
License Type: Permanent Food Service		24856 SW 177TH AVENUE, HOMESTEAD 33031-1827	
Inspection Date: 06/29/2009	Inspection Number: 1914709	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BROWN, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
48	Out of compliance: Gas appliances - properly installed, maintained	NFPA 101, 96, 10 Gas appliances - properly installed, maintained	
License Number: 2331683		TAQUERIA EL PARADITO	
License Type: Permanent Food Service		26115 S DIXIE HWY, HOMESTEAD 33032	
Inspection Date: 06/29/2009	Inspection Number: 1914715	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BROWN, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair	
License Number: 2325119		BANGKOK CUISINE	
License Type: Permanent Food Service		27319 S DIXIE HWY, MIAMI 33032	
Inspection Date: 07/06/2009	Inspection Number: 1884511	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: ALFONSO, ARELYS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 2325195		HOAGIE BEAR SUBS	
License Type: Permanent Food Service		26855 S DIXIE HWY, NARANJA 330327524	
Inspection Date: 07/09/2009	Inspection Number: 1894710	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BROWN, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.back	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	

Dade County

License Number: 2330617

DADE CORNERS PLAZA SUBWAY

License Type: Permanent Food Service

16650 NW 27TH AVE # 200, OPA-LOCKA 33054

Inspection Date: 07/07/2009

Inspection Number: 1852742

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: PIERRE, KEVON

Violation CodeObservationViolation Citation46-05-2 Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.
BLOCKED BY BOXES

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 2301955

MCGEE'S DINER

License Type: Permanent Food Service

14511 NW 27 AVE, OPALOCKS 33054

Inspection Date: 07/02/2009

Inspection Number: 1832225

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: PIERRE, KEVON

Violation CodeObservationViolation Citation

37-20-2 Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2300816

KFC

License Type: Permanent Food Service

15850 NW 27 AVE, OPA LOCKA 330542246

Inspection Date: 07/08/2009

Inspection Number: 1883505

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: PIERRE, KEVON

Violation CodeObservationViolation Citation

45-22-2 Portable fire extinguisher(s) obstructed from view. For reporting purposes only.

NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.

47-16-2 Electrical outlet missing cover plate. For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2332508

LOS GAUCHITOS PIZZA RESTAURANT-BAKERY-MEAT MARKET

License Type: Permanent Food Service

4315 NW 7 ST #21-23, MIAMI 33126

Inspection Date: 07/08/2009

Inspection Number: 1830757

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Warning Issued

Inspector Name: CHOW, ZULEIMA

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. ON FLOOR BY MOPSINK

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

49-12-2

Observed container of flammable material over 5 gallons stored in establishment. For reporting purposes only. BY BAKERY PREP TABLE

61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

License Number: 2355892

ELO CAFETERIA

License Type: Mobile Food Dispensing Vehicle

4387 NW 7 ST, MIAMI 33126

Inspection Date: 07/09/2009

Inspection Number: 1133781

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: NUNEZ, ANDRES

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2356934

ALL AMERICAN HOT DOG CARTS

License Type: Mobile Food Dispensing Vehicle

292 NW 34 ST, MIAMI 33127

Inspection Date: 07/07/2009

Inspection Number: 1132912

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: NUNEZ, ANDRES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-19-2	Mobile food dispensing vehicle lacking a two-stage regulator on the LP-gas line. For reporting purposes only.	NFPA 58, 3.2.12.1 and 3.8.2.7(b) A two-stage regulator system, an integral two-stage regulator, or a two-psi regulator system shall be required on all fixed piping systems that serve 1/2 -psig appliance systems [normally operated at 11 in. w.c. pressure]. The regulators utilized in these systems shall meet the requirements of 2.5.7. This requirement includes fixed piping systems for appliances on RVs (recreational vehicles), mobile home installations, manufactured home installations, catering vehicles, and food service vehicle installations. Single-stage regulators shall not be installed in fixed piping systems after June 30, 1997. Exception No. 1: This requirement does not include small portable appliances and outdoor cooking appliances with input ratings of 100,000 Btu/hr or less. Exception No. 2: Gas distribution systems utilizing multiple second-stage regulators shall be permitted to use a high-pressure regulator installed at the container provided a first-stage regulator is installed downstream of the high-pressure regulator and ahead of the second-stage regulators. Exception No. 3: High-pressure regulators with an overpressure protection device and a rated capacity of more than 500,000 Btu/hr shall be permitted to be used in two-stage systems where the second-stage regulator incorporates an integral or separate overpressure protection device. This overpressure protection device shall limit the outlet pressure of the second-stage regulator to 2.0 psig when the regulator seat disc is removed and with an inlet pressure equivalent to the maximum outlet pressure setting of the high-pressure regulator Exception No. 4: Systems consisting of listed components that provide an equivalent level of overpressure protection. (b) A two-stage regulator system or an integral two-stage regulator in accordance with 3-2.12.1 shall be installed on all vapor withdrawal systems. Regulators shall be protected from the elements in accordance with 3-2.12.4. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2328289		NATURAL CHICKEN GRILL	
License Type: Permanent Food Service		95 NW 1 ST, MIAMI 33128	
Inspection Date: 07/07/2009	Inspection Number: 1894285	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CHI, MAURICE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. Outside gate at the back exit - chained locked.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. Items stored on stair.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	
47-04-2	Observed frayed/spliced electrical wires. For reporting purposes only. Exposed wires on ceiling area by back door of storage area.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 2330382		QUIZNOS	
License Type: Permanent Food Service		91 NW 1 ST, MIAMI 33128	
Inspection Date: 07/07/2009	Inspection Number: 1843139	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CHI, MAURICE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. Outside back exit gate locked with a chain.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	

License Number: 2314785		PAN AMERICAN CAFETERIA	
License Type: Permanent Food Service		445 NW 12 AVE, MIAMI 331281020	
Inspection Date: 07/07/2009	Inspection Number: 1832847	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: KHAN, MOHAMMAD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	

Dade County

License Number: 2301054

CHONG'S CHINESE REST

License Type: Permanent Food Service

1164 W FLAGLER ST, MIAMI 331301034

Inspection Date: 07/06/2009

Inspection Number: 1832755

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: KHAN, MOHAMMAD

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
48-13-2	Violation: 48-13-2 Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.
48-13-2	Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.

License Number: 2330336

FOUR SEASONS HOTEL MIAMI EMPLOYEE CAFETERIA

License Type: Permanent Food Service

1435 BRICKELL AVE, MIAMI 33131

Inspection Date: 07/07/2009

Inspection Number: 1914258

Inspection Type: Complaint Full

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: GARCIA, BARBARO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2330345
 License Type: Permanent Food Service

FOUR SEASONS HOTEL MIAMI BAHIA
 1435 BRICKELL AVE, MIAMI 33131

Inspection Date: 07/07/2009 Inspection Number: 1914259 Inspection Type: Complaint Full Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GARCIA, BARBARO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 2300482
 License Type: Permanent Food Service

CANTON CHINESE RESTAURANT
 2624 PONCE DE LEON BLVD, CORAL GABLES 331346003

Inspection Date: 07/06/2009 Inspection Number: 1853348 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BURROWS, LEON

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-06-2	Ventilation hood not designed to prevent grease or condensation from causing cross-contamination.For reporting purposes only.	NFPA 96, 5.2 Hood Size. Hoods shall be sized and configured to provide for the capture and removal of grease-laden vapors (See 8.2.2.); 8.2.2 Air Volume. 8.2.2.1: Exhaust air volumes for hoods shall be of a sufficient level to provide for capture and removal of grease-laden cooking vapors. 8.2.2.2 Test data, performance acceptable to the authority having jurisdiction, or both, shall be provided, displayed, or both, upon request. 8.2.2.3 Lower exhaust air volumes shall be permitted during no-load cooking conditions provided they are sufficient to capture and remove flue gases and residual vapors from cooking equipment. FOR REPORTING PURPOSES ONLY

Dade County

License Number: 2318312		MCDONALDS RESTAURANT # 7296	
License Type: Permanent Food Service		2940 SW 8 STREET, MIAMI 33135	
Inspection Date: 06/25/2009	Inspection Number: 1914720	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GARCIA, BARBARO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Out of compliance: Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	

License Number: 2328363		LOS VILLARENOS RESTAURANT	
License Type: Permanent Food Service		2516 SW 8 ST, MIAMI 33135	
Inspection Date: 07/09/2009	Inspection Number: 1893892	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GARCIA, BARBARO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 2332005		POLLO CAMPERO	
License Type: Permanent Food Service		2800 SW 8 ST, MIAMI 33135	
Inspection Date: 06/30/2009	Inspection Number: 1914680	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GARCIA, BARBARO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient	

License Number: 2330865		CASA CASOURINA LLC	
License Type: Permanent Food Service		1116 OCEAN DRIVE, MIAMI BEACH 33139	
Inspection Date: 07/08/2009	Inspection Number: 1914788	Inspection Type: Complaint Full	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: RICHARD, DICKSON			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

Dade County

License Number: 2301007 EBEN-EXER RESTAURANT & CAFETERIA
 License Type: Permanent Food Service 2280 NW 20 ST, MIAMI 33142

Inspection Date: 07/07/2009 Inspection Number: 1829240 Inspection Type: Routine - Food Inspection Disposition: Call Back -
 Inspector Name: KHAN, MOHAMMAD Complied

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Violation: 37-20-2 Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY
45-07-2	Violation: 45-07-2 Observed misalignment of hood suppression system nozzles. For reporting purposes only.	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

License Number: 2356767 GUEDELIA HOT DOG
 License Type: Mobile Food Dispensing Vehicle 1880 NW 21ST ST, MIAMI 33142

Inspection Date: 07/08/2009 Inspection Number: 1136343 Inspection Type: Routine - Food Inspection Disposition: Administrative
 Inspector Name: NUNEZ, ANDRES complaint recommended

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-19-2	Mobile food dispensing vehicle lacking a two-stage regulator on the LP-gas line. For reporting purposes only.	NFPA 58, 3.2.12.1 and 3.8.2.7(b) A two-stage regulator system, an integral two-stage regulator, or a two-psi regulator system shall be required on all fixed piping systems that serve 1/2 -psig appliance systems [normally operated at 11 in. w.c. pressure]. The regulators utilized in these systems shall meet the requirements of 2.5.7. This requirement includes fixed piping systems for appliances on RVs (recreational vehicles), mobile home installations, manufactured home installations, catering vehicles, and food service vehicle installations. Single-stage regulators shall not be installed in fixed piping systems after June 30, 1997. Exception No. 1: This requirement does not include small portable appliances and outdoor cooking appliances with input ratings of 100,000 Btu/hr or less. Exception No. 2: Gas distribution systems utilizing multiple second-stage regulators shall be permitted to use a high-pressure regulator installed at the container provided a first-stage regulator is installed downstream of the high-pressure regulator and ahead of the second-stage regulators. Exception No. 3: High-pressure regulators with an overpressure protection device and a rated capacity of more than 500,000 Btu/hr shall be permitted to be used in two-stage systems where the second-stage regulator incorporates an integral or separate overpressure protection device. This overpressure protection device shall limit the outlet pressure of the second-stage regulator to 2.0 psig when the regulator seat disc is removed and with an inlet pressure equivalent to the maximum outlet pressure setting of the high-pressure regulator Exception No. 4: Systems consisting of listed components that provide an equivalent level of overpressure protection. (b) A two-stage regulator system or an integral two-stage regulator in accordance with 3-2.12.1 shall be installed on all vapor withdrawal systems. Regulators shall be protected from the elements in accordance with 3-2.12.4. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2328616 MARHABA MEDITERANEAN CUISINE
 License Type: Permanent Food Service 5701 SUNSET DRIVE, MIAMI 33143

Inspection Date: 07/06/2009 Inspection Number: 1864226 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CONYERS,

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.dishwasher area.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 2327024 ALTA COCINA
 License Type: Permanent Food Service 5837 SUNSET DR, SOUTH MIAMI 33143

Inspection Date: 07/06/2009 Inspection Number: 1894818 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: CONYERS,

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 2319241 EL RINCON CRIOLLO RESTAURANT
 License Type: Permanent Food Service 6752 W FLAGLER STREET, MIAMI 33144

Inspection Date: 07/08/2009 Inspection Number: 1830719 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: STERLING, DANIEL

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only. 07/2008.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

License Number: 2317079 LA ZARAGOZANA RESTAURANT
 License Type: Permanent Food Service 8488 SW 8 ST, WEST MIAMI 33144

Inspection Date: 07/06/2009 Inspection Number: 1873960 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: STERLING, DANIEL

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY
45-37-2	Portable fire extinguisher missing from designated location. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2330361

QUIZNOS SUBS

License Type: Permanent Food Service

2490 SW 17 AVENUE, MIAMI 33145

Inspection Date: 07/06/2009

Inspection Number: 1682481

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Complied

Inspector Name: GANDOLFF, JORGE

Violation CodeObservationViolation Citation

37-20-2

Violation: 37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2301044

SNAPER FISH & CHICKEN

License Type: Permanent Food Service

8995 NW 7 AVE, MIAMI 33150

Inspection Date: 07/08/2009

Inspection Number: 1873170

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: URIARTE, DENNIS

Violation CodeObservationViolation Citation

37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2328679

CHARLES COIN LAUNDRY SNACK & GAMEROOM

License Type: Permanent Food Service

105 NW 62ND STREET, MIAMI 33150

Inspection Date: 07/06/2009

Inspection Number: 1904035

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: URIARTE, DENNIS

Violation CodeObservationViolation Citation

45-36-2

Hood suppression system tag out-of-date. For reporting purposes only.

NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2319089 EL PUNTO DEL CAFE
 License Type: Permanent Food Service 4421 SW 75 AVENUE, MIAMI 33155

Inspection Date: 07/06/2009 Inspection Number: 1843323 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GANDOLFF, JORGE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-12-2	No ground fault interruption protection on electrical outlet located within six feet of a water source. For reporting purposes only.	NFPA 70, 210.8 Ground-Fault Circuit-Interrupter Protection for Personnel. (A) Dwelling Units. All 125-volt, single-phase, 15- and 20-ampere receptacles installed in the locations specified shall have ground-fault circuit-interrupter protection for personnel. (1) Bathrooms; (6) Kitchens - where the receptacles are installed to serve the countertop surfaces; (7) Wet bar sinks - where the receptacles are installed to serve the countertop surfaces and are located within 6 ft of the outside edge of the wet bar sink. (B) Other Than Dwelling Units. All 125-volt, single-phase, 15- and 20-ampere receptacles installed in the locations specified in (1), (2), and (3) shall have ground-fault circuit-interrupter protection for personnel: (1) Bathrooms; (2) Rooftops; Exception: Receptacles that are not readily accessible and are supplied from a dedicated branch circuit for electric snow-melting or deicing equipment shall be permitted to be installed in accordance with the applicable provisions of Article 426. (3) Kitchens. FOR REPORTING PURPOSES ONLY.

License Number: 2323130 MARLENES CAFE
 License Type: Permanent Food Service 8665 SW 24 ST, MIAMI 33155

Inspection Date: 07/10/2009 Inspection Number: 1853584 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GANDOLFF, JORGE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
39-03-2	Exhaust system off during the operation of cooking equipment. For reporting purposes only.	NFPA 96, 11.1.1 Exhaust systems shall be operated whenever cooking equipment is turned on. For reporting purposes only.
45-36-2	Hood suppression system tag missing. For reporting purposes only.	NFPA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

License Number: 2330738 MAO FAST FOOD
 License Type: Permanent Food Service 8438 SW 40 ST, # 125, MIAMI 33155

Inspection Date: 07/08/2009 Inspection Number: 1853566 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GANDOLFF, JORGE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood filters not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

Dade County

License Number: 2313817 COSMES PLACE
 License Type: Permanent Food Service 8390 BIRD RD, MIAMI 331553355

Inspection Date: 07/08/2009 Inspection Number: 1894448 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: GANDOLFF, JORGE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2315872 BANGKOK CITY
 License Type: Permanent Food Service 7378 SW 40 ST, MIAMI 331556634

Inspection Date: 07/06/2009 Inspection Number: 1832977 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GANDOLFF, JORGE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 2328082 IMLEE AN INDIAN BISTRO
 License Type: Permanent Food Service 12663 S DIXIE HWY, KENDALL 33156

Inspection Date: 07/07/2009 Inspection Number: 1843327 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DE LA CRUZ, ADONIS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2328381		LAS CULEBRINAS IN PINECREST	
License Type: Permanent Food Service		12257 S DIXIE HWY, KENDALL 33156	
Inspection Date: 07/06/2009	Inspection Number: 1853648	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DE LA CRUZ, ADONIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 2332046		DADELAND INDIGO HOTEL	
License Type: Permanent Food Service		7600 NORTH KENDALL DRIVE, MIAMI 33156	
Inspection Date: 07/06/2009	Inspection Number: 1905017	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DE LA CRUZ, ADONIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only.	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.	
License Number: 2321148		BIG HOOLI'S SPORTS BAR & GRILL	
License Type: Permanent Food Service		9555 S DIXIE HWY, PINECREST 33156	
Inspection Date: 07/07/2009	Inspection Number: 1874122	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DE LA CRUZ, ADONIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
License Number: 2300392		MCDONALDS UNIT #6280	
License Type: Permanent Food Service		12647 S DIXIE HWY, MIAMI 331565931	
Inspection Date: 07/08/2009	Inspection Number: 1884325	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DE LA CRUZ, ADONIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	

Dade County

License Number: 2324765

JOHNNY ROCKETS

License Type: Permanent Food Service

7439 KENDALL DR, MIAMI 331567702

Inspection Date: 07/07/2009

Inspection Number: 1843343

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: DE LA CRUZ, ADONIS

Violation CodeObservationViolation Citation

46-05-2

Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.backdoor

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 2312404

STEVE'S PIZZA

License Type: Permanent Food Service

18063 SOUTH DIXIE HWY, MIAMI 33157

Inspection Date: 07/10/2009

Inspection Number: 1682269

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: DE LA CRUZ, ADONIS

Violation CodeObservationViolation Citation

37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2328818

JERRY AND JOES PIZZA

License Type: Permanent Food Service

9873 SW 184 ST, MIAMI 33157

Inspection Date: 07/08/2009

Inspection Number: 1884315

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: DE LA CRUZ, ADONIS

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 2325142

POLLO TROPICAL 21

License Type: Permanent Food Service

11670 SW 152 STREET, MIAMI 331571100

Inspection Date: 07/10/2009

Inspection Number: 1833049

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: DE LA CRUZ, ADONIS

Violation CodeObservationViolation Citation

37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

Dade County

License Number: 2325064		POPEYES FAMOUS FRIED CHICKEN 4	
License Type: Permanent Food Service		11205 SW 152 ST, MIAMI 331571101	
Inspection Date: 07/10/2009	Inspection Number: 1905005	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DE LA CRUZ, ADONIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	

License Number: 2322209		OCEANIA CLUB	
License Type: Permanent Food Service		16421 COLLINS AVE, MIAMI BEACH 331604545	
Inspection Date: 07/08/2009	Inspection Number: 1873462	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: TONEY, BRANDY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For ventilation purposes, according to management. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

License Number: 2300906		LA SIRENA RESTAURANT	
License Type: Permanent Food Service		9706 SW 40 STREET, MIAMI 33165	
Inspection Date: 07/08/2009	Inspection Number: 1894476	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GANDOLFF, JORGE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood filters not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	

License Number: 2328410		WENDY'S #2522	
License Type: Permanent Food Service		1651 SW 107 AVE, MIAMI 33165	
Inspection Date: 07/10/2009	Inspection Number: 1874056	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GANDOLFF, JORGE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.Boxes in front of backdoor	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	

Dade County

License Number: 2321838 MCDONALDS OF MILLER EAST
 License Type: Permanent Food Service 9341 SW 56 ST, MIAMI 331656528

Inspection Date: 07/10/2009 Inspection Number: 1894450 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GANDOLFF, JORGE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood filters not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 2356710 EL PALADAR DE VOLAITA
 License Type: Mobile Food Dispensing Vehicle 3946 CURTIS PKWY, VIRGINIA GARDENS 33166

Inspection Date: 07/08/2009 Inspection Number: 1133091 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: NUNEZ, ANDRES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-19-2	Mobile food dispensing vehicle lacking a two-stage regulator on the LP-gas line. For reporting purposes only.	NFPA 58, 3.2.12.1 and 3.8.2.7(b) A two-stage regulator system, an integral two-stage regulator, or a two-psi regulator system shall be required on all fixed piping systems that serve 1/2 -psig appliance systems [normally operated at 11 in. w.c. pressure]. The regulators utilized in these systems shall meet the requirements of 2.5.7. This requirement includes fixed piping systems for appliances on RVs (recreational vehicles), mobile home installations, manufactured home installations, catering vehicles, and food service vehicle installations. Single-stage regulators shall not be installed in fixed piping systems after June 30, 1997. Exception No. 1: This requirement does not include small portable appliances and outdoor cooking appliances with input ratings of 100,000 Btu/hr or less. Exception No. 2: Gas distribution systems utilizing multiple second-stage regulators shall be permitted to use a high-pressure regulator installed at the container provided a first-stage regulator is installed downstream of the high-pressure regulator and ahead of the second-stage regulators. Exception No. 3: High-pressure regulators with an overpressure protection device and a rated capacity of more than 500,000 Btu/hr shall be permitted to be used in two-stage systems where the second-stage regulator incorporates an integral or separate overpressure protection device. This overpressure protection device shall limit the outlet pressure of the second-stage regulator to 2.0 psig when the regulator seat disc is removed and with an inlet pressure equivalent to the maximum outlet pressure setting of the high-pressure regulator Exception No. 4: Systems consisting of listed components that provide an equivalent level of overpressure protection. (b) A two-stage regulator system or an integral two-stage regulator in accordance with 3-2.12.1 shall be installed on all vapor withdrawal systems. Regulators shall be protected from the elements in accordance with 3-2.12.4. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2301079

WESTVIEW C C MENS LNG

License Type: Permanent Food Service

2601 NW 119 ST, MIAMI 331672665

Inspection Date: 07/08/2009

Inspection Number: 1864276

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CHOW, ZULEIMA

Violation Code

Observation

Violation Citation

48-12-2 No current boiler certification provided/available. EXP 4/6/08 For reporting purposes only.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2302524

WEST VIEW C C SNK BAR

License Type: Permanent Food Service

2601 NW 119 ST, MIAMI 331672665

Inspection Date: 07/08/2009

Inspection Number: 1853958

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CHOW, ZULEIMA

Violation Code

Observation

Violation Citation

48-12-2 No current boiler certification provided/available. EXP 4/6/08 For reporting purposes only.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2302525

WEST VIEW C C LADIES L

License Type: Permanent Food Service

2601 NW 119 ST, MIAMI 331672665

Inspection Date: 07/08/2009

Inspection Number: 1905335

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CHOW, ZULEIMA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. EXP 4/6/08 For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2302554 W VIEW CO CLUB DIN RM
 License Type: Permanent Food Service 2601 NW 119 ST, MIAMI 331672665

Inspection Date: 07/08/2009 Inspection Number: 1853962 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CHOW, ZULEIMA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. EXP 4/6/08 For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 2317866 MCDONALD'S
 License Type: Permanent Food Service 15096 NW 7 AVE, MIAMI 33168

Inspection Date: 07/08/2009 Inspection Number: 1842514 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: PIERRE, KEVON

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 2318999 NEW ROSEAU RESTAURANT
 License Type: Permanent Food Service 12900 NW 7 AVE, MIAMI 33168

Inspection Date: 07/01/2009 Inspection Number: 1893654 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: PIERRE, KEVON

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

Dade County

License Number: 2332126

COURTYARD BY MARRIOTT MIAMI DOLPHIN MALL

License Type: Permanent Food Service

11275 NW 12TH STREET, MIAMI 33172

Inspection Date: 07/06/2009

Inspection Number: 1873964

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: STERLING, DANIEL

Violation CodeObservationViolation Citation

45-35-2

No current hood fire suppression system inspection report available. For reporting purposes only. DATE:12/2008. GENERAL MANAGER INDICATES THAT A SCHEDULED APPOINTMENT IS CURRENT FOR THURSDAY 07/09/09.

NFPA 1, 13.1.5 and 10.2.2 Detailed records documenting all systems and equipment testing and maintenance shall be kept by the property owner and shall be made available upon request for review by the AHJ. The AHJ shall be permitted to require the owner, operator, or occupant to provide tests or test reports, without expense to the AHJ, as proof of compliance with the intent of this Code. FOR REPORTING PURPOSES ONLY.

License Number: 2315369

LUCHO'S RESTAURANT

License Type: Permanent Food Service

5628 SW 102 AVENUE, MIAMI 33173

Inspection Date: 07/10/2009

Inspection Number: 1864000

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: VALDERRAMA, ELISA

Violation CodeObservationViolation Citation

45-40-2

Portable fire extinguisher with no approved inspection tag. For reporting purposes only.class k

61C-1.004(9)(b) FAC and NFPA 10, 6.3.4 A standard state approved service tag shall be attached to each extinguisher and a person holding a valid state permit issued by the State Fire Marshal shall recharge or inspect the extinguisher and shall prepare the tag to include the information required by rule 4A-21.241, FAC, herein adopted by reference. Maintenance Recordkeeping. Each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was performed and that identifies the person performing the service. FOR REPORTING PURPOSES ONLY.

45-41-2

Portable fire extinguisher tag out-of-date. For reporting purposes only.all tags marked 1/08

NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

License Number: 2355103

CUE CAFETERIA

License Type: Mobile Food Dispensing Vehicle

11355 NW SOUTH RIVER DRIVE, MIAMI 33178

Inspection Date: 07/07/2009

Inspection Number: 1134455

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: NUNEZ, ANDRES

Violation CodeObservationViolation Citation

37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

Dade County

License Number: 2315217

TRATTORIA IL MIGLIORE OF AVENTURA

License Type: Permanent Food Service

2576 MIAMI GARDEN DR, NORTH MIAMI BEACH 33180

Inspection Date: 07/06/2009

Inspection Number: 1893856

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: TONEY, BRANDY

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 2316026

PRITIKIN LONGEVITY CENTER

License Type: Permanent Food Service

19735 TURNBERRY WAY, AVENTURA 331802590

Inspection Date: 07/06/2009

Inspection Number: 1671439

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Admin. complaint recommended

Inspector Name: TONEY, BRANDY

Violation CodeObservationViolation Citation

15-28-2

Violation: 15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 2330289

LAZEEZ ASIAN CUISINE

License Type: Permanent Food Service

13919 SW 66 STREET, MIAMI 33183

Inspection Date: 07/08/2009

Inspection Number: 1821721

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Admin. complaint recommended

Inspector Name: VALDERRAMA, ELISA

Violation CodeObservationViolation Citation

45-07-2

Violation: 45-07-2

Observed misalignment of hood suppression system nozzles. For reporting purposes only. gas tandoori oven has no nozzle above it

NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

47-07-2

Violation: 47-07-2

Observed grease residue around electrical outlet. For reporting purposes only. next to microwave

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2326261		SUBWAY	
License Type: Permanent Food Service		12046 SW 88 ST, MIAMI 33186	
Inspection Date: 07/10/2009	Inspection Number: 1884411	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: VALDERRAMA, ELISA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-13-2	Circuit breaker box blocked and/or inaccessible. For reporting purposes only.blocked by chip rack	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.	
License Number: 2332459		JAM-ROCK CUISINE	
License Type: Permanent Food Service		12618 SW 88TH ST, MIAMI 33186	
Inspection Date: 07/08/2009	Inspection Number: 1863960	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: VALDERRAMA, ELISA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-15-2	No placard placed near Class K portable fire extinguisher stating the fire suppression system must be activated prior to use of the portable extinguisher. For reporting purposes only.	NFPA 10, 4.3.2.2 A placard shall be conspicuously placed near the extinguisher that states that the fire protection system shall be activated prior to using the fire extinguisher. FOR REPORTING PURPOSES ONLY.	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.class k Corrected On Site.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
License Number: 2325033		CHINA CHINA	
License Type: Permanent Food Service		20505 S DIXIE HWY #1845, MIAMI 331891228	
Inspection Date: 07/07/2009	Inspection Number: 1905171	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BROWN, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
48-13-2	Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.	
License Number: 2330586		CREPEMANIA JUICE BAR	
License Type: Permanent Food Service		15520 SW 72 ST, MIAMI 33193	
Inspection Date: 07/07/2009	Inspection Number: 1914666	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: NUNEZ, ANDRES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	

Duval County

License Number: 2614328 CHURCHS CHICKEN
 License Type: Permanent Food Service 5870 NORMANDY BLVD, JACKSONVILLE 32205

Inspection Date: 07/09/2009 Inspection Number: 1839231 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: RIVERA, STEVEN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces FRYER STATION hood missing filter. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor found on ground in mop sink area. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 2611985 DEWEY'S BAR-B-Q
 License Type: Permanent Food Service 1733 E 21 ST, JACKSONVILLE 32206

Inspection Date: 07/08/2009 Inspection Number: 1881068 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: YOUNG, DERRICK

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-05-2	Observed unprotected gas meter subject to vehicle damage. For reporting purposes only. Repeat Violation.	NFPA 54, 2.7.2(b) (b) Gas meters shall not be placed where they will be subjected to damage, such as adjacent to a driveway, under a fire escape, in public passages, halls, coal bins, or where they will be subjected to excessive corrosion or vibration. FOR REPORTING PURPOSES ONLY.

Duval County

License Number: 2612672

CARL'S MAIN ST RESTAURANT

License Type: Permanent Food Service

1748 N MAIN ST, JACKSONVILLE 32206

Inspection Date: 07/08/2009

Inspection Number: 1881066

Inspection Type: Routine - Food

Inspection Disposition: Administrative
complaint recommended

Inspector Name: YOUNG, DERRICK

Violation CodeObservationViolation Citation

46-07-2	Exit signs missing. For reporting purposes only. Over backroom door;	NFPA 101, 7.10.1.2 Exits, other than main exterior exit doors that obviously and clearly are identifiable as exits, shall be marked by an approved sign readily visible from any direction of exit access. FOR REPORTING PURPOSES ONLY.
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only. hanging behind front counter;	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-08-2	Observed electrical wiring in disrepair. For reporting purposes only. Electricity socket hanging out the wall; cook's line behind steam table;	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
48-05-2	Observed unprotected gas meter subject to vehicle damage. For reporting purposes only. Behind the building	NFPA 54, 2.7.2(b) Gas meters shall not be placed where they will be subjected to damage, such as adjacent to a driveway, under a fire escape, in public passages, halls, coal bins, or where they will be subjected to excessive corrosion or vibration. FOR REPORTING PURPOSES ONLY.

License Number: 2613163

YANG'S TAKE OUT

License Type: Permanent Food Service

1935 N MAIN ST, JACKSONVILLE 32206

Inspection Date: 07/08/2009

Inspection Number: 1891220

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: YOUNG, DERRICK

Violation CodeObservationViolation Citation

45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. ABC nor K CLASS	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
---------	--	---

Duval County

License Number: 2614043

ISLAND TROPICS RESTAURANT

License Type: Permanent Food Service

2527 N MAIN ST, JACKSONVILLE 32206

Inspection Date: 07/06/2009

Inspection Number: 1870767

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: YOUNG, DERRICK

Violation CodeObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.
Powering heat lamps

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 2614360

WAFAA & MIKES CAFE

License Type: Permanent Food Service

1544 NORTH MAIN ST, JACKSONVILLE 32206

Inspection Date: 07/02/2009

Inspection Number: 1901547

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: YOUNG, DERRICK

Violation CodeObservationViolation Citation

47-05-2 Observed a splitter/multi-plug adapter in use. For reporting purposes only.
In the office;

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-16-2 Electrical outlet missing cover plate. For reporting purposes only.
In the office;

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

47-16-2 Electrical outlet cover plate broken; For reporting purposes only.
Over 3 compartment sink

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 2600685

KRYSTAL JAX-09

License Type: Permanent Food Service

7459 LEM TURNER RD, JACKSONVILLE 322083350

Inspection Date: 07/09/2009

Inspection Number: 1911903

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: DAVIS, MOSES

Violation CodeObservationViolation Citation

46-05-2 Observed obstructed exits, stairs, hallways or egress. For reporting purposes only,
REAR. Corrected On Site.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

Duval County

License Number: 2612567

PAUL'S HOMESTYLE COOKING

License Type: Permanent Food Service

5306 N MAIN ST, JACKSONVILLE 322085324

Inspection Date: 07/02/2009

Inspection Number: 1870951

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: DAVIS, MOSES

Violation CodeObservationViolation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only, EAST SIDE DINNING ROOM.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

47-08-2

Observed electrical wiring in disrepair. For reporting purposes only, CORD FOR LINE WARMER.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 2613037

TOP CHINA

License Type: Permanent Food Service

2261 EDGEWOOD AVENUE W #18, JACKSONVILLE 32209

Inspection Date: 07/08/2009

Inspection Number: 1914790

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DAVIS, MOSES

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only, FOR RICE STEAMER.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Duval County

License Number: 2614064 J J'S CRAB HOUSE
 License Type: Permanent Food Service 1963 KINGS RD UNIT 3, JACKSONVILLE 32209

Inspection Date: 07/08/2009 Inspection Number: 1914791 Inspection Type: Complaint Full Inspection Disposition: Warning Issued
 Inspector Name: DAVIS, MOSES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only, LOBBY / BUG ZAPPER.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-15-2	Observed an uncovered electrical box. For reporting purposes only, OVER SHELF IN KITCHEN .	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.
47-15-2	Observed an uncovered electrical box. For reporting purposes only, NEAR DISPLAY CASE.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 2608448 POPEYES CHICKEN & BUSCUIT #160
 License Type: Permanent Food Service 2143 W EDGEWOOD AVE, JACKSONVILLE 322092554

Inspection Date: 07/08/2009 Inspection Number: 1860666 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DAVIS, MOSES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-2	Exit signs not properly illuminated. For reporting purposes only, REAR DOOR	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 2607636 POPEYES CHICKEN&BISCUITS #153
 License Type: Permanent Food Service 1833 KINGS RD, JACKSONVILLE 322095347

Inspection Date: 07/06/2009 Inspection Number: 1881252 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DAVIS, MOSES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-03-2	Observed unused opening in panel box unprotected. For reporting purposes only, NEAR FOOD LINE.	NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.

License Number: 2613746 PIZZA BLITZ
 License Type: Permanent Food Service 8101 OLD KINGS RD S #6, JACKSONVILLE 32217

Inspection Date: 07/01/2009 Inspection Number: 1870611 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: BRADSHAW, BONNIE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair

Duval County

License Number: 2614086

ORANGE TREE

License Type: Permanent Food Service

840 NAUTICA DR BLDG 125, JACKSONVILLE 32218

Inspection Date: 07/07/2009

Inspection Number: 1881260

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: DAVIS, MOSES

Violation CodeObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only, KITCHEN .

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 2612021

MCDONALDS #18308

License Type: Permanent Food Service

13217 ATLANTIC BLVD, JACKSONVILLE 32225

Inspection Date: 07/06/2009

Inspection Number: 1870837

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: CARANGIAN, REYNALDO

Violation CodeObservationViolation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 2613317

DICKS WINGS & GRILL

License Type: Permanent Food Service

2434 MAYPORT RD, ATLANTIC BEACH 32233

Inspection Date: 07/08/2009

Inspection Number: 1839948

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: CARANGIAN, REYNALDO

Violation CodeObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only./ front wait station.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Duval County

License Number: 2612282	SIMPLY TASTY THAI		
License Type: Permanent Food Service	2292 MAYPORT RD #8, JACKSONVILLE 32233		
Inspection Date: 07/08/2009	Inspection Number: 1870823	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CARANGIAN, REYNALDO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only./ kitchen area.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 2612569	THE CRABCAKE FACTORY		
License Type: Permanent Food Service	1396 BEACH BLVD, JACKSONVILLE BEACH 32250		
Inspection Date: 07/09/2009	Inspection Number: 1860526	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CARANGIAN, REYNALDO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only./ warewashing area.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 2613561	LA NOPALERA MEXICAN RESTAURANT		
License Type: Permanent Food Service	14333 BEACH BLVD #39, JACKSONVILLE BEACH 32250		
Inspection Date: 07/02/2009	Inspection Number: 1699607	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Complied
Inspector Name: STOREY, MARIE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient	

License Number: 2613718	GUMBO YAYA'S		
License Type: Permanent Food Service	14333-101 BEACH BLVD, JACKSONVILLE BEACH 32250		
Inspection Date: 07/02/2009	Inspection Number: 1881102	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: STOREY, MARIE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. hallway - backdoor	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	

Duval County

License Number: 2610682

MCDONALD'S RESTAURANT

License Type: Permanent Food Service

11230 OLD ST AUGUSTINE RD #11738, JACKSONVILLE 32257

Inspection Date: 07/06/2009

Inspection Number: 1914453

Inspection Type: Complaint Full

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BRADSHAW, BONNIE

Violation Code

Observation

Violation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. Corrected On Site.
Repeat Violation.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Escambia County

License Number: 2705781

NEW YORK NICKS

License Type: Permanent Food Service

11 S PALAFOX, PENSACOLA 32501

Inspection Date: 07/02/2009

Inspection Number: 1861563

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: RILEY, DAVID

Violation CodeObservationViolation Citation

45-07-2

Observed missing hood filter. For reporting purposes only.

NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

45-39-2

Portable ABC fire extinguisher at bar not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 2702615

WHATABURGER

License Type: Permanent Food Service

417 E GREGORY ST, PENSACOLA 32502

Inspection Date: 07/07/2009

Inspection Number: 1861559

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: RILEY, DAVID

Violation CodeObservationViolation Citation

45-07-2

Observed gaps hood filters at grill. For reporting purposes only.

NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

License Number: 2706045

SOIREE CATERING AND EVENTS

License Type: Permanent Food Service

196 N PALAFOX ST, PENSACOLA 32502

Inspection Date: 07/09/2009

Inspection Number: 1861583

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: RILEY, DAVID

Violation CodeObservationViolation Citation

45-39-2

Portable ABC fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.
Corrected On Site.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Escambia County

License Number: 2705910

LOST KEY GOLF CLUB

License Type: Permanent Food Service

625 LOST KEY DR, PENSACOLA 32507

Inspection Date: 07/08/2009

Inspection Number: 1891560

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: RILEY, DAVID

Violation CodeObservationViolation Citation

45-39-2

Portable k class fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 2706023

MIGUELS

License Type: Permanent Food Service

3230 B W MICHIGAN AVE, PENSACOLA 32526

Inspection Date: 07/08/2009

Inspection Number: 1860833

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: RILEY, DAVID

Violation CodeObservationViolation Citation

45-39-2

Portable k class fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Flagler County

License Number: 2800424

ROADHOUSE (THE)

License Type: Permanent Food Service

3345 S OLD KINGS RD, FLAGLER BCH 32136

Inspection Date: 07/08/2009

Inspection Number: 1859604

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: SCARPELLI, DAVID

Violation Code

Observation

Violation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. STORAGE ROOM

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Franklin County

License Number: 2901216

PIT STOP

License Type: Permanent Food Service

1637 HWY 98 W, CARRABELLE 32322

Inspection Date: 07/10/2009

Inspection Number: 1825884

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PRAGER, JOAN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-42-2	Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.	NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY
45-30-2	No Class K portable fire extinguisher provided for high hazard cooking area (for suppression system/equipment installed after June 30, 1998). For reporting purposes only.	NFPA 10, 4.3.2. and 4.3.2.1 Class K Fire Extinguishers for Cooking Oil Fires. Fire extinguishers provided for the protection of cooking appliances that use combustible cooking media (vegetable or animal oils and fats) shall be listed and labeled for Class K fires. Class K fire extinguishers manufactured after January 1, 2002, shall not be equipped with extended wand-type discharge devices. Fire extinguishers installed specifically for the protection of cooking appliances that use combustible cooking media (animal, vegetable oils and fats) prior to June 30, 1998, shall not be required to comply with 4.3.2. (Also see 4.3.2.3.). FOR REPORTING PURPOSES ONLY.
46-07-2	Exit sign missing at enclosed porch door. For reporting purposes only.	NFPA 101, 7.10.1.2 Exits, other than main exterior exit doors that obviously and clearly are identifiable as exits, shall be marked by an approved sign readily visible from any direction of exit access. FOR REPORTING PURPOSES ONLY.
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.
47-03-2	Observed unused opening in panel box unprotected. For reporting purposes only.	NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.
47-15-2	Observed an uncovered electrical box. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.
47-16-2	Electrical outlets and light switch missing cover plate, cashier area. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Gadsden County

License Number: 3000130

HARDEES OF CHATTAHOOCHEE

License Type: Permanent Food Service

651 W WASHINGTON ST, CHATTAHOOCHEE 32324

Inspection Date: 07/09/2009

Inspection Number: 1912589

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: HARGROVE, DAVID

Violation Code

Observation

Violation Citation

45-38-2

Portable fire extinguisher not fully charged. For reporting purposes only. FRONT COUNTER AREA.

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

Gulf County

License Number: 3300746

PORT INN

License Type: Permanent Food Service

501 MONUMENT AVENUE, PORT SAINT JOE 32456

Inspection Date: 07/09/2009

Inspection Number: 1881794

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: HARDING, LINDA

Violation Code

Observation

Violation Citation

45-41-2 Portable fire extinguisher tag out-of-date. Observed tag date of 2-08. For reporting purposes only.

NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

Hernando County

License Number: 3701005 THE BROOK HOUSE
 License Type: Permanent Food Service 2701 FOREST RD, SPRING HILL 34606

Inspection Date: 07/09/2009 Inspection Number: 1888060 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GLENN, DAVID

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3700314 BRIAN'S PLACE
 License Type: Permanent Food Service 3306 SHOAL LINE BLVD, SPRING HILL 34607

Inspection Date: 07/10/2009 Inspection Number: 1908542 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GLENN, DAVID

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only. Small flat top grill used for cooking sausages not under hood system.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. Extension cords powering roadside sign and decorative lighting on building.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Hernando County

License Number: 3750137

PADDLERS

License Type: Mobile Food Dispensing Vehicle

29295 LAKE LINDSEY RD, NOBLETON 34661

Inspection Date: 07/06/2009

Inspection Number: 1137215

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DANCHO, JOHN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
47-15-2	Observed an uncovered electrical box...interior plate missing to panel box. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Highlands County

License Number: 3800941

JANS COUNTRY KITCHEN

License Type: Permanent Food Service

312 W INTERLAKE BLVD, LAKE PLACID 33852

Inspection Date: 07/10/2009

Inspection Number: 1852506

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: SCHNELL, PAMELA

Violation Code

Observation

Violation Citation

45-33-2

Current hood suppression system report lists violations. Notified Fire AHJ. For reporting purposes only.hood suppression tanks leaking /corrosion evident on tanks and connections-dripping onto electrical outlet at back fryer hood suppression unit

NFPA 96, 4.1.2, 4.1.3, 4.1.4 and 4.1.5 All such equipment and its performance shall be maintained in accordance with the requirements of this standard during all periods of operation of the cooking equipment. The following equipment shall be kept in good working condition: (1) Cooking equipment (2) Hoods (3) Ducts (if applicable) (4) Fans (5) Fire-extinguishing systems (6) Special effluent or energy control equipment All airflows shall be maintained. Maintenance and repairs shall be performed on all components at intervals necessary to maintain these conditions. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3912936

CHINA STAR RESTAURANT

License Type: Permanent Food Service

16733 FISHHAWK BLVD, LITHIA 33547

Inspection Date: 07/06/2009

Inspection Number: 1908164

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: BOWEN, JEFFREY

Violation CodeObservationViolation Citation

46-05-2

Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.
Do not pile empty-chicken cases outside of the rear-kitchen fire-exit door.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 3916241

ANGELINAS BAGEL CAFE

License Type: Permanent Food Service

16721 FISH HAWK BLVD, LITHIA 33547

Inspection Date: 07/06/2009

Inspection Number: 1877414

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: BOWEN, JEFFREY

Violation CodeObservationViolation Citation

47-04-2

Observed sessed electrical wiring. For reporting purposes only. Move the display cooler nearer to the electrical-wall outlet, so as to relieve the stress on the electrical cord.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3951581

ANDREA LEON

License Type: Mobile Food Dispensing Vehicle

4109 A HWY 574, PLANT CITY 33563

Inspection Date: 07/01/2009

Inspection Number: 1133033

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: BOWEN, JEFFREY

Violation CodeObservationViolation Citation

45

Out of compliance: Fire extinguishers - proper and sufficient

NFPA 101, 96, 10 Fire extinguishers - proper and sufficient

License Number: 3916455

ANDREA'S CAFE

License Type: Permanent Food Service

7415 US 301 N, RIVERVIEW 33569

Inspection Date: 07/01/2009

Inspection Number: 1827025

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: BOWEN, JEFFREY

Violation CodeObservationViolation Citation

45

Out of compliance: Fire extinguishers - proper and sufficient

NFPA 101, 96, 10 Fire extinguishers - proper and sufficient

Hillsborough County

License Number: 3912959

TASTE OF BOSTON

License Type: Permanent Food Service

5314 INTERBAY BLVD, TAMPA 33611

Inspection Date: 07/10/2009

Inspection Number: 1836147

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: CANNELLA, MARK

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3915426

VINO E PASTA

License Type: Permanent Food Service

3603 GANDY BLVD, TAMPA 33611

Inspection Date: 07/09/2009

Inspection Number: 1846373

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: CANNELLA, MARK

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3915718

RAMON'S CUBANS

License Type: Permanent Food Service

4053 S DALE MABRY HWY, TAMPA 33611

Inspection Date: 07/09/2009

Inspection Number: 1887351

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: CANNELLA, MARK

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3906211

THE GARDENS REST

License Type: Permanent Food Service

5201 E BUSCH BLVD, TAMPA 33617

Inspection Date: 07/10/2009

Inspection Number: 1835953

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: EDMISTON, ROBERT

Violation CodeObservationViolation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

47-04-2 Observed frayed/spliced electrical wires.....light in storeroom. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3916298

KABAB KORNER

License Type: Permanent Food Service

7521 N 56 ST, TAMPA 33617

Inspection Date: 07/06/2009

Inspection Number: 1877010

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: EDMISTON, ROBERT

Violation CodeObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3916578

BABYLON HOOKAH LOUNGE

License Type: Permanent Food Service

4812 E. BUSCH BLVD SUITE A, TAMPA 33617

Inspection Date: 07/10/2009

Inspection Number: 1897497

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: EDMISTON, ROBERT

Violation CodeObservationViolation Citation49-12-2 Observed 20 lb container of propane stored in establishment. For reporting purposes only.
Corrected On Site.

61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3916664

HAAGEN DAZS NESTLE TOLL HOUSE

License Type: Permanent Food Service

8035 CITRUS PARK TOWN CENTER, TAMPA 33625

Inspection Date: 07/10/2009

Inspection Number: 1830389

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PETERSON, DOUGLAS

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3911477

DELOSA'S PIZZERIA

License Type: Permanent Food Service

4110 HENDERSON BLVD, TAMPA 33629

Inspection Date: 07/09/2009

Inspection Number: 1856618

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CANNELLA, MARK

Violation CodeObservationViolation Citation

46-14-2

Emergency lighting not provided. Notified Fire AHJ. For reporting purposes only. at back door.

NFPA 101, 7.9.1.1 Emergency lighting facilities for means of egress shall be provided in accordance with Section 7.9 for the following: (1) Buildings or structures where required in Chapter 11 through Chapter 42 (2) Underground and limited access structures as addressed in Section 11.7 (3) High-rise buildings as required by other sections of this Code (4) Doors equipped with delayed-egress locks (5) Stair shaft and vestibule of smokeproof enclosures, for which the following also apply: (a) The stair shaft and vestibule shall be permitted to include a standby generator that is installed for the smokeproof enclosure mechanical ventilation equipment. (b) The standby generator shall be permitted to be used for the stair shaft and vestibule emergency lighting power supply. FOR REPORTING PURPOSES ONLY.

License Number: 3916277

ROMANOS RESTAURANT

License Type: Permanent Food Service

20685 BRUCE D DOWN BLVD, TAMPA 33647

Inspection Date: 07/07/2009

Inspection Number: 1813923

Inspection Type: Routine - Food

Inspection Disposition: Call Back - Complied

Inspector Name: CHEW, TEOW

Violation CodeObservationViolation Citation

45-34-2

Violation: 45-34-2

Fire alarm control panel has no tag/tag not for most recent service, repair, test or inspection. For reporting purposes only.

69A-48.006(1) FAC (1) A standard Fire Alarm tag meeting the requirements of this rule shall be securely affixed to the fire alarm control panel of each fire alarm system which is installed, and each time such system is serviced, tested, repaired, inspected, or improved by any person. FOR REPORTING PURPOSES ONLY.

Indian River County

License Number: 4100386

INTERNATIONAL HOUSE OF PANCAKES 36-88

License Type: Permanent Food Service

1838 US HWY 1, VERO BEACH 32960

Inspection Date: 07/10/2009

Inspection Number: 1868058

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: SCHOENLY, BARBARA

Violation Code

Observation

Violation Citation

47-15-2

Observed an uncovered electrical box./under dishmachine For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Jackson County

License Number: 4200396

HARDEE'S

License Type: Permanent Food Service

4652 E LAFAYETTE ST, MARIANNA 32446

Inspection Date: 07/06/2009

Inspection Number: 1871541

Inspection Type: Complaint Full

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: HARDING, LINDA

Violation CodeObservationViolation Citation

45-38-2

Portable fire extinguisher not fully charged. For reporting purposes only.

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

License Number: 4200491

KFC/LONG JOHN SILVERS RESTAURANT #15

License Type: Permanent Food Service

2242 N HWY 71, MARIANNA 32448

Inspection Date: 07/06/2009

Inspection Number: 1871511

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: HARDING, LINDA

Violation CodeObservationViolation Citation

39-05-2

Ventilation inadequate as evidenced by smoke in kitchen area. For reporting purposes only.

NFPA 96, 4.1.1 Cooking equipment used in processes producing smoke or grease-laden vapors shall be equipped with an exhaust system that complies with all the equipment and performance requirements of this standard; and NFPA 96, 8.2.2 Air Volume. NFPA 96, 8.2.2.1: Exhaust air volumes for hoods shall be of a sufficient level to provide for capture and removal of grease-laden cooking vapors. FOR REPORTING PURPOSES ONLY

Lake County

License Number: 4501812 SILVER CRICKET
 License Type: Permanent Food Service 360 S HWY 441, LADY LAKE 32159

Inspection Date: 07/08/2009 Inspection Number: 1914657 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: MARTIN, ROBERT KEVIN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 4508442 TRI CITY GRILL
 License Type: Permanent Food Service 2420 EAST BURLEIGH BLVD, EUSTIS 32726

Inspection Date: 07/06/2009 Inspection Number: 1900183 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: MARTIN, ROBERT KEVIN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 4508220 QUIZNOS SUBS #7126
 License Type: Permanent Food Service 240B CITRUS TOWER BLVD, CLERMONT 34711

Inspection Date: 07/06/2009 Inspection Number: 1859394 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CHIU, ALEX

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. [Rear kitchen exit blocked by garbage can and CO2 tank] For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

Lake County

License Number: 4500938

POPEYES CHICK & BIS #112 (DBA)

License Type: Permanent Food Service

613 N 14 ST, LEESBURG 347484203

Inspection Date: 07/09/2009

Inspection Number: 1848981

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: MARTIN, ROBERT KEVIN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-02-2	Observed circuit breaker taped open. For reporting purposes only.	NFPA 70, 240.80 Circuit breakers shall be tripfree and capable of being closed and opened by manual operation. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Lee County

License Number: 4603488 SAM SELTZER'S STEAKHOUSE
 License Type: Permanent Food Service 12635 S. CLEVELAND, FORT MYERS 33907

Inspection Date: 07/07/2009 Inspection Number: 1882864 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: TORBERT, KIMBERLY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only. ABC extinguisher by office	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

License Number: 4605356 FAIRFIELD INN BY MARRIOTT
 License Type: Permanent Food Service 7090 CYPRESS TERR, FORT MYERS 33907

Inspection Date: 07/08/2009 Inspection Number: 1862373 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: SOMMERS, KARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 4605935 QUIZNOS SUBS
 License Type: Permanent Food Service 10021 ESTERO TOWN COMMONS PL #101B, ESTERO 33928

Inspection Date: 07/10/2009 Inspection Number: 1883193 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: TORBERT, KIMBERLY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only. ABC by back door Repeat Violation.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

Lee County

License Number: 4605273

HYATT REGENCY-EMPLOYEE REST

License Type: Permanent Food Service

5001 COCONUT RD, BONITA SPGS 34134

Inspection Date: 07/06/2009

Inspection Number: 1913999

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: TORBERT, KIMBERLY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only. ABC extinguisher	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. K class, ABC extinguishers	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Leon County

License Number: 4703325		LAZARRE'S CARIBBEAN CUISINE	
License Type: Permanent Food Service		2809 S MONROE ST, TALLAHASSEE 32301	
Inspection Date: 07/07/2009	Inspection Number: 1851223	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SMITH, PAUL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke not under hood suppression system. Notified Fire AHJ. For reporting purposes only. Corrected On Site.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.	
License Number: 4702288		EL TAPATIO MEXICAN RESTAURANT	
License Type: Permanent Food Service		1002 N MONROE ST, TALLAHASSEE 32303	
Inspection Date: 07/08/2009	Inspection Number: 1892204	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: PRAGER, JOAN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-38-2	Portable fire extinguisher in kitchen not fully charged. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
License Number: 4702456		PAPA JOHNS PIZZA	
License Type: Permanent Food Service		1818 N MONROE ST, TALLAHASSEE 32303	
Inspection Date: 07/09/2009	Inspection Number: 1861503	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PRAGER, JOAN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-37-2	Portable fire extinguisher missing from designated location where sign is posted stating "Fire Extinguisher," rear kitchen. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
License Number: 4702607		SONIC DRIVE IN TALLAHASSEE #2	
License Type: Permanent Food Service		1510 N MONROE ST, TALLAHASSEE 32303	
Inspection Date: 07/08/2009	Inspection Number: 1861483	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PRAGER, JOAN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-15-2	Observed an uncovered electrical box. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

Leon County

License Number: 4702957 CHINA KING
 License Type: Permanent Food Service 3840 N MONROE ST #E204, TALLAHASSEE 32303

Inspection Date: 07/09/2009 Inspection Number: 1892216 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: PRAGER, JOAN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period, connecting rice steamer to outlet. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 4703150 EL JALISCO MEXICAN RESTAURANT
 License Type: Permanent Food Service 2022 N MONROE, TALLAHASSEE 32303

Inspection Date: 07/06/2009 Inspection Number: 1914564 Inspection Type: Complaint Full Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: SMITH, PAUL

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 4702227 GUTHRIES OF TALLAHASSEE
 License Type: Permanent Food Service 1818 W TENNESSEE ST, TALLAHASSEE 323043355

Inspection Date: 07/07/2009 Inspection Number: 1840741 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: HARGROVE, DAVID

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Repeat Violation.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 4702226 LOOP (THE)
 License Type: Permanent Food Service 609 W TENNESSEE ST, TALLAHASSEE 323047908

Inspection Date: 07/06/2009 Inspection Number: 1912597 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: HARGROVE, DAVID

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. Corrected On Site.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Levy County

License Number: 4800548

SONIC DRIVE IN

License Type: Permanent Food Service

1019 NW 21ST AVE, CHIEFLAND 32626

Inspection Date: 07/01/2009

Inspection Number: 1915090

Inspection Type: Routine - Food

Inspection Disposition: Administrative
complaint recommended

Inspector Name: WRENNE, LILYANN

Violation Code

Observation

Violation Citation

47 Out of compliance: Electrical wiring - adequate, good repair

NFPA 101, 96, 10 Electrical wiring - adequate, good
repair

Manatee County

License Number: 5105323 THE CONCESSION, GOLF CLUB & RESIDENCES
 License Type: Permanent Food Service 7700 LINDRICK LANE, BRADENTON 34202

Inspection Date: 07/01/2009 Inspection Number: 1825389 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CHRISTENSON, MELISSA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48	WATER HEATER - 130 GALLONS/499900/BTU/HR - REPORTING PURPOSES ONLY	NFPA 101, 96, 10 Gas appliances - properly installed, maintained

License Number: 5104333 GOLDEN CORRAL #871
 License Type: Permanent Food Service 5525 W CORTEZ RD, BRADENTON 34210

Inspection Date: 07/06/2009 Inspection Number: 1882256 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: KEMPA, ALICE M

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-01-2	Boiler certificate not posted in boiler room. For reporting purposes only. Corrected On Site.	69A-51.025(4) FAC (4) Certificate of Compliance. The Certificate of Compliance shall be conspicuously placed so it can be readily identified with the certified boiler, preferably in the boiler room. FOR REPORTING PURPOSES ONLY.

License Number: 5105094 THE FLYING DOG CAFE/ESPRESSO BAR
 License Type: Permanent Food Service 500 TALLEVAST RD, SARASOTA 34243

Inspection Date: 07/06/2009 Inspection Number: 1842152 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: CONTEH, FATIMAH

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
49-06-2	Observed flammable material stored around water heater. For reporting purposes only. Pressurized can of WD 40 stored on top of water heater.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

Marion County

License Number: 5202157		PIZZA QS	
License Type: Permanent Food Service		19721 W HWY 40, DUNNELLON 34431	
Inspection Date: 06/30/2009	Inspection Number: 1914746	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WRENNE, LILYANN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair	
License Number: 5200544		MCDONALD'S #4255	
License Type: Permanent Food Service		3215 E SILVER SPRINGS BLVD, OCALA 34470	
Inspection Date: 07/02/2009	Inspection Number: 1870353	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BRYANT, BENJAMIN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair	
License Number: 5201997		CHINA 1 CHINESE FOOD	
License Type: Permanent Food Service		2703 E SIVER SPGS BLVD, OCALA 34470	
Inspection Date: 07/02/2009	Inspection Number: 1850011	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BRYANT, BENJAMIN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
48	Out of compliance: Gas appliances - properly installed, maintained	NFPA 101, 96, 10 Gas appliances - properly installed, maintained	
License Number: 5202294		CHINA EXPRESS	
License Type: Permanent Food Service		4901 E SILVER SPGS BLV #702, OCALA 34470	
Inspection Date: 07/08/2009	Inspection Number: 1850019	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: BRYANT, BENJAMIN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 5202322		WING HOUSE	
License Type: Permanent Food Service		2145 E SILVER SPGS BLVD, OCALA 34470	
Inspection Date: 07/09/2009	Inspection Number: 1870375	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BRYANT, BENJAMIN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-13-2	Circuit breaker boxes blocked and/or inaccessible. For reporting purposes only.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.	

Marion County

License Number: 5202362		LITTLE CAESAR'S	
License Type: Permanent Food Service		4901 E SILVER SPRINGS BLVD, OCALA 34470	
Inspection Date: 07/08/2009	Inspection Number: 1850023	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BRYANT, BENJAMIN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-27-2	Portable fire extinguisher blocked/not easily accessible. For reporting purposes only.	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.	
46-09-2	Exit sign not properly illuminated over front door. For reporting purposes only. Repeat Violation.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
47-07-2	Observed scorch marks on exit sign above front door. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
47-16-2	Electrical outlet over front door missing cover plate. For reporting purposes only. Repeat Violation.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

License Number: 5202488		KFC/A & W Y309033	
License Type: Permanent Food Service		4903 E SILVER SPRINGS BLVD, OCALA 34470	
Inspection Date: 07/08/2009	Inspection Number: 1901147	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BRYANT, BENJAMIN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-25-2	Hood filters not equipped with a drip tray. For reporting purposes only.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY	

License Number: 5202528		SUBWAY SANDWICHES & SALADS	
License Type: Permanent Food Service		4920 E SILVER SPRINGS BLVD #102, OCALA 34470	
Inspection Date: 07/09/2009	Inspection Number: 1901141	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BRYANT, BENJAMIN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed back door exit obstructed by cardboard boxes. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	

Marion County

License Number: 5202637 HUNGRY HOWIES #133
 License Type: Permanent Food Service 3753 E SILVER SPRINGS BLVD, OCALA 34470

Inspection Date: 07/07/2009 Inspection Number: 1880612 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BRYANT, BENJAMIN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-2	Exit sign over back door not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.
46-12-2	Observed emergency lighting over back door in poor repair. For reporting purposes only.	NFPA 101, 7.9.2.1 Emergency lighting facilities shall be arranged to provide initial illumination that is not less than an average of 1 foot-candle and, at any point, not less than 0.1 foot-candles, measured along the path of egress at floor level. FOR REPORTING PURPOSES ONLY.

License Number: 5201296 ARBY'S #1987
 License Type: Permanent Food Service 2130 E SILVER SPRINGS BLVD, OCALA 344706915

Inspection Date: 07/09/2009 Inspection Number: 1859966 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BRYANT, BENJAMIN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-08-2	Observed electrical cord to slicer in disrepair. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-13-2	Circuit breaker box blocked and/or inaccessible. For reporting purposes only.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.

License Number: 5201062 CICCIO'S RESTAURANT
 License Type: Permanent Food Service 3535 SE MARICAMP RD STE 1002, OCALA 34471

Inspection Date: 07/01/2009 Inspection Number: 1880613 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BRYANT, BENJAMIN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair

License Number: 5201895 VICKI'S PLACE
 License Type: Permanent Food Service 3535 SE MARICAMP RD #104, OCALA 34471

Inspection Date: 07/01/2009 Inspection Number: 1831965 Inspection Type: Complaint Full Inspection Disposition: Warning Issued
 Inspector Name: BRYANT, BENJAMIN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

Marion County

License Number: 5202592 SAMS ST JOHNS SEAFOOD RESTAURANT #8
 License Type: Permanent Food Service 7578 SE MARICAMP RD # 115, OCALA 34472

Inspection Date: 07/01/2009 Inspection Number: 1890824 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: ANAZIA, ROLAND

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

License Number: 5202666 EGGS OVER BASELINE
 License Type: Permanent Food Service 5855 SE 5TH STREET #5, OCALA 34472

Inspection Date: 06/22/2009 Inspection Number: 1915096 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: ANAZIA, ROLAND

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-22-2	Out of compliance: Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORT	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.

License Number: 5202042 MCDONALD'S # 14451
 License Type: Permanent Food Service 2095 SW HWY 484, OCALA 34473

Inspection Date: 07/02/2009 Inspection Number: 1890860 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: ANAZIA, ROLAND

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair

License Number: 5201095 SUBWAY
 License Type: Permanent Food Service 1051 S PINE AVE, OCALA 34474

Inspection Date: 07/06/2009 Inspection Number: 1860029 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: ANAZIA, ROLAND

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

License Number: 5202389 SUBWAY #23785
 License Type: Permanent Food Service 3100 SW COLLEGE RD VCOS, OCALA 34474

Inspection Date: 07/06/2009 Inspection Number: 1911362 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: ANAZIA, ROLAND

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

License Number: 5202036 BOSTON MARKET #763
 License Type: Permanent Food Service 2650 SW COLLEGE RD, OCALA 344743052

Inspection Date: 07/06/2009 Inspection Number: 1880657 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: ANAZIA, ROLAND

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient

Marion County

License Number: 5201726 #1 CHINESE FOOD
 License Type: Permanent Food Service 2400 SW COLLEGE RD #105, OCALA 344743054

Inspection Date: 06/30/2009 Inspection Number: 1647941 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: ANAZIA, ROLAND

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

License Number: 5202685 PALM COURT CARIBBEAN CUSINE
 License Type: Permanent Food Service 8721 SE 58 AVE, OCALA 34480

Inspection Date: 07/01/2009 Inspection Number: 1914883 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: ANAZIA, ROLAND

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair

Martin County

License Number: 5301580		PUEBLO VIEJO IV INC	
License Type: Permanent Food Service		1840 NE JENSEN BEACH BLVD, JENSEN BEACH 34957	
Inspection Date: 07/09/2009	Inspection Number: 1886301	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PETROW, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-25-2	Hood filters not equipped with a drip tray. For reporting purposes only.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY	
License Number: 5300635		BURGER KING MARTIN DWN'S PLZ	
License Type: Permanent Food Service		3030 SW MARTIN BLVD, PALM CITY 349903142	
Inspection Date: 07/02/2009	Inspection Number: 1865924	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: PETROW, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
Inspection Date: 07/06/2009	Inspection Number: 1865924	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Admin. complaint recommended
Inspector Name: PETROW, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 5301171		SUBWAY	
License Type: Permanent Food Service		2870 SW MARTIN DOWNS BLVD, PALM CITY 349906021	
Inspection Date: 07/06/2009	Inspection Number: 1876192	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PETROW, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only... front.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only... tea machine.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Martin County

License Number: 5301400

KING CHARLES TEA SHOP & BAKERY

License Type: Permanent Food Service

662 SE MONTEREY RD, STUART 34994

Inspection Date: 07/07/2009

Inspection Number: 1835129

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: PETROW, MICHAEL

Violation CodeObservationViolation Citation

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only... back kitchen.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5301193

WENDY'S

License Type: Permanent Food Service

726 S FEDERAL HWY, STUART 349942937

Inspection Date: 07/07/2009

Inspection Number: 1845387

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: PETROW, MICHAEL

Violation CodeObservationViolation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 5300974

WILLOUGHBY GOLF CLUB

License Type: Permanent Food Service

3001 SE DOUBLETON DR, STUART 349975608

Inspection Date: 07/08/2009

Inspection Number: 1845307

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: DERVIN, RICHARD

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only. boiler room thru ceiling.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-15-2

Observed an uncovered electrical box. For reporting purposes only. boiler room.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Monroe County

License Number: 5401916

TACO BELL

License Type: Permanent Food Service

2338 N ROOSEVELT BLVD, KEY WEST 330403836

Inspection Date: 07/07/2009

Inspection Number: 1641769

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BOAK, MICHAEL

Violation Code

Observation

Violation Citation

46-05-2 Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

Nassau County

License Number: 5500914		BEEF O BRADYS	
License Type: Permanent Food Service		1916 S 14 ST, FERNANDINA BEACH 32034	
Inspection Date: 07/07/2009	Inspection Number: 1881030	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PHELAN, JOHN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. To lights	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 5500922		LUCKY WOK	
License Type: Permanent Food Service		2114 SADLER RD, FERNANDINA BEACH 32034	
Inspection Date: 07/06/2009	Inspection Number: 1901521	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Extension given, pending
Inspector Name: PHELAN, JOHN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Missing hood filter	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
46-09-2	Violation: 46-09-2 Exit signs not properly illuminated. For reporting purposes only. Rear door	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
47-06-2	Violation: 47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only. Chest freezer	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 5501017		JADE'S BISTRO	
License Type: Permanent Food Service		1484 SADLER RD, FERNANDINA BEACH 32034	
Inspection Date: 07/07/2009	Inspection Number: 1839858	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: PHELAN, JOHN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. By cola syrup rack.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Nassau County

License Number: 5500769

MOON RIVER PIZZA

License Type: Permanent Food Service

925 S 14 ST, FERNANDINA BCH 320342906

Inspection Date: 07/07/2009

Inspection Number: 1860406

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: PHELAN, JOHN

Violation CodeObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only. By reach in cooler

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5501002

SUSHI HOUSE

License Type: Permanent Food Service

463797 SR 200 #5, YULEE 32097

Inspection Date: 07/06/2009

Inspection Number: 1911667

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: PHELAN, JOHN

Violation CodeObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only. Behind pepsi cooler

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5500798

PEPPERS MEXICAN GRILL & CANTINA

License Type: Permanent Food Service

2128 SADLER RD, FERNANDINA BEACH 32304

Inspection Date: 07/06/2009

Inspection Number: 1839850

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: PHELAN, JOHN

Violation CodeObservationViolation Citation

46-09-2 Exit signs not properly illuminated. For reporting purposes only.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

Okaloosa County

License Number: 5603542

WAFFLE HOUSE #1590

License Type: Permanent Food Service

460 RACETRACK RD NW, FT WALTON BCH 32547

Inspection Date: 07/02/2009

Inspection Number: 1881556

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: FRANZALIA, CHARLES

Violation CodeObservationViolation Citation

46-05-2

Observed obstructed exits, stairs, hallways or egress. For reporting purposes only...storage room door...

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 5603635

HAPPY DONUTS AND BREAKFAST

License Type: Permanent Food Service

2387 W HWY 98 UNIT B, MARY ESTHER 32569

Inspection Date: 07/08/2009

Inspection Number: 1881578

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: FRANZALIA, CHARLES

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5603426

OLDE TYME ICE CREAM

License Type: Permanent Food Service

4550 E HWY 20 STE H, NICEVILLE 32578

Inspection Date: 07/07/2009

Inspection Number: 1912807

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: WIGGINS, GISELE

Violation CodeObservationViolation Citation

47-13-2

Circuit breaker box blocked and/or inaccessible. For reporting purposes only.

NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.

Okaloosa County

License Number: 5603522

LA RUMBA OF NICEVILLE

License Type: Permanent Food Service

1128 JOHN SIMS PKWY, NICEVILLE 32578

Inspection Date: 07/10/2009

Inspection Number: 1892240

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: WIGGINS, GISELE

Violation Code

Observation

Violation Citation

47-08-2 Observed exposed electrical wiring in dining room ceiling. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Orange County

License Number: 5811691 ORIGINAL MARYLAND FRIED CHICKEN
 License Type: Permanent Food Service 1672 S ORANGE BLOSSOM TRAIL, APOPKA 32703

Inspection Date: 07/06/2009 Inspection Number: 1900049 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CHIU, CECILIA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 5802458 BURGER KING #2167
 License Type: Permanent Food Service 488 E MAIN ST, APOPKA 327035374

Inspection Date: 07/08/2009 Inspection Number: 1848743 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CHIU, CECILIA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 5810387 CRISPERS
 License Type: Permanent Food Service 391 S. SEMORAN BLVD., WINTER PARK 32792

Inspection Date: 07/06/2009 Inspection Number: 1910475 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: MOORE, CAROLYN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. new pizza oven installed for new menu For reporting purposes only.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

License Number: 5801686 BURGER KING #1287
 License Type: Permanent Food Service 3900 E COLONIAL DR, ORLANDO 328035210

Inspection Date: 07/06/2009 Inspection Number: 1869563 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: MOORE, CAROLYN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

Orange County

License Number: 5852869

SANDYS DOGS

License Type: Mobile Food Dispensing Vehicle

1206 W ROBINSON ST., ORLANDO 32805

Inspection Date: 07/08/2009

Inspection Number: 1134801

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: GORIS, WILBERTO

Violation CodeObservationViolation Citation

45-38-2

Portable fire extinguisher not fully charged. For reporting purposes only.

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

License Number: 5805508

COURTYARD RESTAURANT

License Type: Permanent Food Service

7155 N FRONTAGE RD, ORLANDO 328129012

Inspection Date: 07/09/2009

Inspection Number: 1858398

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: RULLAN, ALFONSO

Violation CodeObservationViolation Citation

48-12-2

No current boiler certification provided/available, was expired. For reporting purposes only.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

Orange County

License Number: 5810065 BEST WESTERN-UNIVERSAL INN
 License Type: Permanent Food Service 5618 VINELAND ROAD, ORLANDO 32819

Inspection Date: 07/02/2009 Inspection Number: 1820738 Inspection Type: Routine - Food Inspection Disposition: Call Back - Complied
 Inspector Name: BACHOO, SAVITRI

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-16-2	Violation: 47-16-2 Electrical outlet missing cover plate. For reporting purposes only.Kitchen area.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 5810435 MCDONALDS #26312
 License Type: Permanent Food Service 7344 SANDLAKE RD, ORLANDO 32819

Inspection Date: 07/08/2009 Inspection Number: 1868452 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: BACHOO, SAVITRI

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-12-2	Observed trouble/alarm light lighted on fire alarm control panel. For reporting purposes only.	NFPA 72, 7.1.1.1, 7.3.1 and 7.4.3 Inspection, testing, and maintenance programs shall satisfy the requirements of this code, conform to the equipment manufacturer's recommendations, and verify proper operation of the fire alarm system. Visual Inspection. Visual Inspection shall be performed in accordance with the schedules in this chapter or more frequently where required by the authority having jurisdiction. The visual inspection shall be made to ensure that there are no changes that can affect equipment performance. All apparatus requiring rewinding or resetting to maintain normal operation shall be restored to normal as promptly as possible after each test and alarm and kept in normal condition for operation. All test signals received shall be recorded to indicate date, time, and type. FOR REPORTING PURPOSES ONLY.

License Number: 5853182 BIG DADDY'S BBQ 5
 License Type: Mobile Food Dispensing Vehicle 6881 KINGSPPOINT PKWY BLDG A UNIT 4, ORLANDO 32819

Inspection Date: 07/02/2009 Inspection Number: 1137909 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BACHOO, SAVITRI

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-13-2	Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.

Orange County

License Number: 5806192 PEARLS CHINESE RESTAURANT
 License Type: Permanent Food Service 5438 CENTRAL FLORIDA PKWY, ORLANDO 32821

Inspection Date: 07/02/2009 Inspection Number: 1900151 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: RULLAN, ALFONSO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period, front service area. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period, connected to freezer . For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5810955 CRACKER BARRELL
 License Type: Permanent Food Service 6699 SEMORAN BLVD, ORLANDO 32822

Inspection Date: 07/09/2009 Inspection Number: 1878986 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: RULLAN, ALFONSO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period, connected to small cooler by training section. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Orange County

License Number: 5811927

KENTUCKY FRIED CHICKEN RESTAURANT

License Type: Permanent Food Service

6041 S GOLDENROD ROAD, ORLANDO 32822

Inspection Date: 07/02/2009

Inspection Number: 1909642

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: RULLAN, ALFONSO

Violation CodeObservationViolation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor, was stored on floor by back door. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

46-05-2 Observed obstructed emergency exits, stairs, hallways or egress, w s blocked with trash cart. For reporting purposes only. Corrected On Site.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 5807828

MCDONALDS #4104

License Type: Permanent Food Service

13401 LANDSTAR BLVD, ORLANDO 32824

Inspection Date: 07/02/2009

Inspection Number: 1867926

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: RIVERA, JESICA M

Violation CodeObservationViolation Citation

46-14-2 Emergency lighting not provided. One is broken in the back area by soda boxes. Notified Fire AHJ. For reporting purposes only.

NFPA 101, 7.9.1.1 Emergency lighting facilities for means of egress shall be provided in accordance with Section 7.9 for the following: (1) Buildings or structures where required in Chapter 11 through Chapter 42 (2) Underground and limited access structures as addressed in Section 11.7 (3) High-rise buildings as required by other sections of this Code (4) Doors equipped with delayed-egress locks (5) Stair shaft and vestibule of smokeproof enclosures, for which the following also apply: (a) The stair shaft and vestibule shall be permitted to include a standby generator that is installed for the smokeproof enclosure mechanical ventilation equipment. (b) The standby generator shall be permitted to be used for the stair shaft and vestibule emergency lighting power supply. FOR REPORTING PURPOSES ONLY.

47-05-2 Observed a splitter/multi-plug adapter in use. For reporting purposes only. By the front shoot.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Orange County

License Number: 5809700 TROPICAL RESTAURANT
 License Type: Permanent Food Service 1875 CENTRAL FLORIDA PKWY, ORLANDO 32837

Inspection Date: 07/09/2009 Inspection Number: 1838465 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: WRIGHT, ANDREW

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-05-2	Observed a splitter/multi-plug adapter in use by blender. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5811044 ORGULLO LATINO # 634
 License Type: Permanent Food Service 1921 CENTRAL FL PARKWAY SUITE -E, ORLANDO 32837

Inspection Date: 07/09/2009 Inspection Number: 1889776 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: WRIGHT, ANDREW

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
49-06-2	Observed flammable material stored around water heater. Spray paint on top of gas water heater. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

License Number: 5807304 PIZZA HUT DELIVERY #760026
 License Type: Permanent Food Service 3908 TOWN CENTER BLVD 106, ORLANDO 328376103

Inspection Date: 07/10/2009 Inspection Number: 1889772 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: WRIGHT, ANDREW

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-13-2	Emergency light does not function when tested; above dish racks. For reporting purposes only.	NFPA 101, 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted at 30-day intervals for not less than 30 seconds. (2) Functional testing shall be conducted annually for not less than 1½ hours if the emergency lighting system is battery powered. (3) The emergency lighting equipment shall be fully operational for the duration of the tests required by 7.9.3.1.1(1) and 7.9.3.1.1(2). FOR REPORTING PURPOSES ONLY.

License Number: 5810716 CHEESECAKE FACTORY (THE)
 License Type: Permanent Food Service 4200 CONROY RD A-148, ORLANDO 32839

Inspection Date: 07/06/2009 Inspection Number: 1858306 Inspection Type: Routine - Food Inspection Disposition: Call Back - Admin. complaint recommended
 Inspector Name: GORIS, WILBERTO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

Orange County

License Number: 5811884

CHICK-FIL-A

License Type: Permanent Food Service

3166 DANIELS RD, WINTER GARDEN 34787

Inspection Date: 07/02/2009

Inspection Number: 1838599

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CRISTWELL, HENRY

Violation Code

Observation

Violation Citation

45-34-2

Fire alarm control panel has no tag/tag not for most recent service, repair, test or inspection. For reporting purposes only.

69A-48.006(1) FAC (1) A standard Fire Alarm tag meeting the requirements of this rule shall be securely affixed to the fire alarm control panel of each fire alarm system which is installed, and each time such system is serviced, tested, repaired, inspected, or improved by any person. FOR REPORTING PURPOSES ONLY.

Osceola County

License Number: 5900845

FRIENDLY'S #7690

License Type: Permanent Food Service

3915 WEST VINE STREET, KISSIMMEE 34741-4652

Inspection Date: 07/09/2009

Inspection Number: 1908882

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: NIEVES, RAFAEL

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. At front area in use for Taylor ice cream machine. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5904251

FIONI'S

License Type: Permanent Food Service

PARKWAY BLVD B 12, KISSIMMEE 34746

Inspection Date: 07/08/2009

Inspection Number: 1857770

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: WRIGHT, ANDREW

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor; by bar. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

47-16-2

Electrical outlet missing cover plate behind pizza make table. For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 5910772

RANCHO TEQUILAS

License Type: Permanent Food Service

2198 FOUR WINDS BLVD, KISSIMMEE 34746

Inspection Date: 07/02/2009

Inspection Number: 1908956

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: RIVERA, JESICA M

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only, At the bar.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Osceola County

License Number: 5910871

DOMINO'S PIZZA

License Type: Permanent Food Service

3253 S. JOHN YOUNG PARKWAY, KISSIMMEE 34746

Inspection Date: 07/06/2009

Inspection Number: 1837183

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: RIVERA, JESICA M

Violation CodeObservationViolation Citation

46-05-2

Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. By bar during operating hrs, the back door.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

47-15-2

Observed an uncovered electrical box. For reporting purposes only. In the back by the door by evidence of duck tape holding the box.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 5910990

INDIA DINER

License Type: Permanent Food Service

4561 W IRLO BRONSON HWY, KISSIMMEE 34746

Inspection Date: 07/09/2009

Inspection Number: 1888452

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: RIVERA, JESICA M

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. Available an being clean at this time. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 5911013

PANDA EXPRESS #1377

License Type: Permanent Food Service

4789 WEST IRLO BRONSON HIGHWAY, KISSIMMEE 34746

Inspection Date: 07/10/2009

Inspection Number: 1888448

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: RIVERA, JESICA M

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. On the floor.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Osceola County

License Number: 5901114

CHECKERS

License Type: Permanent Food Service

FLORIDA TURNPIKE MM 229, ST. CLOUD 34769

Inspection Date: 07/06/2009

Inspection Number: 1867992

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: KHAN, MOZHARUL

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. Grill. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5910972

PIZZA HUT #315487

License Type: Permanent Food Service

1939 S NARCOOSEE ROAD, ST CLOUD 34771

Inspection Date: 07/02/2009

Inspection Number: 1868040

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: KHAN, MOZHARUL

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Corrected On Site.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

Palm Beach County

License Number: 6003943

THE GRILLE ROOM

License Type: Permanent Food Service

2300 PRESIDENTIAL WAY, WEST PALM BEACH 334011510

Inspection Date: 07/09/2009

Inspection Number: 1865606

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: SHAPIRO, STEWART

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only. SHOWS 254 GALLON STATES HAS LETTER FROM BOILER INSPECTOR THAT NOT A BOILER BUT NOT AVAILABLE GAVE BOILER INSPECTOR PH# 561-662-9787	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6000986

PRESIDENT COUNTRY CLUB

License Type: Permanent Food Service

2300 PRESIDENTIAL WAY, WEST PALM BEACH 334011599

Inspection Date: 07/09/2009

Inspection Number: 1896251

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: SHAPIRO, STEWART

Violation CodeObservationViolation Citation

48-12-2

No current boiler certification provided/available. For reporting purposes only.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 6009007

KINGS BUFFET

License Type: Permanent Food Service

1800 PALM BCH LAKES BLVD, WEST PALM BEACH 334012002

Inspection Date: 07/09/2009

Inspection Number: 1834793

Inspection Type: Routine - Food

Inspection Disposition: Administrative
complaint recommended

Inspector Name: SHAPIRO, STEWART

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. BEHIND BAR

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

47-16-2

Electrical outlet missing cover plate. For reporting purposes only. KITCHEN

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6006327

E R BRADLEY'S SALOON

License Type: Permanent Food Service

104 CLEMATIS ST, WEST PALM BEACH 334015511

Inspection Date: 07/07/2009

Inspection Number: 1865618

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: SHAPIRO, STEWART

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6000383

DUNKIN DONUTS

License Type: Permanent Food Service

301 FEDERAL HWY, LAKE PARK 33403

Inspection Date: 07/07/2009

Inspection Number: 1684073

Inspection Type: Routine - Food

Inspection Disposition: Call Back - Complied

Inspector Name: MIDDLETON, ELWYN

Violation CodeObservationViolation Citation

46-13-2

Violation: 46-13-2

Emergency light does not function when tested. For reporting purposes only. women's restroom.

NFPA 101, 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted at 30-day intervals for not less than 30 seconds. (2) Functional testing shall be conducted annually for not less than 1½ hours if the emergency lighting system is battery powered. (3) The emergency lighting equipment shall be fully operational for the duration of the tests required by 7.9.3.1.1(1) and 7.9.3.1.1(2). FOR REPORTING PURPOSES ONLY.

License Number: 6010665

DOWN LOW BAR & GRILLE

License Type: Permanent Food Service

237 E BLUE HERON BLVD, RIVIERA BEACH 33404

Inspection Date: 07/08/2009

Inspection Number: 1834905

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

47-16-2

Electrical outlet missing cover plate. For reporting purposes only. next to rear door

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 6013811

MEALS OF THE CENTURY

License Type: Catering

2000 AVE P, SUITE 4A, RIVIERA BEACH 33404

Inspection Date: 07/10/2009

Inspection Number: 1092611

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

Palm Beach County

License Number: 6019521 FRIED RICE & WINGS
 License Type: Permanent Food Service 1545 W BLUE HERON BLVD, RIVIERA BEACH 33404

Inspection Date: 07/09/2009 Inspection Number: 1906802 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: JONES, ANTHONY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-36-2	Hood suppression system tag missing. For reporting purposes only.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

License Number: 6006491 KENTUCKY FRIED CHICKEN
 License Type: Permanent Food Service 1581 W BLUE HERON BLVD, RIVIERA BCH 334044013

Inspection Date: 07/08/2009 Inspection Number: 1845173 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: JONES, ANTHONY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6012538 RESIDENCE INN BY MARRIOTT
 License Type: Permanent Food Service 2461 METROCENTRE BLVD, WEST PALM BEACH 33407

Inspection Date: 07/09/2009 Inspection Number: 1865764 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: JONES, ANTHONY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces - missing. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
45-36-2	Hood suppression system not tagged. For reporting purposes only.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

License Number: 6019763 BENTLEYS
 License Type: Permanent Food Service 805 DONALD ROSS RD, JUNO BEACH 33408

Inspection Date: 07/09/2009 Inspection Number: 1906856 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: ROTONDI, VICTOR

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.abc/frontline	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6013860

MCDONALD'S #28730

License Type: Permanent Food Service

9880 ALT A1A, PALM BEACH GARDENS 33410

Inspection Date: 07/09/2009

Inspection Number: 1896413

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: ROTONDI, VICTOR

Violation CodeObservationViolation Citation

46-05-2

Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.backdoor Corrected On Site.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 6019912

HURRICANE GRILL AND WINGS

License Type: Permanent Food Service

4550 DONALD ROSS RD STE 107, PALM BEACH GARDENS 33410

Inspection Date: 07/08/2009

Inspection Number: 1865782

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: ROTONDI, VICTOR

Violation CodeObservationViolation Citation

15-26-2

Observed exhaust system operated with filters removed. For reporting purposes only.

NFPA 96, 11.1.2 Filter-equipped exhaust systems shall not be operated with filters removed. For reporting purposes only.

License Number: 6020144

BELLACINO'S

License Type: Permanent Food Service

1760 JOG RD STE 180, WEST PALM BEACH 33411

Inspection Date: 07/09/2009

Inspection Number: 1809998

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Complied

Inspector Name: MIDDLETON, ELWYN

Violation CodeObservationViolation Citation

15-28-2

Violation: 15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

Palm Beach County

License Number: 6019509 IHOP
 License Type: Permanent Food Service 13860 WELLINGTON TRCE, VILLAGE OF WELLINGTO 33414

Inspection Date: 07/09/2009 Inspection Number: 1875712 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: MENOR, MICHAEL

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-07-2	Observed misalignment of hood suppression system nozzles. For reporting purposes only.	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. TANKLESS WATER HEATER	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6011609 DINING ROOM
 License Type: Permanent Food Service 100 BALLENISLE CIR, PALM BCH GARDENS 33418

Inspection Date: 07/09/2009 Inspection Number: 1663691 Inspection Type: Routine - Food Inspection Disposition: Call Back - Complied
 Inspector Name: MIDDLETON, ELWYN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	Violation: 48-12-2 No current boiler certification provided/available. For reporting purposes only. EXPIRED.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6006741

TACO BELL #2595

License Type: Permanent Food Service

22953 SANDLEFOOT PLAZA DR, BOCA RATON 33428

Inspection Date: 07/07/2009

Inspection Number: 1914721

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: PIERI, CYNTHIA

Violation CodeObservationViolation Citation

46-05-2 Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

46-09-2 Exit signs not properly illuminated. For reporting purposes only.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 6007413

BOCA WINGS & RIBS

License Type: Permanent Food Service

2257 N FEDERAL HWY, BOCA RATON 33431

Inspection Date: 07/06/2009

Inspection Number: 1834277

Inspection Type: Quality Assurance

Inspection Disposition: Warning Issued

Inspector Name: BANNIGAN, TIM

Violation CodeObservationViolation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6011711

SUSHI MASA JAPANESE RESTAURANT

License Type: Permanent Food Service

2200 W GLADES RD, BOCA RATON 33431

Inspection Date: 07/09/2009

Inspection Number: 1854894

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BANNIGAN, TIM

Violation CodeObservationViolation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6013577

BOCA BREAKFAST & LUNCH CLUB

License Type: Permanent Food Service

171 SE MIZNER BLVD #18, BOCA RATON 33432

Inspection Date: 07/09/2009

Inspection Number: 1865158

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BANNIGAN, TIM

Violation CodeObservationViolation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6013598

HOLLOWAY'S PUB

License Type: Permanent Food Service

504 VIA DE PALMAS, BOCA RATON 33432

Inspection Date: 07/09/2009

Inspection Number: 1906263

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: BANNIGAN, TIM

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6013344

KYOJIN BUFFET

License Type: Permanent Food Service

21073 POWERLINE RD, BOCA RATON 33433

Inspection Date: 07/10/2009

Inspection Number: 1914734

Inspection Type: Complaint Full

Inspection Disposition: Warning Issued

Inspector Name: PIERI, CYNTHIA

Violation CodeObservationViolation Citation

46-05-2

Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.HIGH CHAIRS STACKED IN FRONT OF FIRE EXIT

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

47-08-2

Observed electrical wiring in disrepair. For reporting purposes only.PLATE COVER MISSIING BEHIND REACHIN OPPOSITE DISHMACHINE AREA

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6008139

WESTCHESTER GOLF & COUNTRY CLB

License Type: Permanent Food Service

12250 WESTCHESTER CLUB DR, BOYNTON BCH 334374104

Inspection Date: 07/09/2009

Inspection Number: 1834593

Inspection Type: Routine - Food

Inspection Disposition: Administrative complaint recommended

Inspector Name: SINGH, GAJENDRA

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.K CLASS ON FLOOR UNDER SHELF IN DISHWASHER AREA

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6010761

ODYSSEY DINER

License Type: Permanent Food Service

15200 JOG RD, DELRAY BCH 33446

Inspection Date: 07/06/2009

Inspection Number: 1906433

Inspection Type: Routine - Food

Inspection Disposition: Administrative
complaint recommended

Inspector Name: PONCE, NUARETTE

Violation CodeObservationViolation Citation

47-16-2

Electrical outlet missing cover plate. For reporting purposes only. BY
STEAMTABLE_SERVERS

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 6012064

DON JUAN PIZZA

License Type: Permanent Food Service

2543 S DIXIE HWY, LAKE WORTH 33460

Inspection Date: 07/02/2009

Inspection Number: 1855184

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: MORALES, DAMIAN

Violation CodeObservationViolation Citation

48-11-2

Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a
building. For reporting purposes only.

NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

License Number: 6019461

MIAMI SUBS GRILL

License Type: Permanent Food Service

821 LAKE AVE, LAKE WORTH 33460

Inspection Date: 07/06/2009

Inspection Number: 1906575

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: MORALES, DAMIAN

Violation CodeObservationViolation Citation

47-16-2

Electrical outlet missing cover plate. For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6013667

LA CASCADA

License Type: Permanent Food Service

4655 LAKE WORTH RD, GREEN ACRES 33463

Inspection Date: 07/09/2009

Inspection Number: 1906425

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: PONCE, NUARETTE

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.FLOOR_UNDER HAND SINK_COOKLINE

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6008279

F & F LA FINESSE RESTAURANT

License Type: Permanent Food Service

4824 10 AVE N, GREENACRES 33463

Inspection Date: 07/08/2009

Inspection Number: 1896055

Inspection Type: Routine - Food

Inspection Disposition: Administrative
complaint recommended

Inspector Name: PONCE, NUARETTE

Violation CodeObservationViolation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only.BACK DOOR

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 6011759

CHINA PAVILION

License Type: Permanent Food Service

4663 LAKE WORTH RD, LAKE WORTH 33463

Inspection Date: 07/09/2009

Inspection Number: 1865370

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Admin. complaint recommended

Inspector Name: PONCE, NUARETTE

Violation CodeObservationViolation Citation

46-09-2

Violation: 46-09-2

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

Exit signs not properly illuminated. For reporting purposes only.BACK DOOR

46-09-2

Exit signs not properly illuminated. For reporting purposes only.BACK DOOR

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 6008838

PIZZA HUT DELIVERY #012564

License Type: Permanent Food Service

3897 JOG RD, LAKE WORTH 334671590

Inspection Date: 07/10/2009

Inspection Number: 1855086

Inspection Type: Routine - Food

Inspection Disposition: Administrative
complaint recommended

Inspector Name: PONCE, NUARETTE

Violation CodeObservationViolation Citation

49-06-2

Observed flammable material stored around water heater. For reporting purposes only.PLASTIC SIGN ON TOP OF GAS WATER HEATER Corrected On Site.

61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6013513

GRASSY FLATS

License Type: Permanent Food Service

157 N US HWY 1, TEQUESTA 33469

Inspection Date: 07/10/2009

Inspection Number: 1855570

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DERVIN, RICHARD

Violation CodeObservationViolation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6019468

MISTER JELLYROLLS COFFEE SHOP & GIFT BOUQUET

License Type: Permanent Food Service

129 N LAKE AVE, PAHOKEE 33476

Inspection Date: 07/07/2009

Inspection Number: 1906603

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: MENOR, MICHAEL

Violation CodeObservationViolation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6003849

SINCLAIR'S

License Type: Permanent Food Service

5 N A1A, JUPITER 33477

Inspection Date: 07/10/2009

Inspection Number: 1855506

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DERVIN, RICHARD

Violation CodeObservationViolation Citation

48-12-2 No current boiler certification provided/available. For reporting purposes only.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6007215

TOOJAY'S

License Type: Permanent Food Service

4050 US 1, JUPITER 33477

Inspection Date: 07/09/2009

Inspection Number: 1886277

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: DERVIN, RICHARD

Violation Code

Observation

Violation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only. cookline

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Pasco County

License Number: 6113213

SHANGHI CHINESE

License Type: Permanent Food Service

32785 EILAND BLVD #105, WESLEY CHAPEL 33545

Inspection Date: 07/10/2009

Inspection Number: 1836559

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: BROTHAG, SANDRA

Violation CodeObservationViolation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6102279

RAPSCALLIONS

License Type: Permanent Food Service

4422 LAND O LAKES BLVD, LAND O LAKES 34639

Inspection Date: 07/06/2009

Inspection Number: 1846789

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: BROTHAG, SANDRA

Violation CodeObservationViolation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6113040

THE LITTLE GREEK

License Type: Permanent Food Service

9818 LITTLE RD, NEW PORT RICHEY 34654

Inspection Date: 07/07/2009

Inspection Number: 1819429

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Complied

Inspector Name: GLENN, DAVID

Violation CodeObservationViolation Citation47-06-2 Violation: 47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Pasco County

License Number: 6113021

HILLTOP CAFE

License Type: Permanent Food Service

9322 LITTLE RD, NEW PORT RICHEY 34654-3415

Inspection Date: 07/07/2009

Inspection Number: 1846973

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: GLENN, DAVID

Violation CodeObservationViolation Citation

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6113090

SHOW PLACE DINNER THEATRE

License Type: Permanent Food Service

16128 US HWY 19, HUDSON 34667

Inspection Date: 07/10/2009

Inspection Number: 1867574

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: GLENN, DAVID

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only. Small household extension cord powering fan in dishroom.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6100249

MAC DADDYS IRISH PUB

License Type: Permanent Food Service

11024 SR 52, HUDSON 34669

Inspection Date: 07/07/2009

Inspection Number: 1877866

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: GLENN, DAVID

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Pinellas County

License Number: 6209625		ORIGINAL PIZZA	
License Type: Permanent Food Service		10661 GULF BLVD, TREASURE ISLAND 337064818	
Inspection Date: 07/07/2009	Inspection Number: 1887730	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BIROCCO, JOSEPH			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-04-2	Observed frayed/spliced electrical wires. For reporting purposes only. Fan in walk in cooler.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 6216400		GELATERIA ADRIA LLC	
License Type: Permanent Food Service		6901 22ND AVE N #784, ST. PETERSBURG 33710	
Inspection Date: 07/06/2009	Inspection Number: 1835335	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BURKE, LAWRENCE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

License Number: 6215057		CAFE PONTE	
License Type: Permanent Food Service		13505 ICOT BLVD, CLEARWATER 33760	
Inspection Date: 07/06/2009	Inspection Number: 1857548	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PORTER, LINDSAY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

License Number: 6215810		J & J COUNTRYSIDE SUBWAY # 4 INC	
License Type: Permanent Food Service		2561 COUNTRYSIDE BLVD #4, CLEARWATER 33761	
Inspection Date: 07/06/2009	Inspection Number: 1856198	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CRAIG, CHRISTINE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-07-2	Exit signs missing. Rear door in back prep room. For reporting purposes only.	NFPA 101, 7.10.1.2 Exits, other than main exterior exit doors that obviously and clearly are identifiable as exits, shall be marked by an approved sign readily visible from any direction of exit access. FOR REPORTING PURPOSES ONLY.	

Pinellas County

License Number: 6216044		CHINA CAFE	
License Type: Permanent Food Service		26236 US HWY 19 N, CLEARWATER 33761	
Inspection Date: 07/06/2009	Inspection Number: 1835693	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: CRAIG, CHRISTINE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-07-2	Observed scorch marks around electrical outlet. by rear freezer For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6212063		SUPER SUB SHOP	
License Type: Permanent Food Service		11681 N 49 ST STE 1, PINELLAS PK 33762	
Inspection Date: 07/06/2009	Inspection Number: 1898559	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: PORTER, LINDSAY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
47-06-2	Violation: 47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6209791		MARIA'S KITCHEN	
License Type: Permanent Food Service		1143 N MISSOURI AVE, LARGO 337701815	
Inspection Date: 07/09/2009	Inspection Number: 1835551	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: OLSEN, JAMES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. in kitchen area to equipment	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Pinellas County

License Number: 6213902		ACROPOL FAMILY RESTAURANT	
License Type: Permanent Food Service		1170 STARKEY DR, LARGO 33771	
Inspection Date: 07/09/2009	Inspection Number: 1898547	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PORTER, LINDSAY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 6209992		SUPER BUFFET	
License Type: Permanent Food Service		11227 PARK BLVD, SEMINOLE 33772	
Inspection Date: 07/09/2009	Inspection Number: 1914736	Inspection Type: Complaint Full	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: OLSEN, JAMES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. abc sitting on floor in dining room	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
License Number: 6216237		PLANET JUMP	
License Type: Permanent Food Service		12640 62 ST N STE 100, LARGO 33773	
Inspection Date: 07/10/2009	Inspection Number: 1908800	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PORTER, LINDSAY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 6216445		SHIP WATCH PANTRY	
License Type: Permanent Food Service		11900 SHIPWATCH DR, LARGO 33774	
Inspection Date: 07/10/2009	Inspection Number: 1855974	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: OLSEN, JAMES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only. small fryer outside of hood suppression system	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.	

Pinellas County

License Number: 6212684

BAYOU CLUB

License Type: Permanent Food Service

7979 BAYOU CLUB BLVD, LARGO 33777

Inspection Date: 07/07/2009

Inspection Number: 1876558

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: OLSEN, JAMES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-01-2	Boiler certificate not posted in boiler room. For reporting purposes only.	69A-51.025(4) FAC (4) Certificate of Compliance. The Certificate of Compliance shall be conspicuously placed so it can be readily identified with the certified boiler, preferably in the boiler room. FOR REPORTING PURPOSES ONLY.
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 6212609

SWEET TOMATOES

License Type: Permanent Food Service

13101 SEMINOLE BLVD, LARGO 337782127

Inspection Date: 07/10/2009

Inspection Number: 1856004

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: OLSEN, JAMES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. in boiler room	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
48-01-2	Boiler certificate not posted in boiler room. For reporting purposes only.	69A-51.025(4) FAC (4) Certificate of Compliance. The Certificate of Compliance shall be conspicuously placed so it can be readily identified with the certified boiler, preferably in the boiler room. FOR REPORTING PURPOSES ONLY.

Pinellas County

License Number: 6215334		EGG PLATTER	
License Type: Permanent Food Service		6767 N 19 US HWY, PINELLAS PARK 33781	
Inspection Date: 07/06/2009	Inspection Number: 1914441	Inspection Type: Complaint Full	Inspection Disposition: Warning Issued
Inspector Name: BURKE, LAWRENCE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.[dining room]	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
License Number: 6212938		PIZZA HUT #4631	
License Type: Permanent Food Service		811 CR 1, PALM HARBOR 34683	
Inspection Date: 07/07/2009	Inspection Number: 1876852	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PEARCE, LAURA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-07-2	Observed misalignment of hood suppression system nozzles. For reporting purposes only. over fryers	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.	
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only. by back door	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. class K on floor near preparation for wings	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
License Number: 6214284		TARPON WOODS COUNTRY CLUB	
License Type: Permanent Food Service		1100 TARPON WOODS BLVD, PALM HARBOR 34685	
Inspection Date: 05/02/2005	Inspection Number: 1300288	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: CRAIG, CHRISTINE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-17	Observed hood suppression system tag out of date.This violation must be corrected by :06/02/05.	NFPA 96, 8-2 Inspection. An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons.	
License Number: 6211664		CURRENTS	
License Type: Permanent Food Service		200 E TARPON AVE, TARPON SPRINGS 34689	
Inspection Date: 07/09/2009	Inspection Number: 1831947	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PEARCE, LAURA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-25-2	Hood filters not equipped with a drip tray. For reporting purposes only.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY	

Pinellas County

License Number: 6212881

PIZZA HUT #4669

License Type: Permanent Food Service

1955 ALT 19 N, TARPON SPRINGS 34689

Inspection Date: 07/09/2009

Inspection Number: 1897279

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PEARCE, LAURA

Violation Code

Observation

Violation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only. used for hot holding equipment near pizza oven and pizza prep reachin cooler

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Polk County

License Number: 6300420		KFC/TACO BELL	
License Type: Permanent Food Service		727 E MEMORIAL BLVD, LAKELAND 33801	
Inspection Date: 07/10/2009	Inspection Number: 1887452	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WHITE, RICKY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
49-06-2	Observed flammable material stored around water heater. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.	
License Number: 6303082		WENDY'S RESTAURANT	
License Type: Permanent Food Service		2520 HWY 92 E, LAKELAND 33801	
Inspection Date: 07/06/2009	Inspection Number: 1907994	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WHITE, RICKY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-26-2	Observed exhaust system operated with filters removed. For reporting purposes only.	NFPA 96, 11.1.2 Filter-equipped exhaust systems shall not be operated with filters removed. For reporting purposes only.	
License Number: 6306577		BUBBAQUE'S #7000	
License Type: Permanent Food Service		2444 HWY 92 E, LAKELAND 33801	
Inspection Date: 07/06/2009	Inspection Number: 1836257	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WHITE, RICKY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 6300140		SKYVIEW GOLF & COUNTRY CLUB	
License Type: Permanent Food Service		1100 SKYVIEW BLVD, LAKELAND 338016732	
Inspection Date: 07/06/2009	Inspection Number: 1887484	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: WHITE, RICKY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 6305785		CARRABBA'S ITALIAN GRILL	
License Type: Permanent Food Service		4829 S FLORIDA AVE, LAKELAND 33813	
Inspection Date: 07/07/2009	Inspection Number: 1829838	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WHITE, RICKY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-02-2	Observed hasp lock on door at walk in freezer . For reporting purposes only.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	

Polk County

License Number: 6307835		SUBWAY	
License Type: Permanent Food Service		7910 LAKE WILSON ROAD, DAVENPORT 33837	
Inspection Date: 07/09/2009	Inspection Number: 1897753	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: ROMANO, JIMMIE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. trash in front of back exit door.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	
License Number: 6350592		ZOCALO DISCOUNT FOOD	
License Type: Mobile Food Dispensing Vehicle		308 US HWY 1792 N, HAINES CITY 33844	
Inspection Date: 07/02/2009	Inspection Number: 1138185	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: ROMANO, JIMMIE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
49	Out of compliance: Flammable/combustible materials - properly stored	NFPA 101, 96, 10 Flammable/combustible materials - properly stored	
License Number: 6307849		WATERS EDGE OF LAKE WALES	
License Type: Permanent Food Service		10 GROVE AVENUE WEST, LAKE WALES 33853	
Inspection Date: 07/07/2009	Inspection Number: 1867048	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: WHITE, CHERYL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
48-01-2	Boiler certificate not posted in boiler room. For reporting purposes only.	69A-51.025(4) FAC (4) Certificate of Compliance. The Certificate of Compliance shall be conspicuously placed so it can be readily identified with the certified boiler, preferably in the boiler room. FOR REPORTING PURPOSES ONLY.	
License Number: 6301842		WAFFLE HOUSE #363	
License Type: Permanent Food Service		44215 US HWY 27 NORTH, DAVENPORT 33897	
Inspection Date: 07/09/2009	Inspection Number: 1836165	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: ROMANO, JIMMIE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. hasp lock on dry storeroom door.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	

Polk County

License Number: 6305769

OUTPOST CLUBHOUSE

License Type: Permanent Food Service

501 PARSLEY COURT, KISSIMMEE 34759

Inspection Date: 07/07/2009

Inspection Number: 1877266

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: ROMANO, JIMMIE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Sarasota County

License Number: 6805049 BOBARINOS PIZZERIA
 License Type: Permanent Food Service 20 MAGNOLIA AVE, ENGLEWOOD 34223

Inspection Date: 07/07/2009 Inspection Number: 1841464 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: LANDMANN, PAUL

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-13-2	Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only. Repeat Violation.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.

License Number: 6804807 PIZZA HUT #4647
 License Type: Permanent Food Service 8197 S TAMIAMI TRL, SARASOTA 34231

Inspection Date: 07/08/2009 Inspection Number: 1882499 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DILLARD, FRANK

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Over pizza oven.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6800253 MCDONALDS #1413
 License Type: Permanent Food Service 6347 S TAMIAMI TRL, SARASOTA 342313936

Inspection Date: 07/08/2009 Inspection Number: 1861935 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DILLARD, FRANK

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. ABC EXTINGUISHER on floor near office.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6803895 HO'S GARDEN
 License Type: Permanent Food Service 3234 17 ST, SARASOTA 34235

Inspection Date: 06/29/2009 Inspection Number: 1914820 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended
 Inspector Name: CONTEH, FATIMAH

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47	EXTENSION CORDS IN USE	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

License Number: 6804915 VICTORIYA'S PLATZ
 License Type: Permanent Food Service 5045 RINGWOOD MEADOWS, SARASOTA 34235

Inspection Date: 07/06/2009 Inspection Number: 1903765 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: CONTEH, FATIMAH

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-04-2	No Hood suppression system. Portable domestic fryer in kitchen.	NFPA 96, 10.6.2 Where a fire alarm signaling system is serving the occupancy where the extinguishing system is located, the activation of the automatic fire-extinguishing system shall activate the fire alarm signaling system. FOR REPORTING PURPOSES ONLY.

Seminole County

License Number: 6900451 I HOP
 License Type: Permanent Food Service 700 E HWY 436, CASSELBERRY 32707

Inspection Date: 07/08/2009 Inspection Number: 1910239 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended
 Inspector Name: WATSON, DENNIS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Hood filter missing Corrected On Site.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6902326 MCDONALD'S #10302
 License Type: Permanent Food Service 1325 TUSCAWILLA RD, WINTER SPRINGS 32708

Inspection Date: 07/08/2009 Inspection Number: 1859504 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: PLEICONES, KIM

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. extension cord used for phone service in storage area	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6903452 BD'S MONGOLIAN GRILL
 License Type: Permanent Food Service 300 S SR 434, ALTAMONTE SPRINGS 32714

Inspection Date: 07/09/2009 Inspection Number: 1910139 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CHIU, CECILIA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-26-2	Observed exhaust system operated with filters removed. For reporting purposes only.	NFPA 96, 11.1.2 Filter-equipped exhaust systems shall not be operated with filters removed. For reporting purposes only.
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 6904544 R G BREWSKIS
 License Type: Permanent Food Service 995 N SR 434 STE# 303, ALTAMONTE SPRINGS 32714

Inspection Date: 07/09/2009 Inspection Number: 1858866 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CHIU, CECILIA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only. Repeat Violation.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

Seminole County

License Number: 6903188

SUBWAY SUBSHOP

License Type: Permanent Food Service

641 W LAKE MARY BLVD #109, LAKE MARY 32746

Inspection Date: 07/06/2009

Inspection Number: 1899979

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: MANTI, KATHRYN

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6903925

PEACH VALLEY CAFE

License Type: Permanent Food Service

1210 S INTERNL PKWY #118, LAKE MARY 32746

Inspection Date: 06/30/2009

Inspection Number: 1914683

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: MANTI, KATHRYN

Violation CodeObservationViolation Citation

45

Out of compliance: Fire extinguishers - proper and sufficient

NFPA 101, 96, 10 Fire extinguishers - proper and sufficient

License Number: 6900429

US HERO'S #1609

License Type: Permanent Food Service

409 N HWY 17-92, LONGWOOD 32750

Inspection Date: 07/10/2009

Inspection Number: 1879378

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: MANTI, KATHRYN

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Seminole County

License Number: 6903461

CHINA KING

License Type: Permanent Food Service

112 W MITCHELL HAMMOCK RD #1140, OVIEDO 32765

Inspection Date: 07/02/2009

Inspection Number: 1820602

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Complied

Inspector Name: PLEICONES, KIM

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	<p>Violation: 45-39-2</p> <p>Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. under shelf in dry storage area Repeat Violation.</p>	<p>NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.</p>
47-06-2	<p>Violation: 47-06-2</p> <p>Observed extension cord in use for non-temporary period. For reporting purposes only. for register at front counter and in kitchen for coffee pot</p>	<p>61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.</p>

St. Lucie County

License Number: 6602689

EL TORITO RESTAURANT

License Type: Permanent Food Service

3500 OKEECHOBEE RD, FORT PIERCE 34947

Inspection Date: 07/08/2009

Inspection Number: 1837379

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: DAVIS, DIANNA

Violation CodeObservationViolation Citation

45-22-2	Portable fire extinguisher(s) obstructed from view-by rest rooms. For reporting purposes only.	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.
45-41-2	Violation: 45-41-2 Constant chirping of smoke detector or other device near kitchen.	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.
47-04-2	Observed frayed/spliced electrical wires. For reporting purposes only. Exit sign at east exit door by restrooms.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Violation: 47-06-2 Observed extension cord in use for non-temporary period-portable fan plugged into cord stretched across ceiling near DJ booth. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. Cords in several locations. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

St. Lucie County

License Number: 6600799	MANGROVE MATTIES	
License Type: Permanent Food Service	1640 SEAWAY DR, FT PIERCE 349493156	
Inspection Date: 07/09/2009	Inspection Number: 1857952	
Inspector Name: DAVIS, DIANNA	Inspection Type: Routine - Food	
	Inspection Disposition: Inspection Completed - No Further Action	
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
47-06-2	Observed extension cord in use for non-temporary period-dessert/salad area, attached to microwaves. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-15-2	Observed an uncovered electrical box-outlets behind fish cooler at cookline/salad area. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 6602821	MCDONALDS RESTAURANT 31281	
License Type: Permanent Food Service	10604 SW VILLAGE PKWY, PORT ST LUCIE 34953	
Inspection Date: 07/06/2009	Inspection Number: 1899021	
Inspector Name: DAVIS, DIANNA	Inspection Type: Routine - Food	
	Inspection Disposition: Inspection Completed - No Further Action	
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress-back door area un passable, blocked with r=todays truck order. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 6650238	CONEY ISLAND CONCESSIONS	
License Type: Mobile Food Dispensing Vehicle	2995 S 25TH STREET, FORT PIERCE 34981	
Inspection Date: 07/08/2009	Inspection Number: 1138191	
Inspector Name: DAVIS, DIANNA	Inspection Type: Food-Licensing Inspection	
	Inspection Disposition: Inspection Completed - No Further Action	
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-41-2	Portable fire extinguisher tag out-of-date and wrong size for hot dog cart. For reporting purposes only.	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

Sumter County

License Number: 7000420 THE VERANDA
 License Type: Permanent Food Service 1000 LAKE SUMTER LANDING, THE VILLAGES 32162

Inspection Date: 07/09/2009 Inspection Number: 1857228 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DANCHO, JOHN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed....cooking fresh eggs with liquid butter used as non-stick agent on small griddle on kitchen line. Notified Fire AHJ. For reporting purp	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

License Number: 7050147 TAQUERIA MEXICANA EL NORTENO
 License Type: Mobile Food Dispensing Vehicle 800 S HWY 301, SUMTERVILLE 33585

Inspection Date: 07/06/2009 Inspection Number: 1138243 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DANCHO, JOHN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only.	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

Suwannee County

License Number: 7100222

THUNDER ALLEY

License Type: Permanent Food Service

1605 OHIO AVE S, LIVE OAK 32064

Inspection Date: 06/30/2009

Inspection Number: 1914703

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: HENTGES, JUDY

Violation Code

Observation

Violation Citation

47 Out of compliance: Electrical wiring - adequate, good repair

NFPA 101, 96, 10 Electrical wiring - adequate, good repair

Volusia County

License Number: 7405483 DAYTONA USA HOSPITALITY KITCHEN
 License Type: Permanent Food Service 1801 W INTN'L SPEEDWAY BLVD, DAYTONA BCH 32114

Inspection Date: 07/01/2009 Inspection Number: 1868997 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BRANNER, LISELOTTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair

License Number: 7405559 PRODUCTION KITCHEN
 License Type: Catering 1801 W INTN'L SPEEDWAY BLVD, DAYTONA BCH 32114

Inspection Date: 07/01/2009 Inspection Number: 1092929 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BRANNER, LISELOTTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair
48	Out of compliance: Gas appliances - properly installed, maintained	NFPA 101, 96, 10 Gas appliances - properly installed, maintained

License Number: 7406544 BISTRO
 License Type: Permanent Food Service 1801 W INTN'L SPEEDWAY BLVD, DAYTONA BCH 32114

Inspection Date: 07/01/2009 Inspection Number: 1889460 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BRANNER, LISELOTTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

License Number: 7405520 DAYTONA BEACH MOTOR SPORTS SPEED PARK CONCESSIONS
 License Type: Permanent Food Service 201 FENTRESS BLVD, DAYTONA BEACH 32114

Inspection Date: 06/29/2009 Inspection Number: 1914726 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BRANNER, LISELOTTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
49	Out of compliance: Flammable/combustible materials - properly stored	NFPA 101, 96, 10 Flammable/combustible materials - properly stored

License Number: 7406249 SMOKEHOUSE SALOON & GRILL
 License Type: Permanent Food Service 116 MADISON AVE, DAYTONA BEACH 32114

Inspection Date: 06/29/2009 Inspection Number: 1830730 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BRANNER, LISELOTTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair

License Number: 7406609 MEDITERRANEAN EXPERIENCE
 License Type: Permanent Food Service 174 N BEACH ST, DAYTONA BEACH 32114

Inspection Date: 07/09/2009 Inspection Number: 1909971 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: BRANNER, LISELOTTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-02-2	Observed lock on exit door that requires a key/frontdoor and reardoor. For reporting purposes only.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.

Volusia County

License Number: 7450015		ROCCA'S BEACH CONCESSIONS	
License Type: Mobile Food Dispensing Vehicle		801 S ATLANTIC AVE, DAYTONA BCH 32118	
Inspection Date: 07/01/2009	Inspection Number: 1134833	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BARRETT, KAREN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient	
License Number: 7404864		NEW YORK STYLE BAGEL DELI	
License Type: Permanent Food Service		3344 S ATLANTIC AVE, DAYTONA BEACH 32118	
Inspection Date: 07/01/2009	Inspection Number: 1899731	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BARRETT, KAREN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair	
License Number: 7406202		BOARDWALK INN SUITES	
License Type: Permanent Food Service		301 S ATLANTIC AVE, DAYTONA BEACH 32118	
Inspection Date: 07/08/2009	Inspection Number: 1909863	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BARRETT, KAREN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open.right side of east door For reporting purposes only.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	
47-06-2	Observed extension cord in use for toaster non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 7406514		NEELAM INDIAN CUISINE	
License Type: Permanent Food Service		318 S ATLANTIC AVE, DAYTONA BEACH 32118	
Inspection Date: 07/09/2009	Inspection Number: 1838085	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BARRETT, KAREN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed damaged taped extension cord in use for pepsi display cooler with packaged cold drinks located in dining room.non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Volusia County

License Number: 7406889

SHOTZ SPORTS BAR INC

License Type: Permanent Food Service

167 S HWY 17 92, DEBARY 32713

Inspection Date: 07/11/2009

Inspection Number: 1848645

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: BRASKA, GEORGIA

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor, ABC class on floor by handsink at bar area. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 7403804

MCDONALDS #10578

License Type: Permanent Food Service

2697 S WOODLAND BLVD, DELAND 32720

Inspection Date: 07/01/2009

Inspection Number: 1838239

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: BRASKA, GEORGIA

Violation CodeObservationViolation Citation

45

Out of compliance: Fire extinguishers - proper and sufficient

NFPA 101, 96, 10 Fire extinguishers - proper and sufficient

License Number: 7406430

LUCKY GARDEN

License Type: Permanent Food Service

2820 DOYLE ROAD-SUITE #7, DELTONA 32738

Inspection Date: 07/09/2009

Inspection Number: 1849459

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: ANGEL, TERRY

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only. Slicer. Repeat Violation.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Wakulla County

License Number: 7550037

SPEEDY D'Z

License Type: Mobile Food Dispensing Vehicle

2627 SPRING CREEK HIGHWAY, CRAWFORDVILLE 32327

Inspection Date: 07/06/2009

Inspection Number: 1132962

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: SMITH, PAUL

Violation Code

Observation

Violation Citation

49-06-2 Observed flammable material stored under grill inside mobile unit. For reporting purposes only.

61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

Walton County

License Number: 7601597		SPICY NOODLE (THE)	
License Type: Permanent Food Service		13667 E EMERALD COAST PKWY, INLET BEACH 32413	
Inspection Date: 07/06/2009	Inspection Number: 1891858	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: VINCENT, STACEY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-15-2	No placard placed near Class K portable fire extinguisher stating the fire suppression system must be activated prior to use of the portable extinguisher. For reporting purposes only.	NFPA 10, 4.3.2.2 A placard shall be conspicuously placed near the extinguisher that states that the fire protection system shall be activated prior to using the fire extinguisher. FOR REPORTING PURPOSES ONLY.	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor...(K-class extinguisher)For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
48-13-2	Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.	

License Number: 7601942		DUNESIDER GRILLE	
License Type: Permanent Food Service		94 S COMPASS WAY, PANAMA CITY BEACH 32413	
Inspection Date: 07/09/2009	Inspection Number: 1912383	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: VINCENT, STACEY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-15-2	No placard placed near Class K portable fire extinguisher stating the fire suppression system must be activated prior to use of the portable extinguisher...placard placed opposite side of kitchen For reporting purposes only.	NFPA 10, 4.3.2.2 A placard shall be conspicuously placed near the extinguisher that states that the fire protection system shall be activated prior to using the fire extinguisher. FOR REPORTING PURPOSES ONLY.	

License Number: 7601598		SEÑOR MOJITO'S CABANA BAR	
License Type: Permanent Food Service		10254 E CTY HWY 30A, SEACREST BEACH 32413	
Inspection Date: 07/09/2009	Inspection Number: 1912381	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: VINCENT, STACEY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

License Number: 7602000		DESTIN CHOPS ON 30-A	
License Type: Permanent Food Service		10343 E COUNTY HWY 30-A UNIT 125-129, SEACREST BEACH 32413	
Inspection Date: 07/09/2009	Inspection Number: 1861119	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: VINCENT, STACEY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor...extinguisher in kitchen near back door and extinguisher in hostess stand For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	

Walton County

License Number: 7601905

TERRACE POOLSIDE BAR

License Type: Permanent Food Service

9300 W EMERALD COAST PKWY, SANDESTIN 32550

Inspection Date: 07/02/2009

Inspection Number: 1850959

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: VINCENT, STACEY

Violation Code

Observation

Violation Citation

46-07-2

Exit sign at a non-exit. For reporting purposes only.

NFPA 101, 7.10.1.2 Exits, other than main exterior exit doors that obviously and clearly are identifiable as exits, shall be marked by an approved sign readily visible from any direction of exit access. FOR REPORTING PURPOSES ONLY.