

**Alachua County**

License Number: 1100747

CLARION INN

License Type: Permanent Food Service

7417 W NEWBERRY RD, GAINESVILLE 32605

Inspection Date: 10/21/2009

Inspection Number: 1859660

Inspection Type: Routine - Food

Inspection Disposition: Call Back -  
Extension given, pending

Inspector Name: BROWNING, JULIANNE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Violation: 45-39-2  Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. BACK EXIT DOOR WITH PADLOCK	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.
46-02-2	Violation: 46-02-2  Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. BACK EXIT DOOR WITH PADLOCK	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.
46-05-2	Violation: 46-05-2  Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. EXERCISE MACHINE BLOCKING DOOR-DOWNSTAIRS . FURNITURE BLOCKING EXITS -UPSTAIRS .	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. EXERCISE MACHINE BLOCKING DOOR-DOWNSTAIRS . FURNITURE BLOCKING EXITS -UPSTAIRS .	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

**Alachua County**

47-08-2	Violation: 47-08-2  Observed electrical wiring in disrepair. For reporting purposes only. NUMEROUS LOOSE WIRES NUMEROUS LOCATIONS THROUGHOUT	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-08-2	Observed electrical wiring in disrepair. For reporting purposes only. NUMEROUS LOOSE WIRES NUMEROUS LOCATIONS THROUGHOUT	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
48-12-2	Violation: 48-12-2  No current boiler certification provided/available. For reporting purposes only. EXPIRED 9-27-09	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

**Alachua County**

48-12-2 No current boiler certification provided/available. For reporting purposes only.  
EXPIRED 9-27-09

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 1101640 NERO'S PIZZA & PASTA  
License Type: Permanent Food Service 5240 NW 34TH STREET, GAINESVILLE 32605

Inspection Date: 10/20/2009 Inspection Number: 1849827 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended  
Inspector Name: BROWNING, JULIANNE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 1102968 WOK N ROLL  
License Type: Permanent Food Service 2106 SW 34TH STREET, GAINESVILLE 32608

Inspection Date: 10/20/2009 Inspection Number: 1859784 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
Inspector Name: WRENNE, LILYANN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-22-2	Portable fire extinguisher(s) obstructed from view chair up front blocking. For reporting purposes only.	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.

**Alachua County**

License Number: 1103119

O' O TAPAS &amp; TINIS'

License Type: Permanent Food Service

2725 SW 91 ST STE 100, GAINESVILLE 32608

Inspection Date: 10/21/2009

Inspection Number: 1880390

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: WRENNE, LILYANN

Violation CodeObservationViolation Citation

45-10-2

Pull station for fire suppression system inaccessible fack wedged in front of pull pin.For reporting purposes only.

NFPA 96, 10.5.1 A readily accessible means for manual activation shall be located between 42 inches and 48 inches above the floor, be accessible in the event of a fire, be located in a path of egress, and clearly identify the hazard protected. FOR REPORTING PURPOSES ONLY.

47-06-2

Observed extension cord in use for non-temporary period in kitchen for radio.For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1103148

INDIAN CUISINE

License Type: Permanent Food Service

3550 SW 34TH ST STE M, GAINESVILLE 32608

Inspection Date: 10/20/2009

Inspection Number: 1890620

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: WRENNE, LILYANN

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period.For radio by dishmachine.For reporting purposes only. Corrected On Site.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1103162

LOS AVINA MEXICAN RESTAURANT

License Type: Permanent Food Service

15 NE 2 AVE, HIGH SPRINGS 32643

Inspection Date: 10/21/2009

Inspection Number: 1920235

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BROWNING, JULIANNE

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Bay County**

License Number: 1302110

SAFFRON'S

License Type: Permanent Food Service

4012 W 23 ST, PANAMA CITY 32405

Inspection Date: 10/22/2009

Inspection Number: 1920343

Inspection Type: Complaint Full

Inspection Disposition: Emergency  
order recommended

Inspector Name: TALLEY, BELINDA

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only. At buffet.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1305272

TOP OF THE GULF CONDOMINIUM

License Type: Permanent Food Service

8817 THOMAS DR, PANAMA CITY BEACH 32408

Inspection Date: 10/19/2009

Inspection Number: 1881694

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: DESHAZIER, ERNEST

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

**Bradford County**

License Number: 1400159

DOLLY'S BAR-B-Q

License Type: Permanent Food Service

607 BROWNLEE STREET, STARKE 32091

Inspection Date: 10/21/2009

Inspection Number: 1881290

Inspection Type: Routine - Food

Inspection Disposition: Call Back -  
Extension given, pending

Inspector Name: DOHERTY, BRENDEN

Violation Code

Observation

Violation Citation

45-40-2

Violation: 45-40-2

Portable fire extinguisher with expired inspection tag. For reporting purposes only.

61C-1.004(9)(b) FAC and NFPA 10, 6.3.4 A standard state approved service tag shall be attached to each extinguisher and a person holding a valid state permit issued by the State Fire Marshal shall recharge or inspect the extinguisher and shall prepare the tag to include the information required by rule 4A-21.241, FAC, herein adopted by reference. Maintenance Recordkeeping. Each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was performed and that identifies the person performing the service. FOR REPORTING PURPOSES ONLY.



**Brevard County**

License Number: 1506023

SONNYS REAL PIT BAR-B-Q OF VIERA

License Type: Permanent Food Service

150 SHERIFF ROAD, MELBOURNE 32940

Inspection Date: 10/22/2009

Inspection Number: 1837005

Inspection Type: Routine - Food

Inspection Disposition: Call Back -  
Complied

Inspector Name: WOODS, CRYSTAL

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
49-09-2	Violation: 49-09-2  Observed paint buckets stored where gas smoker and hot water tank is stored.for reporting purposes only	61C-1.004(7) FAC (7) Attics, basements, boiler rooms, meter rooms, laundry rooms, and storage rooms shall be kept clean and free of debris and flammables. FOR REPORTING PURPOSES ONLY.
49-09-2	Observed paint buckets stored where gas smoker and hot water tank is stored.	61C-1.004(7) FAC (7) Attics, basements, boiler rooms, meter rooms, laundry rooms, and storage rooms shall be kept clean and free of debris and flammables. FOR REPORTING PURPOSES ONLY.



**Broward County**

License Number: 1618824

NANDO TRATTORIA

License Type: Permanent Food Service

2500 E HALLANDALE BEACH BLVD, HALLANDALE 33009

Inspection Date: 10/20/2009

Inspection Number: 1864474

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CONSIGLIO, CAMILLE

Violation CodeObservationViolation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1620739

FRESH CATCH SEAFOOD INC

License Type: Permanent Food Service

1050 W PEMBROKE RD, HALLANDALE 33009

Inspection Date: 10/22/2009

Inspection Number: 1874624

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CONSIGLIO, CAMILLE

Violation CodeObservationViolation Citation

45-36-2

Hood suppression system tag out-of-date. For reporting purposes only.10/08

NFPA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

License Number: 1621192

PRIME ATLANTIS RESTAURANT &amp; BAR

License Type: Permanent Food Service

1727 E HALLANDALE BEACH BLVD, HALLANDALE 33009

Inspection Date: 10/22/2009

Inspection Number: 1833528

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: CONSIGLIO, CAMILLE

Violation CodeObservationViolation Citation

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Broward County**

License Number: 1621151		SUSHI-THAI ON THE BEACH	
License Type: Permanent Food Service		300 S BROADWALK, HOLLYWOOD 33019	
Inspection Date: 10/20/2009	Inspection Number: 1833544	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CONSIGLIO, CAMILLE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 1621295		HOLLYWOOD BEACH MARRIOTT FOOD SERVICE & BAR	
License Type: Permanent Food Service		2501 N OCEAN DR, HOLLYWOOD 33019	
Inspection Date: 10/19/2009	Inspection Number: 1864446	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CONSIGLIO, CAMILLE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-40-2	Portable fire extinguisher with no approved inspection tag. For reporting purposes only.k class	61C-1.004(9)(b) FAC and NFPA 10, 6.3.4 A standard state approved service tag shall be attached to each extinguisher and a person holding a valid state permit issued by the State Fire Marshal shall recharge or inspect the extinguisher and shall prepare the tag to include the information required by rule 4A-21.241, FAC, herein adopted by reference. Maintenance Recordkeeping. Each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was performed and that identifies the person performing the service. FOR REPORTING PURPOSES ONLY.	
45-40-2	Portable fire extinguisher with no approved inspection tag. For reporting purposes only.abc bar	61C-1.004(9)(b) FAC and NFPA 10, 6.3.4 A standard state approved service tag shall be attached to each extinguisher and a person holding a valid state permit issued by the State Fire Marshal shall recharge or inspect the extinguisher and shall prepare the tag to include the information required by rule 4A-21.241, FAC, herein adopted by reference. Maintenance Recordkeeping. Each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was performed and that identifies the person performing the service. FOR REPORTING PURPOSES ONLY.	

License Number: 1622003		YUMMY SHACK II INC	
License Type: Permanent Food Service		311 JOHNSON ST, HOLLYWOOD 33019	
Inspection Date: 10/21/2009	Inspection Number: 1915452	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CONSIGLIO, CAMILLE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only.month not punched	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.	

**Broward County**

License Number: 1609114		OASIS BY THE SEA	
License Type: Permanent Food Service		1211 N SURF RD, HOLLYWOOD 330193303	
Inspection Date: 10/21/2009	Inspection Number: 1905541	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CONSIGLIO, CAMILLE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 1620940		A LA TURCA	
License Type: Permanent Food Service		2027 HOLLYWOOD BLVD, HOLLYWOOD 33020	
Inspection Date: 10/19/2009	Inspection Number: 1905635	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Complied
Inspector Name: CHAPDELAINE, MARIE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
48-13-2	Violation: 48-13-2 Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.	

License Number: 1619111		KFC/TACO BELL	
License Type: Permanent Food Service		3650 UTOPIA DR, MIRAMAR 33023	
Inspection Date: 10/16/2009	Inspection Number: 1843869	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: QUINONES, JOSE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. Corrected On Site.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	

**Broward County**

License Number: 1616203 MARCELLAS RESTAURANT & PIZZA  
 License Type: Permanent Food Service 12305 PEMBROKE RD, PEMBROKE PINES 33025

Inspection Date: 10/20/2009 Inspection Number: 1905421 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: VASQUEZ, JANNETH

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-25-2	Hood filter missing.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.
49-06-2	Observed flammable material stored around water heater. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

License Number: 1610881 BAGEL TIME  
 License Type: Permanent Food Service 10036 PINES BLVD, PEMBROKE PINES 33026

Inspection Date: 10/16/2009 Inspection Number: 1905419 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: QUINONES, JOSE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only. friers.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. backdoor.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 1619841 MCDONALDS  
 License Type: Permanent Food Service 14301 MIRAMAR PKWY, MIRAMAR 33027

Inspection Date: 10/23/2009 Inspection Number: 1884749 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: VASQUEZ, JANNETH

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
49-06-2	Observed flammable material stored around water heater. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

**Broward County**

License Number: 1621789		SALS ITALIAN RISTORANTE	
License Type: Permanent Food Service		15717 PINES BLVD STE C-5, PEMBROKE PINES 33027	
Inspection Date: 10/20/2009	Inspection Number: 1864354	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DURDEN, VICKIE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 1622062		WAHOO'S SPORTS BAR & GRILL	
License Type: Permanent Food Service		3128 N FEDERAL HWY, LIGHTHOUSE POINT 33064	
Inspection Date: 10/19/2009	Inspection Number: 1885467	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: EARP, NICOLETTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 1619669		DI PIZZA	
License Type: Permanent Food Service		3003 N FEDERAL HWY, POMPANO BEACH 33064	
Inspection Date: 10/19/2009	Inspection Number: 1834153	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: EARP, NICOLETTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-08-2	Exit signs not visible from any direction. For reporting purposes only.	NFPA 101, 7.10.1.2 Exits, other than main exterior exit doors that obviously and clearly are identifiable as exits, shall be marked by an approved sign readily visible from any direction of exit access. FOR REPORTING PURPOSES ONLY.	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 1601261		MARYLAND FRIED CHICKEN	
License Type: Permanent Food Service		1821 E SAMPLE RD, POMPANO BCH 330641323	
Inspection Date: 10/20/2009	Inspection Number: 1895712	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: EARP, NICOLETTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
49-06-2	Observed flammable material stored around water heater. For reporting purposes only. Corrected On Site.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.	
License Number: 1613209		CHECKERS #838	
License Type: Permanent Food Service		3541 NW 8 AVE, POMPANO BCH 330643001	
Inspection Date: 10/20/2009	Inspection Number: 1885443	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: EARP, NICOLETTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

**Broward County**

License Number: 1610479 KHANA KHZANA  
 License Type: Permanent Food Service 10345 W SAMPLE RD, CORAL SPRINGS 33065

Inspection Date: 10/20/2009 Inspection Number: 1844391 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: BECKER, ROBERT

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only. K extinguisher	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1614199 VILLA PIZZA  
 License Type: Permanent Food Service FLORIDA TURNPIKE MM 65, POMPANO BEACH 33068

Inspection Date: 10/22/2009 Inspection Number: 1885393 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: WILLIAMS, NOVELETTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 1600891 EGG & YOU DINER  
 License Type: Permanent Food Service 2621 N FEDERAL HWY, FT LAUDERDALE 333061421

Inspection Date: 10/22/2009 Inspection Number: 1875071 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: LITSCHER, JOHN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

License Number: 1619835 ARAMARK @ SPHERION  
 License Type: Permanent Food Service 4050 NW 21 AVE, FORT LAUDERDALE 33309

Inspection Date: 10/16/2009 Inspection Number: 1876308 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: SCHNEIDER, MICHELE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. door in dishroom	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

**Broward County**

License Number: 1611524		BAMBU CAFE	
License Type: Permanent Food Service		2870 SW 54 ST, FORT LAUDERDALE 33312	
Inspection Date: 10/19/2009	Inspection Number: 1920007	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GRAY, ANTHONY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 1622356		NAVAS TAVERNA N GRILL	
License Type: Permanent Food Service		5416 SOUTH STATE ROAD 7, HOLLYWOOD 33314	
Inspection Date: 10/21/2009	Inspection Number: 1874540	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: QUINONES, JOSE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	
License Number: 1619817		FAT TUESDAY	
License Type: Permanent Food Service		17 S FT LAUDERDALE BEACH BLVD, FORT LAUDERDALE 33316	
Inspection Date: 10/19/2009	Inspection Number: 1885111	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: TORRES, LARRY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. used for coolers in rear storage area. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	



**Broward County**

License Number: 1621449

LA QUINTA INN & SUITES #7718

License Type: Permanent Food Service

5070 N SR 7, FORT LAUDERDALE 33319

Inspection Date: 10/22/2009

Inspection Number: 1864800

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: WILLIAMS, NOVELETTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-11-2	Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building, under three compartments sink. For reporting purposes only.	NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.
48-12-2	No current boiler certification provided/available- expired 5/18/08. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

**Broward County**

License Number: 1608604 ISLAND PALACE  
 License Type: Permanent Food Service 4170 N SR 7, LAUDERDALE LAKES 33319

Inspection Date: 10/20/2009 Inspection Number: 1864826 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: WILLIAMS, NOVELETTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-07-2	Observed misalignment of hood suppression system nozzles. For reporting purposes only.	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

License Number: 1618782 GOLDEN CORRAL # 848  
 License Type: Permanent Food Service 7401 W COMMERCIAL BLVD, TAMARAC 33319

Inspection Date: 10/19/2009 Inspection Number: 1833890 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: WILLIAMS, NOVELETTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces, by buffet station. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
39-05-2	Ventilation inadequate as evidenced by smoke stained ceiling by buffet station. For reporting purposes only.	NFPA 96, 4.1.1 Cooking equipment used in processes producing smoke or grease-laden vapors shall be equipped with an exhaust system that complies with all the equipment and performance requirements of this standard; and NFPA 96, 8.2.2 Air Volume. NFPA 96, 8.2.2.1: Exhaust air volumes for hoods shall be of a sufficient level to provide for capture and removal of grease-laden cooking vapors. FOR REPORTING PURPOSES ONLY
46-13-2	Emergency light does not function when tested, in ladies' restroom. For reporting purposes only.	NFPA 101, 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted at 30-day intervals for not less than 30 seconds. (2) Functional testing shall be conducted annually for not less than 1½ hours if the emergency lighting system is battery powered. (3) The emergency lighting equipment shall be fully operational for the duration of the tests required by 7.9.3.1.1(1) and 7.9.3.1.1(2). FOR REPORTING PURPOSES ONLY.
49-06-2	Observed flammable material stored around water heater, approximately 30 cans of Butane fuel. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.
49-10-2	Observed flammables and debris stored in meter room, gasoline and pressure machine, with gasoline. For reporting purposes only. Corrected On Site.	61C-1.004(7) FAC (7) Attics, basements, boiler rooms, meter rooms, laundry rooms, and storage rooms shall be kept clean and free of debris and flammables. FOR REPORTING PURPOSES ONLY.

License Number: 1619182 KINGSHEAD PUB  
 License Type: Permanent Food Service 2692 N UNIVERSITY DR, SUNRISE 33322

Inspection Date: 10/15/2009 Inspection Number: 1833854 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: MULLINGS, SEANTELE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

**Broward County**

License Number: 1620513 POPEYES  
 License Type: Permanent Food Service 12801 W SUNRISE BLVD #849, SUNRISE 33323

Inspection Date: 10/15/2009 Inspection Number: 1833834 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: WILLIAMS, ALECIA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 1619394 ESPOSITO'S PIZZA  
 License Type: Permanent Food Service 2221 S UNIVERSITY DR, DAVIE 33324

Inspection Date: 10/22/2009 Inspection Number: 1833702 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: BECKER, ROBERT

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-42-2	Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.	NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY

License Number: 1613382 STROMBOLI PIZZA  
 License Type: Permanent Food Service 801 S UNIVERSITY DR #F101, PLANTATION 333243334

Inspection Date: 10/20/2009 Inspection Number: 1905689 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: WILLIAMS, FERNANDO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.rear door.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 1619767 DELI BOY SUBS  
 License Type: Permanent Food Service 11328 SR 84, DAVIE 33325

Inspection Date: 03/08/2007 Inspection Number: 1450411 Inspection Type: Routine - Food Inspection Disposition: Call Back - Admin. complaint recommended  
 Inspector Name: WILLIAMS, FERNANDO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-1	Violation: 46-09-1 Exit signs not properly illuminated, in dining room.	61C-1.004(10) FAC:: Exits shall be clearly marked with approved illuminated exit signs.

**Broward County**

License Number: 1621234	RUBY TUESDAY		
License Type: Permanent Food Service	11590 SR 84, DAVIE 33325		
Inspection Date: 10/21/2009	Inspection Number: 1833720	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BECKER, ROBERT			
<u>Violation Code</u>	<u>Observation</u>		<u>Violation Citation</u>
15-42-2	Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.		NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY
License Number: 1600521	COOPER COLONY COUNTRY CLUB		
License Type: Permanent Food Service	5050 S 90 AVE, COOPER CITY 333283623		
Inspection Date: 10/21/2009	Inspection Number: 1886367	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DURDEN, VICKIE			
<u>Violation Code</u>	<u>Observation</u>		<u>Violation Citation</u>
49-12-2	Observed container of flammable material over 5 gallons stored in establishment. For reporting purposes only.		61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.
License Number: 1615798	DISALVO'S		
License Type: Permanent Food Service	5945 S UNIVERSITY DR, DAVIE 333286112		
Inspection Date: 10/22/2009	Inspection Number: 1855646	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DURDEN, VICKIE			
<u>Violation Code</u>	<u>Observation</u>		<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.		NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.
License Number: 1619436	BIG CITY DOGS		
License Type: Permanent Food Service	1199 E COMMERCIAL BLVD, FORT LAUDERDALE 33334		
Inspection Date: 10/21/2009	Inspection Number: 1914374	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SCHNEIDER, MICHELE			
<u>Violation Code</u>	<u>Observation</u>		<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.		NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

**Broward County**

License Number: 1620170 JACK'S BAR-B-Q SMOKEHOUSE  
 License Type: Permanent Food Service 500 E OAKLAND PARK BLVD, WILTON MANORS 33334

Inspection Date: 10/20/2009 Inspection Number: 1886425 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: SCHNEIDER, MICHELE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only main rest room door.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only both doors in dining room.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.

License Number: 1610139 EAST COAST BURRITO FACTORY  
 License Type: Permanent Food Service 261 E COMMERCIAL BLVD, FT LAUDERDALE 333341625

Inspection Date: 10/16/2009 Inspection Number: 1876272 Inspection Type: Routine - Food Inspection Disposition: Call Back - Complied  
 Inspector Name: SCHNEIDER, MICHELE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-2	Violation: 46-09-2 Exit signs not properly illuminated. For reporting purposes only front door.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 1609978 LOVEYS RESTAURANT USA INC  
 License Type: Permanent Food Service 8336 W OAKLAND PARK BLVD, SUNRISE 33351

Inspection Date: 10/15/2009 Inspection Number: 1885179 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: WILLIAMS, ALECIA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1620011 PAPA JOHNS  
 License Type: Permanent Food Service 1420 S FEDERAL HWY, DEERFIELD BCH 33441

Inspection Date: 10/16/2009 Inspection Number: 1875274 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: EARP, NICOLETTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

**Broward County**

License Number: 1621913

LITTLE CAESARS CARRY OUT

License Type: Permanent Food Service

1462 S FEDERAL HWY, DEERFIELD BEACH 33441

Inspection Date: 10/16/2009

Inspection Number: 1854762

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: EARP, NICOLETTE

Violation Code

Observation

Violation Citation

49-06-2

Observed flammable material stored around water heater. For reporting purposes only.

61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

**Charlotte County**

License Number: 1801424

END ZONE (THE)

License Type: Permanent Food Service

2411 S MCCALL RD #A&B, ENGLEWOOD 34224

Inspection Date: 10/20/2009

Inspection Number: 1872279

Inspection Type: Routine - Food

Inspection Disposition: Call Back -  
Extension given, pending

Inspector Name: LANDMANN, PAUL

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-15-2	Violation: 47-15-2  Observed an uncovered electrical box. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.
48-06-2	Violation: 48-06-2  Observed a gas appliance without proper venting. For reporting purposes only. vents instakked wrlong	61C-1.004(13)(a) FAC Gas appliances. All appliances, including water heaters using gas, shall be kept in good repair and properly vented when manufacturers' instructions require venting of the appliance and shall meet the following requirements: (a) All appliances shall have a nationally recognized testing laboratory seal such as AGA or UL seal. FOR REPORTING PURPOSES ONLY.

**Citrus County**

License Number: 1901139

PANETOPIA RESTAURANT AND BAKERY

License Type: Permanent Food Service

721 U.S. HWY 41 S, INVERNESS 34450

Inspection Date: 10/20/2009

Inspection Number: 1898207

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: CRAIG, JILL

Violation CodeObservationViolation Citation

15-25-2

Hood filters not equipped with a drip tray. For reporting purposes only. Repeat Violation.

NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY

46-09-2

Exit signs not properly illuminated-rear kitchen exit. For reporting purposes only.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 1900959

CHECKERS #649

License Type: Permanent Food Service

510 W MAIN ST, INVERNESS 344504749

Inspection Date: 10/20/2009

Inspection Number: 1887894

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: CRAIG, JILL

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor- class K. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

**Clay County**

License Number: 2000902

TAILGATERS SPORTS BAR

License Type: Permanent Food Service

1413 S ORANGE AVE, GREEN COVE SPRINGS 32043

Inspection Date: 10/21/2009

Inspection Number: 1849977

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: D'ANTONIO, JANET

Violation CodeObservationViolation Citation

46-09-2

Observed An Exit signs not properly illuminated. For reporting purposes only.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

47-05-2

Observed several splitter/multi-plug electrical adapters in use, also orange extension cord. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 2001040

THE TOP OF THE REEF

License Type: Permanent Food Service

414 WALNUT ST, GREEN COVE SPRINGS 32043

Inspection Date: 10/21/2009

Inspection Number: 1859930

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: D'ANTONIO, JANET

Violation CodeObservationViolation Citation

47-15-2

Observed an uncovered electrical junction box kitchen ceiling. For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

**Columbia County**

License Number: 2200500

MIKE'S CAFE &amp; GRILLE

License Type: Permanent Food Service

426 SW COMMERCE DR #115, LAKE CITY 32025

Inspection Date: 10/19/2009

Inspection Number: 1849577

Inspection Type: Routine - Food

Inspection Disposition: Warning  
Issued

Inspector Name: WRENNE, LILYANN

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor sitting on floor in closet. For reporting purposes only.  
Repeat Violation.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

47-06-2

Observed extension cord in use for non-temporary period at microwave in kitchen. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 2200588

ZAXBY'S

License Type: Permanent Food Service

2640 W US HWY 90, LAKE CITY 32025

Inspection Date: 10/19/2009

Inspection Number: 1900703

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: WRENNE, LILYANN

Violation CodeObservationViolation Citation

47-05-2

Observed a splitter/multi-plug adapter in use in office. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Dade County**

License Number: 2355062 LOS POTOSINOS TAQUERIA  
 License Type: Mobile Food Dispensing Vehicle 18585 SW 360 ST, FLORIDA CITY 33002

Inspection Date: 09/23/2009 Inspection Number: 1136393 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: NUNEZ, ANDRES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-07-1	OBSERVED MISALIGNMENT OF HOOD SUPPRESSION SYSTEM NOZZLES. FOR REPORTING PURPOSES ONLY.	NFPA 96, 10.2.: Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems

License Number: 2326580 VOLVERE #1  
 License Type: Permanent Food Service 158 HIALEAH DR, HIALEAH 33010

Inspection Date: 10/22/2009 Inspection Number: 1832535 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: BRADOR, MOISES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
48-11-2	Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only.	NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

License Number: 2332251 BENTO SUSHI RESTAURANT  
 License Type: Permanent Food Service 801 BRICKELL BAY DRIVE LOBBY LOUNG, MIAMI 33131

Inspection Date: 10/23/2009 Inspection Number: 1863471 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: PEREZ, TONY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-06-2	Observed a gas appliance without proper venting. For reporting purposes only. HOOD SYSTEM WITH OPEN FLUME INTERRUPTED IN MIDDLE	61C-1.004(13)(a) FAC Gas appliances. All appliances, including water heaters using gas, shall be kept in good repair and properly vented when manufacturers' instructions require venting of the appliance and shall meet the following requirements: (a) All appliances shall have a nationally recognized testing laboratory seal such as AGA or UL seal. FOR REPORTING PURPOSES ONLY.

**Dade County**

License Number: 2331418

PERFORMING ARTS CATERING BY BARTON G

License Type: Permanent Food Service

1300 BISCAYNE BLVD, MIAMI 33132

Inspection Date: 10/19/2009

Inspection Number: 1853138

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PEREZ, TONY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

**Dade County**

License Number: 2331419

PERFORMING ARTS CATERING BY BARTON G

License Type: Permanent Food Service

1300 BISCAYNE BLVD, MIAMI 33132

Inspection Date: 10/19/2009

Inspection Number: 1883899

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PEREZ, TONY

Violation Code

Observation

Violation Citation

48-12-2 No current boiler certification provided/available. For reporting purposes only.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

**Dade County**

License Number: 2331420

PERFORMING ARTS CATERING BY BARTON G

License Type: Permanent Food Service

1300 BISCAYNE BLVD, MIAMI 33132

Inspection Date: 10/19/2009

Inspection Number: 1863411

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PEREZ, TONY

Violation Code

Observation

Violation Citation

48-12-2

No current boiler certification provided/available. For reporting purposes only.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

**Dade County**

License Number: 2331421

PERFORMING ARTS CATERING BY BARTON G

License Type: Permanent Food Service

1300 BISCAYNE BLVD, MIAMI 33132

Inspection Date: 10/19/2009

Inspection Number: 1894034

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PEREZ, TONY

Violation Code

Observation

Violation Citation

48-12-2 No current boiler certification provided/available. For reporting purposes only.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

**Dade County**

License Number: 2331422

PERFORMING ARTS CATERING BY BARTON G

License Type: Permanent Food Service

1300 BISCAYNE BLVD, MIAMI 33132

Inspection Date: 10/19/2009

Inspection Number: 1873692

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PEREZ, TONY

Violation Code

Observation

Violation Citation

48-12-2 No current boiler certification provided/available. For reporting purposes only.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

**Dade County**

License Number: 2331423

PERFORMING ARTS CATERING BY BARTON G

License Type: Permanent Food Service

1300 BISCAYNE BLVD, MIAMI 33132

Inspection Date: 10/19/2009

Inspection Number: 1883901

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PEREZ, TONY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

**Dade County**

License Number: 2332592 PRELUDE BY BARTON G  
 License Type: Permanent Food Service 1300 BISCAYNE BLVD, MIAMI 33132

Inspection Date: 10/19/2009 Inspection Number: 1919553 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: PEREZ, TONY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 2317722 BAYVIEW RESTAURANT  
 License Type: Permanent Food Service 1633 N BAYSHORE DR, MIAMI 331321215

Inspection Date: 10/21/2009 Inspection Number: 1832619 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: PEREZ, TONY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-13-2	Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.

License Number: 2331753 VENETIAN POOL CONCESSION STAND  
 License Type: Permanent Food Service 2701 DE SOTO BLVD, CORAL GABLES 33134

Inspection Date: 10/22/2009 Inspection Number: 1863667 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: BURROWS, LEON

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

**Dade County**

License Number: 2302446		LAS NUEVAS CULEBRINAS REST	
License Type: Permanent Food Service		4700 W FLAGLER ST, MIAMI 331341452	
Inspection Date: 10/23/2009	Inspection Number: 1884089	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BURROWS, LEON			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	

License Number: 2325321		LA PALMA RISTORANTE	
License Type: Permanent Food Service		116 ALHAMBRA CIR, CORAL GABLES 331344531	
Inspection Date: 10/16/2009	Inspection Number: 1884099	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BURROWS, LEON			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.	
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only.	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.	

License Number: 2316334		UNIVERSITY RESTAURANT & PATIO	
License Type: Permanent Food Service		1050 NW 14TH STREET, MIAMI 33136	
Inspection Date: 10/20/2009	Inspection Number: 1920001	Inspection Type: Complaint Full	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BLAIR, ANTONIO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	

License Number: 2331213		POLAR BAR	
License Type: Permanent Food Service		938 LINCOLN RD, MIAMI BEACH 33139	
Inspection Date: 10/19/2009	Inspection Number: 1862933	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BATISTA, JENNY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. class k on floor under 3 compartment sink	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	

**Dade County**

License Number: 2325463

DAYS INN ART DECO REST

License Type: Permanent Food Service

100 21 ST, MIAMI BEACH 331391701

Inspection Date: 10/22/2009

Inspection Number: 1873131

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: BATISTA, JENNY

Violation CodeObservationViolation Citation

48-11-2

Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only. 4 cylinders inside kiTCHEN

NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

License Number: 2325765

MACALUSO'S RESTAURANT

License Type: Permanent Food Service

1747 ALTON RD, MIAMI BEACH 331392411

Inspection Date: 10/22/2009

Inspection Number: 1883401

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: BATISTA, JENNY

Violation CodeObservationViolation Citation

45-38-2

Portable fire extinguisher not fully charged. For reporting purposes only.in kiTCHEN by ice machine

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

45-41-2

Portable fire extinguisher tag out-of-date. For reporting purposes only.

NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

License Number: 2325806

CHINA GRILL

License Type: Permanent Food Service

404 WASHINGTON AVE, MIAMI BEACH 331396600

Inspection Date: 10/20/2009

Inspection Number: 1873083

Inspection Type: Routine - Food

Inspection Disposition: Administrative  
complaint recommended

Inspector Name: RICHARD, DICKSON

Violation CodeObservationViolation Citation

45-02-2

Sprinkler head spray pattern obstructed. For reporting purposes only.At dry storage area.

NFPA 25, 5.2.1.2 Unacceptable obstructions to spray patterns shall be corrected. FOR REPORTING PURPOSES ONLY.

**Dade County**

License Number: 2320498		EL OSO BLANCO CAFETERIA	
License Type: Permanent Food Service		3301 NW 28 ST, MIAMI 33142	
Inspection Date: 10/16/2009	Inspection Number: 1832868	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: KHAN, MOHAMMAD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 2315554		ANGEL'S CAFETERIA	
License Type: Permanent Food Service		3677 NW 50 ST, MIAMI 331423933	
Inspection Date: 10/22/2009	Inspection Number: 1863709	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BLAIR, ANTONIO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-27-2	Observed the presence of mesh filters in a hood where grease laden vapors are produced. For reporting purposes only.	NFPA 96, 6.1.3 Mesh filters shall not be used. FOR REPORTING PURPOSES ONLY	
License Number: 2317285		MCDONALDS #6589	
License Type: Permanent Food Service		2200 NW 36 ST, MIAMI 331425358	
Inspection Date: 10/19/2009	Inspection Number: 1853388	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CHI, MAURICE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. Corrected On Site.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	
License Number: 2321265		DELI LANE CAFE	
License Type: Permanent Food Service		7230 SW 59 AVE, SOUTH MIAMI 331435208	
Inspection Date: 10/19/2009	Inspection Number: 1905279	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: CONYERS,			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only. Repeat Violation.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	

**Dade County**

License Number: 2311742 ZUPERPOLLO RESTAURANT  
 License Type: Permanent Food Service 1247 CORAL WAY, MIAMI 331452963

Inspection Date: 10/20/2009 Inspection Number: 1884281 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: GANDOLFF, JORGE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 2315267 LA ESQUINA HONDURENAL  
 License Type: Permanent Food Service 2240 SW 32 AVE, MIAMI 331453114

Inspection Date: 10/20/2009 Inspection Number: 1874040 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: GANDOLFF, JORGE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-42-2	Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.	NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2317877 CHINA GARDEN RESTAURANT  
 License Type: Permanent Food Service 260 CRANDON BLVD #47, KEY BISCAYNE 33149

Inspection Date: 10/20/2009 Inspection Number: 1864218 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended  
 Inspector Name: CONYERS,

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 2328414 LE CROISI C  
 License Type: Permanent Food Service 180 CRANDON BLVD #11-6, KEY BISCAYNE 33149

Inspection Date: 10/20/2009 Inspection Number: 1884613 Inspection Type: Routine - Food Inspection Disposition: Call Back - Extension given, pending  
 Inspector Name: CONYERS,

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.missing filter.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
47-16-2	Violation: 47-16-2 Electrical outlet missing cover plate. For reporting purposes only.front hws.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

**Dade County**

License Number: 2302624 PICNICS  
 License Type: Permanent Food Service 6500 SW 40 ST, MIAMI 33155

Inspection Date: 10/21/2009 Inspection Number: 1884251 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: NUNEZ, ANDRES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2315937 ELCHORIPAN CAFETERIA  
 License Type: Permanent Food Service 4546 SW 74TH AVE, MIAMI 33155

Inspection Date: 10/22/2009 Inspection Number: 1832971 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: GANDOLFF, JORGE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2329049 CACAO EXPRESS INC  
 License Type: Catering 7165 SW 47 ST #312, MIAMI 33155

Inspection Date: 10/21/2009 Inspection Number: 1092332 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: GANDOLFF, JORGE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2330241 CATERING  
 License Type: Permanent Food Service 4631 SW 75 AVENUE, MIAMI 33155

Inspection Date: 10/20/2009 Inspection Number: 1843321 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: GANDOLFF, JORGE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

**Dade County**

License Number: 2325715		TACO BELL #17108	
License Type: Permanent Food Service		7753 SW 40 ST, MIAMI 331553546	
Inspection Date: 10/22/2009	Inspection Number: 1884285	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GANDOLFF, JORGE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-40-2	Portable fire extinguisher with no approved inspection tag. For reporting purposes only. Class K	61C-1.004(9)(b) FAC and NFPA 10, 6.3.4 A standard state approved service tag shall be attached to each extinguisher and a person holding a valid state permit issued by the State Fire Marshal shall recharge or inspect the extinguisher and shall prepare the tag to include the information required by rule 4A-21.241, FAC, herein adopted by reference. Maintenance Recordkeeping. Each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was performed and that identifies the person performing the service. FOR REPORTING PURPOSES ONLY.	
License Number: 2300076		CHINA TOKYO EXPRESS	
License Type: Permanent Food Service		5796 BIRD RD, MIAMI 33155302	
Inspection Date: 10/23/2009	Inspection Number: 1843280	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: GANDOLFF, JORGE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 2318674		EL EDEN II	
License Type: Permanent Food Service		10755 SW 190 ST, MIAMI 331577628	
Inspection Date: 10/20/2009	Inspection Number: 1833033	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Complied
Inspector Name: DE LA CRUZ, ADONIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Violation: 37-20-2  Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 2325037		NEW TIME	
License Type: Permanent Food Service		2120 NE 123 ST, NORTH MIAMI 33161	
Inspection Date: 10/16/2009	Inspection Number: 1863043	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: URIARTE, DENNIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only. class k extinguishers .	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

**Dade County**

License Number: 2328396	SYNAI GARDENS	
License Type: Permanent Food Service	8356 SW 40 ST, MIAMI	33165
Inspection Date: 10/21/2009	Inspection Number: 1904959	Inspection Type: Routine - Food
Inspector Name: GANDOLFF, JORGE		Inspection Disposition: Inspection Completed - No Further Action

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-11-2	Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only.	NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

License Number: 2330206	WAN ENTERPRISES	
License Type: Permanent Food Service	4635 SW 75 AVENUE, MIAMI	33165
Inspection Date: 10/20/2009	Inspection Number: 1863878	Inspection Type: Routine - Food
Inspector Name: GANDOLFF, JORGE		Inspection Disposition: Inspection Completed - No Further Action

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2303074	BIRD BOWL COFFEE SHOP	
License Type: Permanent Food Service	9275 BIRD RD, MIAMI	331654150
Inspection Date: 10/21/2009	Inspection Number: 1904953	Inspection Type: Routine - Food
Inspector Name: GANDOLFF, JORGE		Inspection Disposition: Inspection Completed - No Further Action

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY
48-13-2	Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.

**Dade County**

License Number: 2326438		JOHNNY ROCKETS	
License Type: Permanent Food Service		8888 SW 136 ST #487, MIAMI 33176	
Inspection Date: 10/20/2009	Inspection Number: 1853688	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DE LA CRUZ, ADONIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
License Number: 2328479		II PASTARO TRATORIA PIZZA CAFE	
License Type: Permanent Food Service		11500 BISCAYNE BLVD, MIAMI 33181	
Inspection Date: 10/22/2009	Inspection Number: 1852746	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: CHOW, ZULEIMA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
48-11-2	Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only.	NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.	
License Number: 2332373		KEYSTONE PIZZA	
License Type: Permanent Food Service		12581 BISCAYNE BLVD, MIAMI 33181	
Inspection Date: 10/22/2009	Inspection Number: 1904101	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: URIARTE, DENNIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

**Dade County**

License Number: 2302903		WOODY'S FAMOUS STEAK SANDWICH	
License Type: Permanent Food Service		13105 BISCAYNE BLVD, N MIAMI 33181	
Inspection Date: 10/20/2009	Inspection Number: 1904095	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Complied
Inspector Name: ALONZO, GUILLERMO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Violation: 15-28-2 Hood filters missing. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 2330198		JUMBO BUFFET II	
License Type: Permanent Food Service		13699 BISCAYNE BLVD, SURFSIDE 33181	
Inspection Date: 10/20/2009	Inspection Number: 1920177	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: JARAMILLO, MARIA C			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 2325149		NEW YORKS BIG APPLE DELI	
License Type: Permanent Food Service		14432 BISCAYNE BLVD, NORTH MIAMI BEACH 33181208	
Inspection Date: 10/21/2009	Inspection Number: 1873238	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: CHOW, ZULEIMA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
45-38-2	Portable fire extinguisher overcharged. For reporting purposes only. K_CLASS	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
45-38-2	Violation: 45-38-2 Portable fire extinguisher overcharged. For reporting purposes only. K_CLASS	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
License Number: 2323079		LITTLE HAVANA REST	
License Type: Permanent Food Service		12727 BISCAYNE BLVD, NORTH MIAMI 331812003	
Inspection Date: 10/21/2009	Inspection Number: 1893666	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: CHOW, ZULEIMA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-07-2	Observed misalignment of hood suppression system nozzles. For reporting purposes only.	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.	

**Dade County**

License Number: 2300740 WONGS  
 License Type: Permanent Food Service 12420 BISCAYNE BLVD, NORTH MIAMI 331812521

Inspection Date: 10/21/2009 Inspection Number: 1904117 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: URIARTE, DENNIS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2313058 STEVE'S PIZZA #3  
 License Type: Permanent Food Service 12101 BISCAYNE BLVD, NORTH MIAMI 331812711

Inspection Date: 10/16/2009 Inspection Number: 1852718 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: URIARTE, DENNIS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2327807 CHINA TOWN WEST  
 License Type: Permanent Food Service 4210 SW 152 AVE, MIAMI 33185

Inspection Date: 10/22/2009 Inspection Number: 1874006 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: MORGADANES, DOUGLAS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2328688 LA GIRALDILLA RESTAURANT  
 License Type: Permanent Food Service 4292 SW 152 AVE, MIAMI 33185

Inspection Date: 10/22/2009 Inspection Number: 1884237 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: MORGADANES, DOUGLAS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

**Dade County**

License Number: 2326461 FUJI HANA  
 License Type: Permanent Food Service 11768 SW 88 ST, MIAMI 33186

Inspection Date: 10/16/2009 Inspection Number: 1843421 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: VALDERRAMA, ELISA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-07-2	Observed grease and dust accumulated around electrical outlet. For reporting purposes only. outlets in kitchen hanging from ceiling	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 2322895 SPORTS GRILL HAMMOCKS  
 License Type: Permanent Food Service 14617 SW 104 ST, MIAMI 331862905

Inspection Date: 10/22/2009 Inspection Number: 1833091 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: VALDERRAMA, ELISA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
39-05-2	Ventilation inadequate as evidenced by smoke in kitchen area. For reporting purposes only. and through out restaurant	NFPA 96, 4.1.1 Cooking equipment used in processes producing smoke or grease-laden vapors shall be equipped with an exhaust system that complies with all the equipment and performance requirements of this standard; and NFPA 96, 8.2.2 Air Volume. NFPA 96, 8.2.2.1: Exhaust air volumes for hoods shall be of a sufficient level to provide for capture and removal of grease-laden cooking vapors. FOR REPORTING PURPOSES ONLY

License Number: 2316556 UNCLE FRANKS PIZZA  
 License Type: Permanent Food Service 20290 OLD CUTLER RD, MIAMI 331891919

Inspection Date: 10/19/2009 Inspection Number: 1833205 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: DE LA CRUZ, ADONIS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

**Duval County**

License Number: 2613632

MI TIERRA MEXICAN GROCERIES #2

License Type: Permanent Food Service

5761 BENEY RD, JACKSONVILLE 32207

Inspection Date: 10/19/2009

Inspection Number: 1860210

Inspection Type: Routine - Food

Inspection Disposition: Administrative complaint recommended

Inspector Name: ESPINOSA-BECKERT, ILIANA

Violation CodeObservationViolation Citation

45-07-2

Observed misalignment of hood suppression system nozzles. For reporting purposes only. 2 burners not under nozzles Corrected On Site.

NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

47-16-2

Electrical outlet missing cover plate. For reporting purposes only. by fire extinguisher

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 2651134

WATER'S KITCHEN

License Type: Mobile Food Dispensing Vehicle

5627 SAN JOSE BLVD, JACKSONVILLE 32207

Inspection Date: 10/23/2009

Inspection Number: 1134267

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: ESPINOSA-BECKERT, ILIANA

Violation CodeObservationViolation Citation

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only. orange by drinks cooler

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Duval County**

License Number: 2612079 CROWNE PLAZA JACKSONVILLE RIVERFRONT  
 License Type: Permanent Food Service 1201 RIVERPLACE BLVD, JACKSONVILLE 32207-9009

Inspection Date: 09/24/2009 Inspection Number: 1839650 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended  
 Inspector Name: ESPINOSA-BECKERT, ILIANA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-11-2	Out of compliance: Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial	NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

License Number: 2610728 JACKIE'S SEAFOOD  
 License Type: Permanent Food Service 8132 TROUT RIVER DRIVE, JACKSONVILLE 32208

Inspection Date: 10/20/2009 Inspection Number: 1920172 Inspection Type: Complaint Full Inspection Disposition: Emergency order recommended  
 Inspector Name: DAVIS, MOSES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only, BAR.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair
46-09-2	Exit signs not properly illuminated. For reporting purposes only, NEAR RESTROOMS.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only, KITCHEN .	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Duval County**

License Number: 2613863	DUNBAR'S HOME COOKED MEALS REST		
License Type: Permanent Food Service	786 BUNKER HILL BLVD, JACKSONVILLE	32208	
Inspection Date: 10/17/2009	Inspection Number: 1860616	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: DAVIS, MOSES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
48-11-2	Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only. Corrected On Site.	NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.	

License Number: 2600685	KRYSTAL JAX-09		
License Type: Permanent Food Service	7459 LEM TURNER RD, JACKSONVILLE	322083350	
Inspection Date: 10/20/2009	Inspection Number: 1920139	Inspection Type: Complaint Full	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DAVIS, MOSES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only, REAR DOOR BLOCKED BY BOXES; .	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	
47-14-2	Insufficient space around electrical equipment to permit ready and safe operation of such equipment. For reporting purposes only, BLOCKED BY BREAD RACK.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.	
47-15-2	Observed an uncovered electrical box. For reporting purposes only, B PANEL .	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

**Duval County**

License Number: 2612208		MOTOGA JAPANESE RESTAURANT	
License Type: Permanent Food Service		7950 ATLANTIC BLVD, JACKSONVILLE 32211	
Inspection Date: 10/19/2009	Inspection Number: 1901571	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: YOUNG, DERRICK			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only. by waitress station	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 2609184		CHARDONNAY'S	
License Type: Catering		3305 PARENTAL HOME ROAD, JACKSONVILLE 32216	
Inspection Date: 10/21/2009	Inspection Number: 1093055	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: ESPINOSA-BECKERT, ILIANA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-15-2	Observed an uncovered electrical box. For reporting purposes only. by washer	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 2611158		HARDEES #1501527	
License Type: Permanent Food Service		5081 J TURNER BUTLER BLVD, JACKSONVILLE 32216	
Inspection Date: 10/23/2009	Inspection Number: 1880840	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: ESPINOSA-BECKERT, ILIANA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. small hood filter, fryer hood Repeat Violation.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 2614137		SANDWICH SHOP KAFFE	
License Type: Permanent Food Service		6536 BEACH BLVD STE 8, JACKSONVILLE 32216	
Inspection Date: 10/21/2009	Inspection Number: 1880850	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: ESPINOSA-BECKERT, ILIANA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
License Number: 2614017		FIVE GUYS FAMOUS BURGER & FRIES	
License Type: Permanent Food Service		13249 CITY SQUARE DR, STE 101, JACKSONVILLE 32218	
Inspection Date: 10/21/2009	Inspection Number: 1840074	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DAVIS, MOSES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-02-2	Observed circuit breaker taped open. For reporting purposes only. Corrected On Site.	NFPA 70, 240.80 Circuit breakers shall be tripfree and capable of being closed and opened by manual operation. FOR REPORTING PURPOSES ONLY.	

**Duval County**

License Number: 2614378 FUJIYAMA JAPANESE STEAKHOUSE  
 License Type: Permanent Food Service 13141 CITY STATION DR STE 153, JACKSONVILLE 32218  
 Inspection Date: 10/20/2009 Inspection Number: 1920125 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: DAVIS, MOSES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only, KITCHEN .WAIT AREA.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 2609881 MARCO POLO CHINESE RESTAURANT  
 License Type: Permanent Food Service 3000 DUNN AVE #14, JACKSONVILLE 322184501  
 Inspection Date: 10/17/2009 Inspection Number: 1870955 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: DAVIS, MOSES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 2614035 FUJI  
 License Type: Permanent Food Service 13740 BEACH BLVD #109, JACKSONVILLE 32224  
 Inspection Date: 10/21/2009 Inspection Number: 1901840 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: STOREY, MARIE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-27-2	Portable fire extinguisher blocked/not easily accessible. For reporting purposes only. sandwiched between wall and beer cooler	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.

License Number: 2614301 MR CHAN ASIAN CUISINE INC  
 License Type: Permanent Food Service 13947 BEACH BLVD #110, JACKSONVILLE 32224  
 Inspection Date: 10/21/2009 Inspection Number: 1891536 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: STOREY, MARIE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. Repeat Violation.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

**Duval County**

License Number: 2612814

WOK EXPRESS

License Type: Permanent Food Service

1301 MONUMENT RD #7, JACKSONVILLE 32225

Inspection Date: 10/20/2009

Inspection Number: 1881370

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: STOREY, MARIE

Violation CodeObservationViolation Citation

46-13-2

Emergency light does not function when tested. For reporting purposes only.

NFPA 101, 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted at 30-day intervals for not less than 30 seconds. (2) Functional testing shall be conducted annually for not less than 1½ hours if the emergency lighting system is battery powered. (3) The emergency lighting equipment shall be fully operational for the duration of the tests required by 7.9.3.1.1(1) and 7.9.3.1.1(2). FOR REPORTING PURPOSES ONLY.

License Number: 2613344

QUEEN SHEBA ETHIOPIAN RESTAURANT

License Type: Permanent Food Service

10214 ATLANTIC BLVD, JACKSONVILLE 32225

Inspection Date: 10/22/2009

Inspection Number: 1920252

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: YOUNG, DERRICK

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. ABC behind the bar

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only. behind the bar

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only. powering reach -in behind the bar

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Duval County**

License Number: 2613946

SUBWAY #34988

License Type: Permanent Food Service

1554 ST JOHNS BLUFF RD NORTH, JACKSONVILLE 32225

Inspection Date: 10/16/2009

Inspection Number: 1870809

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: YOUNG, DERRICK

Violation CodeObservationViolation Citation

47-03-2 Observed unused opening in panel box unprotected. For reporting purposes only.

NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.

License Number: 2611931

SANDOLLAR RESTAURANT &amp; MARINA

License Type: Permanent Food Service

9716 HECKSCHER DR, JACKSONVILLE 322262431

Inspection Date: 10/21/2009

Inspection Number: 1916644

Inspection Type: Routine - Food

Inspection Disposition: Call Back - Complied

Inspector Name: PHELAN, JOHN

Violation CodeObservationViolation Citation47-06-2 Violation: 47-06-2  
Observed extension cord in use for non-temporary period. For reporting purposes only. Behind reach in coolers.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-16-2 Violation: 47-16-2  
Electrical outlet missing cover plate. For reporting purposes only. Exposed electric wires ceiling dry storage area.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 2612133

FARAH'S COURTYARD DELI

License Type: Permanent Food Service

10151 DEERWOOD PARK BLVD, BLDG 200 SUITE #104, JACKSONVILLE 32256

Inspection Date: 10/20/2009

Inspection Number: 1919922

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: STOREY, MARIE

Violation CodeObservationViolation Citation45-31-2 Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only.  
Cooking ground beef on table top burner in back prep area.

NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

License Number: 2613096

PIZZA 622153

License Type: Permanent Food Service

6140 MERRILL RD, JACKSONVILLE 32277

Inspection Date: 10/19/2009

Inspection Number: 1901575

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: YOUNG, DERRICK

Violation CodeObservationViolation Citation47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.  
powering hot bar

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Escambia County**

License Number: 2750077

KABOBS N STUFF

License Type: Mobile Food Dispensing Vehicle

1717 N T ST, PENSACOLA 32505

Inspection Date: 10/17/2009

Inspection Number: 1137435

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: WINN, RONALD

Violation CodeObservationViolation Citation

48-20-2

Observed loose/unsecured LP-gas tank on mobile food dispensing vehicle. For reporting purposes only.

NFPA 58, 3.8.2.4 Containers shall be mounted securely on the vehicle, or within the enclosing recess or cabinet, and shall be located and installed so as to minimize the possibility of damage to containers, their appurtenances, or contents as follows: (a) Containers shall be installed with road clearance in accordance with 8-2.6.5. (b) Fuel containers shall be mounted securely to prevent jarring loose and slipping or rotating, and the fastenings shall be designed and constructed to withstand, without permanent visible deformation, static loading in any direction equal to four times the weight of the container filled with fuel. Where containers are mounted within a vehicle housing, the securing of the housing to the vehicle shall comply with this provision. Any hoods, domes, or removable portions of the housing or cabinet shall be provided with means to keep them firmly in place in transit. Field welding shall comply with 3-2.4.1(e). (c) All container valves, appurtenances, and connections shall be adequately protected to prevent damage from accidental contacts with stationary objects, from loose objects, stones, mud, or ice thrown up from the ground or floor, and from damage due to overturn or similar vehicular accident. In the case of permanently mounted ASME containers, this provision shall be met by the location on the vehicle, with parts of the vehicle furnishing the protection. On cylinders, the protection for cylinder valves and connections shall be attached permanently to the cylinder (see 2-2.4.1 and 2-2.4.2). Such weather protection necessary to ensure safe operation shall be provided for cylinders and systems mounted on the outside of vehicles. FOR REPORTING PURPOSES ONLY.

License Number: 2702620

BURGER KING 4914

License Type: Permanent Food Service

13392 PERDIDO KEY DR, PENSACOLA 32507

Inspection Date: 10/20/2009

Inspection Number: 1860851

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: WINN, RONALD

Violation CodeObservationViolation Citation

45-38-2

Portable ABC fire extinguishers (3) not fully charged. For reporting purposes only.

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

45-39-2

Portable ABC fire extinguishers (3) not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

49-06-2

Observed flammable material stored around water heater. For reporting purposes only.

61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

**Escambia County**

License Number: 2706025 JELLY FISH BAR LLC  
 License Type: Permanent Food Service 13700 PERDIDO KEY DR UNIT 207A, PENSACOLA 32507

Inspection Date: 10/20/2009 Inspection Number: 1912083 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: WINN, RONALD

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-30-2	No Class K portable fire extinguisher provided for high hazard cooking area (for suppression system/equipment installed after June 30, 1998). For reporting purposes only.	NFPA 10, 4.3.2. and 4.3.2.1 Class K Fire Extinguishers for Cooking Oil Fires. Fire extinguishers provided for the protection of cooking appliances that use combustible cooking media (vegetable or animal oils and fats) shall be listed and labeled for Class K fires. Class K fire extinguishers manufactured after January 1, 2002, shall not be equipped with extended wand-type discharge devices. Fire extinguishers installed specifically for the protection of cooking appliances that use combustible cooking media (animal, vegetable oils and fats) prior to June 30, 1998, shall not be required to comply with 4.3.2. (Also see 4.3.2.3.). FOR REPORTING PURPOSES ONLY.
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

License Number: 2706091 MCDONALDS RESTAURANT  
 License Type: Permanent Food Service 13145 SORRENTO RD, PENSACOLA 32507

Inspection Date: 10/19/2009 Inspection Number: 1918611 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: WINN, RONALD

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-13-2	Circuit breaker box blocked and/or inaccessible. For reporting purposes only. Corrected On Site.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.

**Flagler County**

License Number: 2800494		BEER HOUSE (THE)	
License Type: Permanent Food Service		616 N STATE ST, BUNNELL 32110	
Inspection Date: 10/22/2009	Inspection Number: 1890394	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SCARPELLI, DAVID			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-27-2	Portable fire extinguisher blocked/not easily accessible. For reporting purposes only. STEP LADDER IN FRONT OF EXTINGUISER	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.	
License Number: 2800714		BED AND BREAKFAST BY THE SEA	
License Type: Permanent Food Service		1536 S OCEANSHORE DR, FLAGLER BEACH 32136	
Inspection Date: 10/22/2009	Inspection Number: 1914949	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Complied
Inspector Name: SCARPELLI, DAVID			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-31-2	Violation: 45-31-2  Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. For reporting purposes only. BACON, EGGS	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.	
License Number: 2800632		OUTBACK STEAKHOUSE	
License Type: Permanent Food Service		45 PLAZA DR, PALM COAST 32137	
Inspection Date: 10/21/2009	Inspection Number: 1829093	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SCARPELLI, DAVID			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-13-2	Circuit breaker box blocked and/or inaccessible. For reporting purposes only. BLOCKED BY KEGS	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.	

**Gadsden County**

License Number: 3000299

MOCKINGBIRD CAFE

License Type: Permanent Food Service

211 NW 1 STREET, HAVANA 32333

Inspection Date: 10/16/2009

Inspection Number: 1881854

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: HARGROVE, DAVID

Violation CodeObservationViolation Citation

47-15-2

Observed an uncovered electrical box. For reporting purposes only. Corrected On Site.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 3000346

RICHIES CAFE

License Type: Permanent Food Service

8007 N FLORIDA GEORGIA HWY, HAVANA 32333

Inspection Date: 10/16/2009

Inspection Number: 1861293

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: HARGROVE, DAVID

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

**Hernando County**

License Number: 3701081 BEEF O BRADYS  
 License Type: Permanent Food Service 7601 HORSE LAKE RD, BROOKSVILLE 34601

Inspection Date: 10/19/2009 Inspection Number: 1846909 Inspection Type: Routine - Food Inspection Disposition: Call Back - Complied  
 Inspector Name: DANCHO, JOHN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-27-2	Violation: 45-27-2  Portable fire extinguisher blocked/not easily accessible....K Class at rear kitchen exit. For reporting purposes only.	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.

License Number: 3700499 KALLY K'S  
 License Type: Permanent Food Service 3383 COMMERCIAL WAY, SPRING HILL 346062618

Inspection Date: 10/21/2009 Inspection Number: 1846991 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: GLENN, DAVID

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. Under cooks line by lift top salad cooler.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3700811 BEEF O BRADY'S  
 License Type: Permanent Food Service 9021 COUNTY LINE RD, SPRING HILL 34608

Inspection Date: 10/21/2009 Inspection Number: 1867566 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: GLENN, DAVID

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Hood filters getting sucked into hood.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

**Hernando County**

License Number: 3700414

LITTLE CAESAR'S PIZZA

License Type: Permanent Food Service

11066 SPRING HILL DR, SPRING HILL 34608-5093

Inspection Date: 10/21/2009

Inspection Number: 1888008

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: GLENN, DAVID

Violation Code

Observation

Violation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

**Highlands County**

License Number: 3800954

LA CASITA MEXICAN FAMILY RESTAURANT

License Type: Permanent Food Service

131 S SUN N LAKES BLVD, LAKE PLACID 33852

Inspection Date: 10/22/2009

Inspection Number: 1862803

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: SCHNELL, PAMELA

Violation Code

Observation

Violation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

**Hillsborough County**

License Number: 3911847

TACO BELL 19986

License Type: Permanent Food Service

11315 CAUSEWAY BLVD, BRANDON 33511

Inspection Date: 07/29/2009

Inspection Number: 1816910

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: LEWIS, RICKY

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 3912734

DRAGON CITY CHINESE REST

License Type: Permanent Food Service

871 W BLOOMINGDALE AVE, BRANDON 33511

Inspection Date: 10/21/2009

Inspection Number: 1836011

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: LEWIS, RICKY

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 3916179

JAKES HAMBURGERS

License Type: Permanent Food Service

17695 N DALE MABRY HWY, LUTZ 33548

Inspection Date: 10/20/2009

Inspection Number: 1836767

Inspection Type: Routine - Food

Inspection Disposition: Call Back - Complied

Inspector Name: CHEW, TEOW

Violation CodeObservationViolation Citation

45-39-2

Violation: 45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.(class - K)

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

**Hillsborough County**

License Number: 3916200 MARIPOSA MEXICAN GRILLE  
 License Type: Permanent Food Service 17623 N DALE MABRY HWY, LUTZ 33548

Inspection Date: 10/20/2009 Inspection Number: 1898421 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: CHEW, TEOW

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.(ABC)	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 3912281 BEEF O BRADY'S  
 License Type: Permanent Food Service 18421 HWY US 41 N, LUTZ 33549

Inspection Date: 10/21/2009 Inspection Number: 1847095 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: CHEW, TEOW

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only.	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

License Number: 3915748 PACIFIC GRILL  
 License Type: Permanent Food Service 3452 LITHIA PINECREST RD, VALRICO 33596

Inspection Date: 10/22/2009 Inspection Number: 1887241 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: LEWIS, RICKY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Hillsborough County**

License Number: 3901774 BOSS HOGS  
 License Type: Permanent Food Service 511 N FRANKLIN ST, TAMPA 33602

Inspection Date: 10/21/2009 Inspection Number: 1847166 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: KLUSENDORF, JEANNE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-12-2	No ground fault interruption protection on electrical outlet located within six feet of a water source. For reporting purposes only. handsink in kitchen	NFPA 70, 210.8 Ground-Fault Circuit-Interrupter Protection for Personnel. (A) Dwelling Units. All 125-volt, single-phase, 15- and 20-ampere receptacles installed in the locations specified shall have ground-fault circuit-interrupter protection for personnel. (1) Bathrooms; (6) Kitchens - where the receptacles are installed to serve the countertop surfaces; (7) Wet bar sinks - where the receptacles are installed to serve the countertop surfaces and are located within 6 ft of the outside edge of the wet bar sink. (B) Other Than Dwelling Units. All 125-volt, single-phase, 15- and 20-ampere receptacles installed in the locations specified in (1), (2), and (3) shall have ground-fault circuit-interrupter protection for personnel: (1) Bathrooms; (2) Rooftops; Exception: Receptacles that are not readily accessible and are supplied from a dedicated branch circuit for electric snow-melting or deicing equipment shall be permitted to be installed in accordance with the applicable provisions of Article 426. (3) Kitchens. FOR REPORTING PURPOSES ONLY.

License Number: 3911432 HATTRICKS  
 License Type: Permanent Food Service 107 S FRANKLIN ST, TAMPA 33602

Inspection Date: 10/19/2009 Inspection Number: 1867669 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: KLUSENDORF, JEANNE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 3906229 PRIMOS DELI CAFE  
 License Type: Permanent Food Service 101 N FRANKLIN ST, TAMPA 336025831

Inspection Date: 10/21/2009 Inspection Number: 1847132 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: KLUSENDORF, JEANNE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. near 3-comp sink,	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3900931 VENEZIA PIZZERIA & RESTAURANT  
 License Type: Permanent Food Service 1002 E HILLSBOROUGH AVE, TAMPA 33604

Inspection Date: 10/22/2009 Inspection Number: 1847182 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: PETERSON, DOUGLAS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

**Hillsborough County**

License Number: 3903795		WENDY'S	
License Type: Permanent Food Service		8330 N FLORIDA AVE, TAMPA 33604	
Inspection Date: 10/23/2009	Inspection Number: 1836890	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PETERSON, DOUGLAS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-40-2	No metal container installed for catching grease from hood drip tray. For reporting purposes only.	NFPA 96, 6.2.4.3 Grease drip trays shall be pitched to drain into an enclosed metal container having a capacity not exceeding 1 gallon. FOR REPORTING PURPOSES ONLY	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only. painted surface peeling	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 3903956		COCO'S SANDWICH SHOP	
License Type: Permanent Food Service		1507 S 22 ST, TAMPA 33605	
Inspection Date: 10/19/2009	Inspection Number: 1867285	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: OGDEN, RICHARD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
48-13-2	Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.	
License Number: 3912918		LAUGHING CAT	
License Type: Permanent Food Service		1820 N 15 ST, TAMPA 33605	
Inspection Date: 10/20/2009	Inspection Number: 1887786	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: OGDEN, RICHARD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. unit broken.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 3907339		CYPRESS GOURMET DELI	
License Type: Permanent Food Service		5300 W CYPRESS ST, TAMPA 33607	
Inspection Date: 10/20/2009	Inspection Number: 1846047	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: MIRABELLA, FRANK			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only.	NFPA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.	
License Number: 3911820		VENDING ROOM 143V	
License Type: Permanent Food Service		4116 N HIMES AVE, TAMPA 33607	
Inspection Date: 10/20/2009	Inspection Number: 1907630	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: MIRABELLA, FRANK			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient	

**Hillsborough County**

---

License Number: 3911823                      GRID IRON GRILL 143C  
License Type: Permanent Food Service                      4116 N HIMES AVE, TAMPA 33607

Inspection Date: 10/18/2009                      Inspection Number: 1907628                      Inspection Type: Routine - Food                      Inspection Disposition: Inspection Completed - No Further Action  
Inspector Name: MIRABELLA, FRANK

Violation Code                      Observation                      Violation Citation

45                      Out of compliance: Fire extinguishers - proper and sufficient                      NFPA 101, 96, 10 Fire extinguishers - proper and sufficient

---

License Number: 3911838                      STADIUM STEAKERY 129C  
License Type: Permanent Food Service                      4116 N HIMES AVE, TAMPA 33607

Inspection Date: 10/18/2009                      Inspection Number: 1856346                      Inspection Type: Routine - Food                      Inspection Disposition: Inspection Completed - No Further Action  
Inspector Name: MIRABELLA, FRANK

Violation Code                      Observation                      Violation Citation

47                      Out of compliance: Electrical wiring - adequate, good repair                      NFPA 101, 96, 10 Electrical wiring - adequate, good repair

---

License Number: 3911859                      STADIUM STEAKERY 103C  
License Type: Permanent Food Service                      4116 N HIMES AVE, TAMPA 33607

Inspection Date: 10/18/2009                      Inspection Number: 1835855                      Inspection Type: Routine - Food                      Inspection Disposition: Inspection Completed - No Further Action  
Inspector Name: MIRABELLA, FRANK

Violation Code                      Observation                      Violation Citation

45                      Out of compliance: Fire extinguishers - proper and sufficient                      NFPA 101, 96, 10 Fire extinguishers - proper and sufficient

---

License Number: 3911865                      VENDING ROOM 118V  
License Type: Permanent Food Service                      4116 N HIMES AVE, TAMPA 33607

Inspection Date: 10/18/2009                      Inspection Number: 1907632                      Inspection Type: Routine - Food                      Inspection Disposition: Inspection Completed - No Further Action  
Inspector Name: MIRABELLA, FRANK

Violation Code                      Observation                      Violation Citation

47                      Out of compliance: Electrical wiring - adequate, good repair                      NFPA 101, 96, 10 Electrical wiring - adequate, good repair

**Hillsborough County**

License Number: 3900071 SNACK CITY DAIRY BAR  
 License Type: Permanent Food Service 2506 W COLUMBUS DR, TAMPA 336072212

Inspection Date: 10/20/2009 Inspection Number: 1866614 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: MIRABELLA, FRANK

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. television	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. microwave	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3910221 LONGHORN STEAKHOUSE OF TAMPA  
 License Type: Permanent Food Service 2055 N DALE MABRY, TAMPA 336072542

Inspection Date: 10/20/2009 Inspection Number: 1886999 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: MIRABELLA, FRANK

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 3907997 KFC  
 License Type: Permanent Food Service 4402 W GANDY BLVD, TAMPA 33611

Inspection Date: 10/22/2009 Inspection Number: 1866871 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: CANNELLA, MARK

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-04-2	Observed frayed/spliced electrical wires. For reporting purposes only. outside walkin cooler door.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Hillsborough County**

License Number: 3915414

TASTE OF CHINA

License Type: Permanent Food Service

5827 S DALE MABRY, TAMPA 33611

Inspection Date: 10/21/2009

Inspection Number: 1887345

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: CANNELLA, MARK

Violation CodeObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3915718

RAMON'S CUBANS

License Type: Permanent Food Service

4053 S DALE MABRY HWY, TAMPA 33611

Inspection Date: 10/22/2009

Inspection Number: 1887350

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: CANNELLA, MARK

Violation CodeObservationViolation Citation

47-16-2 Electrical outlet missing cover plate. For reporting purposes only. in dinningroom .

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 3912868

WING KING OF FLETCHER

License Type: Permanent Food Service

1132 E FLETCHER AVE, TAMPA 33612

Inspection Date: 10/22/2009

Inspection Number: 1846193

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: CHEW, TEOW

Violation CodeObservationViolation Citation

45-36-2 Hood suppression system tag out-of-date. For reporting purposes only.

NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

45-41-2 Portable fire extinguisher tag out-of-date. For reporting purposes only.

NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

**Hillsborough County**

License Number: 3916163

BRAVO BRAVO

License Type: Permanent Food Service

11311 NEBRASKA AVE, TAMPA 33612

Inspection Date: 10/22/2009

Inspection Number: 1877018

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: EDMISTON, ROBERT

Violation CodeObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3910414

ARBY'S ROAST BEEF #6055

License Type: Permanent Food Service

2230 E FLETCHER AVE, TAMPA 336129402

Inspection Date: 10/22/2009

Inspection Number: 1866708

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: CHEW, TEOW

Violation CodeObservationViolation Citation

45-38-2 Portable fire extinguisher not fully charged. For reporting purposes only.(ABC by 3 compartment sink)

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

47-13-2 Circuit breaker box blocked and/or inaccessible. For reporting purposes only.

NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.

License Number: 3911991

SOUTHERN GROUND SALOON

License Type: Permanent Food Service

14802 N NEBRASKA AVE, TAMPA 33613

Inspection Date: 10/21/2009

Inspection Number: 1898425

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: CHEW, TEOW

Violation CodeObservationViolation Citation

45-15-2 No placard placed near Class K portable fire extinguisher stating the fire suppression system must be activated prior to use of the portable extinguisher. For reporting purposes only.

NFPA 10, 4.3.2.2 A placard shall be conspicuously placed near the extinguisher that states that the fire protection system shall be activated prior to using the fire extinguisher. FOR REPORTING PURPOSES ONLY.

45-36-2 Hood suppression system tag out-of-date. For reporting purposes only.

NFPA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

45-41-2 Portable fire extinguisher tag out-of-date. For reporting purposes only.

NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

47-16-2 Electrical outlet with broken cover plate. For reporting purposes only.(kitchen)

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

**Hillsborough County**

License Number: 3911681		CITRUS PARK BALLYHOO GRILL	
License Type: Permanent Food Service		7604 ERLICH RD, TAMPA 33624	
Inspection Date: 10/22/2009	Inspection Number: 1920194	Inspection Type: Complaint Full	Inspection Disposition: Warning Issued
Inspector Name: DORSEY, KATHY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-25-2	Hood filters missing. For reporting purposes only.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY	
48-13-2	Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.	

License Number: 3911563		MCDONALDS	
License Type: Permanent Food Service		5393 EHRLICH RD, TAMPA 33625	
Inspection Date: 10/22/2009	Inspection Number: 1887065	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DECKER, RICHARD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. Corrected On Site. Repeat Violation.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	

License Number: 3912920		CHILI'S BAR & GRILL	
License Type: Permanent Food Service		8402 CITRUS PARK DR, TAMPA 33625	
Inspection Date: 10/19/2009	Inspection Number: 1856388	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DECKER, RICHARD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
46-02-2	Observed hasp lock on freezer door For reporting purposes only.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	

License Number: 3907159		ELLIE'S	
License Type: Permanent Food Service		12008 RACE TRACK ROAD, TAMPA 33626	
Inspection Date: 10/20/2009	Inspection Number: 1846149	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DECKER, RICHARD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-22-2	Portable fire extinguisher(s) obstructed from view. For reporting purposes only. by circuit breaker box	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.	

**Hillsborough County**

License Number: 3911121		WESTCHASE GOLF CLUB	
License Type: Permanent Food Service		11602 WESTCHASE GOLF DR, TAMPA 33626	
Inspection Date: 10/21/2009	Inspection Number: 1887107	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DECKER, RICHARD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. hasp lock on cooler/freezer doors	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	
License Number: 3911100		GOLDEN CORRAL #766	
License Type: Permanent Food Service		6942 W HILLSBOROUGH AVE, TAMPA 33634	
Inspection Date: 10/21/2009	Inspection Number: 1876962	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Admin. complaint recommended
Inspector Name: DORSEY, KATHY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Violation: 15-28-2  Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 3915508		ONE FAMILY RESTAURANT	
License Type: Permanent Food Service		7030 W HILLSBOROUGH AVE, TAMPA 33634	
Inspection Date: 10/22/2009	Inspection Number: 1915055	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DECKER, RICHARD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 3912530		PEABODYS	
License Type: Permanent Food Service		15333 AMBERLY DR, TAMPA 33647	
Inspection Date: 10/19/2009	Inspection Number: 1888084	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CHEW, TEOW			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.(kitchen hallway)	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only.	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.	

**Hillsborough County**

License Number: 3909798

JOY O WOK

License Type: Permanent Food Service

15309 AMBERLY DR, TAMPA 336472144

Inspection Date: 10/19/2009

Inspection Number: 1847077

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CHEW, TEOW

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-15-2	No placard placed near Class K portable fire extinguisher stating the fire suppression system must be activated prior to use of the portable extinguisher. For reporting purposes only.	NFPA 10, 4.3.2.2 A placard shall be conspicuously placed near the extinguisher that states that the fire protection system shall be activated prior to using the fire extinguisher. FOR REPORTING PURPOSES ONLY.
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only.	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.
47-03-2	Observed unused opening in panel box unprotected. For reporting purposes only. Repeat Violation. 3	NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.

**Indian River County**

License Number: 4101120

THE PIZZA & PASTA HOUSE INC

License Type: Permanent Food Service

620 SW OLD DIXIE HWY, VERO BEACH 32962

Inspection Date: 10/21/2009

Inspection Number: 1827914

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DAVIS, DIANNA

Violation Code

Observation

Violation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces-Filters being cleaned-facility not open yet, will be reinstalled prior to open. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 4100470

NINO'S RESTAURANT

License Type: Permanent Food Service

1006 EASTERLILY LM, VERO BCH 32963

Inspection Date: 10/22/2009

Inspection Number: 1857934

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DAVIS, DIANNA

Violation Code

Observation

Violation Citation

45-38-2 Portable fire extinguisher not fully charged-k class extinguisher by mixer in dishwash room. For reporting purposes only.

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

**Lake County**

License Number: 4508332

SAN JOSES ORIGINAL MEXICAN RESTAURANT

License Type: Permanent Food Service

4315 HIGHWAY 27 SUITE A-1, CLERMONT 34711

Inspection Date: 10/19/2009

Inspection Number: 1869790

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CHIU, ALEX

Violation Code

Observation

Violation Citation

47 Out of compliance: Electrical wiring - adequate, good repair

NFPA 101, 96, 10 Electrical wiring - adequate, good repair



**Lee County**

License Number: 4605686

JIMMY'S PINK CADILLAC CAFE

License Type: Permanent Food Service

16641 SAN CARLOS BLVD, FORT MYERS 33908

Inspection Date: 10/14/2009

Inspection Number: 1893110

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: HUGHES, RANDALL

Violation Code

Observation

Violation Citation

45-31-2

Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only. observed frying equipment outside under roof with no suppression system This violation m

NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

**Lee County**

---

License Number: 4606292

MARKER 92

License Type: Permanent Food Service

5951 - 5961 SILVER KING BLVD, CAPE CORAL 33914

**Lee County**

Inspection Date: 10/23/2009

Inspection Number: 1917162

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: SOMMERS, KARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-28-2	40BC fire extinguisher not located within 30 feet of high hazard cooking area (for suppression system/equipment installed prior to June 30, 1998). For reporting purposes only.	NFPA 10, 5.3.1 Fire extinguishers shall be located so that the maximum travel distances do not exceed those specified in the table used. Table 5.3.1 Fire Extinguisher Size and Placement for Class B Hazards Light (low) Minimum Extinguisher Rating 10-B Maximum Travel Distance to Extinguishers 50 ft. Ordinary (moderate) Minimum Extinguisher Rating 10-B Maximum Travel Distance to Extinguishers 30 ft. Extra (high) Minimum Extinguisher Rating 40-B Maximum Travel Distance to Extinguishers 30 ft. FOR REPORTING PURPOSES ONLY.
48-01-2	Boiler certificate not posted in boiler room. For reporting purposes only.	69A-51.025(4) FAC (4) Certificate of Compliance. The Certificate of Compliance shall be conspicuously placed so it can be readily identified with the certified boiler, preferably in the boiler room. FOR REPORTING PURPOSES ONLY.
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.
48-21-1	No carbon monoxide sensor device located in a gas boiler room in a building which also contains sleeping rooms.  Boiler Information: *No Boiler Certificate Provided.	509.211(5) FS Every enclosed space or room that contains a boiler regulated under chapter 554 which is fired by the direct application of energy from the combustion of fuels and that is located in any portion of a public lodging establishment that also contains sleeping rooms shall be equipped with one or more carbon monoxide sensor devices that bear the label of a nationally recognized testing laboratory and have been tested and listed as complying with the most recent Underwriters Laboratories, Inc., Standard 2034, or its equivalent, unless it is determined that carbon monoxide hazards have otherwise been adequately mitigated as determined by the division.
48-23-1	Carbon monoxide sensor device located in a gas boiler room in a building which also contains sleeping rooms is not integrated with the building's fire detection system.  Boiler Information: *No Boiler Certificate Provided.	509.211(5) FS Every enclosed space or room that contains a boiler regulated under chapter 554 which is fired by the direct application of energy from the combustion of fuels and that is located in any portion of a public lodging establishment that also contains sleeping rooms shall be equipped with one or more carbon monoxide sensor devices. Such devices shall be integrated with the public lodging establishment's fire detection system.

**Lee County**

License Number: 4602441 TERRA NOSTRA RESTAURANT  
 License Type: Permanent Food Service 1821 ESTERO BLVD, FT MYERS BCH 33931

Inspection Date: 10/09/2009 Inspection Number: 1882761 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: HUGHES, RANDALL

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only.experation date of 10/02/2009	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

License Number: 4603464 MANGO'S  
 License Type: Permanent Food Service 533 RUM ROAD, N CAPTIVA 33945

Inspection Date: 10/21/2009 Inspection Number: 1862225 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: SOMMERS, KARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-16-2	Electrical outlet missing cover plate--outside on corner behind dry storage room For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 4605074 TKS SPORTS BAR  
 License Type: Permanent Food Service 12951 METRO PKWY # 4, FORT MYERS 33966-1333

Inspection Date: 10/20/2009 Inspection Number: 1883259 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: TORBERT, KIMBERLY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-2	Exit sign not properly illuminated. For reporting purposes only. back door exit	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

**Leon County**

License Number: 4703094 FIREHOUSE SUBS  
 License Type: Permanent Food Service 1420 CAPITAL CIRCLE NW, TALLAHASSEE 32303

Inspection Date: 10/19/2009 Inspection Number: 1861469 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: WRIGHT, ANDREW

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-03-2	Observed unused opening in panel box unprotected. For reporting purposes only. Repeat Violation.	NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.

License Number: 4703239 RODIZIO'S RESTUARANT  
 License Type: Permanent Food Service 1122 THOMASVILLE RD UNIT 1, TALLAHASSEE 32303

Inspection Date: 10/20/2009 Inspection Number: 1882004 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended  
 Inspector Name: WRIGHT, ANDREW

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
47-05-2	Observed a splitter/multi-plug adapter in use, at podium. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 4702395 NO. 1 CHINESE RESTAURANT  
 License Type: Permanent Food Service 1434 NW CAPITAL CIR, TALLAHASSEE 32303-1110

Inspection Date: 10/19/2009 Inspection Number: 1851293 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: WRIGHT, ANDREW

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. Missing filter above bbq oven. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

**Leon County**

License Number: 4702225 PARADISE GRILLE & BAR  
 License Type: Permanent Food Service 1406 N MERIDIAN RD, TALLAHASSEE 323035642

Inspection Date: 10/20/2009 Inspection Number: 1902506 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: WRIGHT, ANDREW

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-13-2	Emergency light does not function when tested, in kitchen. For reporting purposes only.	NFPA 101, 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted at 30-day intervals for not less than 30 seconds. (2) Functional testing shall be conducted annually for not less than 1½ hours if the emergency lighting system is battery powered. (3) The emergency lighting equipment shall be fully operational for the duration of the tests required by 7.9.3.1.1(1) and 7.9.3.1.1(2). FOR REPORTING PURPOSES ONLY.

License Number: 4702561 PO' BOYS CREOLE CAFE  
 License Type: Permanent Food Service 1944 W PENSACOLA, TALLAHASSEE 32304

Inspection Date: 10/20/2009 Inspection Number: 1871601 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: TALLEY, BELINDA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 4702922 CALIFORNIA CHICKEN GRILL  
 License Type: Permanent Food Service 1904 W PENSACOLA ST, TALLAHASSEE 32304

Inspection Date: 10/20/2009 Inspection Number: 1861301 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: TALLEY, BELINDA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 4702484 GREAT WALL CHINESE RESTAURANT  
 License Type: Permanent Food Service 4220 W TENNESSEE ST, TALLAHASSEE 323041033

Inspection Date: 10/20/2009 Inspection Number: 1919935 Inspection Type: Complaint Full Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: HARGROVE, DAVID

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-15-2	Observed an uncovered electrical box. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 4702500 GORDO'S CUBAN CUISINE  
 License Type: Permanent Food Service 1907 W PENSACOLA ST, TALLAHASSEE 323043224

Inspection Date: 10/20/2009 Inspection Number: 1881842 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended  
 Inspector Name: TALLEY, BELINDA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

**Leon County**

License Number: 4703093		HILLTOP COUNTRY STORE	
License Type: Permanent Food Service		14807 MAHAN DRIVE, TALLAHASSEE 32309	
Inspection Date: 10/22/2009	Inspection Number: 1861439	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DODSON, FRED			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-38-2	Portable fire extinguisher .overcharged For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
47-15-2	Observed an uncovered electrical box. For reporting purposes only.breaker box open	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

License Number: 4702716		CHOPSTIX CHINESE RESTAURANT	
License Type: Permanent Food Service		3539-A APALACHEE PKWY, TALLAHASSEE 32311	
Inspection Date: 10/20/2009	Inspection Number: 1919934	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DODSON, FRED			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
49-06-2	Observed flammable material stored around water heater. For reporting purposes only. Corrected On Site.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.	

License Number: 4703335		SMOKIES BBQ	
License Type: Permanent Food Service		4176 APALACHEE PKWY, TALLAHASSEE 32311	
Inspection Date: 10/20/2009	Inspection Number: 1871689	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DODSON, FRED			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-03-2	Observed unused opening in panel box unprotected. For reporting purposes only.	NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.	

License Number: 4702616		Z BARDHI'S ITALIAN CUISINE	
License Type: Permanent Food Service		3596 KINHEGA DR, TALLAHASSEE 32312	
Inspection Date: 10/20/2009	Inspection Number: 1892162	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DODSON, FRED			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.back door	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	

**Manatee County**

License Number: 5104195		WOODYS BAR-B-Q	
License Type: Permanent Food Service		3142 53 AVE, BRADENTON 34203	
Inspection Date: 10/22/2009	Inspection Number: 1842148	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: POSA, ANTHONY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 5103815		DAVID TOOLES ORIGINAL ROADHOUSE	
License Type: Permanent Food Service		4502 14 ST WEST, BRADENTON 34207	
Inspection Date: 10/22/2009	Inspection Number: 1920137	Inspection Type: Complaint Full	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DILLARD, FRANK			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-42-2	Observed hood filters installed horizontally, rather than vertically. For reporting purposes only. One hood filter panel over two burner stove in kitchen .	NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. ABC extinguisher on floor in kitchen .	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
License Number: 5104385		DONGTIAN COURT	
License Type: Permanent Food Service		6409 MANATEE AVE W, BRADENTON 34209	
Inspection Date: 10/19/2009	Inspection Number: 1902690	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: KEMPA, ALICE M			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-07-2	Observed scorch marks around electrical outlet. [waitstation by microwave. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

**Marion County**

License Number: 5202670

KEALAS CASUAL DINING

License Type: Permanent Food Service

18651 N US HWY 301 STE A-6, CITRA 32113

Inspection Date: 10/20/2009

Inspection Number: 1890752

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: BRYANT, BENJAMIN

Violation CodeObservationViolation Citation

47-06-2

Observed orange, and white extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5200597

AUNT FANNIE'S RESTAURANT

License Type: Permanent Food Service

6147 S US 441, BELLEVIEW 34420

Inspection Date: 10/20/2009

Inspection Number: 1880674

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: ANAZIA, ROLAND

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. K- class extinguisher on kitchen floor .

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 5202020

110TH STREET GRILLE

License Type: Permanent Food Service

10901 S HWY 441, BELLEVIEW 34420

Inspection Date: 10/20/2009

Inspection Number: 1850053

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: ANAZIA, ROLAND

Violation CodeObservationViolation Citation

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only. Waiter's station .

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Marion County**

License Number: 5200652

BURGER KING NO 46

License Type: Permanent Food Service

2301 E SILVER SPGS BLVD, OCALA 344706910

Inspection Date: 10/23/2009

Inspection Number: 1880598

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BRYANT, BENJAMIN

Violation CodeObservationViolation Citation

45-27-2

Portable fire extinguisher blocked/not easily accessible in first drive-thru by buns. For reporting purposes only. Corrected On Site.

NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.

47-16-2

Electrical outlet missing cover plate in chemical storage room. For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 5202017

BELLACINIS ITALIAN TO GO SHOP

License Type: Permanent Food Service

2506 SE 17TH ST, SUITE A, OCALA 34471

Inspection Date: 10/21/2009

Inspection Number: 1880558

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: BRYANT, BENJAMIN

Violation CodeObservationViolation Citation

46-05-2

Observed back door exit obstructed by boxes, and black mats. For reporting purposes only. Corrected On Site.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 5200561

POPEYES CHICKEN &amp; BISCUITS#113

License Type: Permanent Food Service

1713 S PINE AVE, OCALA 34474

Inspection Date: 10/22/2009

Inspection Number: 1880672

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: ANAZIA, ROLAND

Violation CodeObservationViolation Citation

46-05-2

Observed back exit obstructed by cardboard boxes and cleaning bucket. Corrected On Site.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

**Marion County**

License Number: 5202452 OASIS RESTAURANT  
 License Type: Permanent Food Service 7651 SW HWY 200, OCALA 34474

Inspection Date: 10/22/2009 Inspection Number: 1911325 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended  
 Inspector Name: ANAZIA, ROLAND

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. For toaster oven in the kitchen .	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5202696 GATORS DOCKSIDE OCALA  
 License Type: Permanent Food Service 3920 SW 42ND STREET STE 101, OCALA 34474

Inspection Date: 10/19/2009 Inspection Number: 1890870 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: ANAZIA, ROLAND

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 5200508 SONNY'S REAL PIT B B Q  
 License Type: Permanent Food Service 1845 SW COLLEGE RD, OCALA 344743021

Inspection Date: 10/22/2009 Inspection Number: 1870435 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: ANAZIA, ROLAND

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. For industrial fan in dish washing area .	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5202588 TRAVELODGE  
 License Type: Permanent Food Service 4040 W SILVER SPRINGS BLVD, OCALA 34482

Inspection Date: 10/22/2009 Inspection Number: 1870349 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: BRYANT, BENJAMIN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-13-2	Circuit breaker box blocked and/or inaccessible. For reporting purposes only.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.

**Marion County**

License Number: 5202633

MANGOS

License Type: Permanent Food Service

12210 NW HWY 27, OCALA 34482

Inspection Date: 10/22/2009

Inspection Number: 1880620

Inspection Type: Routine - Food

Inspection Disposition: Warning  
Issued

Inspector Name: BRYANT, BENJAMIN

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor in bar area. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 5202412

SUNSET HARBOR MARINA REST

License Type: Permanent Food Service

10333 SE SUNSET HARBOR RD, SUMMERFIELD 34491

Inspection Date: 10/23/2009

Inspection Number: 1860060

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: ANAZIA, ROLAND

Violation CodeObservationViolation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only. Over back door .

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only. Dish wash area .

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Martin County**

License Number: 5301231

PAPA JOHN'S PIZZA #1072

License Type: Permanent Food Service

1956 S FEDERAL HWY, STUART 34994-3916

Inspection Date: 10/16/2009

Inspection Number: 1845401

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PETROW, MICHAEL

Violation Code

Observation

Violation Citation

47-16-2

Electrical outlet missing cover plate. For reporting purposes only... behind pizza boxes.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

**Monroe County**

License Number: 5402689	GREAT WALL TAKI OUTI		
License Type: Permanent Food Service	82685 OVERSEAS HWY, ISLAMORADA, VLG OF I 33036		
Inspection Date: 10/20/2009	Inspection Number: 1864085	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BROWN, MICHAEL			

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 5402035	GREAT WALL CHINESE RESTAURANT		
License Type: Permanent Food Service	91200 OVERSEAS HWY, TAVERNIER 33070		
Inspection Date: 10/20/2009	Inspection Number: 1853789	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BROWN, MICHAEL			

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

**Nassau County**

License Number: 5500510

BD &amp; R CAFE

License Type: Permanent Food Service

600 N 8TH ST, FERNANDINA BEACH 32034

Inspection Date: 10/19/2009

Inspection Number: 1839838

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: PHELAN, JOHN

Violation CodeObservationViolation Citation

47-03-2

Observed unused opening in panel box unprotected. For reporting purposes only.

NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.

License Number: 5500813

ANGELS PORCH &amp; JACK AND DIANES

License Type: Permanent Food Service

708 CENTRE ST, FERNANDINA BEACH 32034

Inspection Date: 10/22/2009

Inspection Number: 1920132

Inspection Type: Complaint Full

Inspection Disposition: Warning  
Issued

Inspector Name: PHELAN, JOHN

Violation CodeObservationViolation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only. By 3 comp sink.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only. Rear door.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Nassau County**

License Number: 5500918 PABLO'S MEXICAN REST GRILL & CANTINA  
 License Type: Permanent Food Service 12 N 2 ST, FERNANDINA BEACH 32034

Inspection Date: 10/22/2009 Inspection Number: 1880994 Inspection Type: Routine - Food Inspection Disposition: Call Back - Extension given, pending  
 Inspector Name: PHELAN, JOHN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Open space between hood filters.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
46-09-2	Violation: 46-09-2 Exit signs not properly illuminated. For reporting purposes only. Upstairs.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.
47-05-2	Violation: 47-05-2 Observed a splitter/multi-plug adapter in use. For reporting purposes only. Kitchen by cola cooler.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Violation: 47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only. Upstairs kitchen chest freezer.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5501055 DOO WOP DINER LLC  
 License Type: Permanent Food Service 1120 S 14TH STREET, FERNANDINA BEACH 32034

Inspection Date: 10/19/2009 Inspection Number: 1919818 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: PHELAN, JOHN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-2	Exit signs not properly illuminated. For reporting purposes only. Rear door	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

**Okaloosa County**

License Number: 5601474	HARDEE'S #1507		
License Type: Permanent Food Service	3702 S FERNDON BLVD, CRESTVIEW	32536	
Inspection Date: 10/21/2009	Inspection Number: 1871787	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: FRANZALIA, CHARLES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only....back door...cardboard boxes..	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	

License Number: 5602157	HOOTERS OF CRESTVIEW		
License Type: Permanent Food Service	3698 S FERDON BLVD, CRESTVIEW	32536	
Inspection Date: 10/21/2009	Inspection Number: 1892254	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: FRANZALIA, CHARLES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 5603018	MIA'S ITALIAN RESTAURANT		
License Type: Permanent Food Service	2203 S FERDON BLVD, CRESTVIEW	32536	
Inspection Date: 10/21/2009	Inspection Number: 1851351	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: FRANZALIA, CHARLES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only...back door exit...	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

**Okaloosa County**

License Number: 5603750

BEST WESTERN

License Type: Permanent Food Service

900 SOUTH KREST DRIVE, CRESTVIEW 32536

Inspection Date: 10/15/2009

Inspection Number: 1861537

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: FRANZALIA, CHARLES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only. Repeat Violation.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

**Okaloosa County**

License Number: 5603245

GOLDEN CORRAL OF DESTIN

License Type: Permanent Food Service

733 E HWY 98, DESTIN 32541

Inspection Date: 10/22/2009

Inspection Number: 1861063

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PEREZ, FELIPE

Violation CodeObservationViolation Citation

47-15-2

Observed an uncovered electrical box...exposed wiring at garbage disposal unit. For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

48-12-2

No current boiler certification provided/available. For reporting purposes only. Repeat Violation.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 5603377

OUTBACK STEAKHOUSE

License Type: Permanent Food Service

34908 EMERALD COAST PKWY, DESTIN 32541

Inspection Date: 10/22/2009

Inspection Number: 1850897

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PEREZ, FELIPE

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Repeat Violation.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 5603484

CHILI'S BAR &amp; GRILL

License Type: Permanent Food Service

34902 EMERALD COAST PKWY, DESTIN 32541

Inspection Date: 10/20/2009

Inspection Number: 1902090

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PEREZ, FELIPE

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. Repeat Violation.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

**Okaloosa County**

---

License Number: 5602127

790 NORTH

License Type: Permanent Food Service

790 N BEAL PKWY, FORT WALTON BEACH 32547

Inspection Date: 10/20/2009

Inspection Number: 1861075

Inspection Type: Routine - Food

Inspection Disposition: Call Back -  
Complied

Inspector Name: PEREZ, FELIPE

Violation CodeObservationViolation Citation

47-06-2

Violation: 47-06-2

Observed extension cords in use for non-temporary period...outside back. For reporting purposes only. Repeat Violation.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5603128

LITTLE CAESARS NICEVILLE

License Type: Permanent Food Service

1067 JOHN SIMS PKWY, NICEVILLE 32578

Inspection Date: 10/14/2009

Inspection Number: 1892285

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: FRANZALIA, CHARLES

Violation CodeObservationViolation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

**Okeechobee County**

License Number: 5700463

JOEY'S SUPREME PIZZA

License Type: Permanent Food Service

107 SW PARK ST, OKEECHOBEE 34972

Inspection Date: 10/19/2009

Inspection Number: 1893472

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: SCHNELL, PAMELA

Violation Code

Observation

Violation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

47-16-2 Electrical outlet with broken cover plate. at slicer/handsink areaFor reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

**Orange County**

License Number: 5807053 YING CHINESE RESTAURANT  
 License Type: Permanent Food Service 2356 E SEMORAN BLVD, APOPKA 32703

Inspection Date: 10/15/2009 Inspection Number: 1919460 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: CHIU, CECILIA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. Sushi area	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 5808486 MCDONALDS  
 License Type: Permanent Food Service 228 S ORLANDO AVE, MAITLAND 32751

Inspection Date: 10/19/2009 Inspection Number: 1858884 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: WATSON, DENNIS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-37-2	Portable fire extinguisher missing from designated location. For reporting purposes only. Empty bracket by back door	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

License Number: 5810954 NAPASORN THAI RESTAURANT  
 License Type: Permanent Food Service 56 E PINE ST #100, ORLANDO 32801

Inspection Date: 10/21/2009 Inspection Number: 1837921 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: PIEL, ANDREA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
39-05-2	Ventilation inadequate as evidenced by smoke and grease in kitchen area. For reporting purposes only.	NFPA 96, 4.1.1 Cooking equipment used in processes producing smoke or grease-laden vapors shall be equipped with an exhaust system that complies with all the equipment and performance requirements of this standard; and NFPA 96, 8.2.2 Air Volume. NFPA 96, 8.2.2.1: Exhaust air volumes for hoods shall be of a sufficient level to provide for capture and removal of grease-laden cooking vapors. FOR REPORTING PURPOSES ONLY

License Number: 5806487 CONCESSION STAND #38  
 License Type: Permanent Food Service 1610 W CHURCH ST, ORLANDO 32805

Inspection Date: 10/07/2009 Inspection Number: 1919628 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended  
 Inspector Name: GORIS, WILBERTO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

**Orange County**

License Number: 5805155

CAFE EXPRESS

License Type: Permanent Food Service

712 W CHURCH ST, ORLANDO 328052210

Inspection Date: 10/19/2009

Inspection Number: 1899397

Inspection Type: Routine - Food

Inspection Disposition: Call Back -  
Admin. complaint recommended

Inspector Name: GORIS, WILBERTO

Violation CodeObservationViolation Citation

45-07-2

Violation: 45-07-2

Observed misalignment of hood suppression system nozzles. For reporting purposes only. EQUIPMENT OUTSIDE OF HOOD FRYER

NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

46-05-2

Violation: 46-05-2

Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. EXCESS EQUIPMENT STORED IN FRONT OF REAR DOOR

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

47-04-2

Violation: 47-04-2

Observed frayed/spliced electrical wires. For reporting purposes only. BEHIND COOLER BY THE SERVICE WINDOW

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-16-2

Violation: 47-16-2

Electrical outlet missing cover plate. For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 5808149

HUNGRY HOWIES

License Type: Permanent Food Service

11774 E COLONIAL DR, ORLANDO 32817

Inspection Date: 10/21/2009

Inspection Number: 1878858

Inspection Type: Routine - Food

Inspection Disposition: Warning  
Issued

Inspector Name: SINGH, GAJENDRA

Violation CodeObservationViolation Citation

37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

**Orange County**

License Number: 5811662

FUJI SUSHI &amp; TEPPAN INC

License Type: Permanent Food Service

504 NORTH ALAFAYA TR #117, ORLANDO 32817

Inspection Date: 10/22/2009

Inspection Number: 1878824

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: SINGH, GAJENDRA

Violation CodeObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only. BY HOT WATER HEATER

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5805988

CVI DINNING ROOM

License Type: Permanent Food Service

11850 UNIVERSITY BLVD, ORLANDO 328172146

Inspection Date: 10/19/2009

Inspection Number: 1878862

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: SINGH, GAJENDRA

Violation CodeObservationViolation Citation

47-04-2 Observed frayed/spliced electrical wires. For reporting purposes only. DISH ROOM Corrected On Site.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-16-2 Electrical outlet missing cover plate. For reporting purposes only. BY MILK MACHINE

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 5808562

SPICE CAFE

License Type: Permanent Food Service

7536 DR PHILLIPS BLVD #360, ORLANDO 32819

Inspection Date: 10/19/2009

Inspection Number: 1919946

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BACHOO, SAVITRI

Violation CodeObservationViolation Citation

48-13-2 Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.

NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.

**Orange County**

License Number: 5809069 RESTAURA INC A-2 CAFETERIA A  
 License Type: Vending Machine 5600 SANDLAKE RD MP235, ORLANDO 32819

Inspection Date: 10/20/2009 Inspection Number: 1093423 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: NEGRON, LARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 5809071 RESTAURA INC MICRO BLDG  
 License Type: Vending Machine 5600 SANDLAKE RD MP 235, ORLANDO 32819

Inspection Date: 10/20/2009 Inspection Number: 1093425 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: NEGRON, LARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-01-2	Boiler certificate not posted in boiler room. For reporting purposes only.	69A-51.025(4) FAC (4) Certificate of Compliance. The Certificate of Compliance shall be conspicuously placed so it can be readily identified with the certified boiler, preferably in the boiler room. FOR REPORTING PURPOSES ONLY.

**Orange County**

License Number: 5809072

RESTAURA INC M BLDG

License Type: Vending Machine

5600 SANDLAKE RD MP 235, ORLANDO 32819

Inspection Date: 10/20/2009

Inspection Number: 1092671

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: NEGRON, LARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

**Orange County**

License Number: 5809073 RESTAURA INC FAB BLDG A  
 License Type: Vending Machine 5600 SANDLAKE RD MD 235, ORLANDO 32819

Inspection Date: 10/20/2009 Inspection Number: 1093747 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: NEGRON, LARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 5809163 LOGAN'S ROADHOUSE  
 License Type: Permanent Food Service 3060 W SANDLAKE RD, ORLANDO 32819

Inspection Date: 10/15/2009 Inspection Number: 1879974 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: NEGRON, LARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only,fan	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Orange County**

License Number: 5809849		HYATT PLACE	
License Type: Permanent Food Service		5895 CARAVAN CT, ORLANDO 32819	
Inspection Date: 10/19/2009	Inspection Number: 1878762	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BACHOO, SAVITRI			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-13-2	Circuit breaker box blocked .Table in storage area.For reporting purposes only.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.	

License Number: 5810420		PIZZA ROMA'S	
License Type: Permanent Food Service		8540 INTERNATIONAL DRIVE, ORLANDO 32819	
Inspection Date: 10/16/2009	Inspection Number: 1838861	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: NEGRON, LARA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only,randall cooler	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
49-07-2	Observed flammable material stored near fuse box/electric meter room. For reporting purposes only. Corrected On Site.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.	

License Number: 5810514		VINES GRILLE & WINE BAR	
License Type: Permanent Food Service		7533 W SANDLAKE ROAD, ORLANDO 32819	
Inspection Date: 10/22/2009	Inspection Number: 1858160	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Complied
Inspector Name: BACHOO, SAVITRI			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-15-2	Violation: 45-15-2  No placard placed near Class K portable fire extinguisher stating the fire suppression system must be activated prior to use of the portable extinguisher. For reporting purposes only.	NFPA 10, 4.3.2.2 A placard shall be conspicuously placed near the extinguisher that states that the fire protection system shall be activated prior to using the fire extinguisher. FOR REPORTING PURPOSES ONLY.	

**Orange County**

License Number: 5811313

CASABLANCA SPORTS CAFE

License Type: Permanent Food Service

6700 KINGSPONTE PKWY, ORLANDO 32819

Inspection Date: 10/21/2009

Inspection Number: 1919980

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BACHOO, SAVITRI

Violation CodeObservationViolation Citation

47-16-2

Electrical outlet broken cover plate. For reporting purposes only. Entrance of kitchen .

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 5811398

RESTAURA, INC @ LOCKHEED MARTIN

License Type: Permanent Food Service

5600 SANDLAKE ROAD, ORLANDO 32819

Inspection Date: 10/20/2009

Inspection Number: 1849343

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: NEGRON, LARA

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

48-01-2

Boiler certificate not posted in boiler room. For reporting purposes only.

69A-51.025(4) FAC (4) Certificate of Compliance. The Certificate of Compliance shall be conspicuously placed so it can be readily identified with the certified boiler, preferably in the boiler room. FOR REPORTING PURPOSES ONLY.

48-12-2

No current boiler certification provided/available. For reporting purposes only.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

**Orange County**

License Number: 5811399	QUIZNO'S SUBS #7658
License Type: Permanent Food Service	5615 INTERNATIONAL DRIVE, ORLANDO 32819
Inspection Date: 10/13/2009	Inspection Number: 1909431
Inspector Name: BACHOO, SAVITRI	Inspection Type: Routine - Food
	Inspection Disposition: Warning Issued

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair

License Number: 5811409	PAO GOSTOSO BAKERY
License Type: Permanent Food Service	5472 INTERNATIONAL DR., ORLANDO 32819
Inspection Date: 10/19/2009	Inspection Number: 1847995
Inspector Name: BACHOO, SAVITRI	Inspection Type: Routine - Food
	Inspection Disposition: Warning Issued

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-04-2	Observed exposed electrical wires. For reporting purposes only. Roller machine area.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. Roller machine area.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Orange County**

License Number: 5800555

MARTIN CAFETERIA MAIN

License Type: Permanent Food Service

5600 SANDLAKE RD, ORLANDO 328198907

Inspection Date: 10/20/2009

Inspection Number: 1900495

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: NEGRON, LARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-01-2	Boiler certificate not posted in boiler room. For reporting purposes only.	69A-51.025(4) FAC (4) Certificate of Compliance. The Certificate of Compliance shall be conspicuously placed so it can be readily identified with the certified boiler, preferably in the boiler room. FOR REPORTING PURPOSES ONLY.
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 5806606

TONY ROMA'S #3038

License Type: Permanent Food Service

8560 INTERNATIONAL DR, ORLANDO 328199331

Inspection Date: 10/16/2009

Inspection Number: 1869743

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: NEGRON, LARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only,randall cooler	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
49-07-2	Observed flammable material stored near fuse box/electric meter room. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

**Orange County**

License Number: 5806635 PONDEROSA STEAK HOUSE  
 License Type: Permanent Food Service 8510 INTERNATIONAL DR, ORLANDO 328199331

Inspection Date: 10/16/2009 Inspection Number: 1849353 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: NEGRON, LARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only,mop sink area.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Inspection Date: 10/20/2009 Inspection Number: 1849352 Inspection Type: Routine - Food Inspection Disposition: Call Back - Complied  
 Inspector Name: NEGRON, LARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Violation: 47-06-2  Observed extension cord in use for non-temporary period. For reporting purposes only,mop sink area.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5804477 MCDONALDS RESTAURANT #10140  
 License Type: Permanent Food Service 5401 ALTAMIRA DR, ORLANDO 328199430

Inspection Date: 10/15/2009 Inspection Number: 1899217 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: BACHOO, SAVITRI

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-13-2	Circuit breaker box blocked .For reporting purposes only.Equipment and boxes.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.

License Number: 5810902 HOFFNER CATERING & SUPPLY  
 License Type: Catering 4880 B DISTRIBUTION CT UNIT 1-2, ORLANDO 32822

Inspection Date: 10/22/2009 Inspection Number: 1093285 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: RULLAN, ALFONSO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
49-12-2	Observed container of flammable material over 5 gallons stored in establishment. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

**Orange County**

License Number: 5809018		888 CHINESE RESTAURANT	
License Type: Permanent Food Service		2188 S CHICKASAW TRAIL, ORLANDO 32825	
Inspection Date: 10/21/2009	Inspection Number: 1919792	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SINGH, GAJENDRA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 5809971		POLLO TROPICAL	
License Type: Permanent Food Service		11860 E COLONIAL DR, ORLANDO 32826	
Inspection Date: 10/22/2009	Inspection Number: 1868586	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SINGH, GAJENDRA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 5804891		LAKE NONA DINING ROOM	
License Type: Permanent Food Service		9100 CHILTERN DR, ORLANDO 328277029	
Inspection Date: 03/20/2008	Inspection Number: 1920404	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: RULLAN, ALFONSO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient	
License Number: 5809650		LONGHORN STEAKS OF WATERFD LKS 5133	
License Type: Permanent Food Service		309 N ALAFAYA TRL, ORLANDO 32828	
Inspection Date: 10/16/2009	Inspection Number: 1909526	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: SINGH, GAJENDRA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-25-2	Hood filters not equipped with a drip tray. For reporting purposes only.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 5810121		FRIENDLY CONFINES REST (THE)	
License Type: Permanent Food Service		435 N ALAFAYA TRL, ORLANDO 32828	
Inspection Date: 10/16/2009	Inspection Number: 1889058	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SINGH, GAJENDRA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	

**Orange County**

License Number: 5811854

PIE IN THE SKY

License Type: Permanent Food Service

588 SOUTH ALAFAYA TRAIL SUITE 30, ORLANDO 32828

Inspection Date: 10/21/2009

Inspection Number: 1909516

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: SINGH, GAJENDRA

Violation CodeObservationViolation Citation

37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

37-20-2

Violation: 37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 5808148

BOARDWALK CONVENTION CENTER

License Type: Permanent Food Service

2101 N EPCOT RESORTS BLVD, LAKE BUENA VISTA 328301000

Inspection Date: 10/21/2009

Inspection Number: 1848039

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: TILLEY, GEMMA

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only. For milk reach in cooler at hallway .

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5808129

GIORDANO'S RESTAURANT &amp; PIZZERIA

License Type: Permanent Food Service

12151 S APOPKA VINELAND RD, LAKE BUENA VISTA 32836

Inspection Date: 10/15/2009

Inspection Number: 1858333

Inspection Type: Routine - Food

Inspection Disposition: Call Back - Complied

Inspector Name: RIVERA, JESICA M

Violation CodeObservationViolation Citation

15-28-2

Violation: 15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Part in order.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 5812288

KABOB N CURRY

License Type: Permanent Food Service

12185 SOUTH APOPKA VINELAND RD, ORLANDO 32836

Inspection Date: 10/19/2009

Inspection Number: 1909638

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: RIVERA, JESICA M

Violation CodeObservationViolation Citation

37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only. At the end of the hood.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

47-15-2

Observed an uncovered electrical box. For reporting purposes only. By the office hallway.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

**Orange County**

License Number: 5810722 CALIFORNIA PIZZA KITCHEN  
 License Type: Permanent Food Service 4200 CONROY RD STE 251, ORLANDO 32839

Inspection Date: 10/20/2009 Inspection Number: 1837823 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: GORIS, WILBERTO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-13-2	Circuit breaker box blocked and/or inaccessible. For reporting purposes only.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.

License Number: 5810738 HAAGEN-DAZS MALL MILLERNIA  
 License Type: Permanent Food Service 4200 CONROY RD #210, ORLANDO 32839

Inspection Date: 10/20/2009 Inspection Number: 1868648 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: GORIS, WILBERTO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-13-2	Circuit breaker box blocked and/or inaccessible. For reporting purposes only.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.

**Osceola County**

License Number: 5910284 GARIBALDI MEXICAN CUISINE I  
 License Type: Permanent Food Service 1804 W VINE ST, KISSIMMEE 34741

Inspection Date: 10/20/2009 Inspection Number: 1867866 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended  
 Inspector Name: KHAN, MOZHARUL

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 5907691 CARRABBA'S ITALIAN GRILL  
 License Type: Permanent Food Service 7890 W IRLO BRONSON HWY, KISSIMMEE 34747

Inspection Date: 10/21/2009 Inspection Number: 1888356 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: NIEVES, RAFAEL

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. Boiler certificate expired on 07/09/09. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 5906560 CHINA STAR RESTAURANT  
 License Type: Permanent Food Service 14944 E ORANGE LAKE BLVD, KISSIMMEE 347478210

Inspection Date: 10/21/2009 Inspection Number: 1847413 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: NIEVES, RAFAEL

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exit or egress. Table and chairs blocking exit in dining area. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

**Osceola County**

License Number: 5907193

PIZZA HUT #622140

License Type: Permanent Food Service

898 CYPRESS PKWY, KISSIMMEE 347593456

Inspection Date: 10/19/2009

Inspection Number: 1898741

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: RIVERA, JESICA M

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only. For the pizza oven.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only. For the deep fryer.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

**Palm Beach County**

License Number: 6006496

MARIO'S RESTAURANT

License Type: Permanent Food Service

933 PARK AVE, LAKE PARK 33403

Inspection Date: 10/21/2009

Inspection Number: 1886053

Inspection Type: Routine - Food

Inspection Disposition: Warning  
Issued

Inspector Name: MIDDLETON, ELWYN

Violation CodeObservationViolation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only. back door.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 6013594

MILLENNIUM RESTAURANT

License Type: Permanent Food Service

940 PARK AVE #107, LAKE PARK 33403

Inspection Date: 10/19/2009

Inspection Number: 1896293

Inspection Type: Routine - Food

Inspection Disposition: Warning  
Issued

Inspector Name: MIDDLETON, ELWYN

Violation CodeObservationViolation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only. back door.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 6051352

EATS &amp; SWEETS

License Type: Mobile Food Dispensing Vehicle

8110 MONETARY DR, TR INDUSTRIES, RIVIERA BEACH 33404

Inspection Date: 10/19/2009

Inspection Number: 1136495

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

**Palm Beach County**

License Number: 6000073

HOWLEY'S RESTAURANT

License Type: Permanent Food Service

4700 S DIXIE HWY, WEST PALM BEACH 33405

Inspection Date: 10/20/2009

Inspection Number: 1875784

Inspection Type: Routine - Food

Inspection Disposition: Warning  
Issued

Inspector Name: SHAPIRO, STEWART

Violation CodeObservationViolation Citation

15-42-2	Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.	NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. IN KITCHEN	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
49-06-2	Observed flammable material stored around water heater. For reporting purposes only. PAINTS ON SHELF NEXT TO HOTWATER HEATER	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

License Number: 6003799

DONTÉE'S RESTAURANT

License Type: Permanent Food Service

620 BELVEDERE RD, WEST PALM BEACH 334051231

Inspection Date: 10/23/2009

Inspection Number: 1885995

Inspection Type: Routine - Food

Inspection Disposition: Warning  
Issued

Inspector Name: SHAPIRO, STEWART

Violation CodeObservationViolation Citation

45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
---------	---	---

**Palm Beach County**

License Number: 6013325		BERT'S HOT BAKED GRINDERS	
License Type: Permanent Food Service		2448 OKEECHOBEE BLVD, WEST PALM BCH 33409	
Inspection Date: 10/21/2009	Inspection Number: 1886145	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: JONES, ANTHONY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	

License Number: 6007587		BURGER KING #5777	
License Type: Permanent Food Service		2949 N MILITARY TRL, WEST PALM BEACH 33409	
Inspection Date: 10/20/2009	Inspection Number: 1855426	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: JONES, ANTHONY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Corrected On Site.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

License Number: 6012913		SAFFRON	
License Type: Permanent Food Service		731 VILLAGE BLVD #110-111, WEST PALM BEACH 33409	
Inspection Date: 10/19/2009	Inspection Number: 1834915	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: JONES, ANTHONY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only. k-class	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	

License Number: 6019655		DIPIETROS PIZZERIA AND RESTAURANT	
License Type: Permanent Food Service		2550 OKEECHOBEE BLVD STE G, WEST PALM BEACH 33409	
Inspection Date: 10/21/2009	Inspection Number: 1886121	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: JONES, ANTHONY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-26-2	Observed exhaust system operated with filters dusty. For reporting purposes only.	NFPA 96, 11.1.2 Filter-equipped exhaust systems shall not be operated with filters removed. For reporting purposes only.	

**Palm Beach County**

License Number: 6019687

BIG CITY BAGELS

License Type: Permanent Food Service

871 VILLAGE BLVD STE# 602-A, WEST PALM BEACH 33409

Inspection Date: 10/19/2009

Inspection Number: 1914289

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only. abc	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. abc	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6019908

ZAZA MEDITERRANEAN GRILL

License Type: Permanent Food Service

911 VILLAGE BLVD STE 801, WEST PALM BEACH 33409

Inspection Date: 10/20/2009

Inspection Number: 1845165

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. missing one hood filter. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
---------	--	---

License Number: 6019992

LA GRANJA RESTAURANT

License Type: Permanent Food Service

4282 OKEECHOBEE BLVD, WEST PALM BEACH 33409

Inspection Date: 10/21/2009

Inspection Number: 1834901

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. abc	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
47-16-2	Electrical outlet missing cover plate. For reporting purposes only. behind grill	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.
47-16-2	Electrical outlet missing cover plate. For reporting purposes only. near back door	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

**Palm Beach County**

License Number: 6020162

RANDY'S SEAFOOD &amp; PASTA

License Type: Permanent Food Service

2905-E N MILITARY TRL, WEST PALM BEACH 33409

Inspection Date: 10/20/2009

Inspection Number: 1875996

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. abc

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6020138

KONTIKI RESTAURANT

License Type: Permanent Food Service

13860 WELLINGTON TRACE, VILLAGE OF WELLINGTO 33414

Inspection Date: 10/19/2009

Inspection Number: 1896173

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: MENOR, MICHAEL

Violation CodeObservationViolation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6009595

DON RAMON RESTAURANT

License Type: Permanent Food Service

502 S MILITARY TRL, WEST PALM BCH 334153902

Inspection Date: 10/21/2009

Inspection Number: 1828552

Inspection Type: Complaint Full

Inspection Disposition: Call Back - Complied

Inspector Name: CONCEPCION, MARIA

Violation CodeObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only. Corrected On Site.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6019116

SUSHI MASA

License Type: Permanent Food Service

2282 N CONGRESS AVE, BOYNTON BEACH 33426

Inspection Date: 10/22/2009

Inspection Number: 1896063

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: SHAPIRO, STEWART

Violation CodeObservationViolation Citation

45-11-2 Observed cooking equipment in use while hood suppression/exhaust system is inoperable. Notified Fire AHJ. For reporting purposes only. PAOF GREASE ON BURNER HALF NOT UNDER HOOD

NFPA 96, 11.1.6 Cooking equipment shall not be operated while its fire-extinguishing system or exhaust system is nonoperational or otherwise impaired. FOR REPORTING PURPOSES ONLY.

**Palm Beach County**

License Number: 6013000 WING WAH EXPRESS  
 License Type: Permanent Food Service 115 N CONGRESS AVE, BOYNTON BCH 334261223

Inspection Date: 10/16/2009 Inspection Number: 1834585 Inspection Type: Routine - Food Inspection Disposition: Call Back - Complied  
 Inspector Name: SHAPIRO, STEWART

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Violation: 15-28-2  Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6001023 OLDE STYLE PIZZA  
 License Type: Permanent Food Service 1455 BOYNTON BEACH BLVD, BOYNTON BEACH 33426-3411

Inspection Date: 10/22/2009 Inspection Number: 1844877 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: SHAPIRO, STEWART

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. BAGS OF FLOUR	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.
46-07-2	Exit signs missing. For reporting purposes only. BACK DOOR	NFPA 101, 7.10.1.2 Exits, other than main exterior exit doors that obviously and clearly are identifiable as exits, shall be marked by an approved sign readily visible from any direction of exit access. FOR REPORTING PURPOSES ONLY.

License Number: 6012705 BISTRO PROVENCE  
 License Type: Permanent Food Service 2399 N FEDERAL HWY, BOCA RATON 33431

Inspection Date: 10/22/2009 Inspection Number: 1875370 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: BANNIGAN, TIM

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. --- at rear door.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6012335 TAVERNA HELIOS  
 License Type: Permanent Food Service 297 E PALMETTO PARK RD, BOCA RATON 33432

Inspection Date: 10/22/2009 Inspection Number: 1917445 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: BANNIGAN, TIM

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-13-2	Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only. --- Operated Agreed That This Would be Corrected Prior to Restaurant Opening.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.

**Palm Beach County**

License Number: 6013586

LASTELLA'S MARKET INC

License Type: Permanent Food Service

159 E PALMETTO PARK ROAD, BOCA RATON 33432

Inspection Date: 10/23/2009

Inspection Number: 1914395

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: BANNIGAN, TIM

Violation CodeObservationViolation Citation

49-12-2

Observed container of flammable material over 5 gallons stored in establishment. For reporting purposes only. Corrected On Site.

61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

License Number: 6018968

CHICK'N CHOP ON THE GRILL #5

License Type: Permanent Food Service

555 N FEDERAL HWY, BOCA RATON 33432

Inspection Date: 10/23/2009

Inspection Number: 1885589

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BANNIGAN, TIM

Violation CodeObservationViolation Citation

48-11-2

Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only. --- (2) 2.5 lb. LP tanks stored in kitchen.

NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

License Number: 6019451

MOQUILA RESTAURANT &amp; TEQUILA BAR

License Type: Permanent Food Service

99 SE MIZNER BLVD, BOCA RATON 33432

Inspection Date: 10/19/2009

Inspection Number: 1854862

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BANNIGAN, TIM

Violation CodeObservationViolation Citation

45-15-2

No placard placed near Class K portable fire extinguisher stating the fire suppression system must be activated prior to use of the portable extinguisher. For reporting purposes only.

NFPA 10, 4.3.2.2 A placard shall be conspicuously placed near the extinguisher that states that the fire protection system shall be activated prior to using the fire extinguisher. FOR REPORTING PURPOSES ONLY.

**Palm Beach County**

License Number: 6010751

STONE CRABS RESTAURANT

License Type: Permanent Food Service

514 VIA DE PALMAS, BOCA RATON 33432-6012

Inspection Date: 10/19/2009

Inspection Number: 1895878

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: BANNIGAN, TIM

Violation CodeObservationViolation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.  
--- ABC in servers station.  
--- ABC in stairway to office.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6009270

OUTBACK STEAKHOUSE

License Type: Permanent Food Service

6030 SW 18 ST, BOCA RATON 33433

Inspection Date: 10/16/2009

Inspection Number: 1895892

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: PIERI, CYNTHIA

Violation CodeObservationViolation Citation

46-05-2 Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.MANY CARDBOARD BOXES

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

46-08-2 Exit signs not visible from any direction. For reporting purposes only.BACK DOOR

NFPA 101, 7.10.1.2 Exits, other than main exterior exit doors that obviously and clearly are identifiable as exits, shall be marked by an approved sign readily visible from any direction of exit access. FOR REPORTING PURPOSES ONLY.

47-08-2 Observed electrical wiring in disrepair. For reporting purposes onlySOCKET BROKEN FROM WALL

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Palm Beach County**

License Number: 6020288		EUROPEAN CORNER CAFE	
License Type: Permanent Food Service		7300 W CAMINO REAL, BOCA RATON 33433	
Inspection Date: 10/19/2009	Inspection Number: 1920065	Inspection Type: Complaint Full	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PIERI, CYNTHIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6005520		PLATINUM SHOWGIRLS	
License Type: Permanent Food Service		1115 N FEDERAL HWY, BOYNTON BCH 334353228	
Inspection Date: 06/23/2009	Inspection Number: 1643016	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: VAVALA, LARRY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair	
License Number: 6006407		CHINA VAN	
License Type: Permanent Food Service		3639 WOOLBRIGHT RD, BOYNTON BEACH 33436	
Inspection Date: 10/19/2009	Inspection Number: 1865430	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: SHAPIRO, STEWART			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 6012572		WINGS PLUS	
License Type: Permanent Food Service		9804 S MILITARY TRL #E-8, BOYNTON BEACH 33436	
Inspection Date: 10/20/2009	Inspection Number: 1885857	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SHAPIRO, STEWART			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

**Palm Beach County**

License Number: 6019392		CARBONES GRILL	
License Type: Permanent Food Service		10114 S MILITARY TRL #102, BOYNTON BEACH 33436	
Inspection Date: 10/21/2009	Inspection Number: 1875620	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: SHAPIRO, STEWART			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-25-2	Hood filters not equipped with a drip tray. For reporting purposes only.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	

License Number: 6012683		BENNY'S ICE HOUSE	
License Type: Permanent Food Service		9803 S MILITARY TRL, BOYNTON BCH 334363202	
Inspection Date: 10/21/2009	Inspection Number: 1906523	Inspection Type: Routine - Food	Inspection Disposition: Emergency order recommended
Inspector Name: SHAPIRO, STEWART			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are in disrepair. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
15-28-2	Violation: 15-28-2 Hood filters are in disrepair. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	

License Number: 6010541		PALM ISLES CAFE	
License Type: Permanent Food Service		9545 PALM ISLE DR, BOYNTON BEACH 33437	
Inspection Date: 10/20/2009	Inspection Number: 1906528	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: MENOR, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-13-2	Circuit breaker box blocked and/or inaccessible. For reporting purposes only. BLOCKED	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.	
47-15-2	Observed an uncovered electrical box. For reporting purposes only. CIRCUTE BREAKER BOX IS OPEN	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

**Palm Beach County**

License Number: 6013201

CLOCK TOWER GRILL

License Type: Permanent Food Service

7720 BOYNTON BEACH BLVD, BOYNTON BEACH 33437

Inspection Date: 10/19/2009

Inspection Number: 1885827

Inspection Type: Routine - Food

Inspection Disposition: Administrative  
complaint recommended

Inspector Name: SHAPIRO, STEWART

Violation CodeObservationViolation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. K ON FLOOR LINE

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6007075

MCDONALDS #7974

License Type: Permanent Food Service

6581 FOREST HILL BLVD, GREENACRES 33463

Inspection Date: 10/22/2009

Inspection Number: 1906421

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: PONCE, NUARETTE

Violation CodeObservationViolation Citation

15-42-2 Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.

NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY

License Number: 6007470

DOMINO'S PIZZA #3880

License Type: Permanent Food Service

5891 S MILITARY TRL, LAKE WORTH 334636920

Inspection Date: 10/21/2009

Inspection Number: 1919806

Inspection Type: Complaint Full

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: PONCE, NUARETTE

Violation CodeObservationViolation Citation

46-05-2 Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. BACK DOOR\_EMPTY BOXES

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

**Palm Beach County**

License Number: 6000455

COUNTRY CLUB DINING RM

License Type: Permanent Food Service

7500 ST ANDREWS RD, LAKE WORTH 334671317

Inspection Date: 10/23/2009

Inspection Number: 1896030

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: PONCE, NUARETTE

Violation CodeObservationViolation Citation

48-12-2

No current boiler certification provided/available. EXPIRED For reporting purposes only.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 6020118

BEST WESTERN INTRACOASTAL INN

License Type: Permanent Food Service

810 S US HWY 1, JUPITER 33477

Inspection Date: 10/23/2009

Inspection Number: 1835069

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: DERVIN, RICHARD

Violation CodeObservationViolation Citation

49-06-2

Observed flammable material stored around water heater. For reporting purposes only. card board boxes in boiler room.

61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

License Number: 6011119

DUFFYS SPORTS GRILL

License Type: Permanent Food Service

1750 S FEDERAL HWY, DELRAY BEACH 33483

Inspection Date: 10/20/2009

Inspection Number: 1844749

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: MULLINGS, SEANTELE

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

**Palm Beach County**

License Number: 6000516

SANDE'S

License Type: Permanent Food Service

1717 N FEDERAL HWY, DELRAY BCH 334836003

Inspection Date: 10/19/2009

Inspection Number: 1885715

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: MULLINGS, SEANTELE

Violation CodeObservationViolation Citation

46-02-2

Observed lock on exit door that requires a key, tool or special knowledge to open.  
For reporting purposes only. walkin cooler

NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.

License Number: 6013800

CHINA ONE

License Type: Permanent Food Service

1285 W PALMETTO PARK RD, BOCA RATON 33486

Inspection Date: 10/21/2009

Inspection Number: 1920191

Inspection Type: Complaint Full

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: PIERI, CYNTHIA

Violation CodeObservationViolation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only.FRONT

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 6019941

SALAD CREATIONS

License Type: Permanent Food Service

5250 TOWN CENTER CIR STE 129, BOCA RATON 33486

Inspection Date: 10/19/2009

Inspection Number: 1854936

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: PIERI, CYNTHIA

Violation CodeObservationViolation Citation

46-05-2

Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.CARDBOARD BOXES

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Pasco County**

License Number: 6112863

VALLARTA MEXICAN RESTAURANT INC

License Type: Permanent Food Service

22948 SR 54, LUTZ 33549

Inspection Date: 10/20/2009

Inspection Number: 1877936

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: CHEW, TEOW

Violation CodeObservationViolation Citation

45-36-2

Hood suppression system tag out-of-date. For reporting purposes only.

NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

47-16-2

Electrical outlet with broken cover plate. For reporting purposes only.(kitchen)

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 6102211

TOP CHINA

License Type: Permanent Food Service

9135 LITTLE RD, NEW PORT RICHEY 34654

Inspection Date: 10/20/2009

Inspection Number: 1857362

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: GLENN, DAVID

Violation CodeObservationViolation Citation

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6102811

RIVER RIDGE GOLF CLUB

License Type: Permanent Food Service

11022 TEE TIME CIR, NEW PORT RICHEY 34654

Inspection Date: 10/20/2009

Inspection Number: 1888048

Inspection Type: Routine - Food

Inspection Disposition: Warning  
Issued

Inspector Name: GLENN, DAVID

Violation CodeObservationViolation Citation

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Pasco County**

License Number: 6101463		JADE FIRE	
License Type: Permanent Food Service		13422 HWY 19, HUDSON 34667	
Inspection Date: 10/19/2009	Inspection Number: 1847045	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GLENN, DAVID			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6102773		TASTE OF CHINA	
License Type: Permanent Food Service		13710 LITTLE RD, HUDSON 34667	
Inspection Date: 10/19/2009	Inspection Number: 1836723	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GLENN, DAVID			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6102810		TJ'S FAMILY RESTAURANT INC	
License Type: Permanent Food Service		15215 US HWY 19 UNIT J, HUDSON 34667	
Inspection Date: 10/19/2009	Inspection Number: 1898293	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: GLENN, DAVID			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

**Pasco County**

License Number: 6113032

DENTON AVE DELI AND MARKET, INC

License Type: Permanent Food Service

9226 DENTON AVENUE, HUDSON 34667

Inspection Date: 10/20/2009

Inspection Number: 1857360

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: GLENN, DAVID

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only. Small deep fryer not under hood system.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.



**Pinellas County**

License Number: 6212463

KAYS KITCHEN FAMILY RESTAURANT

License Type: Permanent Food Service

6475 CENTRAL AVE, ST PETERSBURG 337108411

Inspection Date: 10/21/2009

Inspection Number: 1876368

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BURKE, LAWRENCE

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6215758

GOLDEN KRUST CARIBBEAN BAKERY &amp; GRILL

License Type: Permanent Food Service

3010 54TH AVE SOUTH, ST PETERSBURG 33712

Inspection Date: 10/22/2009

Inspection Number: 1845609

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: WILLIAMS, TRINETTE

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-16-2

Electrical outlet missing cover plate. For reporting purposes only Near restroom.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 6213631

RUBINO'S PERFECT SLICE

License Type: Permanent Food Service

8400 4TH ST NORTH, ST. PETERSBURG 33716

Inspection Date: 10/19/2009

Inspection Number: 1917848

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: JACKSON, BEATRICE

Violation CodeObservationViolation Citation

47-16-2

Electrical outlets missing cover plates. For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

47-16-2

Electrical outlet missing cover plate on employee restroom light switch. For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

**Pinellas County**

License Number: 6214617		FLORIDA BLOOD SERVICES CAFETERIA	
License Type: Permanent Food Service		10100 9 ST N, ST. PETERSBURG 33716	
Inspection Date: 10/20/2009	Inspection Number: 1907362	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: JACKSON, BEATRICE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 6215532		THE EXECUTIVE'S CHEF	
License Type: Catering		10901 ROOSEVELT BLVD UNIT 800D, ST. PETERSBURG 33716	
Inspection Date: 10/21/2009	Inspection Number: 1093017	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: JACKSON, BEATRICE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
License Number: 6216442		BANANA BOAT TOO	
License Type: Permanent Food Service		5858 ROOSEVELT BLVD, CLEARWATER 33760	
Inspection Date: 10/22/2009	Inspection Number: 1908788	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: PORTER, LINDSAY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.(kitchen )	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.( throughout )	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

**Pinellas County**

License Number: 6216114

SUBWAY #37909

License Type: Permanent Food Service

1111 MISSOURI AVE, LARGO 33770

Inspection Date: 10/19/2009

Inspection Number: 1907350

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: OLSEN, JAMES

Violation CodeObservationViolation Citation

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only. near kitchen prep table

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6215191

ITALIAN VILLA

License Type: Permanent Food Service

7155 SEMINOLE PLZ, SEMINOLE 33772

Inspection Date: 10/22/2009

Inspection Number: 1876580

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: OLSEN, JAMES

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. abc fire extinguisher sitting on floor in kitchen area

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

46-05-2

Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. dinnig room back door blocked by stuff

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only. to microwave oven in kitchen area

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Pinellas County**

License Number: 6210275		TACO BELL #3861	
License Type: Permanent Food Service		10749 PARK BLVD, SEMINOLE 337725420	
Inspection Date: 10/23/2009	Inspection Number: 1896989	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: OLSEN, JAMES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only. in drive thru area	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 6208923		HUNGRY HOWIES PIZZA & SUBS	
License Type: Permanent Food Service		6989 SEMINOLE BLVD, SEMINOLE 337726026	
Inspection Date: 10/23/2009	Inspection Number: 1907336	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: OLSEN, JAMES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. kitchen back door marked exit locked with key Corrected On Site.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	
License Number: 6211599		DOMINO'S PIZZA #3159	
License Type: Permanent Food Service		12735 STARKEY RD, LARGO 33773	
Inspection Date: 10/16/2009	Inspection Number: 1919819	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Complied
Inspector Name: PORTER, LINDSAY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Violation: 47-06-2  Observed extension cord in use for non-temporary period. For reporting purposes only.(near microwave)	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6212392		GRANDE PIZZA	
License Type: Permanent Food Service		13355 BELCHER RD UNIT F, LARGO 33773	
Inspection Date: 10/16/2009	Inspection Number: 1847225	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PORTER, LINDSAY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.(front area)	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	



**Pinellas County**

License Number: 6251148	DELI-ICIOUS
License Type: Mobile Food Dispensing Vehicle	7801 PARK BLVD, PINELLAS PARK 33781
Inspection Date: 10/17/2009	Inspection Number: 1138299
Inspector Name: BURKE, LAWRENCE	Inspection Type: Routine - Food
	Inspection Disposition: Inspection Completed - No Further Action
<u>Violation Code</u>	<u>Observation</u>
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only.
	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

License Number: 6251149	MEXICAN DELIGHTS
License Type: Mobile Food Dispensing Vehicle	7801 PARK BLVD, PINELLAS PARK 33781
Inspection Date: 10/17/2009	Inspection Number: 1134585
Inspector Name: BURKE, LAWRENCE	Inspection Type: Routine - Food
	Inspection Disposition: Inspection Completed - No Further Action
<u>Violation Code</u>	<u>Observation</u>
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only.
	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.
	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6214417	INDIAN SHORES COFFEE COMPANY
License Type: Permanent Food Service	19221 GULF BLVD, INDIAN SHORES 33785
Inspection Date: 10/22/2009	Inspection Number: 1835533
Inspector Name: OLSEN, JAMES	Inspection Type: Routine - Food
	Inspection Disposition: Inspection Completed - No Further Action
<u>Violation Code</u>	<u>Observation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only. frying of eggs on small hot plate
	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only. near dishwasher
	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Pinellas County**

License Number: 6213466 CRABBY BILLS TARPON SPRINGS  
 License Type: Permanent Food Service 900 N PINELLAS AVE, TARPON SPRINGS 34689

Inspection Date: 10/22/2009 Inspection Number: 1918881 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: PEARCE, LAURA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-25-2	Hood filters not equipped with a drip tray. For reporting purposes only.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY

License Number: 6214178 T-FLY'S FAMILY SPORTS BAR  
 License Type: Permanent Food Service 224 E TARPON AVE, TARPON SPRINGS 34689

Inspection Date: 10/20/2009 Inspection Number: 1846013 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: PEARCE, LAURA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only. dining room	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

License Number: 6216083 GREEK TAVERN & RESTAURANT INC  
 License Type: Permanent Food Service 210 DODECANESE BLVD, TARPON SPRINGS 34689

Inspection Date: 10/20/2009 Inspection Number: 1866580 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: PEARCE, LAURA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-04-2	Observed frayed/spliced electrical wires. For reporting purposes only. behind microwaves	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6201051 WHISTLE STOP GRILL AND BAR  
 License Type: Permanent Food Service 915 MAIN ST, SAFETY HARBOR 346953455

Inspection Date: 10/20/2009 Inspection Number: 1866426 Inspection Type: Routine - Food Inspection Disposition: Warning Issued  
 Inspector Name: WINSOR, KIMBERLY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-07-2	Observed misalignment of hood suppression system nozzles. For reporting purposes only....salamandar suppression nozzle not pointing towards flame area-pointed outward	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

**Pinellas County**

License Number: 6200165	ATHENS RESTAURANT & ICE CREAM		
License Type: Permanent Food Service	226 MAIN ST, SAFETY HARBOR 346953643		
Inspection Date: 10/16/2009	Inspection Number: 1835679	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WINSOR, KIMBERLY			

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces- -broken by cleaning people-. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6215504	BELLINI RESTAURANT		
License Type: Permanent Food Service	487 MAIN ST, DUNEDIN 34698		
Inspection Date: 10/23/2009	Inspection Number: 1876836	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PEARCE, LAURA			

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only. by back door	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. furniture at side exit by restrooms	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

**Polk County**

License Number: 6305934 CHECKERS  
 License Type: Permanent Food Service 991 E MEMORIAL BLVD, LAKELAND 33801

Inspection Date: 10/19/2009 Inspection Number: 1897794 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: WHITE, RICKY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6301199 MCDONALD'S 6136  
 License Type: Permanent Food Service 1715 S BARTOW RD, LAKELAND 338016553

Inspection Date: 10/20/2009 Inspection Number: 1887471 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: WHITE, RICKY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.

License Number: 6306981 CHINA ONE  
 License Type: Permanent Food Service 2938 LAKELAND HIGHLANDS, LAKELAND 33803

Inspection Date: 10/22/2009 Inspection Number: 1856767 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: WHITE, RICKY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6307789 HAMPTON INN & SUITES LAKELAND-SOUTH POLK PARKWAY  
 License Type: Permanent Food Service 3630 LAKESIDE VILLAGE BLVD, LAKELAND 33803

Inspection Date: 10/19/2009 Inspection Number: 1867029 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: WHITE, RICKY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.



**Polk County**

License Number: 6303440 KFC  
 License Type: Permanent Food Service 401 CYPRESS GARDENS BLVD, WINTER HAVEN 33880

Inspection Date: 10/21/2009 Inspection Number: 1877374 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: WHITE, CHERYL

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-07-2	Observed misalignment of hood suppression system nozzles. Over fryers. For reporting purposes only.	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. By employee door. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6307516 THE PUB  
 License Type: Permanent Food Service 1 CENTURY LN, WINTER HAVEN 33881

Inspection Date: 10/20/2009 Inspection Number: 1866946 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: ROMANO, JIMMIE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-11-2	Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only.	NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

**Putnam County**

License Number: 6400709

D &amp; E'S BACKWOODS BUFFET

License Type: Permanent Food Service

N HWY 17 SEMINOLE ELEC, PALATKA 32177

Inspection Date: 10/20/2009

Inspection Number: 1871035

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: DOHERTY, BRENDEN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke not positioned under hood suppression system. For reporting purposes only. SMALL FRYER ON COUNTERTOP NEAR HANDSINK	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.
48-12-2	No current boiler certification provided/available. For reporting purposes only. Repeat Violation.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 6400745

HUDDLE HOUSE RESTAURANT

License Type: Permanent Food Service

3909 CRILL AVE, PALATKA 32177

Inspection Date: 10/20/2009

Inspection Number: 1840186

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: DOHERTY, BRENDEN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-22-2	Portable fire extinguisher(s) obstructed from view. For reporting purposes only. CLASS K COVERED WITH CLOTHING Corrected On Site.	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.

**Putnam County**

License Number: 6400669

KRYSTAL

License Type: Permanent Food Service

505 N HWY 19, PALATKA 321773033

Inspection Date: 10/20/2009

Inspection Number: 1850673

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: DOHERTY, BRENDEN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-40-2	Hood system bearing expired inspection tag. For reporting purposes only.	61C-1.004(9)(b) FAC and NFPA 10, 6.3.4 A standard state approved service tag shall be attached to each extinguisher and a person holding a valid state permit issued by the State Fire Marshal shall recharge or inspect the extinguisher and shall prepare the tag to include the information required by rule 4A-21.241, FAC, herein adopted by reference. Maintenance Recordkeeping. Each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was performed and that identifies the person performing the service. FOR REPORTING PURPOSES ONLY.
45-40-2	Portable fire extinguisher with expired inspection tag. For reporting purposes only.	61C-1.004(9)(b) FAC and NFPA 10, 6.3.4 A standard state approved service tag shall be attached to each extinguisher and a person holding a valid state permit issued by the State Fire Marshal shall recharge or inspect the extinguisher and shall prepare the tag to include the information required by rule 4A-21.241, FAC, herein adopted by reference. Maintenance Recordkeeping. Each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was performed and that identifies the person performing the service. FOR REPORTING PURPOSES ONLY.

**Santa Rosa County**

License Number: 6701334

RYANS STEAKHOUSE

License Type: Permanent Food Service

4955 HWY 90, PACE 32571

Inspection Date: 10/16/2009

Inspection Number: 1901964

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: WINN, RONALD

Violation Code

Observation

Violation Citation

47-03-2

Observed unused opening in panel box unprotected. For reporting purposes only.

NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.

**Sarasota County**

License Number: 6803489		CAFE BACI	
License Type: Permanent Food Service		4001 S TAMIAMI TRL, SARASOTA 342313647	
Inspection Date: 10/20/2009	Inspection Number: 1913221	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DILLARD, FRANK			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 6800167		GULF GATE GOLF CLUB	
License Type: Permanent Food Service		2550 BISPHAM RD, SARASOTA 342315727	
Inspection Date: 10/21/2009	Inspection Number: 1913231	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DILLARD, FRANK			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. B C extinguisher on floor in kitchen .	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
License Number: 6803816		MCDONALDS #13787	
License Type: Permanent Food Service		4301 N WASHINGTON BLVD, SARASOTA 342344801	
Inspection Date: 10/19/2009	Inspection Number: 1883159	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: POSA, ANTHONY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-12-2	Observed trouble/alarm light lighted on fire alarm control panel. For reporting purposes only.	NFPA 72, 7.1.1.1, 7.3.1 and 7.4.3 Inspection, testing, and maintenance programs shall satisfy the requirements of this code, conform to the equipment manufacturer's recommendations, and verify proper operation of the fire alarm system. Visual Inspection. Visual Inspection shall be performed in accordance with the schedules in this chapter or more frequently where required by the authority having jurisdiction. The visual inspection shall be made to ensure that there are no changes that can affect equipment performance. All apparatus requiring rewinding or resetting to maintain normal operation shall be restored to normal as promptly as possible after each test and alarm and kept in normal condition for operation. All test signals received shall be recorded to indicate date, time, and type. FOR REPORTING PURPOSES ONLY.	
License Number: 6803895		HO'S GARDEN	
License Type: Permanent Food Service		3234 17 ST, SARASOTA 34235	
Inspection Date: 10/20/2009	Inspection Number: 1852430	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: POSA, ANTHONY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-38-2	Portable fire extinguisher not fully charged in storeroom. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	



**Sarasota County**

License Number: 6804473 SARASOTA BAY CLUB  
 License Type: Permanent Food Service 1301 N TAMIAMI TRL, SARASOTA 34236

Inspection Date: 10/23/2009 Inspection Number: 1841292 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: POSA, ANTHONY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 6802129 CHUTNEY'S ETC  
 License Type: Permanent Food Service 1944 HILLVIEW ST, SARASOTA 342393607

Inspection Date: 10/23/2009 Inspection Number: 1861917 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: DILLARD, FRANK

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. ABC extinguisher on floor in kitchen . Corrected On Site.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

**Seminole County**

License Number: 6903672

CHINA FIRST BUFFET

License Type: Permanent Food Service

691 E ALTAMONTE DR, ALTAMONTE SPGS 32701

Inspection Date: 10/21/2009

Inspection Number: 1848839

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: WATSON, DENNIS

Violation CodeObservationViolation Citation

48-12-2

No current boiler certification provided/available.Expired 10-1-09 For reporting purposes only.

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 6904772

CHIPOTLE

License Type: Permanent Food Service

5637 RED BUG LAKE RD, WINTER SPRINGS 32708

Inspection Date: 10/21/2009

Inspection Number: 1915473

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PLEICONES, KIM

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6903754

TAQUERIA TACO RIENDO #2 INC

License Type: Permanent Food Service

1156 W SR 436 STE 9, ALTAMONTE SPGS 32714

Inspection Date: 10/15/2009

Inspection Number: 1848773

Inspection Type: Routine - Food

Inspection Disposition: Call Back - Admin. complaint recommended

Inspector Name: CHIU, CECILIA

Violation CodeObservationViolation Citation

47-05-2

Violation: 47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only.  
Kitchen

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Seminole County**

License Number: 6903629

JOE'S CRAB SHACK

License Type: Permanent Food Service

4659 W STATE ROAD 46, SANFORD 32771

Inspection Date: 10/23/2009

Inspection Number: 1920167

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: ANGEL, TERRY

Violation CodeObservationViolation Citation

46-02-2

Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. Hasp on walk-in cooler door.

NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.

License Number: 6903384

BBEE'S HOME COOKING INC

License Type: Permanent Food Service

2511 SANFORD AVE, SANFORD 32773

Inspection Date: 10/19/2009

Inspection Number: 1889588

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: MANTI, KATHRYN

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

15-28-2

Violation: 15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6903668

SERGIOS ITALIAN REST

License Type: Permanent Food Service

2895 S ORLANDO DR, SANFORD 32773

Inspection Date: 10/19/2009

Inspection Number: 1889562

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: MANTI, KATHRYN

Violation CodeObservationViolation Citation

45

Out of compliance: Fire extinguishers - proper and sufficient

NFPA 101, 96, 10 Fire extinguishers - proper and sufficient

**St. Johns County**

License Number: 6501762		THE BACK FORTY CAFE	
License Type: Permanent Food Service		40 S DIXIE HWY, SAINT AUGUSTINE 32084	
Inspection Date: 10/19/2009	Inspection Number: 1911653	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: GOSAI, MATT			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-08-2	Observed electrical wiring in disrepair. For reporting purposes only. LOOSE ELECTRIC BOX. PREPLINE	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6501691		GEORGIE'S DINER	
License Type: Permanent Food Service		100 MALAGA ST, ST AUGUSTINE 32084	
Inspection Date: 10/21/2009	Inspection Number: 1911627	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GOSAI, MATT			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 6501813		SIDELINES	
License Type: Permanent Food Service		4010 US HWY 1 SOUTH #116, SAINT AUGUSTINE 32086	
Inspection Date: 10/19/2009	Inspection Number: 1860300	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GOSAI, MATT			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. LATCH ADDED TO PANIC BAR ON BOT EXIT DOORS	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	

**St. Lucie County**

License Number: 6600072		ARCHIES SEABREAZE	
License Type: Permanent Food Service		401 S OCEAN DR, FT PIERCE 349493256	
Inspection Date: 10/19/2009	Inspection Number: 1847729	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DAVIS, DIANNA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period-orange cord at cookline. For reporting purposes only. Repeat Violation.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6602096		BOOMER'S PLACE	
License Type: Permanent Food Service		4812 NORTH KINGS HWY, FORT PIERCE 34951	
Inspection Date: 10/15/2009	Inspection Number: 1909158	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: ONELL, DANIEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair	
License Number: 6600835		GATWICK'S RESTAURANT & BANQUET AREA	
License Type: Permanent Food Service		10120 S FEDERAL HWY, PORT ST LUCIE 34952	
Inspection Date: 10/20/2009	Inspection Number: 1888713	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PARNASS, LAUREN P			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
48-12-2	No current boiler certification provided/available. For reporting purposes only. Repeat Violation. Observed paid invoice for Division of State Fire Marshal's office, dated 09/29/09.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.	

**St. Lucie County**

License Number: 6602490

CARBONES ITALIAN

License Type: Permanent Food Service

8950 S US HWY 1, PORT ST LUCIE 34952

Inspection Date: 10/22/2009

Inspection Number: 1868294

Inspection Type: Routine - Food

Inspection Disposition: Warning  
Issued

Inspector Name: PARNASS, LAUREN P

Violation CodeObservationViolation Citation

37-20-2 Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor, ABC extinguisher sitting on dry food storage shelf near the mop sink. For reporting purposes only. Repeat Violation.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6602728

GOODFELLAS PIZZA PASTA SUBS #111 INC

License Type: Permanent Food Service

7550 S US 1, PORT ST LUCIE 34952

Inspection Date: 10/22/2009

Inspection Number: 1847821

Inspection Type: Routine - Food

Inspection Disposition: Warning  
Issued

Inspector Name: PARNASS, LAUREN P

Violation CodeObservationViolation Citation

45-07-2 Observed misalignment of hood suppression system nozzles, fryer not under nozzle coverage. For reporting purposes only. Repeat Violation.

NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

License Number: 6602887

SANDPIPER GOLF CLUB RESTAURANT

License Type: Permanent Food Service

4500 SE PINE VALLEY DR, PORT ST LUCIE 34952

Inspection Date: 10/20/2009

Inspection Number: 1878583

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: PARNASS, LAUREN P

Violation CodeObservationViolation Citation

39-05-2 Ventilation inadequate as evidenced by smoke in kitchen area. For reporting purposes only.

NFPA 96, 4.1.1 Cooking equipment used in processes producing smoke or grease-laden vapors shall be equipped with an exhaust system that complies with all the equipment and performance requirements of this standard; and NFPA 96, 8.2.2 Air Volume. NFPA 96, 8.2.2.1: Exhaust air volumes for hoods shall be of a sufficient level to provide for capture and removal of grease-laden cooking vapors. FOR REPORTING PURPOSES ONLY

**Sumter County**

License Number: 7000443

CODYS ORIGINAL ROADHOUSE

License Type: Permanent Food Service

1041 LAKESHORE DRIVE, THE VILLAGES 32162

Inspection Date: 10/21/2009

Inspection Number: 1919195

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DANCHO, JOHN

Violation CodeObservationViolation Citation

47-15-2

Observed an uncovered electrical box....near office.For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 7000164

HOWIE'S FAMILY RESTAURANT

License Type: Permanent Food Service

840 N MAIN ST, BUSHNELL 33513

Inspection Date: 10/22/2009

Inspection Number: 1836677

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DANCHO, JOHN

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor.....K Class in kitchen.For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 7000205

LISA'S PLACE

License Type: Permanent Food Service

524 N MARKET BLVD, WEBSTER 33597

Inspection Date: 10/19/2009

Inspection Number: 1857300

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DANCHO, JOHN

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

47-03-2

Observed unused opening in panel box unprotected. For reporting purposes only.

NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.

**Sumter County**

License Number: 7050114

S & S CATERING

License Type: Mobile Food Dispensing Vehicle

WEBSTER FLEA MARKET, WEBSTER 33597

Inspection Date: 10/19/2009

Inspection Number: 1134693

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DANCHO, JOHN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-26-2	Observed exhaust system operated with filters removed. For reporting purposes only.	NFPA 96, 11.1.2 Filter-equipped exhaust systems shall not be operated with filters removed. For reporting purposes only.
45-25-2	No 2A10BC portable fire extinguisher installed for an ordinary hazard. For reporting purposes only.	NFPA 10, 5.2.1, 5.3.1 and 5.5 Minimal sizes of fire extinguishers for the listed grades of hazards shall be provided on the basis of Table 5.2.1, except as modified by 5.2.2. Fire extinguishers shall be located so that the maximum travel distances shall not exceed those specified in Table 5.2.1, except as modified by 5.2.2. Table 5.2.1 Fire Extinguisher Size and Placement for Class A Hazards Criteria Light (Low) Hazard Occupancy Ordinary Minimum rated single extinguisher 2-A Maximum floor area per unit of A 3000 ft <sup>2</sup> Maximum floor area for extinguisher 11,250 ft <sup>2</sup> Maximum travel distance to extinguisher 75 ft. (Moderate) Hazard Occupancy Minimum rated single extinguisher 2-A Maximum floor area per unit of A 1500 ft <sup>2</sup> Maximum floor area for extinguisher 11,250 ft <sup>2</sup> Maximum travel distance to extinguisher 75 ft. Extra (High) Hazard Occupancy Minimum rated single extinguisher 4-A Maximum floor area per unit of A 1000 ft <sup>2</sup> Maximum floor area for extinguisher 11,250 ft <sup>2</sup> Maximum travel distance to extinguisher 75 ft. Minimal sizes of fire extinguishers for the listed grades of hazard shall be provided on the basis of Table 5.3.1. Fire extinguishers shall be located so that the maximum travel distances do not exceed those specified in the table used. Table 5.3.1 Fire Extinguisher Size and Placement for Class B Hazards Light (low) Minimum Extinguisher Rating 10-B Maximum Travel Distance to Extinguishers 50 ft. Ordinary (moderate) Minimum Extinguisher Rating 10-B Maximum Travel Distance to Extinguishers 30 ft. Extra (high) Minimum Extinguisher Rating 40-B Maximum Travel Distance to Extinguishers 30 ft. Fire Extinguisher Size and Placement for Class C Hazards. Fire extinguishers with Class C ratings shall be required where energized electrical equipment can be encountered. This requirement includes situations where fire either directly involves or surrounds electrical equipment. Since the fire itself is a Class A or Class B hazard, the fire extinguishers shall be sized and located on the basis of the anticipated Class A or Class B hazard. FOR REPORTING PURPOSES ONLY.

**Sumter County**

License Number: 7050124

AGATHA I

License Type: Mobile Food Dispensing Vehicle

WEBSTER FLEA MARKET, WEBSTER 33597

Inspection Date: 10/19/2009

Inspection Number: 1135997

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DANCHO, JOHN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
47-03-2	Observed unused opening in panel box unprotected. For reporting purposes only.	NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.
48-20-2	Observed loose/unsecured LP-gas tank on mobile food dispensing vehicle. For reporting purposes only.	NFPA 58, 3.8.2.4 Containers shall be mounted securely on the vehicle, or within the enclosing recess or cabinet, and shall be located and installed so as to minimize the possibility of damage to containers, their appurtenances, or contents as follows: (a) Containers shall be installed with road clearance in accordance with 8-2.6.5. (b) Fuel containers shall be mounted securely to prevent jarring loose and slipping or rotating, and the fastenings shall be designed and constructed to withstand, without permanent visible deformation, static loading in any direction equal to four times the weight of the container filled with fuel. Where containers are mounted within a vehicle housing, the securing of the housing to the vehicle shall comply with this provision. Any hoods, domes, or removable portions of the housing or cabinet shall be provided with means to keep them firmly in place in transit. Field welding shall comply with 3-2.4.1(e). (c) All container valves, appurtenances, and connections shall be adequately protected to prevent damage from accidental contacts with stationary objects, from loose objects, stones, mud, or ice thrown up from the ground or floor, and from damage due to overturn or similar vehicular accident. In the case of permanently mounted ASME containers, this provision shall be met by the location on the vehicle, with parts of the vehicle furnishing the protection. On cylinders, the protection for cylinder valves and connections shall be attached permanently to the cylinder (see 2-2.4.1 and 2-2.4.2). Such weather protection necessary to ensure safe operation shall be provided for cylinders and systems mounted on the outside of vehicles. FOR REPORTING PURPOSES ONLY.

**Sumter County**

License Number: 7050125

OLD FASHIONED CREAM PUFFS

License Type: Mobile Food Dispensing Vehicle

WEBSTER FLEA MARKET, WEBSTER 33597

Inspection Date: 10/19/2009

Inspection Number: 1134053

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DANCHO, JOHN

Violation Code

Observation

Violation Citation

48-20-2 Observed loose/unsecured LP-gas tank on mobile food dispensing vehicle. For reporting purposes only.

NFPA 58, 3.8.2.4 Containers shall be mounted securely on the vehicle, or within the enclosing recess or cabinet, and shall be located and installed so as to minimize the possibility of damage to containers, their appurtenances, or contents as follows: (a) Containers shall be installed with road clearance in accordance with 8-2.6.5. (b) Fuel containers shall be mounted securely to prevent jarring loose and slipping or rotating, and the fastenings shall be designed and constructed to withstand, without permanent visible deformation, static loading in any direction equal to four times the weight of the container filled with fuel. Where containers are mounted within a vehicle housing, the securing of the housing to the vehicle shall comply with this provision. Any hoods, domes, or removable portions of the housing or cabinet shall be provided with means to keep them firmly in place in transit. Field welding shall comply with 3-2.4.1(e). (c) All container valves, appurtenances, and connections shall be adequately protected to prevent damage from accidental contacts with stationary objects, from loose objects, stones, mud, or ice thrown up from the ground or floor, and from damage due to overturn or similar vehicular accident. In the case of permanently mounted ASME containers, this provision shall be met by the location on the vehicle, with parts of the vehicle furnishing the protection. On cylinders, the protection for cylinder valves and connections shall be attached permanently to the cylinder (see 2-2.4.1 and 2-2.4.2). Such weather protection necessary to ensure safe operation shall be provided for cylinders and systems mounted on the outside of vehicles. FOR REPORTING PURPOSES ONLY.

**Suwannee County**

License Number: 7100267 CUZIN'S CAFE  
 License Type: Permanent Food Service 109 SAVANNAH ST SW, BRANFORD 32008

Inspection Date: 10/19/2009 Inspection Number: 1859828 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action  
 Inspector Name: HENTGES, JUDY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. Heat Lamp	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 7100285 BB ANN'S COUNTRY KITCHEN PUB & ARCADE  
 License Type: Permanent Food Service 2953 CR 136, WHITE SPRINGS 32096

Inspection Date: 10/20/2009 Inspection Number: 1849879 Inspection Type: Routine - Food Inspection Disposition: Call Back - Complied  
 Inspector Name: HENTGES, JUDY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Violation: 47-06-2  Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

**Volusia County**

License Number: 7405729

GENE'S STEAK HOUSE

License Type: Permanent Food Service

3674 US HWY 92, DAYTONA BCH 32114

Inspection Date: 10/20/2009

Inspection Number: 1889456

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: BRANNER, LISELOTTE

Violation CodeObservationViolation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor/on floor by walkin. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

46-12-2 Emergency lighting illumination insufficient/kitchen. For reporting purposes only.

NFPA 101, 7.9.2.1 Emergency lighting facilities shall be arranged to provide initial illumination that is not less than an average of 1 foot-candle and, at any point, not less than 0.1 foot-candles, measured along the path of egress at floor level. FOR REPORTING PURPOSES ONLY.

License Number: 7406716

TASTE OF THE TROPICS SEAFOOD &amp; GRILL INC

License Type: Permanent Food Service

933 W INTERNATIONAL SPDWY BLVD, DAYTONA BEACH 32114

Inspection Date: 10/20/2009

Inspection Number: 1848574

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: BRANNER, LISELOTTE

Violation CodeObservationViolation Citation

48-10-2 Gas appliance lacking seal (AGA/UL, etc.)/water heater. For reporting purposes only.

61C-1.004(13)(a) FAC Gas appliances. All appliances, including water heaters using gas, shall be kept in good repair and properly vented when manufacturers' instructions require venting of the appliance and shall meet the following requirements: (a) All appliances shall have a nationally recognized testing laboratory seal such as AGA or UL seal. FOR REPORTING PURPOSES ONLY.

License Number: 7406869

TROP TWILITE

License Type: Permanent Food Service

827 S DR MARTIN LUTHER KING BLVD, DAYTONA BEACH 32114

Inspection Date: 10/19/2009

Inspection Number: 1858697

Inspection Type: Routine - Food

Inspection Disposition: Warning  
Issued

Inspector Name: BRANNER, LISELOTTE

Violation CodeObservationViolation Citation

46-02-2 Observed lock on exit door that requires a key, tool or special knowledge to open/hasp and lock on storage room door. For reporting purposes only.

NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.

49-06-2 Observed flammable material stored around water heater. For reporting purposes only. Corrected On Site.

61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

**Volusia County**

License Number: 7406142

DOGHOUSE

License Type: Permanent Food Service

601 MAIN ST, DAYTONA BEACH 32118

Inspection Date: 10/22/2009

Inspection Number: 1848462

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: BARRETT, KAREN

Violation CodeObservationViolation Citation

45-39-2	Portable fire extinguisher size K not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. upstairs bar. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
48-06-2	Observed a gas appliance without proper venting. Noticed strong odor of gas coming from behind the American Range area For reporting purposes only.	61C-1.004(13)(a) FAC Gas appliances. All appliances, including water heaters using gas, shall be kept in good repair and properly vented when manufacturers' instructions require venting of the appliance and shall meet the following requirements: (a) All appliances shall have a nationally recognized testing laboratory seal such as AGA or UL seal. FOR REPORTING PURPOSES ONLY.

License Number: 7403841

WHISTLE JUNCTION - SOUTH DAYTONA BEACH

License Type: Permanent Food Service

1854 S RIDGEWOOD AVE, SOUTH DAYTONA BEACH 32119

Inspection Date: 10/22/2009

Inspection Number: 1838097

Inspection Type: Routine - Food

Inspection Disposition: Inspection  
Completed - No Further Action

Inspector Name: LARSON, SARAH

Violation CodeObservationViolation Citation

45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
---------	---	---

**Volusia County**

License Number: 7403741		KENTUCKY FRIED CHICKEN #434	
License Type: Permanent Food Service		1035 DUNLAWTON AVE, PORT ORANGE 32127-4708	
Inspection Date: 10/20/2009	Inspection Number: 1868924	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: LARSON, SARAH			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
License Number: 7405965		CHINA WOK	
License Type: Permanent Food Service		102 W INDIAN RIVER BLVD, EDGEWATER 32132	
Inspection Date: 10/19/2009	Inspection Number: 1900395	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: ZALESKI, AMY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
49-06-2	Observed combustible material- cardboard boxes stored around water heater. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.	
License Number: 7403792		SUBWAY	
License Type: Permanent Food Service		1922 SR 44, NEW SMYRNA BEACH 32168	
Inspection Date: 10/21/2009	Inspection Number: 1838116	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: LARSON, SARAH			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
License Number: 7405248		JASON'S CORNER DELI	
License Type: Permanent Food Service		135 CANAL ST, NEW SMYRNA BCH 32168-7067	
Inspection Date: 10/20/2009	Inspection Number: 1858637	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: LARSON, SARAH			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

**Volusia County**

License Number: 7400575		AIRPORT RESTAURANT	
License Type: Permanent Food Service		1120 FLIGHT LINE BLVD, DELAND 327242112	
Inspection Date: 10/21/2009	Inspection Number: 1879354	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BRASKA, GEORGIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters missing during operation. Cook advised she had it out for cleaning. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
47-06-2	Observed extension cord in use for non-temporary period, in kitchen For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 7405833		HONG KONG BUFFET	
License Type: Permanent Food Service		852 SAXON BLVD STE 32-34, ORANGE CITY 32763	
Inspection Date: 10/22/2009	Inspection Number: 1869089	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BRASKA, GEORGIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Repeat Violation.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

License Number: 7406363		TONY'S NY PIZZA	
License Type: Permanent Food Service		864 SAXON BLVD STE 36/37, ORANGE CITY 32763	
Inspection Date: 10/22/2009	Inspection Number: 1879326	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BRASKA, GEORGIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor ABC type by back door For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	



**Walton County**

License Number: 7601873

ANOTHER BROKEN EGG CAFE

License Type: Permanent Food Service

9100 BAYTOWNE WHARF BLVD4, SANDESTIN 32550

Inspection Date: 10/21/2009

Inspection Number: 1912365

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: VINCENT, STACEY

Violation Code

Observation

Violation Citation

45-02-1

Sprinkler head spray pattern obstructed. For reporting purposes only.

NFPA 25, 5.2.1.2:: Unacceptable obstructions to spray patterns shall be corrected.