

Alachua County

License Number: 1102931 SAIGON LEGEND
 License Type: Permanent Food Service 1228 W UNIVERSITY, GAINESVILLE 32601

Inspection Date: 11/03/2009 Inspection Number: 1870991 Inspection Type: Routine - Food Inspection Disposition: Call Back -
 Inspector Name: DOHERTY, BRENDEN Complied

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-38-2	Violation: 45-38-2 Portable fire extinguisher not fully charged. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.
45-39-2	Violation: 45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
45-40-2	Violation: 45-40-2 Portable fire extinguisher with expired inspection tag. For reporting purposes only.	61C-1.004(9)(b) FAC and NFPA 10, 6.3.4 A standard state approved service tag shall be attached to each extinguisher and a person holding a valid state permit issued by the State Fire Marshal shall recharge or inspect the extinguisher and shall prepare the tag to include the information required by rule 4A-21.241, FAC, herein adopted by reference. Maintenance Recordkeeping. Each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was performed and that identifies the person performing the service. FOR REPORTING PURPOSES ONLY.

License Number: 1102039 BURGER KING #0056
 License Type: Permanent Food Service 20 NW 16 AVE, GAINESVILLE 326013776

Inspection Date: 11/03/2009 Inspection Number: 1860715 Inspection Type: Routine - Food Inspection Disposition: Inspection
 Inspector Name: DOHERTY, BRENDEN Completed - No Further Action

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 1102839 JIMMY JOHN'S GOURMET SANDWICHES
 License Type: Permanent Food Service 1724 W UNIVERSITY AVE, GAINESVILLE 32603

Inspection Date: 11/05/2009 Inspection Number: 1869985 Inspection Type: Routine - Food Inspection Disposition: Inspection
 Inspector Name: FULTON, DANIEL Completed - No Further Action

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. ON THE FLOOR .For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Alachua County

License Number: 1102856

TIJUANA FLATS BURRITO COMPANY

License Type: Permanent Food Service

1720 W UNIVERSITY AVE, GAINESVILLE 32603

Inspection Date: 11/05/2009

Inspection Number: 1839089

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: FULTON, DANIEL

Violation CodeObservationViolation Citation

47-06-2

Observed electrical cord in use under register covered with slim, setting in water.
For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1102274

BALLYHOO GRILL

License Type: Permanent Food Service

3700 NEWBERRY, GAINESVILLE 32607

Inspection Date: 11/05/2009

Inspection Number: 1839317

Inspection Type: Routine - Food

Inspection Disposition: Administrative
complaint recommended

Inspector Name: FULTON, DANIEL

Violation CodeObservationViolation Citation

46-05-2

Observed obstructed exits, stairs, hallways or egress. BAR. For reporting
purposes only.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 1102566

SUBWAY #18269

License Type: Permanent Food Service

19975 NW 244 ST UNIT #20, HIGH SPRINGS 32643

Inspection Date: 11/02/2009

Inspection Number: 1839202

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: BROWNING, JULIANNE

Violation CodeObservationViolation Citation

45

Out of compliance: Fire extinguishers - proper and sufficient

NFPA 101, 96, 10 Fire extinguishers - proper and sufficient

Brevard County

License Number: 1506133	NEW PEKING BUFFET		
License Type: Permanent Food Service	725 N WASHINGTON AVE, TITUSVILLE 32796		
Inspection Date: 11/04/2009	Inspection Number: 1890024	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: ZALESKI, AMY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
49-06-2	Observed combustible material- cardboard boxes stored around water heater. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.	

License Number: 1506192	FISHERMAN'S WORLD PC		
License Type: Permanent Food Service	602 GLEN CHEEK DR, CAPE CANAVERAL 32920		
Inspection Date: 11/05/2009	Inspection Number: 1919923	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: MAYNARD, DIANE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-04-2	Observed frayed/spliced electrical wires. For reporting purposes only.by ice bin outside	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
47-04-2	Observed frayed/spliced electrical wires. For reporting purposes only.bathroom womens	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Brevard County

License Number: 1501452

GRAHAM'S BEACH GRILL

License Type: Permanent Food Service

5920 N. ATLANTIC AVE., COCOA BEACH 32931

Inspection Date: 11/05/2009

Inspection Number: 1847837

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: MAYNARD, DIANE

Violation CodeObservationViolation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.liquor room

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.behind ice bin

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-12-2 No ground fault interruption protection on electrical outlet located within six feet of a water source. For reporting purposes only.over 3 bin sink

NFPA 70, 210.8 Ground-Fault Circuit-Interrupter Protection for Personnel. (A) Dwelling Units. All 125-volt, single-phase, 15- and 20-ampere receptacles installed in the locations specified shall have ground-fault circuit-interrupter protection for personnel. (1) Bathrooms; (6) Kitchens - where the receptacles are installed to serve the countertop surfaces; (7) Wet bar sinks - where the receptacles are installed to serve the countertop surfaces and are located within 6 ft of the outside edge of the wet bar sink. (B) Other Than Dwelling Units. All 125-volt, single-phase, 15- and 20-ampere receptacles installed in the locations specified in (1), (2), and (3) shall have ground-fault circuit-interrupter protection for personnel: (1) Bathrooms; (2) Rooftops; Exception: Receptacles that are not readily accessible and are supplied from a dedicated branch circuit for electric snow-melting or deicing equipment shall be permitted to be installed in accordance with the applicable provisions of Article 426. (3) Kitchens. FOR REPORTING PURPOSES ONLY.

License Number: 1501737

BIG SURF CAFE

License Type: Permanent Food Service

3210 S A1A, COCOA BEACH 32931-2194

Inspection Date: 10/30/2009

Inspection Number: 1899091

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: MAYNARD, DIANE

Violation CodeObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Brevard County

License Number: 1505685

JOY LUCK

License Type: Permanent Food Service

125 E. MERRITT ISLAND CSWY STE 117, MERRITT ISLAND 32952

Inspection Date: 11/04/2009

Inspection Number: 1879898

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: PFISTER, JOHN

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 1504825

DAVES SNACK SHOP

License Type: Permanent Food Service

920 ROCKLEDGE AVE, ROCKLEDGE 32955

Inspection Date: 10/30/2009

Inspection Number: 1847369

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: WOODS, CRYSTAL

Violation CodeObservationViolation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

Broward County

License Number: 1601136		ACQUOLINA	
License Type: Permanent Food Service		124 S FEDERAL HWY, HALLANDALE 33009	
Inspection Date: 11/04/2009	Inspection Number: 1920792	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CONSIGLIO, CAMILLE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-08-2	Observed electrical wiring in draped across hw sink front. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 1651864		BEACH SOUTH	
License Type: Mobile Food Dispensing Vehicle		2805 E HALLANDALE BEACH BLVD, HALLANDALE 33009	
Inspection Date: 11/04/2009	Inspection Number: 1135180	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CONSIGLIO, CAMILLE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-40-2	Portable fire extinguisher with no approved inspection tag. For reporting purposes only.k. class	61C-1.004(9)(b) FAC and NFPA 10, 6.3.4 A standard state approved service tag shall be attached to each extinguisher and a person holding a valid state permit issued by the State Fire Marshal shall recharge or inspect the extinguisher and shall prepare the tag to include the information required by rule 4A-21.241, FAC, herein adopted by reference. Maintenance Recordkeeping. Each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was performed and that identifies the person performing the service. FOR REPORTING PURPOSES ONLY.	
45-40-2	Portable fire extinguisher approved inspection tag not readable. For reporting purposes only.	61C-1.004(9)(b) FAC and NFPA 10, 6.3.4 A standard state approved service tag shall be attached to each extinguisher and a person holding a valid state permit issued by the State Fire Marshal shall recharge or inspect the extinguisher and shall prepare the tag to include the information required by rule 4A-21.241, FAC, herein adopted by reference. Maintenance Recordkeeping. Each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was performed and that identifies the person performing the service. FOR REPORTING PURPOSES ONLY.	
License Number: 1621824		JIMBOS SAND BAR INC	
License Type: Permanent Food Service		6200 N OCEAN DR, HOLLYWOOD 33019	
Inspection Date: 11/04/2009	Inspection Number: 1854131	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: CONSIGLIO, CAMILLE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.rear storage	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Broward County

License Number: 1601038		ORIENT TAKEOUT RESTAURANT	
License Type: Permanent Food Service		2021 PEMBROKE RD, HOLLYWOOD 33020	
Inspection Date: 11/05/2009	Inspection Number: 1884896	Inspection Type: Complaint Full	Inspection Disposition: Warning Issued
Inspector Name: CHAPDELAINE, MARIE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only--fish-tank, freezers.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 1617281		OVER THE TOP CATERING	
License Type: Permanent Food Service		116 N 46 AVE, HOLLYWOOD 33021	
Inspection Date: 11/02/2009	Inspection Number: 1864528	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: CHAPDELAINE, MARIE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only--hot holding serving buffet.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 1622270		LEVY'S KOSHER OF HOLLYWOOD	
License Type: Permanent Food Service		3357 SHERIDAN ST, HOLLYWOOD 33021	
Inspection Date: 11/06/2009	Inspection Number: 1895132	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CHAPDELAINE, MARIE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only--freezer-prep room--use overload protector.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Broward County

License Number: 1622097

LE TAPIOCA & SANDWICH

License Type: Permanent Food Service

136 S SR 7, HOLLYWOOD 33023

Inspection Date: 11/02/2009

Inspection Number: 1884843

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: QUINONES, JOSE

Violation CodeObservationViolation Citation

45-31-2

Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only. portable stoves.

NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

License Number: 1620953

LA MANNE RESTAURANT INC

License Type: Permanent Food Service

7108 PEMBROKE ROAD, MIRAMAR 33023

Inspection Date: 11/02/2009

Inspection Number: 1833464

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: QUINONES, JOSE

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1621197

TROPICAL OASIS RESTAURANT

License Type: Permanent Food Service

9017 PINES BLVD, PEMBROKE PINES 33024

Inspection Date: 10/30/2009

Inspection Number: 1895034

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: QUINONES, JOSE

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Broward County

License Number: 1612778

SUBWAY #1515

License Type: Permanent Food Service

3364 S UNIVERSITY DR, MIRAMAR 330253017

Inspection Date: 11/05/2009

Inspection Number: 1843761

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Complied

Inspector Name: VASQUEZ, JANNETH

Violation CodeObservationViolation Citation

45-39-2

Violation: 45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

47-06-2

Violation: 47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1621119

ORIENT CHEF

License Type: Permanent Food Service

17155 MIRAMAR PKWY, MIRAMAR 33027

Inspection Date: 11/06/2009

Inspection Number: 1874510

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: VASQUEZ, JANNETH

Violation CodeObservationViolation Citation

45-13-2

No proof of hood cleaning performed by cleaning service. For reporting purposes only.

NFPA 96, 11.4.12 When a vent cleaning service is used, a certificate showing date of inspection or cleaning shall be maintained on the premises. FOR REPORTING PURPOSES ONLY.

License Number: 1621174

SUBWAY # 28591

License Type: Permanent Food Service

17137 MIRAMAR PKWY, MIRAMAR 33027

Inspection Date: 11/06/2009

Inspection Number: 1884767

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: VASQUEZ, JANNETH

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Broward County

License Number: 1620912 MCDONALD'S
 License Type: Permanent Food Service 17001 MIRAMAR PKWY, MIRAMAR 33029

Inspection Date: 11/06/2009 Inspection Number: 1874526 Inspection Type: Training Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: VASQUEZ, JANNETH

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-09-2	One pull station 's pin for fire suppression system in disrepair. For reporting purposes only.	NFPA 96, 10.5.1 A readily accessible means for manual activation shall be located between 42 inches and 48 inches above the floor, be accessible in the event of a fire, be located in a path of egress, and clearly identify the hazard protected. FOR REPORTING PURPOSES ONLY.

License Number: 1617858 ANNIE'S PIZZA & SUBS
 License Type: Permanent Food Service 2524 N SR 7, POMPANO BEACH 33063

Inspection Date: 11/03/2009 Inspection Number: 1844534 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended
 Inspector Name: DIEHL, TERENCE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. WEST HALLWAY.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 1601623 CHINA DRAGON RESTAURANT
 License Type: Permanent Food Service 4051 N FEDERAY HWY, POMPANO BEACH 33064

Inspection Date: 11/04/2009 Inspection Number: 1865062 Inspection Type: Routine - Food Inspection Disposition: Administrative complaint recommended
 Inspector Name: BECKER, ROBERT

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use throughout kitchen for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Broward County

License Number: 1617512 EBAR/ CLUB BAR 13/ EL CARNIVALE
 License Type: Permanent Food Service 209 - 215 SW 2 ST, FORT LAUDERDALE 33301

Inspection Date: 11/04/2009 Inspection Number: 1920042 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: LEWIS, LYNDEN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-30-2	No Class K portable fire extinguisher provided for high hazard cooking area (for suppression system/equipment installed after June 30, 1998). For reporting purposes only.	NFPA 10, 4.3.2. and 4.3.2.1 Class K Fire Extinguishers for Cooking Oil Fires. Fire extinguishers provided for the protection of cooking appliances that use combustible cooking media (vegetable or animal oils and fats) shall be listed and labeled for Class K fires. Class K fire extinguishers manufactured after January 1, 2002, shall not be equipped with extended wand-type discharge devices. Fire extinguishers installed specifically for the protection of cooking appliances that use combustible cooking media (animal, vegetable oils and fats) prior to June 30, 1998, shall not be required to comply with 4.3.2. (Also see 4.3.2.3.). FOR REPORTING PURPOSES ONLY.
45-40-2	Portable fire extinguisher with no approved inspection tag. For reporting purposes only. Kitchen	61C-1.004(9)(b) FAC and NFPA 10, 6.3.4 A standard state approved service tag shall be attached to each extinguisher and a person holding a valid state permit issued by the State Fire Marshal shall recharge or inspect the extinguisher and shall prepare the tag to include the information required by rule 4A-21.241, FAC, herein adopted by reference. Maintenance Recordkeeping. Each fire extinguisher shall have a tag or label securely attached that indicates the month and year the maintenance was performed and that identifies the person performing the service. FOR REPORTING PURPOSES ONLY.

License Number: 1611050 POP ROCK SUSHI CAFE
 License Type: Permanent Food Service 2831 E OAKLAND PARK BLVD, FT LAUDERDALE 333061813

Inspection Date: 11/05/2009 Inspection Number: 1885305 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: MERNO, RAHLIBA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 1620839 THAI BAYSHORE RESTAURANT
 License Type: Permanent Food Service 4838 N FEDERAL HWY, FORT LAUDERDALE 33308

Inspection Date: 11/02/2009 Inspection Number: 1834048 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: MERNO, RAHLIBA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY
37-20-2	Violation: 37-20-2 Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

Broward County

License Number: 1612853 JAX HOUSE OF RIBS
 License Type: Permanent Food Service 5401 POWERLINE RD, FORT LAUDERDALE 33309

Inspection Date: 11/04/2009 Inspection Number: 1855724 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: SCHNEIDER, MICHELE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only.1/09	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

License Number: 1617198 ARBY'S #195
 License Type: Permanent Food Service 924 NW 62 ST, FORT LAUDERDALE 33309

Inspection Date: 11/05/2009 Inspection Number: 1835281 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: SCHNEIDER, MICHELE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only gate in breezeway.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.

License Number: 1600955 MCDONALDS #6269
 License Type: Permanent Food Service 1140 N SR 7, LAUDERHILL 33313

Inspection Date: 11/02/2009 Inspection Number: 1854496 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: WILLIAMS, NOVELETTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open, hasp on walkin cooler door. For reporting purposes only.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.

License Number: 1619546 KINGS SUPER BUFFET
 License Type: Permanent Food Service 7101 W OAKLAND PARK BLVD, LAUDERHILL 33313

Inspection Date: 11/03/2009 Inspection Number: 1854513 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: WILLIAMS, NOVELETTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

Broward County

License Number: 1620109

CAPT. SHRIMP

License Type: Permanent Food Service

1550 NW SR 7, LAUDERHILL 33313

Inspection Date: 11/04/2009

Inspection Number: 1885189

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: WILLIAMS, NOVELETTE

Violation CodeObservationViolation Citation

15-42-2

Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.

NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY

47-06-2

Observed extension cord in use for non-temporary period, with microwave. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 1616491

MCDONALDS #12396

License Type: Permanent Food Service

1201 SR 84, FT LAUDERDALE 33315

Inspection Date: 11/05/2009

Inspection Number: 1895171

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: GRAY, ANTHONY

Violation CodeObservationViolation Citation

46-05-2

Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 1600001

CATERING BY DAVID AT INVERRARY

License Type: Permanent Food Service

3840 INVERRARY BLVD, LAUDERHILL 33319

Inspection Date: 11/02/2009

Inspection Number: 1864802

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: WILLIAMS, NOVELETTE

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

Broward County

License Number: 1611318		MCDONALD'S (#6908)	
License Type: Permanent Food Service		10013 SUNSET STRIP, SUNRISE 33322	
Inspection Date: 11/03/2009	Inspection Number: 1833863	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WILLIAMS, ALECIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. Corrected On Site.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	
License Number: 1611839		CHEERS	
License Type: Permanent Food Service		941 E CYPRESS CRK RD, FORT LAUDERDALE 33334	
Inspection Date: 11/05/2009	Inspection Number: 1835286	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: SCHNEIDER, MICHELE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.	
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. exit door east side.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	
License Number: 1612006		GRANNY'S PLACE BY THE TRACKS	
License Type: Permanent Food Service		3236 NE 11 AVE, OAKLAND PARK 33334	
Inspection Date: 10/30/2009	Inspection Number: 1896661	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SCHNEIDER, MICHELE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.	
License Number: 1619239		BRAZIL CONNECTIONS	
License Type: Permanent Food Service		490 W HILLSBORO BLVD, DEERFIELD BCH 33441	
Inspection Date: 10/30/2009	Inspection Number: 1885459	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: EARP, NICOLETTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-08-2	Exit signs not visible from any direction. For reporting purposes only. observed exit sign giving wrong directions	NFPA 101, 7.10.1.2 Exits, other than main exterior exit doors that obviously and clearly are identifiable as exits, shall be marked by an approved sign readily visible from any direction of exit access. FOR REPORTING PURPOSES ONLY.	

Broward County

License Number: 1612805		COURTYARD CAFE & CATERING	
License Type: Permanent Food Service		700 W HILLSBORO BLVD BLDG 4-106, DEERFIELD BEACH 33441	
Inspection Date: 11/03/2009	Inspection Number: 1920008	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: EARP, NICOLETTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 1615024		UMBERTOS PIZZA	
License Type: Permanent Food Service		233 NE 21 AVE, DEERFIELD BEACH 33441	
Inspection Date: 11/03/2009	Inspection Number: 1865076	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BECKER, ROBERT			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only. ABC extinguisher	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.	
46-08-2	Exit signs not visible from any direction. For reporting purposes only. Blocked by food containers Corrected On Site.	NFPA 101, 7.10.1.2 Exits, other than main exterior exit doors that obviously and clearly are identifiable as exits, shall be marked by an approved sign readily visible from any direction of exit access. FOR REPORTING PURPOSES ONLY.	
License Number: 1619222		HOOK FISH & CHICKEN	
License Type: Permanent Food Service		244 W HILLSBORO BLVD, DEERFIELD BEACH 33441	
Inspection Date: 11/03/2009	Inspection Number: 1895716	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BECKER, ROBERT			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only. Unber drive - thru window.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 1617548		SUBWAY 740	
License Type: Permanent Food Service		261 S FEDERAL HWY, DEERFIELD BCH 334414161	
Inspection Date: 11/05/2009	Inspection Number: 1895730	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BECKER, ROBERT			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-02-2	Observed lock on exit door. Rear door For reporting purposes only.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	

Broward County

License Number: 1618945

MCDONALDS #21285

License Type: Permanent Food Service

3901 W HILLSBORO BLVD, DEERFIELD BEACH 33442

Inspection Date: 11/04/2009

Inspection Number: 1895791

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DIEHL, TERRENCE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. IN DINING ROOM	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

Charlotte County

License Number: 1801387

WHISKEY CREEK

License Type: Permanent Food Service

2746 TAMIAMI TRL, PORT CHARLOTTE 339525129

Inspection Date: 10/30/2009

Inspection Number: 1882573

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: LANDMANN, PAUL

Violation Code

Observation

Violation Citation

47-15-2 Observed an uncovered electrical box. For reporting purposes only. 2 main boxes uncovered

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Citrus County

License Number: 1901086

PAPA J'S CAFE

License Type: Permanent Food Service

1458 N US HWY 41, INVERNESS 34450

Inspection Date: 11/03/2009

Inspection Number: 1867452

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: CRAIG, JILL

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 1900440

PINE RIDGE GOLF AND COUNTRY CLUB

License Type: Permanent Food Service

5600 ELKAM BLVD, BEVERLY HILLS 34465

Inspection Date: 11/04/2009

Inspection Number: 1887934

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: CRAIG, JILL

Violation CodeObservationViolation Citation

45-31-2

Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only. Corrected On Site.

NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

Columbia County

License Number: 2200396

CHERYL BOCHETTE

License Type: Permanent Food Service

2140 N HWY 441, LAKE CITY 32055

Inspection Date: 11/04/2009

Inspection Number: 1890308

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: FULTON, DANIEL

Violation Code

Observation

Violation Citation

45-36-2

Hood suppression system tag out-of-date. For reporting purposes only.4/09

NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2331324	LITTLE CESARS PIZZA	
License Type: Permanent Food Service	3335 W 80TH ST, HIALEAH 33018	
Inspection Date: 10/30/2009	Inspection Number: 1832579	
Inspector Name: CHI, MAURICE	Inspection Type: Routine - Food	
	Inspection Disposition: Inspection Completed - No Further Action	
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only - empty boxes stored in front of back door. Corrected On Site.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 2324358	LA HACIENDA SEAFOOD RESTAURANT	
License Type: Permanent Food Service	29363 SW 152 AVE, MIAMI 33033	
Inspection Date: 11/03/2009	Inspection Number: 1884434	
Inspector Name: BROWN, MICHAEL	Inspection Type: Routine - Food	
	Inspection Disposition: Inspection Completed - No Further Action	
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 2330966	FRITANGA EL CHELE INC	
License Type: Permanent Food Service	4617 NW 199 ST, MIAMI GARDENS 33055	
Inspection Date: 11/03/2009	Inspection Number: 1832371	
Inspector Name: UNOLD, RICARDO	Inspection Type: Routine - Food	
	Inspection Disposition: Inspection Completed - No Further Action	
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. Corrected On Site.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.

License Number: 2331150	POLLO TROPICAL RESTAURANT #89	
License Type: Permanent Food Service	19700 NW 27 AVE, MIAMI 33056	
Inspection Date: 10/30/2009	Inspection Number: 1863135	
Inspector Name: UNOLD, RICARDO	Inspection Type: Routine - Food	
	Inspection Disposition: Inspection Completed - No Further Action	
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. Corrected On Site.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2315521

WENDYS INTL #1702-142

License Type: Permanent Food Service

697 NW 37 AVE, MIAMI 331254063

Inspection Date: 11/05/2009

Inspection Number: 1904663

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BLAIR, ANTONIO

Violation CodeObservationViolation Citation

46-05-2

Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. Corrected On Site.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 2330214

NATURAL CHICKEN GRILL

License Type: Permanent Food Service

5799 NW 7 ST, MIAMI 33126

Inspection Date: 11/04/2009

Inspection Number: 1843727

Inspection Type: Routine - Food

Inspection Disposition: Call Back - Admin. complaint recommended

Inspector Name: CHOW, ZULEIMA

Violation CodeObservationViolation Citation

45-07-2

Violation: 45-07-2

Observed misalignment of hood suppression system nozzles. For reporting purposes only.

NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

License Number: 2315911

MONTES DE OCA ORIGINAL PIZZA C

License Type: Permanent Food Service

4360 NW 7 ST, MIAMI 331263516

Inspection Date: 11/04/2009

Inspection Number: 1874434

Inspection Type: Routine - Food

Inspection Disposition: Call Back - Complied

Inspector Name: CHOW, ZULEIMA

Violation CodeObservationViolation Citation

45-39-2

Violation: 45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. K_CLASS ON FLOOR NEXT TO SHELF

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2332176		BLESSED CATERING	
License Type: Permanent Food Service		5711 NW 7 AVE, MIAMI 33127	
Inspection Date: 11/04/2009	Inspection Number: 1873826	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BLAIR, ANTONIO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
48-11-2	Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only.	NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.	

License Number: 2325121		INDOCHINE BISTRO	
License Type: Permanent Food Service		638 SOUTH MIAMI AVENUE, MIAMI 33130	
Inspection Date: 10/30/2009	Inspection Number: 1894240	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: KHAN, MOHAMMAD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	

License Number: 2328816		DELICIAS HONDURAS	
License Type: Permanent Food Service		955 WEST FLAGLER STREET, MIAMI 33130	
Inspection Date: 11/05/2009	Inspection Number: 1894214	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: KHAN, MOHAMMAD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
45-07-2	Observed misalignment of hood suppression system nozzles. For reporting purposes only.	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.	

Dade County

License Number: 2330431		DOLORES/LOLITA	
License Type: Permanent Food Service		1000 S MIAMI AVENUE, MIAMI 33130	
Inspection Date: 11/03/2009	Inspection Number: 1894224	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: KHAN, MOHAMMAD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 2332322		ROSAVITO	
License Type: Permanent Food Service		1036 SOUTH MIAMI AVE, MIAMI 33130	
Inspection Date: 11/03/2009	Inspection Number: 1894248	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Admin. complaint recommended
Inspector Name: KHAN, MOHAMMAD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Violation: 47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 2325141		LOS CATRACHOS INC	
License Type: Permanent Food Service		755 W FLAGLER ST, MIAMI 331301219	
Inspection Date: 11/05/2009	Inspection Number: 1843054	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: KHAN, MOHAMMAD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 2317602		BANQUET MAIN KICHEN & BAKERY	
License Type: Permanent Food Service		100 CHOPIN PLAZA, MIAMI 33131	
Inspection Date: 11/05/2009	Inspection Number: 1842875	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BURROWS, LEON			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only.rear of banquet rooms	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	

Dade County

License Number: 2319516

MOZZARELLA GRILL

License Type: Permanent Food Service

401 BISCAYNE BLVD SUITE 210, MIAMI 33132

Inspection Date: 11/05/2009

Inspection Number: 1863462

Inspection Type: Routine - Food

Inspection Disposition: Emergency
order recommended

Inspector Name: KHAN, MOHAMMAD

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-25-2	Hood filters not equipped with a drip tray. For reporting purposes only.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 2328442

CHICKEN CONNECTION

License Type: Permanent Food Service

401 BISCAYNE BLVD S 205, MIAMI 33132

Inspection Date: 11/05/2009

Inspection Number: 1873725

Inspection Type: Routine - Food

Inspection Disposition: Emergency
order recommended

Inspector Name: CHI, MAURICE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-04-2	Observed frayed/spliced electrical wires. For reporting purposes only. Under steam table.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 2322061

KELLY'S CAJUN GRILL/ YEUNG'S LOTUS EXPRESS

License Type: Permanent Food Service

401 BISCAYNE BLVD, MIAMI 331321924

Inspection Date: 11/05/2009

Inspection Number: 1883912

Inspection Type: Routine - Food

Inspection Disposition: Emergency
order recommended

Inspector Name: KHAN, MOHAMMAD

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY
45-07-2	Observed misalignment of hood suppression system nozzles. For reporting purposes only.	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2331713 THE IVY
 License Type: Permanent Food Service 3175 COMMODORE PLAZA, COCONUT GROVE 33133

Inspection Date: 10/30/2009 Inspection Number: 1920702 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CONYERS,

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.3rd floor.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
45-41-2	Portable fire extinguisher tag out-of-date. For reporting purposes only. Corrected On Site.	NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.
47-08-2	Observed electrical wiring in disrepair. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 2302354 ORIGINAL UNCLE TOMS BARBECUE
 License Type: Permanent Food Service 3988 SW 8 ST, MIAMI 33134

Inspection Date: 10/28/2009 Inspection Number: 1904759 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BURROWS, LEON

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-06-2	Ventilation hood not designed to prevent grease or condensation from causing cross-contamination.For reporting purposes only.	NFPA 96, 5.2 Hood Size. Hoods shall be sized and configured to provide for the capture and removal of grease-laden vapors (See 8.2.2.); 8.2.2 Air Volume. 8.2.2.1: Exhaust air volumes for hoods shall be of a sufficient level to provide for capture and removal of grease-laden cooking vapors. 8.2.2.2 Test data, performance acceptable to the authority having jurisdiction, or both, shall be provided, displayed, or both, upon request. 8.2.2.3 Lower exhaust air volumes shall be permitted during no-load cooking conditions provided they are sufficient to capture and remove flue gases and residual vapors from cooking equipment. FOR REPORTING PURPOSES ONLY

Dade County

License Number: 2301278

LA CARRETA REST

License Type: Permanent Food Service

3632 SW 8 ST, MIAMI 331354112

Inspection Date: 11/04/2009

Inspection Number: 1852953

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: GARCIA, BARBARO

Violation CodeObservationViolation Citation

47-04-2

Observed frayed/spliced electrical wires. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 2328639

CHEESE BURGER BABY

License Type: Permanent Food Service

1505 WASHINGTON STREET, MIAMI BEACH 33139

Inspection Date: 11/03/2009

Inspection Number: 1903981

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Admin. complaint recommended

Inspector Name: BATISTA, JENNY

Violation CodeObservationViolation Citation

46-02-2

Violation: 46-02-2

Observed lock on exit door that requires a key, tool or special knowledge to open.
For reporting purposes only.
REAR DOOR

NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.

License Number: 2332057

HALF MOON EMPANADAS

License Type: Permanent Food Service

1616 WASHINGTON AVENUE, MIAMI BEACH 33139

Inspection Date: 11/04/2009

Inspection Number: 1842341

Inspection Type: Routine - Food

Inspection Disposition: Administrative
complaint recommended

Inspector Name: BATISTA, JENNY

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2317498

LOS GUANDULES RESTAURANT

License Type: Permanent Food Service

7463 SW 8 ST, MIAMI 33144

Inspection Date: 10/30/2009

Inspection Number: 1843204

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: STERLING, DANIEL

Violation CodeObservationViolation Citation45-36-2 Hood suppression system tag out-of-date. For reporting purposes only. (01/2008).
Repeat Violation.

NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

45-41-2 Portable fire extinguisher tag out-of-date. For reporting purposes only. BC
EXTINGUISHER (01/2008). Repeat Violation.

NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

License Number: 2302947

BANQUET KITCHEN

License Type: Permanent Food Service

1155 BLUE RD, CORAL GABLES 33146

Inspection Date: 11/04/2009

Inspection Number: 1904723

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: KHAN, MOHAMMAD

Violation CodeObservationViolation Citation

48-01-2 Boiler certificate not posted in boiler room. For reporting purposes only.

69A-51.025(4) FAC (4) Certificate of Compliance. The Certificate of Compliance shall be conspicuously placed so it can be readily identified with the certified boiler, preferably in the boiler room. FOR REPORTING PURPOSES ONLY.

License Number: 2325282

WHISK GOURMET ROOD & CATERING SERVICES

License Type: Permanent Food Service

4702 S LE JEUNE ROAD, CORAL GABLES 33146

Inspection Date: 11/04/2009

Inspection Number: 1863625

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: KHAN, MOHAMMAD

Violation CodeObservationViolation Citation

15-25-2 Hood filters not equipped with a drip tray. For reporting purposes only.

NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes
only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2330886

RIVIERA COUNTRY CLUB OF CORAL GABLES

License Type: Permanent Food Service

1155 BLUE RD, CORAL GABLES 33146

Inspection Date: 11/04/2009

Inspection Number: 1832783

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: KHAN, MOHAMMAD

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 2323481

CHEF TIAN EXPRESS

License Type: Permanent Food Service

4700 S LEJUNE RD, CORAL GALBES 33146

Inspection Date: 11/04/2009

Inspection Number: 1832781

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: KHAN, MOHAMMAD

Violation CodeObservationViolation Citation

37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

45-07-2

Observed misalignment of hood suppression system nozzles. For reporting purposes only.

NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

License Number: 2328507

DELICIAS DE ESPANA

License Type: Permanent Food Service

4016 SW 57 AVE, MIAMI 33155

Inspection Date: 11/04/2009

Inspection Number: 1832995

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: GANDOLFF, JORGE

Violation CodeObservationViolation Citation

37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

Dade County

License Number: 2332097		ALEX'S PLACE CAFÉ	
License Type: Permanent Food Service		4550 SW 71 AVE, MIAMI 33155	
Inspection Date: 11/03/2009	Inspection Number: 1884295	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DE LA CRUZ, ADONIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.	
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
License Number: 2313533		EL GALLEGAZO RESTAURANT	
License Type: Permanent Food Service		7467 CORAL WAY, MIAMI 331551403	
Inspection Date: 10/29/2009	Inspection Number: 1843297	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GANDOLFF, JORGE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Out of compliance: Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 2315935		WENDY REST	
License Type: Permanent Food Service		6898 BIRD RD, MIAMI 331553708	
Inspection Date: 11/03/2009	Inspection Number: 1843290	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GANDOLFF, JORGE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
39-05-2	Ventilation inadequate as evidenced by smoke in kitchen area. For reporting purposes only.	NFPA 96, 4.1.1 Cooking equipment used in processes producing smoke or grease-laden vapors shall be equipped with an exhaust system that complies with all the equipment and performance requirements of this standard; and NFPA 96, 8.2.2 Air Volume. NFPA 96, 8.2.2.1: Exhaust air volumes for hoods shall be of a sufficient level to provide for capture and removal of grease-laden cooking vapors. FOR REPORTING PURPOSES ONLY	
License Number: 2356601		GOLDEN RULE SEAFOOD	
License Type: Mobile Food Dispensing Vehicle		15705 S DIXIE HWY, MIAMI 33157	
Inspection Date: 11/02/2009	Inspection Number: 1138897	Inspection Type: Complaint Full	Inspection Disposition: Administrative complaint recommended
Inspector Name: NUNEZ, ANDRES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	

Dade County

License Number: 2303173

KENTUCKY FRIED CHICKEN

License Type: Permanent Food Service

16215 NE 15 AVE, NORTH MIAMI BEACH 331624754

Inspection Date: 11/05/2009

Inspection Number: 1893768

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: UNOLD, RICARDO

Violation CodeObservationViolation Citation

15-42-2

Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.

NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY

License Number: 2324641

DEWAN RESTAURANT

License Type: Permanent Food Service

16606 N MIAMI AVE, MIAMI 33166

Inspection Date: 11/03/2009

Inspection Number: 1852878

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: UNOLD, RICARDO

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 2315853

CAFE FARAYA

License Type: Permanent Food Service

8398 NW 58 ST, MIAMI 331663409

Inspection Date: 11/06/2009

Inspection Number: 1873318

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: JARAMILLO, MARIA C

Violation CodeObservationViolation Citation

48-11-2

Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only.

NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

Dade County

License Number: 2326699		LUNCH BREAK CAFE	
License Type: Permanent Food Service		9682 NW 25 ST, DORAL 33172	
Inspection Date: 11/04/2009	Inspection Number: 1843162	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: STERLING, DANIEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 2331623		QIANLONG	
License Type: Permanent Food Service		8726 NW 26 ST #15, DORAL 33172	
Inspection Date: 11/04/2009	Inspection Number: 1873936	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: STERLING, DANIEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-36-2	Hood suppression system with no tag . For reporting purposes only.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.	
License Number: 2326790		P F CHANGS	
License Type: Permanent Food Service		8888 SW 136 ST, MIAMI 33176	
Inspection Date: 11/02/2009	Inspection Number: 1863986	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DE LA CRUZ, ADONIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only.by office	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
License Number: 2331081		LIME FRESH MEXICAN GRILL	
License Type: Permanent Food Service		14831 BISCAYNE BLVD, MIAMI 33181	
Inspection Date: 11/05/2009	Inspection Number: 1883531	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CHOW, ZULEIMA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. K_CLASS ON FLOOR	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
License Number: 2332271		PIZZA FUSION # 025	
License Type: Permanent Food Service		14815 BISCAYNE BLVD, MIAMI 33181	
Inspection Date: 11/05/2009	Inspection Number: 1873280	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: CHOW, ZULEIMA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only. BY DISHMACHINE	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

Dade County

License Number: 2326714	FRITANGA SAN JUAN DEL SUR		
License Type: Permanent Food Service	9558 SW 137 AVE, MIAMI 33186		
Inspection Date: 11/05/2009	Inspection Number: 1894582	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DE LA CRUZ, ADONIS			

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 2330495	HARVEY'S SMOKEHOUSE BBQ		
License Type: Permanent Food Service	20218 OLD CUTLER ROAD, CUTLER BAY 33189		
Inspection Date: 11/02/2009	Inspection Number: 1833197	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: DE LA CRUZ, ADONIS			

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY
45-36-2	Hood suppression system tag out-of-date. For reporting purposes only.	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

Duval County

License Number: 2614368 JP LEES
 License Type: Permanent Food Service 1402-1 SAN MARCO BLVD 103, JACKSONVILLE 32207

Inspection Date: 11/05/2009 Inspection Number: 1850195 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: ESPINOSA-BECKERT, ILIANA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. stroller, folding chair on hallway	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 2614443 M&M CRAB HOUSE
 License Type: Permanent Food Service 2905 PHILLIPS HWY, JACKSONVILLE 32207

Inspection Date: 11/06/2009 Inspection Number: 1921007 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: ESPINOSA-BECKERT, ILIANA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-15-2	Observed an uncovered electrical box. For reporting purposes only. display cooler	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.
47-16-2	Electrical outlet missing cover plate. For reporting purposes only. cracked in mop room	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 2611395 JENKINS QUALITY BBQ
 License Type: Permanent Food Service 2025 EMERSON ST, JACKSONVILLE 322075541

Inspection Date: 11/06/2009 Inspection Number: 1880824 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: ESPINOSA-BECKERT, ILIANA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-16-2	Electrical outlet missing cover plate. For reporting purposes only. where bowls are stored by fryer Repeat Violation.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 2610548 WOODY'S BARBECUE
 License Type: Permanent Food Service 4291 ROOSEVELT BLVD, JACKSONVILLE 32210

Inspection Date: 08/13/2009 Inspection Number: 1860561 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: SILBERMAN, STEPHANIE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair

Duval County

License Number: 2609557		SUBWAY# 1071	
License Type: Permanent Food Service		1821 PARENTAL HOME RD STE# 1, JACKSONVILLE 32216	
Inspection Date: 08/27/2009	Inspection Number: 1920815	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Warning Issued
Inspector Name: ESPINOSA-BECKERT, ILIANA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient	
License Number: 2613835		ARBY'S #7750	
License Type: Permanent Food Service		656 AIRPORT CENTER DR, JACKSONVILLE 32218	
Inspection Date: 11/03/2009	Inspection Number: 1840126	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DAVIS, MOSES			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only, REAR DOOR.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
License Number: 2612089		CARRABBA'S ITALIAN GRILL	
License Type: Permanent Food Service		9840 ATLANTIC BLVD, JACKSONVILLE 32225	
Inspection Date: 10/30/2009	Inspection Number: 1839902	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: YOUNG, DERRICK			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. powering TV behind the bar	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 2613675		FIONN MACCOOL'S IRISH PUB & RESTAURANT	
License Type: Permanent Food Service		333 1 ST N #150, JACKSONVILLE BEACH 32250	
Inspection Date: 11/05/2009	Inspection Number: 1891298	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CARANGIAN, REYNALDO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
47-06-2	Observed extension cord in use for non-temporary period./ kitchen area near food rack. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Duval County

License Number: 2608406	REB LOBSTER		
License Type: Permanent Food Service	8720 BAYMEADOWS, JACKSONVILLE	32256	
Inspection Date: 10/13/2009	Inspection Number: 1880735	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: HAYNES, MICHELLE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47	Out of compliance: Electrical wiring - adequate, good repair	NFPA 101, 96, 10 Electrical wiring - adequate, good repair	

License Number: 2613410	STICKY FINGERS		
License Type: Permanent Food Service	8129 POINT MEADOWS WAY, JACKSONVILLE	32256	
Inspection Date: 10/14/2009	Inspection Number: 1911422	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: HAYNES, MICHELLE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient	
46	Out of compliance: Exiting system - adequate, good repair	NFPA 101, 96, 10 Exiting system - adequate, good repair	

License Number: 2613647	PANDA HOUSE		
License Type: Permanent Food Service	7643 GATE PKWY #106, JACKSONVILLE	32256	
Inspection Date: 10/14/2009	Inspection Number: 1850138	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: HAYNES, MICHELLE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
49	Out of compliance: Flammable/combustible materials - properly stored	NFPA 101, 96, 10 Flammable/combustible materials - properly stored	

License Number: 2614016	LAS TAPATIAS TIENDA AND RESTAURANT		
License Type: Permanent Food Service	9974 OLD BAYMEADOWS RD, STE 3, JACKSONVILLE	32256	
Inspection Date: 10/13/2009	Inspection Number: 1911392	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: HAYNES, MICHELLE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient	

Escambia County

License Number: 2705217		MONTERREY MEXICAN GRILL INC	
License Type: Permanent Food Service		5030 BAYOU BLVD, PENSACOLA 325032504	
Inspection Date: 10/30/2009	Inspection Number: 1871231	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: RILEY, DAVID			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-38-2	Portable ABC fire extinguisher at cookline not fully charged. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	
45-38-2	Portable k class fire extinguisher at cookline not fully charged. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.	

License Number: 2705207		SAM'S LOUNGE	
License Type: Permanent Food Service		1225 N OLD CORRY RD, PENSACOLA 32506	
Inspection Date: 10/30/2009	Inspection Number: 1881436	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: RILEY, DAVID			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable ABC fire extinguisher at bar not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	
46-09-2	Exit sign in rear of bar not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	

License Number: 2705543		MONTERREYS #2	
License Type: Permanent Food Service		5190 MOBILE HWY, PENSACOLA 32526	
Inspection Date: 11/03/2009	Inspection Number: 1850749	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Extension given, pending
Inspector Name: CROWLEY, RUSSELL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Violation: 47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Flagler County

License Number: 2800641

BARBARA JEANS RESTAURANT OF PALM COAST

License Type: Permanent Food Service

101 PALM HARBOR PARKWAY #124, PALM COAST 32137

Inspection Date: 11/05/2009

Inspection Number: 1859576

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: GOSAI, MATT

Violation Code

Observation

Violation Citation

47-08-2 Observed electrical wiring in disrepair. For reporting purposes only. BY MIXER

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Gadsden County

License Number: 3000351

EL POTRILLO MEXICAN RESTAURANT & BAR

License Type: Permanent Food Service

1951 W JEFFERSON ST, QUINCY 32351

Inspection Date: 11/02/2009

Inspection Number: 1679777

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: HARGROVE, DAVID

Violation Code

Observation

Violation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. DINING ROOM.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. KITCHEN

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Hernando County

License Number: 3700815

CRACKER BARREL OLD COUNTRY STR

License Type: Permanent Food Service

30405 CRACKER CROSSING, BROOKSVILLE 34602

Inspection Date: 11/05/2009

Inspection Number: 1857254

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DANCHO, JOHN

Violation CodeObservationViolation Citation

45-12-2

Observed trouble/alarm light lighted on fire alarm control panel. For reporting purposes only.

NFPA 72, 7.1.1.1, 7.3.1 and 7.4.3 Inspection, testing, and maintenance programs shall satisfy the requirements of this code, conform to the equipment manufacturer's recommendations, and verify proper operation of the fire alarm system. Visual Inspection. Visual Inspection shall be performed in accordance with the schedules in this chapter or more frequently where required by the authority having jurisdiction. The visual inspection shall be made to ensure that there are no changes that can affect equipment performance. All apparatus requiring rewinding or resetting to maintain normal operation shall be restored to normal as promptly as possible after each test and alarm and kept in normal condition for operation. All test signals received shall be recorded to indicate date, time, and type. FOR REPORTING PURPOSES ONLY.

License Number: 3700479

CRAIG'S KITCHEN CAFE

License Type: Permanent Food Service

3480 DELTONA BLVD, SPRING HILL 34606

Inspection Date: 11/05/2009

Inspection Number: 1920924

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: GLENN, DAVID

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only. Small white household extension cord by back door of kitchen.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3701005

THE BROOK HOUSE

License Type: Permanent Food Service

2701 FOREST RD, SPRING HILL 34606

Inspection Date: 11/03/2009

Inspection Number: 1888059

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: GLENN, DAVID

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Hernando County

License Number: 3700499 KALLY K'S
 License Type: Permanent Food Service 3383 COMMERCIAL WAY, SPRING HILL 346062618

Inspection Date: 11/05/2009 Inspection Number: 1920804 Inspection Type: Complaint Full Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GLENN, DAVID

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. Under cooks line, next to ft top lad cooler.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3700314 BRIAN'S PLACE
 License Type: Permanent Food Service 3306 SHOAL LINE BLVD, SPRING HILL 34607

Inspection Date: 11/06/2009 Inspection Number: 1908541 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GLENN, DAVID

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only. Small flat top grill not under hood system.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. Powering sign at sign of road. Repeat Violation.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Hernando County

License Number: 3700912

BESTA ONE PIZZA & ITALIAN GRILLE

License Type: Permanent Food Service

13103 CORTEZ BLVD, BROOKSVILLE 34613-4802

Inspection Date: 11/05/2009

Inspection Number: 1920805

Inspection Type: Complaint Full

Inspection Disposition: Warning Issued

Inspector Name: DANCHO, JOHN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
47-16-2	Electrical outlet missing cover plate....above salad prep unit in kitchen. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3912991

MOE'S SOUTHWEST GRILL

License Type: Permanent Food Service

2338 W BRANDON BLVD, BRANDON 33511

Inspection Date: 11/04/2009

Inspection Number: 1897516

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: LEWIS, RICKY

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. Corrected On Site.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 3915643

HAWKEYE NYS PIZZA LLC

License Type: Permanent Food Service

1232 KINGSWAY RD, BRANDON 33511

Inspection Date: 11/02/2009

Inspection Number: 1920776

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: LEWIS, RICKY

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

47-15-2

Observed an uncovered electrical box. For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 3911463

KAZBORS SPORTS GRILLE

License Type: Permanent Food Service

9992 S HWY 301, RIVERVIEW 33569

Inspection Date: 11/05/2009

Inspection Number: 1908148

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BOWEN, JEFFREY

Violation CodeObservationViolation Citation

45-36-2

Hood suppression system tag out-of-date. For reporting purposes only. Hood fire-suppression system must be serviced and tagged at least once every-six months.

NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.

45-41-2

Portable fire extinguisher tag out-of-date. For reporting purposes only. Fire extinguishers must be serviced and tagged at least once per year.

NFPA 10, 6.3.1 Frequency. Fire extinguishers shall be subjected to maintenance at intervals of not more than 1 year, at the time of hydrostatic test, or when specifically indicated by an inspection or electronic notification. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3916013 PIZZA'S & STUFF
 License Type: Permanent Food Service 10664 US HWY 301 S, RIVERVIEW 33569

Inspection Date: 11/05/2009 Inspection Number: 1856856 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BOWEN, JEFFREY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. Do not store chair in front of the fire-exit door from the game room. Corrected On Site.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 3916054 MCDONALDS
 License Type: Permanent Food Service 13118 S US HWY 301, RIVERVIEW 33569

Inspection Date: 11/05/2009 Inspection Number: 1877444 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BOWEN, JEFFREY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. Mount the silver-fire extinguisher on a kitchen wall.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 3915815 DOMINO'S PIZZA #3252
 License Type: Permanent Food Service 1534 E BLOOMINGDALE AVE, VALRICO 33594

Inspection Date: 11/06/2009 Inspection Number: 1866753 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: LEWIS, RICKY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-13-2	Circuit breaker box blocked and/or inaccessible. For reporting purposes only.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.

License Number: 3916644 MI PUEBLITO BAKERY AND RESTAURANT INC
 License Type: Permanent Food Service 5802 NORTH ARMENIA AVE, TAMPA 33603

Inspection Date: 11/03/2009 Inspection Number: 1847178 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: PETERSON, DOUGLAS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only. 3 crock pots set up for frying in bakery on preparation table	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3906889		CHECKER'S #115	
License Type: Permanent Food Service		3002 N NEBRASKA AVE, TAMPA 336036028	
Inspection Date: 11/02/2009	Inspection Number: 1867727	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: PETERSON, DOUGLAS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-26-2	Observed exhaust system operated with filters removed. For reporting purposes only. Repeat Violation.	NFPA 96, 11.1.2 Filter-equipped exhaust systems shall not be operated with filters removed. For reporting purposes only.	
License Number: 3912162		DAVANIS CAFE	
License Type: Permanent Food Service		802 E WATERS, TAMPA 33604	
Inspection Date: 11/04/2009	Inspection Number: 1847206	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PETERSON, DOUGLAS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-42-2	Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.	NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY	
License Number: 3912472		GOOD TASTE	
License Type: Permanent Food Service		8221 N FLORIDA AVE, TAMPA 33604	
Inspection Date: 11/05/2009	Inspection Number: 1836914	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PETERSON, DOUGLAS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 3951232		EL TACONAZO	
License Type: Mobile Food Dispensing Vehicle		913 E. HILLSBOROUGH AVE, TAMPA 33604	
Inspection Date: 11/02/2009	Inspection Number: 1135372	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PETERSON, DOUGLAS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
15-42-2	Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.	NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY	
License Number: 3916447		TACO-NAZE	
License Type: Permanent Food Service		1001 E HILLSBOROUGH AVE, TAMPA 33604-7109	
Inspection Date: 11/02/2009	Inspection Number: 1898516	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PETERSON, DOUGLAS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only. side door	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	

Hillsborough County

License Number: 3910226	MS ROSE DINER		
License Type: Permanent Food Service	2916 34 ST, TAMPA 33605		
Inspection Date: 11/06/2009	Inspection Number: 1915687	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: PETERSON, DOUGLAS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only.table top fryer used on preparation table not under hood	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.	

License Number: 3912334	D'ITALIA		
License Type: Permanent Food Service	1811 NORTH 15TH STREET, TAMPA 33605		
Inspection Date: 11/04/2009	Inspection Number: 1887756	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: OGDEN, RICHARD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 3911799	SOHO OASIS		
License Type: Permanent Food Service	410 S HOWARD AVE C, TAMPA 33606		
Inspection Date: 11/03/2009	Inspection Number: 1867649	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: KLUSENDORF, JEANNE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-26-2	Observed exhaust system operated with filters removed. For reporting purposes only.	NFPA 96, 11.1.2 Filter-equipped exhaust systems shall not be operated with filters removed. For reporting purposes only.	

License Number: 3907250	LA IDEAL SANDWICH SHOP		
License Type: Permanent Food Service	2924 W TAMPA BAY BLVD, TAMPA 33607		
Inspection Date: 11/02/2009	Inspection Number: 1897289	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: MIRABELLA, FRANK			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. microwave	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Hillsborough County

License Number: 3911844 STADIUM STEAKERY 329C
 License Type: Permanent Food Service 4116 N HIMES AVE, TAMPA 33607

Inspection Date: 10/30/2009 Inspection Number: 1887006 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: MIRABELLA, FRANK

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient

License Number: 3911845 GRID IRON GRILL 342C
 License Type: Permanent Food Service 4116 N HIMES AVE, TAMPA 33607

Inspection Date: 10/30/2009 Inspection Number: 1846064 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: MIRABELLA, FRANK

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45	Out of compliance: Fire extinguishers - proper and sufficient	NFPA 101, 96, 10 Fire extinguishers - proper and sufficient

License Number: 3915975 CAFE JAPON
 License Type: Permanent Food Service 2223 N WESTSHORE BLVD B224, TAMPA 33607

Inspection Date: 11/03/2009 Inspection Number: 1897341 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: MIRABELLA, FRANK

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. coffee	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3916230 BOIZAO STEAKHOUSE
 License Type: Permanent Food Service 4606 BOY SCOUT BLVD, TAMPA 33607

Inspection Date: 11/06/2009 Inspection Number: 1835817 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: MIRABELLA, FRANK

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. at bar	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3906297 HANA DELI
 License Type: Permanent Food Service 5201 KENNEDY BLVD STE 130, TAMPA 33609

Inspection Date: 11/03/2009 Inspection Number: 1836120 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CANNELLA, MARK

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3904572 WENDY'S
 License Type: Permanent Food Service 1501 E HILLSBOROUGH AVE, TAMPA 33610

Inspection Date: 11/04/2009 Inspection Number: 1898490 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: PETERSON, DOUGLAS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only. painted surface peeling	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only. diningroom	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

License Number: 3905610 KFC
 License Type: Permanent Food Service 3202 E HILLSBOROUGH AVE, TAMPA 33610

Inspection Date: 11/03/2009 Inspection Number: 1867703 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: PETERSON, DOUGLAS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-42-2	Observed hood filters installed horizontally, rather than vertically. For reporting purposes only. Corrected On Site.	NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY

Hillsborough County

License Number: 3916639

HECTOR'S RESTAURANT

License Type: Permanent Food Service

3120 EAST HILLSBOROUGH AVENUE, TAMPA 33610

Inspection Date: 11/04/2009

Inspection Number: 1915626

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: PETERSON, DOUGLAS

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
39-03-2	Exhaust system off during the operation of cooking equipment. For reporting purposes only. Corrected On Site.	NFPA 96, 11.1.1 Exhaust systems shall be operated whenever cooking equipment is turned on. For reporting purposes only.
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-05-2	Violation: 47-05-2 Observed a splitter/multi-plug adapter in use. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Violation: 47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3951289

PARK'S HOT DOGS

License Type: Mobile Food Dispensing Vehicle

11612 NORTH NEBRASKA, TAMPA 33612-5760

Inspection Date: 11/04/2009

Inspection Number: 1133981

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CHEW, TEOW

Violation Code ObservationViolation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

48-11-2 Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only.

NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

License Number: 3900680

I H O PANCAKES

License Type: Permanent Food Service

3501 E BUSCH BLVD, TAMPA 336128743

Inspection Date: 11/02/2009

Inspection Number: 1887131

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: EDMISTON, ROBERT

Violation Code ObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3915696 SONIC DRIVE IN #4617
 License Type: Permanent Food Service 4315 W HILLSBOROUGH, TAMPA 33614

Inspection Date: 10/28/2009 Inspection Number: 1907856 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DORSEY, KATHY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-1	Out of compliance: Grease filters shall be arranged so that all exhaust air shall pass through the grease filters.	NFPA 96, 6.2.3.3:: Grease filters shall be arranged so that all exhaust air shall pass through the grease filters.

License Number: 3912541 BAMBOO EXPRESS
 License Type: Permanent Food Service 7540 WEST HILLSBOROUGH AVENUE, TAMPA 33615

Inspection Date: 11/02/2009 Inspection Number: 1887039 Inspection Type: Complaint Full Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DECKER, RICHARD

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 3915771 WENDY'S
 License Type: Permanent Food Service 11720 N 56 ST, TEMPLE TERRACE 33617

Inspection Date: 11/04/2009 Inspection Number: 1897481 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CHEW, TEOW

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-12-2	Observed trouble and silence alarm light lighted on fire alarm control panel. For reporting purposes only.	NFPA 72, 7.1.1.1, 7.3.1 and 7.4.3 Inspection, testing, and maintenance programs shall satisfy the requirements of this code, conform to the equipment manufacturer's recommendations, and verify proper operation of the fire alarm system. Visual Inspection. Visual Inspection shall be performed in accordance with the schedules in this chapter or more frequently where required by the authority having jurisdiction. The visual inspection shall be made to ensure that there are no changes that can affect equipment performance. All apparatus requiring rewinding or resetting to maintain normal operation shall be restored to normal as promptly as possible after each test and alarm and kept in normal condition for operation. All test signals received shall be recorded to indicate date, time, and type. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3912851 J CHRISTOPHERS
 License Type: Permanent Food Service 14366 N DALE MABRY, TAMPA 33618

Inspection Date: 11/05/2009 Inspection Number: 1856586 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: DORSEY, KATHY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-25-2	Hood filters not equipped with a drip tray. For reporting purposes only.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY
15-26-2	Observed exhaust system operated with filter removed. For reporting purposes only.	NFPA 96, 11.1.2 Filter-equipped exhaust systems shall not be operated with filters removed. For reporting purposes only.
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. rear of restaurant	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 3900244 HARBOURSIDE GRILL
 License Type: Permanent Food Service 4103 CAUSEWAY BLVD, TAMPA 33619

Inspection Date: 11/02/2009 Inspection Number: 1846762 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: OGDEN, RICHARD

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
47-15-2	Observed an uncovered electrical box. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 3916080 DI SANDARA CAFFEE
 License Type: Permanent Food Service 7201 W LINEBAUGH AVENUE, TAMPA 33625

Inspection Date: 11/05/2009 Inspection Number: 1887055 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: DECKER, RICHARD

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3916279

LA CREPERIA CAFE II INC

License Type: Permanent Food Service

9664 W LINEBAUGH AVE, TAMPA 33626

Inspection Date: 11/04/2009

Inspection Number: 1920932

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PETERSON, DOUGLAS

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3916242

PACI'S PIZZA

License Type: Permanent Food Service

2307 S DALE MABRY STE A, TAMPA 33629

Inspection Date: 11/06/2009

Inspection Number: 1846411

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CANNELLA, MARK

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only. in back area.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3904632

A LA CARTE EVENT PAVILION

License Type: Permanent Food Service

4050 DANA SHORES DR, TAMPA 33634

Inspection Date: 11/05/2009

Inspection Number: 1856374

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DECKER, RICHARD

Violation CodeObservationViolation Citation

46-02-2

Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. hasp lock on cooler

NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3912105 CAPITAL ONE CAFE
 License Type: Permanent Food Service 8745 HENDERSON RD, TAMPA 33634

Inspection Date: 11/03/2009 Inspection Number: 1907690 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DECKER, RICHARD

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 3916537 VIET ASIAN
 License Type: Permanent Food Service 5707 W WATER AVE #101, TAMPA 33634

Inspection Date: 11/03/2009 Inspection Number: 1920638 Inspection Type: Food-Licensing Inspection Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DECKER, RICHARD

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-07-2	Observed misalignment of hood suppression system nozzles. For reporting purposes only.	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.
48-13-2	Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.

Hillsborough County

License Number: 3911384

CAFE DE SIAM

License Type: Permanent Food Service

11242 HILLSBOROUGH AVE, TAMPA 33635

Inspection Date: 11/03/2009

Inspection Number: 1866676

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: DECKER, RICHARD

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 3951497

KENNEDY BAR B QUE & CATERING

License Type: Mobile Food Dispensing Vehicle

10960 MORRIS BRIDGE RD, TAMPA 33647

Inspection Date: 11/03/2009

Inspection Number: 1134067

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: CHEW, TEOW

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Indian River County

License Number: 4101197

EARL'S HIDEAWAY LOUNGE INC

License Type: Permanent Food Service

1405 INDIAN RIVER DR, SEBASTIAN 32958

Inspection Date: 11/06/2009

Inspection Number: 1898909

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: SCHOENLY, BARBARA

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 4101201

KFC/TACO BELL/PIZZA HUT #3

License Type: Permanent Food Service

1809 US HWY 1, SEBASTIAN 32958

Inspection Date: 11/02/2009

Inspection Number: 1920731

Inspection Type: Complaint Full

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: WEIMER, EDWIN

Violation CodeObservationViolation Citation

47-15-2

Observed an uncovered electrical box.in the chicken walk in cooler For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Indian River County

License Number: 4105121

BEST WESTERN CONT. BREAKFAST

License Type: Permanent Food Service

1655 US HWY 1, SEBASTIAN 32958

Inspection Date: 11/06/2009

Inspection Number: 1847618

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: SCHOENLY, BARBARA

Violation Code

Observation

Violation Citation

48-12-2 No current boiler certification provided/available. For reporting purposes only./expired in August-sent as other on call back done on 11/6/09

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

48-12-2 Violation: 48-12-2
Boiler Certification Expired For reporting purposes only./

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

Jackson County

License Number: 4200348

BAY'S

License Type: Permanent Food Service

2019 S HWY 69, GRAND RIDGE 32442

Inspection Date: 11/05/2009

Inspection Number: 1840701

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: HARDING, LINDA

Violation Code

Observation

Violation Citation

48-11-2 Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only. Repeat Violation.

NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

Jefferson County

License Number: 4300111 SUBWAY
 License Type: Permanent Food Service 1246 S JEFFERSON ST, MONTICELLO 323441634

Inspection Date: 11/02/2009 Inspection Number: 1881932 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DODSON, FRED

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

License Number: 4300064 PIZZA HUT #2997
 License Type: Permanent Food Service 1403 S JEFFERSON ST, MONTICELLO 323441637

Inspection Date: 11/04/2009 Inspection Number: 1881928 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DODSON, FRED

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-2	Exit signs not properly illuminated. For reporting purposes only.back door	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 4300034 CHICKEN DELITE
 License Type: Permanent Food Service 635 S JEFFERSON ST, MONTICELLO 323441823

Inspection Date: 11/04/2009 Inspection Number: 1892152 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: DODSON, FRED

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-03-2	Observed unused opening in panel box unprotected. For reporting purposes only.	NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.

Lake County

License Number: 4508444

SOL DE MEXICO

License Type: Permanent Food Service

125 N BAY STREET, EUSTIS 32726

Inspection Date: 11/04/2009

Inspection Number: 1915853

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: MARTIN, ROBERT KEVIN

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 4501575

AWARD WINNING MAGNOLIA INN

License Type: Permanent Food Service

347 E THIRD AVE, MT DORA 327575654

Inspection Date: 11/04/2009

Inspection Number: 1859116

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: MOORE, CAROLYN

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 4508453

SUNRISE SNACK SHACK II

License Type: Permanent Food Service

40400 ROGER GILLS RD, UMATILLA 32784

Inspection Date: 11/03/2009

Inspection Number: 1916356

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: MARTIN, ROBERT KEVIN

Violation CodeObservationViolation Citation

45-31-2

Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only.

NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

Lake County

License Number: 4508301 AY JALISCO
 License Type: Permanent Food Service 580 E HWY 50, CLERMONT 34711

Inspection Date: 11/03/2009 Inspection Number: 1920657 Inspection Type: Complaint Full Inspection Disposition: Administrative complaint recommended
 Inspector Name: CHIU, ALEX

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
15-42-2	Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.	NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY
46-05-2	Observed obstructed exits, stairs, hallways or egress. Side dining room fire egress exit blocked by a row of chairs. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.
49-06-2	Observed flammable material stored around water heater. Cardboard box on top of water heater] For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

License Number: 4500533 WENDYS
 License Type: Permanent Food Service 917 N 14 ST, LEESBURG 347483816

Inspection Date: 10/29/2009 Inspection Number: 1848957 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: MARTIN, ROBERT KEVIN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-02-2	Suppression head spray pattern obstructed. For reporting purposes only. Blocked by tongs	NFPA 25, 5.2.1.2 Unacceptable obstructions to spray patterns shall be corrected. FOR REPORTING PURPOSES ONLY.

Lee County

License Number: 4602892		SAKURA JAPANESE STEAK HOUSE	
License Type: Permanent Food Service		3034 DEL PRADO BLVD, CAPE CORAL 339047212	
Inspection Date: 11/05/2009	Inspection Number: 1851960	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: SOMMERS, KARA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-15-2	Observed an uncovered electrical boxes. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
47-15-2	Violation: 47-15-2 Observed an uncovered electrical boxes. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
47-16-2	Violation: 47-16-2 Electrical outlet missing cover plate--back office area in corner near bar/dining room For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
47-16-2	Electrical outlet missing cover plate--back office area in corner near bar/dining room For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 4602469		PEKING AVENUE	
License Type: Permanent Food Service		14561 PALM BEACH BLVD SUITE 21, FORT MYERS 33905	
Inspection Date: 10/29/2009	Inspection Number: 1842104	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BAMBREY, SHAWN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 4605395		WANG'S CHINA CITY	
License Type: Permanent Food Service		14630 PALM BEACH BLVD STE 4, FORT MYERS 33905	
Inspection Date: 10/29/2009	Inspection Number: 1872873	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Admin. complaint recommended
Inspector Name: BAMBREY, SHAWN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. upon reinspection 10/29/2009 observed hood filters not tight-fitting and firmly held in place, leaving open spaces	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. cookline Repeat Violation.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

Lee County

License Number: 4604492 GULF HARBOUR GOLF & COUNTRY CLUB
 License Type: Permanent Food Service 14500 VISTA RIVER DR, FORT MYERS 33908

Inspection Date: 11/05/2009 Inspection Number: 1862349 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: CERQUERA, LINA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-12-2	No current boiler certification provided/available. For reporting purposes only.	69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 4602901 APPLEBEE'S NEIGHBORHOOD GRILL & BAR #4006
 License Type: Permanent Food Service 13550 S TAMIAMI HWY, FORT MYERS 33912

Inspection Date: 11/04/2009 Inspection Number: 1873027 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: TORBERT, KIMBERLY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only. ABC extinguisher by back handwash sink Repeat Violation.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

License Number: 4605677 BONEFISH GRILL
 License Type: Permanent Food Service 14261 S TAMIAMI TRL #1, FORT MYERS 33912

Inspection Date: 11/04/2009 Inspection Number: 1842158 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: TORBERT, KIMBERLY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only. K class extinguisher left of cook line	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

Leon County

License Number: 4702526		KOOL BEANZ CAFE	
License Type: Permanent Food Service		921 THOMASVILLE RD, TALLAHASSEE 32303	
Inspection Date: 11/02/2009	Inspection Number: 1892220	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: WRIGHT, ANDREW			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate by dish machine. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 4702118		LOS AMIGOS MEXICAN RESTAURANT	
License Type: Permanent Food Service		2736 NE CAPITAL CIRCLE, TALLAHASSEE 32308	
Inspection Date: 11/04/2009	Inspection Number: 1912715	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: TALLEY, BELINDA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 4702465		OUTBACK STEAKHOUSE	
License Type: Permanent Food Service		1820 RAYMOND DIEHL RD, TALLAHASSEE 32308	
Inspection Date: 11/02/2009	Inspection Number: 1912671	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WRIGHT, ANDREW			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-12-2	Observed no power on fire alarm control panel. For reporting purposes only.	NFPA 72, 7.1.1.1, 7.3.1 and 7.4.3 Inspection, testing, and maintenance programs shall satisfy the requirements of this code, conform to the equipment manufacturer's recommendations, and verify proper operation of the fire alarm system. Visual Inspection. Visual Inspection shall be performed in accordance with the schedules in this chapter or more frequently where required by the authority having jurisdiction. The visual inspection shall be made to ensure that there are no changes that can affect equipment performance. All apparatus requiring rewinding or resetting to maintain normal operation shall be restored to normal as promptly as possible after each test and alarm and kept in normal condition for operation. All test signals received shall be recorded to indicate date, time, and type. FOR REPORTING PURPOSES ONLY.	
License Number: 4703216		SAMURAI EXPRESS	
License Type: Permanent Food Service		3111 MAHAN DRIVE UNIT 26, TALLAHASSEE 32308	
Inspection Date: 11/03/2009	Inspection Number: 1861455	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DODSON, FRED			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-15-2	Observed an uncovered electrical box. For reporting purposes only. Corrected On Site.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

Leon County

License Number: 4701671

GOLDEN EAGLE COUNTRY CLUB INC

License Type: Permanent Food Service

3700 GOLDEN EAGLE DR, TALLAHASSEE 32312

Inspection Date: 11/03/2009

Inspection Number: 1861413

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DODSON, FRED

Violation Code

Observation

Violation Citation

46-09-2

Exit signs not properly illuminated. For reporting purposes only.back door down stairs

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

Levy County

License Number: 4800507 SHAKER'S
 License Type: Permanent Food Service 750 E HATHAWAY AVE, BRONSON 32621

Inspection Date: 11/05/2009 Inspection Number: 1920533 Inspection Type: Complaint Full Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BROWNING, JULIANNE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.
47-08-2	Observed electrical wiring in disrepair. For reporting purposes only. emergency light hanging by wires	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 4800574 BUBBAQUES
 License Type: Permanent Food Service 830 E HATHAWAY AVENUE, BRONSON 32621

Inspection Date: 11/05/2009 Inspection Number: 1849703 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BROWNING, JULIANNE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. Repeat Violation. Repeat Violation.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 4800271 HUDDLE HOUSE RESTAURANT # 297
 License Type: Permanent Food Service 1402 N YOUNG BLVD, CHEIFLAND 32626

Inspection Date: 11/05/2009 Inspection Number: 1900817 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: WRENNE, LILYANN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. 2 extension chords going to monitor in office. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-13-2	Circuit breaker box blocked and/or inaccessible. For reporting purposes only. Corrected On Site.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.

Manatee County

License Number: 5104391

FIRST WATCH #56

License Type: Permanent Food Service

8306 MARKET ST, BRADENTON 34202

Inspection Date: 11/03/2009

Inspection Number: 1912994

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CHRISTENSON, MELISSA

Violation CodeObservationViolation Citation

45-38-2

Portable fire extinguisher not fully charged. For reporting purposes only.-next to mop sink

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

License Number: 5101360

CUERNAVACA BAR & GRILL

License Type: Permanent Food Service

830 301 BLVD EAST, BRADENTON 34203

Inspection Date: 10/30/2009

Inspection Number: 1920807

Inspection Type: Routine - Food

Inspection Disposition: Administrative complaint recommended

Inspector Name: BAGLEY, VICTORIA

Violation CodeObservationViolation Citation

47-04-2

Observed frayed/spliced electrical wires. For reporting purposes only.at outside electric water heater

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-15-2

Observed an uncovered electrical box in closet and back warewash room For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

47-16-2

Electrical outlet missing cover plate. For reporting purposes only. Bovr 3 compartment sink

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 5104248

MAWS PLACE

License Type: Permanent Food Service

1707 E 1 ST, BRADENTON 34208

Inspection Date: 11/06/2009

Inspection Number: 1882261

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CHRISTENSON, MELISSA

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Manatee County

License Number: 5102655

BURGER KING #5479

License Type: Permanent Food Service

3803 E 1 ST, BRADENTON 342084447

Inspection Date: 11/06/2009

Inspection Number: 1861714

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: CHRISTENSON, MELISSA

Violation CodeObservationViolation Citation

45-38-2

Portable fire extinguisher not fully charged. For reporting purposes only.-Hanging
next to back exit.NFPA 10, 1.5.2 Portable fire extinguishers shall be
maintained in a fully charged and operable condition
and shall be kept in their designated places at all times
when they are not being used. FOR REPORTING
PURPOSES ONLY.

License Number: 5104353

ALA MODE ICE CREAM PARLOUR

License Type: Permanent Food Service

336 WEST 8TH AVENUE, PALMETTO 34221

Inspection Date: 11/05/2009

Inspection Number: 1861690

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Extension given, pending

Inspector Name: CHRISTENSON, MELISSA

Violation CodeObservationViolation Citation

45-38-2

Violation: 45-38-2

Portable fire extinguisher not fully charged. For reporting purposes onlyOn floor
under dishwash machine. Upon callback, operator contacted Palmetto fire
department to have extinguisher re charged.NFPA 10, 1.5.2 Portable fire extinguishers shall be
maintained in a fully charged and operable condition
and shall be kept in their designated places at all times
when they are not being used. FOR REPORTING
PURPOSES ONLY.

45-38-2

Portable fire extinguisher not fully charged. For reporting purposes onlyOn floor
under dishwash machine.NFPA 10, 1.5.2 Portable fire extinguishers shall be
maintained in a fully charged and operable condition
and shall be kept in their designated places at all times
when they are not being used. FOR REPORTING
PURPOSES ONLY.

License Number: 5105175

TACO BELL LJS #22787

License Type: Permanent Food Service

640 10 ST E, PALMETTO 34221

Inspection Date: 11/04/2009

Inspection Number: 1841177

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: CHRISTENSON, MELISSA

Violation CodeObservationViolation Citation

45-38-2

Portable fire extinguisher not fully charged. For reporting purposes only. Next to
back exit door.NFPA 10, 1.5.2 Portable fire extinguishers shall be
maintained in a fully charged and operable condition
and shall be kept in their designated places at all times
when they are not being used. FOR REPORTING
PURPOSES ONLY.

Marion County

License Number: 5202430

KELLY STREET CAFE

License Type: Permanent Food Service

12991 NE 245 ST ROAD, ORANGE SPRINGS 32182

Inspection Date: 11/04/2009

Inspection Number: 1920847

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BRYANT, BENJAMIN

Violation CodeObservationViolation Citation

46-09-2

Exit sign in dining area not properly illuminated. For reporting purposes only.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

47-16-2

Electrical outlet missing cover plate in back storage room. For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 5202595

BRUSTER'S REAL ICE CREAM

License Type: Permanent Food Service

2705 E SILVER SPRINGS BLVD, OCALA 34470

Inspection Date: 11/04/2009

Inspection Number: 1870381

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BRYANT, BENJAMIN

Violation CodeObservationViolation Citation

47-06-2

Observed extension plug, and white extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5202154

WOODLEA GARDENS

License Type: Catering

2201 SW COLLEGE RD #3, OCALA 34474

Inspection Date: 11/06/2009

Inspection Number: 1093309

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: ANAZIA, ROLAND

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. K class extinguisher on bottom shelf with flour / sugar containers .

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Marion County

License Number: 5200671

ROGERS BAR B Q

License Type: Permanent Food Service

10863 E SILVER SPRINGS BLVD, SILVER SPGS 34488

Inspection Date: 11/03/2009

Inspection Number: 1880600

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: BROWNING, JULIANNE

Violation CodeObservationViolation Citation

46-05-2

Observed obstructed exits, stairs, hallways or egress. exit leads to an area surrounded by a 6' chain link fence w/ a padlocked gate. reporting purposes only.

NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

License Number: 5201971

STONECREST GOLF & COUNTRY CLUB

License Type: Permanent Food Service

11560 SE 176 PL RD, SUMMERFIELD 344917810

Inspection Date: 11/03/2009

Inspection Number: 1860046

Inspection Type: Routine - Food

Inspection Disposition: Administrative
complaint recommended

Inspector Name: BROWNING, JULIANNE

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Martin County

License Number: 5300029		JUPITER ISLAND CLUB D R	
License Type: Permanent Food Service		JUPITER IS, HOBE SOUND 33455	
Inspection Date: 11/04/2009	Inspection Number: 1865860	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DERVIN, RICHARD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-07-2	Observed misalignment of hood suppression system nozzles. For reporting purposes only. fryer not under hood at employee dining room.	NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.	

License Number: 5300086		GOLF HOUSE RESTAURANT	
License Type: Permanent Food Service		JUPITER IS, HOBE SOUND 33455	
Inspection Date: 11/04/2009	Inspection Number: 1876116	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DERVIN, RICHARD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only. kitchen.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	

License Number: 5301071		LOBLOLLY CLUBHOUSE	
License Type: Permanent Food Service		7626 GOLFHOUSE DR, HOBE SOUND 33455	
Inspection Date: 11/05/2009	Inspection Number: 1876124	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DERVIN, RICHARD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only. base ment.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	

License Number: 5300766		LA BORGATA RISTORANTE AND PIZZERIA	
License Type: Permanent Food Service		3227 SW MAPP RD, PALM CITY 34990	
Inspection Date: 11/05/2009	Inspection Number: 1886347	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PETROW, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only... by restrooms.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	

Martin County

License Number: 5301393

OSCEOLA STREET CAFE

License Type: Permanent Food Service

26 W OSCEOLA ST, STUART 34994

Inspection Date: 10/29/2009

Inspection Number: 1907002

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PETROW, MICHAEL

Violation Code

Observation

Violation Citation

47-16-2

Electrical outlet missing cover plate. For reporting purposes only... cook line.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Monroe County

License Number: 5401911		DENNY'S LATIN CAFE	
License Type: Permanent Food Service		99610 OVERSEAS HWY, KEY LARGO 33037	
Inspection Date: 11/05/2009	Inspection Number: 1864067	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BROWN, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 5401967		SHIPWRECK	
License Type: Permanent Food Service		45 GARDEN COVE DR, KEY LARGO 33037	
Inspection Date: 11/02/2009	Inspection Number: 1853770	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BROWN, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 5402783		PH MARINA/RESTAURANT	
License Type: Permanent Food Service		13 SEAGATE BLVD, KEY LARGO 33037	
Inspection Date: 11/04/2009	Inspection Number: 1894676	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BROWN, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.broken	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 5402787		SU CASA RESTAURANT & CAFE	
License Type: Permanent Food Service		99246 OVERSEAS HWY, KEY LARGO 33037	
Inspection Date: 11/05/2009	Inspection Number: 1864065	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BROWN, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
License Number: 5401810		KEY LARGO ARBYS	
License Type: Permanent Food Service		101377 OVERSEAS HWY, KEY LARGO 330374576	
Inspection Date: 11/02/2009	Inspection Number: 1894662	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BROWN, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-13-2	Circuit breaker box blocked and/or inaccessible. For reporting purposes only.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.	

Monroe County

License Number: 5401630		HIDEOUT RESTAURANT	
License Type: Permanent Food Service		47 SHORELAND DR, KEY LARGO 330374752	
Inspection Date: 11/05/2009	Inspection Number: 1843495	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BROWN, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
License Number: 5400007		THE WOODEN SPOON	
License Type: Permanent Food Service		7007 OVERSEAS HWY, MARATHON 33050	
Inspection Date: 11/02/2009	Inspection Number: 1894735	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: MORGADANES, DOUGLAS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
49-06-2	Observed flammable material stored around water heater. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.	
License Number: 5401077		PANDA HOUSE CHINESE RESTAURANT	
License Type: Permanent Food Service		5230 OVERSEAS HWY, MARATHON 330502604	
Inspection Date: 11/02/2009	Inspection Number: 1864125	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: MORGADANES, DOUGLAS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	

Nassau County

License Number: 5500834 JOES 2ND ST BISTRO
 License Type: Permanent Food Service 14 S SECOND ST, FERNANDINA BEACH 32034

Inspection Date: 11/03/2009 Inspection Number: 1881026 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: PHELAN, JOHN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-09-2	Exit signs not properly illuminated. For reporting purposes only. Side kitchen door	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. To kitchen television	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5500972 LUIGI'S TRATTORIA
 License Type: Permanent Food Service 31 S 5 ST, FERNANDINA BEACH 32034

Inspection Date: 11/03/2009 Inspection Number: 1870751 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: PHELAN, JOHN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only. Behind reach in cooler kitchen.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. Behind reach in cooler kitchen.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Nassau County

License Number: 5500673

BEECH ST GRILL & FISH MARKET

License Type: Permanent Food Service

801 BEECH ST, FERNANDINA BCH 320343634

Inspection Date: 11/03/2009

Inspection Number: 1901515

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: PHELAN, JOHN

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5500801

CONNIES PIZZA & BBQ

License Type: Permanent Food Service

ORANGE ST & HWY 108, HILLIARD 32046

Inspection Date: 11/05/2009

Inspection Number: 1901519

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: PHELAN, JOHN

Violation CodeObservationViolation Citation

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only. At television.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Okaloosa County

License Number: 5603400 LA RUMBA
 License Type: Permanent Food Service 36112 EMERALD COAST PKWY, DESTIN 32541

Inspection Date: 11/03/2009 Inspection Number: 1914965 Inspection Type: Routine - Food Inspection Disposition: Call Back - Complied
 Inspector Name: PEREZ, FELIPE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Violation: 15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 5603407 O'CHARLEY'S #325
 License Type: Permanent Food Service 34906 EMERALD COAST PKWY, DESTIN 32541

Inspection Date: 11/02/2009 Inspection Number: 1881614 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: PEREZ, FELIPE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. Repeat Violation.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 5603594 HARD ROCK CAFE DESTIN
 License Type: Permanent Food Service 4260 LEGENDARY DR #D 135, DESTIN 32541

Inspection Date: 11/02/2009 Inspection Number: 1840524 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: PEREZ, FELIPE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-26-2	Observed dishmachine hood exhaust system filter/screen removed.	NFPA 96, 11.1.2 Filter-equipped exhaust systems shall not be operated with filters removed. For reporting purposes only.

License Number: 5603142 FISHERMANS WHARF
 License Type: Permanent Food Service 210 E HWY 98 UNIT D, DESTIN 325414941

Inspection Date: 11/03/2009 Inspection Number: 1850917 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: PEREZ, FELIPE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period...operating reach in cooler. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5650084 TACOS LA DONA
 License Type: Mobile Food Dispensing Vehicle 436 OAKLAND CIRCLE, FORT WALTON BEACH 32548

Inspection Date: 11/06/2009 Inspection Number: 1134329 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: WIGGINS, GISELE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

Orange County

License Number: 5811390		HIGHLAND MANOR	
License Type: Permanent Food Service		604 E MAIN ST, APOPKA 32703	
Inspection Date: 11/03/2009	Inspection Number: 1889678	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: CHIU, CECILIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-12-2	Observed trouble/alarm light lighted on fire alarm control panel. For reporting purposes only.	NFPA 72, 7.1.1.1, 7.3.1 and 7.4.3 Inspection, testing, and maintenance programs shall satisfy the requirements of this code, conform to the equipment manufacturer's recommendations, and verify proper operation of the fire alarm system. Visual Inspection. Visual Inspection shall be performed in accordance with the schedules in this chapter or more frequently where required by the authority having jurisdiction. The visual inspection shall be made to ensure that there are no changes that can affect equipment performance. All apparatus requiring rewinding or resetting to maintain normal operation shall be restored to normal as promptly as possible after each test and alarm and kept in normal condition for operation. All test signals received shall be recorded to indicate date, time, and type. FOR REPORTING PURPOSES ONLY.	
License Number: 5808323		FIDDLERS GREEN	
License Type: Permanent Food Service		544 W FAIRBANKS AVE # 4-B, WINTER PARK 32789	
Inspection Date: 11/03/2009	Inspection Number: 1869269	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WATSON, DENNIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-15-2	Observed an uncovered electrical box. For reporting purposes only. By bar 3 bay sink	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 5809032		310 PARK SOUTH	
License Type: Permanent Food Service		310 PARK AVE S, WINTER PARK 32789	
Inspection Date: 11/04/2009	Inspection Number: 1848827	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: WATSON, DENNIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
48-13-2	Deep fat fryer installed without 16-inch separation from open flame. For reporting purposes only.	NFPA 96, 12.1.2.4 All deep fat fryers shall be installed with at least a 16-inch space between the fryer and surface flames from adjacent cooking equipment. FOR REPORTING PURPOSES ONLY.	
License Number: 5811381		WAZZABI SUSHI RESTAURANT	
License Type: Permanent Food Service		1408 GAY RD, WINTER PARK 32789	
Inspection Date: 11/04/2009	Inspection Number: 1900057	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WATSON, DENNIS			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
49-12-2	Observed container of flammable material over 5 gallons stored in establishment. For reporting purposes only. In back storage room Repeat Violation.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.	

Orange County

License Number: 5806638		MCDONALD'S 11958	
License Type: Permanent Food Service		3162 UNIVERSITY BLVD, WINTER PARK 327924424	
Inspection Date: 11/05/2009	Inspection Number: 1920718	Inspection Type: Complaint Full	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: MOORE, CAROLYN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 5806499		TROPICAL RESTAURANT	
License Type: Permanent Food Service		2680 S RIO GRANDE AVE, ORLANDO 328056141	
Inspection Date: 10/30/2009	Inspection Number: 1889106	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Complied
Inspector Name: PIEL, ANDREA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-03-2	Violation: 47-03-2 Observed unused opening in panel box unprotected. For reporting purposes only. BY REAR DOOR	NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.	
49-12-2	Violation: 49-12-2 Observed container of flammable material over 5 gallons stored in establishment. For reporting purposes only. 17 POUND GAS TANK IN KITCHEN Repeat Violation.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.	
License Number: 5810774		CLIFF'S RESTAURANT INC	
License Type: Permanent Food Service		4849 W COLONIAL DR, ORLANDO 32808	
Inspection Date: 11/03/2009	Inspection Number: 1909736	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GORDON, NORMA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. [Small fryer on the prep table frying fryers]. Notified Fire AHJ. For reporting purposes only. Corrected On Site.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.	
License Number: 5811209		GYROS	
License Type: Permanent Food Service		4863 W COLONIAL DRIVE, ORLANDO 32808	
Inspection Date: 11/03/2009	Inspection Number: 1837969	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: GORDON, NORMA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. [Rear exit]. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	

Orange County

License Number: 5804182		MANCHU WOK	
License Type: Permanent Food Service		8001 S ORANGE BLOSSOM TRL #940, ORLANDO 32809	
Inspection Date: 11/03/2009	Inspection Number: 1899169	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Admin. complaint recommended
Inspector Name: LAMBERT, LISA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-31-2	Violation: 45-31-2 Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Cooking plantains in fryer without hood. Notified Fire AHJ. For reporting purposes only.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.	
License Number: 5804647		KING EXPRESS	
License Type: Permanent Food Service		2225 W OAKRIDGE RD, ORLANDO 32809	
Inspection Date: 10/29/2009	Inspection Number: 1868400	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: MOORE, CAROLYN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 5808391		BROADWAY RISTORANTE & PIZZEIRA IV	
License Type: Permanent Food Service		12279 UNIVERSITY BLVD, ORLANDO 32817	
Inspection Date: 11/03/2009	Inspection Number: 1889076	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SINGH, GAJENDRA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.HOOD FILTER GAP	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 5808714		T D'S SPORTS BAR & GRILL	
License Type: Permanent Food Service		11400 UNIVERSITY BLVD, ORLANDO 32817	
Inspection Date: 11/02/2009	Inspection Number: 1848127	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SINGH, GAJENDRA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

Orange County

License Number: 5808757 HOOTERS OF POINTE ORLANDO INC
 License Type: Permanent Food Service 9101 INTL DR STE 2210, ORLANDO 32819

Inspection Date: 11/04/2009 Inspection Number: 1879958 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: NEGRON, LARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-44-2	Observed fire sprinkler head obstructed. For reporting purposes only.	NFPA 25, 5.2.1.1.1 and 5.4.1.8 Sprinklers shall not show signs of leakage; shall be free of corrosion, foreign materials, paint, and physical damage; and shall be installed in the proper orientation (e.g., upright, pendent, or sidewall). Sprinklers shall not be altered in any respect or have any type of ornamentation, paint, or coatings applied after shipment from the place of manufacture. FOR REPORTING PURPOSES ONLY.

License Number: 5809151 CHICK-FIL-A SANDLAKE
 License Type: Permanent Food Service 7333 SANDLAKE ROAD, ORLANDO 32819

Inspection Date: 10/26/2009 Inspection Number: 1847961 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: NEGRON, LARA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only,multi-plug for electronics.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 5810497 MOES SOUTHWEST GRILL SANDLAKE
 License Type: Permanent Food Service 7541 W SANDLAKE RD UNIT D, ORLANDO 32819

Inspection Date: 11/04/2009 Inspection Number: 1837629 Inspection Type: Routine - Food Inspection Disposition: Call Back - Admin. complaint recommended
 Inspector Name: BACHOO, SAVITRI

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-15-2	Violation: 45-15-2 No placard placed near Class K portable fire extinguisher stating the fire suppression system must be activated prior to use of the portable extinguisher. For reporting purposes only.	NFPA 10, 4.3.2.2 A placard shall be conspicuously placed near the extinguisher that states that the fire protection system shall be activated prior to using the fire extinguisher. FOR REPORTING PURPOSES ONLY.

License Number: 5812224 BENTO CAFE
 License Type: Permanent Food Service 7335 W SAND LAKE RD, ORLANDO 32819

Inspection Date: 11/03/2009 Inspection Number: 1900475 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BACHOO, SAVITRI

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-13-2	Circuit breaker box blocked and/or inaccessible. For reporting purposes only.Boxes.	NFPA 70, 110.32 Work Space about Equipment. Sufficient space shall be provided and maintained about electrical equipment to permit ready and safe operation and maintenance of such equipment. In all cases, the work space shall be adequate to permit at least a 90-degree opening of doors or hinged panels. FOR REPORTING PURPOSES ONLY.

Orange County

License Number: 5812334		FIREHOUSE SUBS	
License Type: Permanent Food Service		7541A W SAND LAKE RD, ORLANDO 32819	
Inspection Date: 10/30/2009	Inspection Number: 1888900	Inspection Type: Routine - Food	Inspection Disposition: Call Back - Complied
Inspector Name: BACHOO, SAVITRI			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-02-2	Violation: 45-02-2 Sprinkler head spray pattern obstructed. For reporting purposes only.Boxes require eighteen inches clearance from the ceiling.	NFPA 25, 5.2.1.2 Unacceptable obstructions to spray patterns shall be corrected. FOR REPORTING PURPOSES ONLY.	
License Number: 5810473		RESIDENCE INN CASTAWAY BAY	
License Type: Permanent Food Service		11000 WESTWOOD BLVD, ORLANDO 32821	
Inspection Date: 11/03/2009	Inspection Number: 1889784	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: NEGRON, LARA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only,fan near bar	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 5808951		SONNY'S BAR-B-Q	
License Type: Permanent Food Service		7055 S SEMORAN BLVD, ORLANDO 32822	
Inspection Date: 11/03/2009	Inspection Number: 1920516	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: RULLAN, ALFONSO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 5809419		TACO BELL #16729	
License Type: Permanent Food Service		2050 S SEMORAN BLVD, ORLANDO 32822	
Inspection Date: 11/03/2009	Inspection Number: 1909655	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: RULLAN, ALFONSO			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed emergency exits, stairs, hallways or egress. For reporting purposes only. Corrected On Site.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	

Orange County

License Number: 5810011		EUREST DINING SERVICE	
License Type: Permanent Food Service		11050 LAKE UNDERHILL DR, ORLANDO 32825	
Inspection Date: 10/30/2009	Inspection Number: 1878860	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: SINGH, GAJENDRA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. IN THE KITCHEN	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 5800351		RIO PINAR CO CLUB D R	
License Type: Permanent Food Service		8600 EL PRADO DR, ORLANDO 328258228	
Inspection Date: 10/30/2009	Inspection Number: 1909532	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SINGH, GAJENDRA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only. BY MIXER	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

License Number: 5807437		RIO PINAR LOUNGE	
License Type: Permanent Food Service		8600 EL PRADO DR, ORLANDO 328258228	
Inspection Date: 10/30/2009	Inspection Number: 1909536	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: SINGH, GAJENDRA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

License Number: 5805928		BLUEZOO	
License Type: Permanent Food Service		1500 EPCOT BLVD, LAKE BUENA VISTA 32830	
Inspection Date: 11/04/2009	Inspection Number: 1848166	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: RIVERA, JESICA M			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. By the unit close to the walk in cooler.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

Orange County

License Number: 5805937

CABANA BAR & GRILL

License Type: Permanent Food Service

1500 EPCOT RESORT BLVD, LAKE BUENA VISTA 32830

Inspection Date: 11/04/2009

Inspection Number: 1858350

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: RIVERA, JESICA M

Violation CodeObservationViolation Citation

45-37-2

Portable fire extinguisher missing from designated location. For reporting purposes only. Many others available.

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

License Number: 5812006

CHIPS AND SLICES

License Type: Permanent Food Service

2200 CLUB LAKE DR, LAKE BUENA VISTA 32830

Inspection Date: 10/30/2009

Inspection Number: 1837685

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: TILLEY, GEMMA

Violation CodeObservationViolation Citation

48-12-2

No current boiler certification provided/available. For reporting purposes only. Expired .

69A-51.050(2) FAC (2) Inspection Requirements. Each boiler used or proposed to be used in a place of public assembly within this state except boilers exempt under subsection 69A-51.045(6), F.A.C., shall be thoroughly inspected as to its construction, installation and condition as follows: (a) Power boilers and high pressure, high temperature water boilers shall receive a certificate inspection annually. They shall be inspected annually both internally, where construction permits, and externally while not under pressure. They shall also be inspected annually externally while under pressure, if possible, within six (6) months of the internal inspection. (b) Heating boilers, except those constructed of cast iron, shall receive a certificate inspection biennially. This inspection may be an external inspection unless an internal inspection is required by the Authorized Inspector. The Authorized Inspector, due to operating conditions, may require additional inspections. (c) Hot water boilers and hot water supply boilers, except those constructed of cast iron, shall receive a certificate inspection biennially with an internal inspection every four (4) years if the construction of the boiler so permits. (d) Heating boilers and hot water supply boilers constructed of cast iron shall receive a certificate inspection biennially. (e) A grace period of one (1) month beyond the periods specified in paragraphs (a)-(d), above, may elapse between certificate inspections; however, the inspection certificate due date shall not be affected. (f) The Boiler Safety Program may, in its discretion, permit longer periods between certificate inspections. FOR REPORTING PURPOSES ONLY.

License Number: 5809327

SAN ANGEL INN BAR

License Type: Theme Park Food Cart

1480 AVE OF THE STARS, ORLANDO 32830

Inspection Date: 11/04/2009

Inspection Number: 1056020

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: TILLEY, GEMMA

Violation CodeObservationViolation Citation

45-38-2

Portable fire extinguisher not fully charged. For reporting purposes only. In recharge zone by exit door.

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

Orange County

License Number: 5811407 BLUE MARTINI ORLANDO
 License Type: Permanent Food Service 4200 CONROY ROAD-SUITE H-246, ORLANDO 32839

Inspection Date: 11/03/2009 Inspection Number: 1868624 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GORIS, WILBERTO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-22-2	Portable fire extinguisher(s) obstructed from view. For reporting purposes only. SILVER EXTINGUISHER IN KITCHEN BLOCKED BY RACK	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. SEVERAL CORDS IN THE KITCHEN	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.
49-12-2	Observed container of flammable material over 5 gallons stored in establishment. For reporting purposes only. 12 17 POUND PRESSURIZED TANKS IN THE REAR STORAGE AREA	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

License Number: 5811826 IKEA FURNITURE STORE MAIN RESTAURANT
 License Type: Permanent Food Service 4092 EASTGATE DR, ORLANDO 32839

Inspection Date: 11/03/2009 Inspection Number: 1858280 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GORIS, WILBERTO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-06-2	Observed a gas appliance without proper venting. For reporting purposes only. GAS ODER IN BOILER ROOM	61C-1.004(13)(a) FAC Gas appliances. All appliances, including water heaters using gas, shall be kept in good repair and properly vented when manufacturers' instructions require venting of the appliance and shall meet the following requirements: (a) All appliances shall have a nationally recognized testing laboratory seal such as AGA or UL seal. FOR REPORTING PURPOSES ONLY.

License Number: 5812241 Q KARAOKE
 License Type: Permanent Food Service 4519 S ORANGE BLOSSOM TR, ORLANDO 32839

Inspection Date: 11/03/2009 Inspection Number: 1878918 Inspection Type: Routine - Food Inspection Disposition: Call Back - Complied
 Inspector Name: GORIS, WILBERTO

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-05-2	Violation: 46-05-2 Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. KITCHEN EXIT DOORS X2 ARE BLOCKED WITH EQUIPMENT	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

Osceola County

License Number: 5901188

KENTUCKY FRIED CHICKEN W750273

License Type: Permanent Food Service

3187 S JOHN YOUNG PARKWAY, KISSIMMEE 347466537

Inspection Date: 11/03/2009

Inspection Number: 1837141

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: RIVERA, JESICA M

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 5907271

COLUMBIA REST

License Type: Permanent Food Service

649 FRONT ST, CELEBRATION 34747

Inspection Date: 11/03/2009

Inspection Number: 1837087

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: NIEVES, RAFAEL

Violation CodeObservationViolation Citation

48-01-2

Boiler certificate not posted in boiler room. For reporting purposes only. Corrected On Site.

69A-51.025(4) FAC (4) Certificate of Compliance. The Certificate of Compliance shall be conspicuously placed so it can be readily identified with the certified boiler, preferably in the boiler room. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6011216

DEMPSEY'S CAFE

License Type: Permanent Food Service

400 CLEMATIS ST #102, WEST PALM BEACH 33401

Inspection Date: 11/04/2009

Inspection Number: 1918117

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: SHAPIRO, STEWART

Violation CodeObservationViolation Citation

45-31-2

Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only. COOKING EGGS IN FRY PANS WITHOUT HOOD USING BUTTER PER PERSON IN CHARGE MENU HAS EGGS &

NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

License Number: 6019146

MAKEB'S BAGELS

License Type: Permanent Food Service

401 S OLIVE AVE, WEST PALM BEACH 33401

Inspection Date: 11/06/2009

Inspection Number: 1886015

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: SHAPIRO, STEWART

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6009007

KINGS BUFFET

License Type: Permanent Food Service

1800 PALM BCH LAKES BLVD, WEST PALM BEACH 334012002

Inspection Date: 02/14/2008

Inspection Number: 1583193

Inspection Type: Routine - Food

Inspection Disposition: Call Back - Admin. complaint recommended

Inspector Name: MIDDLETON, ELWYN

Violation CodeObservationViolation Citation

37-20-1

Violation: 37-20-1

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge.
Repeat Violation.

NFPA 96, 11.4.2.: Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge.

License Number: 6004369

LAKE PARK BBQ EXPRESS

License Type: Permanent Food Service

1205 10 ST, LAKE PARK 33403

Inspection Date: 11/06/2009

Inspection Number: 1906732

Inspection Type: Routine - Food

Inspection Disposition: Call Back - Complied

Inspector Name: MIDDLETON, ELWYN

Violation CodeObservationViolation Citation

48-11-2

Violation: 48-11-2

Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only. Corrected On Site.

NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6011663

SOMEPLACE RESTAURANT

License Type: Permanent Food Service

1301 10 ST, LAKE PARK 33403

Inspection Date: 11/06/2009

Inspection Number: 1865716

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Complied

Inspector Name: MIDDLETON, ELWYN

Violation CodeObservationViolation Citation

46-13-2

Violation: 46-13-2

Emergency light does not function when tested. For reporting purposes only.
mens' & women's restrooms .

NFPA 101, 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted at 30-day intervals for not less than 30 seconds. (2) Functional testing shall be conducted annually for not less than 1½ hours if the emergency lighting system is battery powered. (3) The emergency lighting equipment shall be fully operational for the duration of the tests required by 7.9.3.1.1(1) and 7.9.3.1.1(2). FOR REPORTING PURPOSES ONLY.

License Number: 6011681

APPLEBEES #4241

License Type: Permanent Food Service

3167 NORTHLAKE BLVD, LAKE PARK 33403

Inspection Date: 11/06/2009

Inspection Number: 1886101

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: MIDDLETON, ELWYN

Violation CodeObservationViolation Citation

15-42-2

Observed some of the hood filters installed horizontally, rather than vertically. For reporting purposes only.

NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY

46-13-2

Emergency light does not function when tested. For reporting purposes only.
mens' restroom.

NFPA 101, 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted at 30-day intervals for not less than 30 seconds. (2) Functional testing shall be conducted annually for not less than 1½ hours if the emergency lighting system is battery powered. (3) The emergency lighting equipment shall be fully operational for the duration of the tests required by 7.9.3.1.1(1) and 7.9.3.1.1(2). FOR REPORTING PURPOSES ONLY.

49-06-2

Observed flammable material stored around water heater. For reporting purposes only. towels/cardboard . Corrected On Site.

61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

License Number: 6012376

CARIBBEAN CONNECTION

License Type: Permanent Food Service

619 W MARTIN L KING DR, RIVIERA BCH 33404

Inspection Date: 10/29/2009

Inspection Number: 1896367

Inspection Type: Routine - Food

Inspection Disposition: Call Back -
Admin. complaint recommended

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

45-39-2

Violation: 45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. k-class

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6019616		SOLID GOLD PALM BEACH	
License Type: Permanent Food Service		8340 RESOURCE DR, RIVIERA BEACH 33404	
Inspection Date: 11/05/2009	Inspection Number: 1865776	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: JONES, ANTHONY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-22-2	Portable fire extinguisher(s) obstructed from view. For reporting purposes only. Corrected On Site.	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. Corrected On Site.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	

License Number: 6019748		LA FAMILLIA #1 RESTAURANT	
License Type: Permanent Food Service		1530 BROADWAY, RIVIERA BEACH 33404	
Inspection Date: 09/02/2009	Inspection Number: 1906812	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: JONES, ANTHONY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	

License Number: 6051445		BIG HERMAN'S BAR-B-QUE AND MORE	
License Type: Mobile Food Dispensing Vehicle		8110 MONETARY DR, RIVIERA BEACH 33404	
Inspection Date: 11/05/2009	Inspection Number: 1137669	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: JONES, ANTHONY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	

License Number: 6011618		LAS BRISAS OF PALM BEACH	
License Type: Permanent Food Service		5201 GEORGIA AVE, WEST PALM BEACH 33405	
Inspection Date: 11/05/2009	Inspection Number: 1845037	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CONCEPCION, MARIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

Palm Beach County

License Number: 6013657

DJ CAFE

License Type: Permanent Food Service

6230 S DIXIE HWY, WEST PALM BEACH 33405

Inspection Date: 11/04/2009

Inspection Number: 1906680

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: SHAPIRO, STEWART

Violation CodeObservationViolation Citation

37-20-2

Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.

NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6006432

DENNY'S RESTAURANT #7638

License Type: Permanent Food Service

1507 BELVEDERE RD, WEST PALM BCH 334061501

Inspection Date: 06/12/2009

Inspection Number: 1828654

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: CONCEPCION, MARIA

Violation CodeObservationViolation Citation

15-42-2

Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.

NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY

License Number: 6020388

NEGRIL RESTAURANT & LOUNGE

License Type: Permanent Food Service

5335 N MILITARY TRAIL #26&27, WEST PALM BEACH 33407

Inspection Date: 11/02/2009

Inspection Number: 1919653

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

Palm Beach County

License Number: 6009558

OUTBACK STEAKHOUSE

License Type: Permanent Food Service

871 VILLAGE BLVD, WEST PALM BEACH 33409

Inspection Date: 11/03/2009

Inspection Number: 1855398

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

15-24-2	Hood filter missing from hood suppression. For reporting purposes only.	NFPA 96, 6.2.3.4 Grease filters shall be easily accessible and removable for cleaning. FOR REPORTING PURPOSES ONLY
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
45-38-2	Portable fire extinguisher not fully charged. For reporting purposes only. k-class	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.
47-16-2	Electrical switch broken to walk-in freezer . For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 6010958

APPLEBEE'S NEIGHBORHOOD GRILL & BAR #4118

License Type: Permanent Food Service

1975 N MILITARY TRL, WEST PALM BEACH 33409

Inspection Date: 10/29/2009

Inspection Number: 1865772

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
---------	---	---

License Number: 6011176

CARRABBA'S ITALIAN GRILL

License Type: Permanent Food Service

2224 PALM BEACH LAKES BLVD, WEST PALM BEACH 33409

Inspection Date: 11/04/2009

Inspection Number: 1845151

Inspection Type: Complaint Full

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
---------	---	---

Palm Beach County

License Number: 6019134

POPEYES FRIED CHICKEN

License Type: Permanent Food Service

2825 N MILITARY TRL, WEST PALM BEACH 33409

Inspection Date: 11/02/2009

Inspection Number: 1834891

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. k-class

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

47-07-2

Observed scorch marks around electrical outlet. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6019577

AIR CHEF

License Type: Permanent Food Service

1399 N MILITARY TRL, WEST PALM BEACH 33409

Inspection Date: 10/29/2009

Inspection Number: 1834963

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6007601

GINZA JAPANESE STEAK HOUSE AND SUSHI BAR

License Type: Permanent Food Service

871 VILLAGE BLVD, WEST PALM BEACH 334091937

Inspection Date: 11/04/2009

Inspection Number: 1865752

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6009958

CHILI'S SOUTHWEST GRILL & BAR

License Type: Permanent Food Service

4252 OKEECHOBEE BLVD, WEST PALM BEACH 334093206

Inspection Date: 11/05/2009

Inspection Number: 1834939

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

Palm Beach County

License Number: 6005658

ZUCCARELLI'S ITALIAN KITCHEN

License Type: Permanent Food Service

1937 N MILITARY TRL, WEST PALM BEACH 334094762

Inspection Date: 11/03/2009

Inspection Number: 1834925

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: JONES, ANTHONY

Violation CodeObservationViolation Citation

15-27-2

Observed the presence of mesh filters in a hood where grease laden vapors are produced. For reporting purposes only.

NFPA 96, 6.1.3 Mesh filters shall not be used. FOR REPORTING PURPOSES ONLY

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6013572

RUBY TUESDAY #7124

License Type: Permanent Food Service

1271 N SR 7, ROYAL PALM BCH 33411

Inspection Date: 11/05/2009

Inspection Number: 1886075

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: MIDDLETON, ELWYN

Violation CodeObservationViolation Citation

46-13-2

Emergency light does not function when tested. For reporting purposes only women's restroom.

NFPA 101, 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted at 30-day intervals for not less than 30 seconds. (2) Functional testing shall be conducted annually for not less than 1½ hours if the emergency lighting system is battery powered. (3) The emergency lighting equipment shall be fully operational for the duration of the tests required by 7.9.3.1.1(1) and 7.9.3.1.1(2). FOR REPORTING PURPOSES ONLY.

License Number: 6019871

AUNTY MERL'S KITCHEN

License Type: Permanent Food Service

10385 SOUTHERN BLVD, ROYAL PALM BEACH 33411

Inspection Date: 11/03/2009

Inspection Number: 1875882

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: MIDDLETON, ELWYN

Violation CodeObservationViolation Citation

46-13-2

Emergency light does not function when tested. For reporting purposes only. mens' & women's restrooms .

NFPA 101, 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted at 30-day intervals for not less than 30 seconds. (2) Functional testing shall be conducted annually for not less than 1½ hours if the emergency lighting system is battery powered. (3) The emergency lighting equipment shall be fully operational for the duration of the tests required by 7.9.3.1.1(1) and 7.9.3.1.1(2). FOR REPORTING PURPOSES ONLY.

License Number: 6019923

BUTTERFIELDS SOUTHERN CAFE

License Type: Permanent Food Service

1145 ROYAL PALM BEACH BLVD, ROYAL PALM BEACH 33411

Inspection Date: 11/03/2009

Inspection Number: 1855362

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: MIDDLETON, ELWYN

Violation CodeObservationViolation Citation

46-13-2

Emergency light does not function when tested. For reporting purposes only. mens' & women's restrooms .

NFPA 101, 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted at 30-day intervals for not less than 30 seconds. (2) Functional testing shall be conducted annually for not less than 1½ hours if the emergency lighting system is battery powered. (3) The emergency lighting equipment shall be fully operational for the duration of the tests required by 7.9.3.1.1(1) and 7.9.3.1.1(2). FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6009595

DON RAMON RESTAURANT

License Type: Permanent Food Service

502 S MILITARY TRL, WEST PALM BCH 334153902

Inspection Date: 06/17/2009

Inspection Number: 1828552

Inspection Type: Complaint Full

Inspection Disposition: Warning Issued

Inspector Name: CONCEPCION, MARIA

Violation CodeObservationViolation Citation

47-08-2 Observed electrical wiring in disrepair. For reporting purposes only. capped wires sticking out of floor - cookline .

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

47-15-2 Observed an uncovered electrical box. For reporting purposes only. switch plate broken - electrical room.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Inspection Date: 08/17/2009

Inspection Number: 1828552

Inspection Type: Complaint Full

Inspection Disposition: Call Back - Complied

Inspector Name: CONCEPCION, MARIA

Violation CodeObservationViolation Citation

47-06-2 Out of compliance: Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Inspection Date: 10/21/2009

Inspection Number: 1896195

Inspection Type: Complaint Full

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CONCEPCION, MARIA

Violation CodeObservationViolation Citation

47-06-2 Out of compliance: Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6012425

DUFFYS DRAFTHOUSE

License Type: Permanent Food Service

4280 NORTHLAKE BLVD, PALM BCH GDNS 33418

Inspection Date: 11/05/2009

Inspection Number: 1906770

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: MIDDLETON, ELWYN

Violation CodeObservationViolation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

Palm Beach County

License Number: 6019935

M & H CAFE

License Type: Permanent Food Service

2200 GLADES RD #102A, BOCA RATON 33431

Inspection Date: 11/02/2009

Inspection Number: 1844585

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: BANNIGAN, TIM

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6012237

THE LODGE BEER & GRILL

License Type: Permanent Food Service

200 S FEDERAL HWY, BOCA RATON 33432

Inspection Date: 11/04/2009

Inspection Number: 1885539

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: BANNIGAN, TIM

Violation CodeObservationViolation Citation

15-42-2

Observed hood filters installed horizontally, rather than vertically. For reporting purposes only.

NFPA 96, 6.2.5 and 6.2.1.4 Grease Filter Orientation. Grease filters that require a specific orientation to drain grease shall be clearly so designated, or the hood shall be constructed so that filters cannot be installed in the wrong orientation; NFPA 96, 6.2.1.4: Grease removal devices supplied as part of listed hood assemblies shall be installed in accordance with the terms of the listing and the manufacturer's instructions. FOR REPORTING PURPOSES ONLY

Palm Beach County

License Number: 6010693

LILLYS

License Type: Permanent Food Service

451 E PALMETTO PARK RD, BOCA RATON 334325017

Inspection Date: 10/30/2009

Inspection Number: 1865170

Inspection Type: Routine - Food

Inspection Disposition: Administrative complaint recommended

Inspector Name: BANNIGAN, TIM

Violation CodeObservationViolation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. Repeat Violation. Corrected On Site.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

48-11-2 Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only.
--- (2) 2.5 lb. LP tanks.

NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

License Number: 6010375

SAPORI

License Type: Permanent Food Service

301 VIA DE PALMAS, BOCA RATON 334326007

Inspection Date: 11/04/2009

Inspection Number: 1895846

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BANNIGAN, TIM

Violation CodeObservationViolation Citation45-37-2 Portable fire extinguisher missing from designated location. For reporting purposes only.
--- portable deep fryer in use without FSS.

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

License Number: 6011168

THE MUSE

License Type: Permanent Food Service

7136 BERACASA WAY, BOCA RATON 334334448

Inspection Date: 11/06/2009

Inspection Number: 1895928

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: PIERI, CYNTHIA

Violation CodeObservationViolation Citation

46-09-2 Exit signs not properly illuminated. For reporting purposes only.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

Palm Beach County

License Number: 6012606	BAGEL TREE RESTAURANT AND DELI		
License Type: Permanent Food Service	9080 KIMBERLY BLVD, BOCA RATON 33434		
Inspection Date: 11/05/2009	Inspection Number: 1885672	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PIERI, CYNTHIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
License Number: 6005984	CAPTAIN'S CATCH SEAFOOD REST INC		
License Type: Permanent Food Service	9851 S MILITARY TRL STE G, BOYNTON BEACH 33436		
Inspection Date: 11/03/2009	Inspection Number: 1885850	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CONCEPCION, MARIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 6011568	ADDISON RESERVE COUNTRY CLUB		
License Type: Permanent Food Service	7201 ADDISON RESERVE BLVD, DELRAY BCH 33446		
Inspection Date: 11/04/2009	Inspection Number: 1875546	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: PONCE, NUARETTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-22-2	Portable fire extinguisher(s) obstructed from view. For reporting purposes only. K CLASS SALAD STATION _COOKLINE BY SLICER	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.	
License Number: 6019396	BRIX ITALIAN FISHERY		
License Type: Permanent Food Service	1000 N U S HWY 1, JUPITER 33458		
Inspection Date: 11/03/2009	Inspection Number: 1865778	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DERVIN, RICHARD			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
License Number: 6019712	2 CHEFS SOUPAREE		
License Type: Permanent Food Service	6338 LANTANA RD STE 60, LANTANA 33462		
Inspection Date: 11/04/2009	Inspection Number: 1865482	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: MENOR, MICHAEL			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
License Number: 6019827	COCOCABANA BAR & GRILL		
License Type: Permanent Food Service	2944 N JOG ROAD, LAKE WORTH 33467		
Inspection Date: 11/02/2009	Inspection Number: 1914843	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: PONCE, NUARETTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-02-2	Sprinkler head spray pattern obstructed. For reporting purposes only. BOXES UNDER SPRINKLER HEADS ABOVE COOLER _COOKLINE Corrected On Site.	NFPA 25, 5.2.1.2 Unacceptable obstructions to spray patterns shall be corrected. FOR REPORTING PURPOSES ONLY.	

Palm Beach County

License Number: 6008017		BICE RISTORANTE	
License Type: Permanent Food Service		313 WORTH AVE #1/2, PALM BCH 334806010	
Inspection Date: 11/03/2009	Inspection Number: 1875814	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: SHAPIRO, STEWART			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 6011646		KAGURA SUSHI	
License Type: Permanent Food Service		5030 CHAMPION BLVD #D-8, BOCA RATON 33496	
Inspection Date: 11/06/2009	Inspection Number: 1885685	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PONCE, NUARETTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
49-06-2	Observed flammable material stored around water heater. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.	
License Number: 6010257		ROTELLI PIZZA & PASTA	
License Type: Permanent Food Service		20449 SR 7, BOCA RATON 33498	
Inspection Date: 11/04/2009	Inspection Number: 1895915	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PIERI, CYNTHIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6012825		YOGURT & ICE CREAM	
License Type: Permanent Food Service		10075 YAMATO RD #1, BOCA RATON 33498	
Inspection Date: 11/04/2009	Inspection Number: 1895929	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PIERI, CYNTHIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	

Pasco County

License Number: 6150273

RICHMON CONCESSIONS

License Type: Mobile Food Dispensing Vehicle

3903 WEBSTER FLEA MARKET, WEBSTER 33597

Inspection Date: 11/02/2009

Inspection Number: 1136637

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DANCHO, JOHN

Violation CodeObservationViolation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

48-20-2 Observed loose/unsecured LP-gas tank on mobile food dispensing vehicle. For reporting purposes only.

NFPA 58, 3.8.2.4 Containers shall be mounted securely on the vehicle, or within the enclosing recess or cabinet, and shall be located and installed so as to minimize the possibility of damage to containers, their appurtenances, or contents as follows: (a) Containers shall be installed with road clearance in accordance with 8-2.6.5. (b) Fuel containers shall be mounted securely to prevent jarring loose and slipping or rotating, and the fastenings shall be designed and constructed to withstand, without permanent visible deformation, static loading in any direction equal to four times the weight of the container filled with fuel. Where containers are mounted within a vehicle housing, the securing of the housing to the vehicle shall comply with this provision. Any hoods, domes, or removable portions of the housing or cabinet shall be provided with means to keep them firmly in place in transit. Field welding shall comply with 3-2.4.1(e). (c) All container valves, appurtenances, and connections shall be adequately protected to prevent damage from accidental contacts with stationary objects, from loose objects, stones, mud, or ice thrown up from the ground or floor, and from damage due to overturn or similar vehicular accident. In the case of permanently mounted ASME containers, this provision shall be met by the location on the vehicle, with parts of the vehicle furnishing the protection. On cylinders, the protection for cylinder valves and connections shall be attached permanently to the cylinder (see 2-2.4.1 and 2-2.4.2). Such weather protection necessary to ensure safe operation shall be provided for cylinders and systems mounted on the outside of vehicles. FOR REPORTING PURPOSES ONLY.

License Number: 6113214

SUMMERTREE GOLF CLUB

License Type: Permanent Food Service

11816 PARADISE POINTE WAY, NEW PORT RICHEY 34654

Inspection Date: 11/04/2009

Inspection Number: 1847042

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: GLENN, DAVID

Violation CodeObservationViolation Citation

45-31-2 Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only. Small electric skillet in use.

NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

47-03-2 Observed unused opening in panel box unprotected. For reporting purposes only. Breaker box on partition wall between kitchen and hallway.

NFPA 70, 110.12(a) Unused Openings - Unused openings in boxes or housings shall be effectively closed to afford protection substantially equivalent to the wall of the equipment. FOR REPORTING PURPOSES ONLY.

Pasco County

License Number: 6101803

THE HAYLOFT

License Type: Permanent Food Service

8954 SR 52, HUDSON 34669

Inspection Date: 11/02/2009

Inspection Number: 1847026

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: GLENN, DAVID

Violation Code

Observation

Violation Citation

47-05-2

Observed a splitter/multi-plug adapter in use. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

Pinellas County

License Number: 6216483		SUBWAY #1748	
License Type: Permanent Food Service		5406 GALL BLVD UNIT A, ZEPHYRHILLS 33541	
Inspection Date: 11/02/2009	Inspection Number: 1898093	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BROTHAG, SANDRA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-27-2	Portable fire extinguisher blocked/not easily accessible. For reporting purposes only.	NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.	
License Number: 6214795		FRESCOS	
License Type: Permanent Food Service		300 NE 300 2ND AVE, ST PETERSBURG 33701	
Inspection Date: 11/04/2009	Inspection Number: 1907396	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WAGNER, MARGARET			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-16-2	Electrical outlet missing cover plate. under dishwashing machine For reporting purposes only.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 6215886		VALENTINO'S LITTLE ITALY	
License Type: Permanent Food Service		1003 4TH STREET NORTH, ST. PETERSBURG 33701	
Inspection Date: 11/02/2009	Inspection Number: 1886759	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: WAGNER, MARGARET			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6207474		ITALIA MIA	
License Type: Permanent Food Service		1163 N 62 AVE, ST PETERSBURG 337027421	
Inspection Date: 11/03/2009	Inspection Number: 1920677	Inspection Type: Complaint Full	Inspection Disposition: Warning Issued
Inspector Name: JACKSON, BEATRICE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	

Pinellas County

License Number: 6200853

MCDONALDS ST PETE #5397

License Type: Permanent Food Service

300 N 38 AVE, ST PETERSBURG 337041332

Inspection Date: 11/03/2009

Inspection Number: 1876648

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: WAGNER, MARGARET

Violation CodeObservationViolation Citation

45-27-2 Portable fire extinguisher blocked/not easily accessible. blocked by storage rack components For reporting purposes only. Corrected On Site.

NFPA 10, 1.5.6 Fire extinguishers shall not be obstructed or obscured from view. In large rooms, and in certain locations where visual obstructions cannot be completely avoided, means shall be provided to indicate the extinguisher location. FOR REPORTING PURPOSES ONLY.

47-16-2 Electrical outlet missing cover plate. side 1 [grill area] For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

License Number: 6212681

FERGS SPORTS BAR & GRILLE

License Type: Permanent Food Service

1320 CENTRAL AVE, ST PETERSBURG 337051654

Inspection Date: 11/03/2009

Inspection Number: 1835435

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: WILLIAMS, TRINETTE

Violation CodeObservationViolation Citation

47-06-2 Observed extension cord in use for non-temporary period plug into a surge protector at front bar area. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6215068

MCDONALDS

License Type: Permanent Food Service

4595 S 34 ST, ST PETERSBURG 33711

Inspection Date: 11/04/2009

Inspection Number: 1835427

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: WILLIAMS, TRINETTE

Violation CodeObservationViolation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. at front counter area

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6215734

KFC/AWR

License Type: Permanent Food Service

770 34 ST N, ST. PETERSBURG 33713

Inspection Date: 11/04/2009

Inspection Number: 1876601

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: JACKSON, BEATRICE

Violation CodeObservationViolation Citation

15-28-2 Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

46-09-2 Exit signs not properly illuminated. For reporting purposes only.

61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

Pinellas County

License Number: 6210802 TASTE OF PHILLY INC
 License Type: Permanent Food Service 5545 ROOSEVELT BLVD, CLEARWATER 33760

Inspection Date: 11/03/2009 Inspection Number: 1915929 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: PORTER, LINDSAY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.(front area)	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6208711 CLEARWATER CINEMA CAFE
 License Type: Permanent Food Service 24095 US 19 NORTH, CLEARWATER 33763

Inspection Date: 11/02/2009 Inspection Number: 1897231 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: PEARCE, LAURA

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-25-2	Hood filters not equipped with a drip tray. For reporting purposes only.	NFPA 96, 6.2.4.1 Grease filters shall be equipped with a grease drip tray beneath their lower edges. FOR REPORTING PURPOSES ONLY

License Number: 6215671 GREEK ISLAND RESTAURANT
 License Type: Permanent Food Service 1501 CLEARWATER LARGO RD, LARGO 33770

Inspection Date: 11/04/2009 Inspection Number: 1886660 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: OLSEN, JAMES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. to chest freezer in storage area	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6201341 PIZZA HUT #4652
 License Type: Permanent Food Service 8380 SEMINOLE BLVD, SEMINOLE 33772

Inspection Date: 11/03/2009 Inspection Number: 1856027 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: OLSEN, JAMES

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. class k fire extinguisher sitting on floor near front service counter	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

Pinellas County

License Number: 6216445

SHIP WATCH PANTRY

License Type: Permanent Food Service

11900 SHIPWATCH DR, LARGO 33774

Inspection Date: 11/06/2009

Inspection Number: 1855973

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: OLSEN, JAMES

Violation CodeObservationViolation Citation

45-07-2

Observed misalignment of hood suppression system nozzles. For reporting purposes only. no coverage over small fryer

NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

License Number: 6207562

ROCKWELL CORNER PUB

License Type: Permanent Food Service

10801 STARKEY RD #1, LARGO 337771146

Inspection Date: 11/02/2009

Inspection Number: 1835555

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: OLSEN, JAMES

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only. in bar area

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6215805

BUFFALO GOURMET RESTAURANT

License Type: Permanent Food Service

10525 US HWY 19 N, PINELLAS PARK 33782

Inspection Date: 11/03/2009

Inspection Number: 1918049

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: PORTER, LINDSAY

Violation CodeObservationViolation Citation

45-12-2

Observed trouble/alarm light lighted on fire alarm control panel. For reporting purposes only.

NFPA 72, 7.1.1.1, 7.3.1 and 7.4.3 Inspection, testing, and maintenance programs shall satisfy the requirements of this code, conform to the equipment manufacturer's recommendations, and verify proper operation of the fire alarm system. Visual Inspection. Visual Inspection shall be performed in accordance with the schedules in this chapter or more frequently where required by the authority having jurisdiction. The visual inspection shall be made to ensure that there are no changes that can affect equipment performance. All apparatus requiring rewinding or resetting to maintain normal operation shall be restored to normal as promptly as possible after each test and alarm and kept in normal condition for operation. All test signals received shall be recorded to indicate date, time, and type. FOR REPORTING PURPOSES ONLY.

Pinellas County

License Number: 6216529		JERSEY MIKE'S SUBS	
License Type: Permanent Food Service		3860 TAMPA ROAD STE 107, OLDSMAR 34677	
Inspection Date: 11/04/2009	Inspection Number: 1918975	Inspection Type: Food-Licensing Inspection	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CRAIG, CHRISTINE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.	

License Number: 6210581		MAGNOLIA GRILL	
License Type: Permanent Food Service		600 ALT US HWY 19, PALM HARBOR 34683	
Inspection Date: 11/04/2009	Inspection Number: 1866546	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PEARCE, LAURA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only. by kitchen handsink	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	

License Number: 6213327		BOYLES BACK YARD	
License Type: Permanent Food Service		1101 NEBRASKA AVE, PALM HARBOR 34683	
Inspection Date: 11/04/2009	Inspection Number: 1866534	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PEARCE, LAURA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-05-2	Observed obstructed exits, stairs, hallways or egress. For reporting purposes only. boxes and keg, sign at back door	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.	

License Number: 6215804		ORANGE STREET CAFE INC	
License Type: Permanent Food Service		306 ORANGE STREET, PALM HARBOR 34683	
Inspection Date: 11/03/2009	Inspection Number: 1876810	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PEARCE, LAURA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.	

Pinellas County

License Number: 6212692

AUNT CHILADA'S CANTINA

License Type: Permanent Food Service

34718 N US HWY 19, PALM HARBOR 346842120

Inspection Date: 11/04/2009

Inspection Number: 1897213

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: CRAIG, CHRISTINE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.by water heaters	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.
47-16-2	Electrical outlet missing cover plate. For reporting purposes only.under table by stove	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Polk County

License Number: 6303756 CHAMPS FAMILY GRILL
 License Type: Permanent Food Service 1950 S COMBEE RD, LAKELAND 33801

Inspection Date: 11/02/2009 Inspection Number: 1915928 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: WHITE, RICKY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6302800 HOOTERS
 License Type: Permanent Food Service 3437 S FLORIDA AVE, LAKELAND 33803

Inspection Date: 11/03/2009 Inspection Number: 1887463 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: WHITE, RICKY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48-11-2	Observed LP-gas cylinder with greater than one pound LP-gas capacity inside a building. For reporting purposes only.	NFPA 58, 3.4.8.4 and 5.3.1.2 Cylinders used with commercial food service appliances shall be used inside restaurants and in attended commercial food catering operations in accordance with the following: (a) Cylinders and appliances shall be listed. (b) Commercial food service appliances shall not have more than two 10-oz nonrefillable butane gas cylinders, each having a maximum capacity of 1.08 lb. (c) Cylinders shall comply with UL 147B, Standard for Nonrefillable (Disposal) Type Metal Container Assemblies for Butane. (d) Cylinders shall be connected directly to the appliance and shall not be manifolded. (e) Cylinders shall be an integral part of the listed, approved, commercial food service device and shall be connected without the use of a rubber hose. (f) Storage of cylinders shall be in accordance with 5.3.1. The cylinders shall not exceed a water capacity of 2.7 lb [nominal 1 lb. LP-Gas] Exception: Storage in restaurants and at food service locations of 10-oz butane nonrefillable containers shall be limited to no more than 24 containers, and an additional twenty-four 10-oz butane nonrefillable containers stored in another location within the building, where constructed with at least a 2-hour fire wall protection. FOR REPORTING PURPOSES ONLY.

Polk County

License Number: 6307261 THE GARDEN DELI
 License Type: Permanent Food Service 3342 WINTER LAKE ROAD, LAKELAND 33803

Inspection Date: 11/03/2009 Inspection Number: 1908003 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: WHITE, RICKY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-31-2	Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only.	NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

License Number: 6303516 RIB HOUSE THE
 License Type: Permanent Food Service 2918 S FLORIDA AVE, LAKELAND 33803-4033

Inspection Date: 11/02/2009 Inspection Number: 1856745 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: WHITE, RICKY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY

License Number: 6306692 WENDY'S #8181
 License Type: Permanent Food Service 5740 US 98 N, LAKELAND 33809

Inspection Date: 11/03/2009 Inspection Number: 1887687 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: JACKSON, SHARON

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only./ above grills on side near ice machine. Repeat Violation.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6307649 WINGHOUSE OF LAKELAND
 License Type: Permanent Food Service 4515 S FLORIDA AVE, LAKELAND 33813

Inspection Date: 11/02/2009 Inspection Number: 1887459 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: WHITE, RICKY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-02-2	Observed lock on exit gate that requires a key, tool or special knowledge to open. For reporting purposes only.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.
46-05-2	Observed obstructed exit back dock gate chained closed with a pad lock. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

Polk County

License Number: 6307688

THE PROPER PIE COMPANY LLC

License Type: Permanent Food Service

145 RIDGE CENTER DR, DAVENPORT 33837

Inspection Date: 11/04/2009

Inspection Number: 1897700

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: ROMANO, JIMMIE

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period. For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6307636

COLONY HOUSE POOL HOUSE

License Type: Permanent Food Service

2300 N SCENIC HWY, LAKE WALES 33853

Inspection Date: 11/03/2009

Inspection Number: 1836311

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: WHITE, CHERYL

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 6307469

BEEF O BRADY'S

License Type: Permanent Food Service

43653 US HWY 27, DAVENPORT 33897

Inspection Date: 11/02/2009

Inspection Number: 1897686

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: ROMANO, JIMMIE

Violation CodeObservationViolation Citation

15-28-2

Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.
Corrected On Site.

NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

Santa Rosa County

License Number: 6700356

KWIKBURGER

License Type: Permanent Food Service

5173 STEWART ST, MILTON 32570

Inspection Date: 11/03/2009

Inspection Number: 1850783

Inspection Type: Routine - Food

Inspection Disposition: Warning
Issued

Inspector Name: WIGGINS, GISELE

Violation Code

Observation

Violation Citation

47-15-2

Observed an uncovered electrical box dishwashing area. For reporting purposes only.

NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.

Sarasota County

License Number: 6803956

MOROCCO RESTAURANT

License Type: Permanent Food Service

7119 S TAMIAMI TRL STE# E5-G7, SARASOTA 34231

Inspection Date: 11/05/2009

Inspection Number: 1920920

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DILLARD, FRANK

Violation CodeObservationViolation Citation

45-39-2

Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only. K class extinguisher on bottom shelf of table in kitchen .

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 6804770

FIREHOUSE SUBS

License Type: Permanent Food Service

5416 FRUITVILLE RD, SARASOTA 34232

Inspection Date: 11/02/2009

Inspection Number: 1915056

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: DILLARD, FRANK

Violation CodeObservationViolation Citation

45-38-2

Portable fire extinguisher not fully charged. For reporting purposes only. ABC extinguisher next to soda dispenser .

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

License Number: 6805091

DESOTO BEACH CLUB

License Type: Permanent Food Service

5201 DESOTO RD, SARASOTA 34235

Inspection Date: 11/05/2009

Inspection Number: 1913927

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: POSA, ANTHONY

Violation CodeObservationViolation Citation

47-06-2

Observed extension cord in use for non-temporary period in dry storeroom . For reporting purposes only.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6805010

DAAWAT INDIAN RESTAURANT

License Type: Permanent Food Service

1912 ADAM'S LN, SARASOTA 34236

Inspection Date: 11/04/2009

Inspection Number: 1918241

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: POSA, ANTHONY

Violation CodeObservationViolation Citation

45-31-2

Observed the use of cooking equipment producing grease laden vapors/smoke with no hood suppression system installed. Notified Fire AHJ. For reporting purposes only.-fryer and flat grill not under hood.

NFPA 96, 10.1.2 Cooking equipment that produces grease-laden vapors and that might be a source of ignition of grease in the hood, grease removal device, or duct shall be protected by fire-extinguishing equipment. FOR REPORTING PURPOSES ONLY.

Sarasota County

License Number: 6850178

BEANIE WEENIE

License Type: Mobile Food Dispensing Vehicle

4460 TALAVASTE RD, SARASOTA 34243

Inspection Date: 11/06/2009

Inspection Number: 1134414

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: POSA, ANTHONY

Violation Code

Observation

Violation Citation

45-38-2

Portable fire extinguisher not fully charged. For reporting purposes only.

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

Seminole County

License Number: 6902406		BURGER KING #5969	
License Type: Permanent Food Service		3010 E SEMORAN BLVD, APOPKA 327035940	
Inspection Date: 11/03/2009	Inspection Number: 1869209	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CHIU, CECILIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
License Number: 6900934		HABANA GRILL	
License Type: Permanent Food Service		937 W STATE RD 436 #1095, ALTAMONTE SPGS 327142927	
Inspection Date: 11/02/2009	Inspection Number: 1910169	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: CHIU, CECILIA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only. Repeat Violation.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 6903657		TIJUANA FLATS BURRITO CO	
License Type: Permanent Food Service		3005 W LAKE MARY BLVD, LAKE MARY 32746	
Inspection Date: 11/06/2009	Inspection Number: 1920997	Inspection Type: Complaint Full	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: MANTI, KATHRYN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
License Number: 6904407		SUSHIN JAPANESE RESTAURANT	
License Type: Permanent Food Service		1155 W STATE ROAD 434 #161, LONGWOOD 32750	
Inspection Date: 11/03/2009	Inspection Number: 1838259	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: MANTI, KATHRYN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	
License Number: 6900863		ENZO'S MAMA MARIA REST ON LAKE	
License Type: Permanent Food Service		1130 S HWY 17-92, LONGWOOD 327505718	
Inspection Date: 11/06/2009	Inspection Number: 1879402	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: MANTI, KATHRYN			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.	

Seminole County

License Number: 6902928		HUNGRY HOWIE'S PIZZA & SUBS	
License Type: Permanent Food Service		1333 BROADWAY STREET, OVIEDO 32765	
Inspection Date: 11/03/2009	Inspection Number: 1859522	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PLEICONES, KIM			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. used for pizza make table	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
47-16-2	Electrical outlet missing cover plate. For reporting purposes only. on wall by pizza make table for extension cord Repeat Violation.	NFPA 70, 300.31 Covers Required. Suitable covers shall be installed on all boxes to prevent accidental contact with energized parts or physical damage to parts or insulation. FOR REPORTING PURPOSES ONLY.	
License Number: 6903461		CHINA KING	
License Type: Permanent Food Service		112 W MITCHELL HAMMOCK RD #1140, OVIEDO 32765	
Inspection Date: 11/02/2009	Inspection Number: 1910849	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: PLEICONES, KIM			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only. Corrected On Site.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. in back storage room for permit equipment Repeat Violation.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6903146		CHECKERS #3277	
License Type: Permanent Food Service		1501 S FRENCH AVE, SANFORD 32771	
Inspection Date: 11/03/2009	Inspection Number: 1838945	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: ANGEL, TERRY			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open. For reporting purposes only. Hasp on walk-in cooler door.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	

Seminole County

License Number: 6900781 CHINA 28
 License Type: Permanent Food Service 895 FOX VALLEY DR #121, LONGWOOD 32779

Inspection Date: 11/04/2009 Inspection Number: 1869101 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: MANTI, KATHRYN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-26-2	Observed exhaust system operated with filters removed. For reporting purposes only.	NFPA 96, 11.1.2 Filter-equipped exhaust systems shall not be operated with filters removed. For reporting purposes only.
46-09-2	Exit signs not properly illuminated. For reporting purposes only.	61C-1.004(10) FAC Exits shall be clearly marked with approved illuminated exit signs. FOR REPORTING PURPOSES ONLY.

License Number: 6904422 THE MELTING POT
 License Type: Permanent Food Service 1200 DOUGLAS AVE, LONGWOOD 32779

Inspection Date: 11/04/2009 Inspection Number: 1910055 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: MANTI, KATHRYN

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

St. Johns County

License Number: 6501701 ISLAND JOE'S
 License Type: Permanent Food Service 909 ANASTASIA PARK RD, SAINT AUGUSTINE 32080

Inspection Date: 11/06/2009 Inspection Number: 1911617 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GOSAI, MATT

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-05-2	Observed a splitter/multi-plug adapter in use. For reporting purposes only. (OK IF OVERLOAD PROTECTOR)	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6550075 THE CHILL GRILLE
 License Type: Mobile Food Dispensing Vehicle 102 BRIDGE ST, SAINT AUGUSTINE 32084

Inspection Date: 11/04/2009 Inspection Number: 1138606 Inspection Type: Routine - Food Inspection Disposition: Warning Issued
 Inspector Name: GOSAI, MATT

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
47-08-2	Observed electrical wiring in disrepair. For reporting purposes only. BROKEN WIRES TO BRAKE WIRES . (NOT CONNECTED)	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6500071 SANTA MARIA REST
 License Type: Permanent Food Service 135 AVENIDA MENENDEZ, ST AUGUSTINE 320844402

Inspection Date: 10/31/2009 Inspection Number: 1901467 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: GOSAI, MATT

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.
47-08-2	Observed electrical wiring in disrepair. For reporting purposes only. HANGING WIRES BY DISHMACHINE , LOOSE WIRES UNDER PREPTABLE	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

St. Johns County

License Number: 6501859

LEWI'S ITALIAN DELI & CATERING

License Type: Permanent Food Service

2245 CR 210 W #117, ST. JOHNS 32259

Inspection Date: 11/04/2009

Inspection Number: 1920864

Inspection Type: Food-Licensing Inspection

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: TUCKER, CATHY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-36-2	Hood suppression system has not been inspected/tag . For reporting purposes only. new license-scheduled for 11/4/09	NPFA 96, 11.2.1 An inspection and servicing of the fire-extinguishing system and listed exhaust hoods containing a constant or fire-actuated water system shall be made at least every 6 months by properly trained and qualified persons. FOR REPORTING PURPOSES ONLY.
45-37-2	Portable fire extinguisher missing from designated location. For reporting purposes only. none on premises	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.
47-06-2	Observed extension cord in use for non-temporary period. For reporting purposes only. several pieces of equipment in dining area	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

St. Lucie County

License Number: 6601854		TACO BELL # 24538	
License Type: Permanent Food Service		1812 S US HWY 1, FT PIERCE 34950	
Inspection Date: 10/30/2009	Inspection Number: 1888662	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DAVIS, DIANNA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-06-2	Observed extension cord in use for non-temporary period. Orange cord behind soda dispenser. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6602151		MCDONALDS	
License Type: Permanent Food Service		4878 N KINGS HWY, FT PIERCE 349512244	
Inspection Date: 10/30/2009	Inspection Number: 1878482	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DAVIS, DIANNA			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
47-05-2	Observed a splitter/multi-plug adapter in use-splitter at drive through window.. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
47-06-2	Observed extension cord in use for non-temporary period-orange cord at drive through window. For reporting purposes only.	61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.	
License Number: 6602735		CHINA KING	
License Type: Permanent Food Service		10923 S US HWY 1, PORT ST LUCIE 34952	
Inspection Date: 11/04/2009	Inspection Number: 1878598	Inspection Type: Routine - Food	Inspection Disposition: Administrative complaint recommended
Inspector Name: PARNASS, LAUREN P			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	

St. Lucie County

License Number: 6600714

DOMINO'S PIZZA #5124

License Type: Permanent Food Service

10642 S US HWY 1, PORT ST LUCIE 349526402

Inspection Date: 11/04/2009

Inspection Number: 1888750

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: PARNASS, LAUREN P

Violation CodeObservationViolation Citation

47-07-2

Observed scorch marks around electrical outlet, above pizza make unit. For reporting purposes only. Repeat Violation.

61C-1.004(11) FAC Electrical wiring. To prevent fire or injury, defective electrical wiring shall be replaced and wiring shall be kept in good repair. No extension cords shall be used except during cleaning, maintenance and other temporary activities. Only a wall switch or approved pull cord shall be permitted in bathrooms. In accordance with the provisions of NFPA 70, the National Electrical Code, as adopted by the Division of State Fire Marshal in Chapter 69A-3, FAC, Uniform Fire Safety Rules and Standards, sufficient electrical outlets shall be provided. FOR REPORTING PURPOSES ONLY.

License Number: 6602844

NINOS PIZZERIA AND CAFE

License Type: Permanent Food Service

466 SW PORT ST LUCIE BLVD, PORT ST LUCIE 34953

Inspection Date: 11/03/2009

Inspection Number: 1847758

Inspection Type: Routine - Food

Inspection Disposition: Inspection
Completed - No Further Action

Inspector Name: PARNASS, LAUREN P

Violation CodeObservationViolation Citation

45-07-2

Observed misalignment of hood suppression system nozzles, fryers not under nozzle coverage and large strainer baskets hanging from nozzles. For reporting purposes only.

NFPA 96, 10.2 Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems. FOR REPORTING PURPOSES ONLY.

Sumter County

License Number: 7000458	GOLDEN CORRAL OF THE VILLAGES		
License Type: Permanent Food Service	3950 WEDGEWOOD LANE, THE VILLAGES 32162		
Inspection Date: 11/06/2009	Inspection Number: 1836659	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DANCHO, JOHN			

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.

License Number: 7000399	J & N LENNA MARIE'S		
License Type: Permanent Food Service	265 NW 1 ST, WEBSTER 33597		
Inspection Date: 11/02/2009	Inspection Number: 1887998	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: DANCHO, JOHN			

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-30-2	No Class K portable fire extinguisher provided for high hazard cooking area (for suppression system/equipment installed after June 30, 1998). For reporting purposes only.	NFPA 10, 4.3.2. and 4.3.2.1 Class K Fire Extinguishers for Cooking Oil Fires. Fire extinguishers provided for the protection of cooking appliances that use combustible cooking media (vegetable or animal oils and fats) shall be listed and labeled for Class K fires. Class K fire extinguishers manufactured after January 1, 2002, shall not be equipped with extended wand-type discharge devices. Fire extinguishers installed specifically for the protection of cooking appliances that use combustible cooking media (animal, vegetable oils and fats) prior to June 30, 1998, shall not be required to comply with 4.3.2. (Also see 4.3.2.3.). FOR REPORTING PURPOSES ONLY.

Volusia County

License Number: 7401992 MR DUNDERBAKS
 License Type: Permanent Food Service 1700 W INTL SPEEDWAY BLVD, DAYTONA BCH 32114

Inspection Date: 11/02/2009 Inspection Number: 1879307 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BRANNER, LISELOTTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
49-06-2	Observed flammable material stored around water heater and in attic. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

License Number: 7403812 HOOTERS
 License Type: Permanent Food Service 2100 INT'L SPEEDWAY BLVD, DAYTONA BCH 32114

Inspection Date: 11/04/2009 Inspection Number: 1899844 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BRANNER, LISELOTTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
46-02-2	Observed lock on exit door that requires a key, tool or special knowledge to open on water heaterroom.. For reporting purposes only.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.
46-02-2	Observed a hasp and lock on beer cooler/walkin and storage room. Manager states fire inspector said they were ok. For reporting purposes only.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.
49-06-2	Observed flammable material stored around water heater. For reporting purposes only.	61C-1.004(8) FAC (8) Flammable materials inside an establishment shall be stored in approved-type containers (maximum size 5 gallons) and in such a manner as to prevent a fire hazard. FOR REPORTING PURPOSES ONLY.

License Number: 7400392 MCDONALDS
 License Type: Permanent Food Service 1388 W INTL SPEEDWAY BLVD, DAYTONA BEACH 32114

Inspection Date: 11/02/2009 Inspection Number: 1909950 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: BRANNER, LISELOTTE

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-37-2	Portable fire extinguisher missing breaking device by emergency exit second floor.. For reporting purposes only.	NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.
45-39-2	Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor by coffee station . For reporting purposes only.	NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.
46-05-2	Observed obstructed exits, stairs/ blocked by wet vac. For reporting purposes only.	NFPA 101, 7.1.10.1 and 61C-1.004(10) FAC Means of egress shall be continuously maintained free of all obstructions or impediments to full instant use in the case of fire or other emergency. Means of access must permit unobstructed travel at all times and be maintained free of obstructions and fire hazards. Halls, entrances and stairways shall be clean, ventilated and well-lighted day and night. Hall and stair runners shall be kept in good condition. Hand rails shall be installed on all stairways and guard rails around all porches and steps. Adequate means of exit shall be provided pursuant to NFPA 101. FOR REPORTING PURPOSES ONLY.

Volusia County

License Number: 7402941		THE OLIVE GARDEN ITALIAN RESTAURANT	
License Type: Permanent Food Service		1725 W INTERNATIONAL SPEEDWAY, DAYTONA BEACH 32114	
Inspection Date: 10/30/2009	Inspection Number: 1920598	Inspection Type: Complaint Full	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BRANNER, LISELOTTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
45-02-2	Sprinkler head spray pattern obstructed/storage room.. For reporting purposes only.	NFPA 25, 5.2.1.2 Unacceptable obstructions to spray patterns shall be corrected. FOR REPORTING PURPOSES ONLY.	
License Number: 7405888		PAPA JOHNS PIZZA #2115	
License Type: Permanent Food Service		1506 S NOVA RD, DAYTONA BEACH 32114	
Inspection Date: 10/30/2009	Inspection Number: 1919039	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: BRANNER, LISELOTTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 7406919		STARLITE PRINCESS	
License Type: Permanent Food Service		721 BALLOUGH RD, DAYTONA BEACH 32114	
Inspection Date: 10/30/2009	Inspection Number: 1920660	Inspection Type: Complaint Full	Inspection Disposition: Administrative complaint recommended
Inspector Name: BRANNER, LISELOTTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
46-02-2	Observed a hasp(type) and locl on liquor room. For reporting purposes only.	NFPA 101, 7.2.1.5.2 Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. FOR REPORTING PURPOSES ONLY.	
License Number: 7404502		SOUTH TURN LOUNGE	
License Type: Permanent Food Service		1540 S NOVA RD, DAYTONA BCH 321145816	
Inspection Date: 11/04/2009	Inspection Number: 1899830	Inspection Type: Routine - Food	Inspection Disposition: Warning Issued
Inspector Name: BRANNER, LISELOTTE			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	
37-20-2	Hood not cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. For reporting purposes only.	NFPA 96, 11.4.2 Hoods, grease removal devices, fans, ducts, and other appurtenances shall be cleaned to bare metal prior to surfaces becoming heavily contaminated with grease or oily sludge. FOR REPORTING PURPOSES ONLY	
License Number: 7406480		HONG KONG CHINESE RESTAURANT	
License Type: Permanent Food Service		5287 S. NOVA ROAD, PORT ORANGE 32127	
Inspection Date: 11/04/2009	Inspection Number: 1879275	Inspection Type: Routine - Food	Inspection Disposition: Inspection Completed - No Further Action
Inspector Name: LARSON, SARAH			
<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>	
15-28-2	Hood filters are not tight-fitting and firmly held in place - leaving open spaces. For reporting purposes only.	NFPA 96, 6.2.3.3 Grease filters shall be arranged so that all exhaust air shall pass through the grease filters. For reporting purposes only.	

Volusia County

License Number: 7406272

FILIPPO'S PIZZA

License Type: Permanent Food Service

132 W PARK AVE #10, EDGEWATER 32132

Inspection Date: 11/03/2009

Inspection Number: 1838771

Inspection Type: Routine - Food

Inspection Disposition: Warning Issued

Inspector Name: ZALESKI, AMY

Violation CodeObservationViolation Citation

15-24-2 All hood filters are missing from hood system. For reporting purposes only.

NFPA 96, 6.2.3.4 Grease filters shall be easily accessible and removable for cleaning. FOR REPORTING PURPOSES ONLY

15-24-2 Violation: 15-24-2

All hood filters are missing from hood system. For reporting purposes only.

NFPA 96, 6.2.3.4 Grease filters shall be easily accessible and removable for cleaning. FOR REPORTING PURPOSES ONLY

License Number: 7405552

MERK'S BAR & GRILL

License Type: Permanent Food Service

193 NORTH CAUSEWAY, NEW SMYRNA BEACH 32168

Inspection Date: 10/30/2009

Inspection Number: 1920585

Inspection Type: Complaint Full

Inspection Disposition: Warning Issued

Inspector Name: LARSON, SARAH

Violation CodeObservationViolation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 7403620

ARBYS

License Type: Permanent Food Service

380 W GRANADA BLVD, ORMOND BEACH 32174

Inspection Date: 10/30/2009

Inspection Number: 1879169

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BERGSTRESSER, REBECCA L

Violation CodeObservationViolation Citation

45-39-2 Portable fire extinguisher not properly mounted at least 4 inches off the floor and the top no higher than 5 feet off the floor. For reporting purposes only.

NFPA 10, 1.5.10 Fire extinguishers having a gross weight not exceeding 40 lb shall be installed so that the top of the fire extinguisher is not more than 5 ft above the floor. Fire extinguishers having a gross weight greater than 40 lb (except wheeled types) shall be so installed that the top of the fire extinguisher is not more than 3½ ft above the floor. In no case shall the clearance between the bottom of the fire extinguisher and the floor be less than 4 in. FOR REPORTING PURPOSES ONLY.

License Number: 7404557

TONYS N Y PIZZA

License Type: Permanent Food Service

146 W NEW YORK AVE, DELAND 32720

Inspection Date: 11/04/2009

Inspection Number: 1899863

Inspection Type: Routine - Food

Inspection Disposition: Inspection Completed - No Further Action

Inspector Name: BRASKA, GEORGIA

Violation CodeObservationViolation Citation

45-38-2 Portable fire extinguisher not fully charged ABC class behind bar.. For reporting purposes only. Repeat Violation.

NFPA 10, 1.5.2 Portable fire extinguishers shall be maintained in a fully charged and operable condition and shall be kept in their designated places at all times when they are not being used. FOR REPORTING PURPOSES ONLY.

Walton County

License Number: 7601983 THE LAKE PLACE
 License Type: Permanent Food Service 5994 W CO HIGHWAY 30-A, SANTA ROSA BEACH 32459

Inspection Date: 11/02/2009 Inspection Number: 1850961 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: VINCENT, STACEY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
48	Out of compliance: Gas appliances - properly installed, maintained	NFPA 101, 96, 10 Gas appliances - properly installed, maintained

License Number: 7601993 STINKY'S FISH CAMP
 License Type: Permanent Food Service 5960 W COUNTY HIGHWAY 30A, SANTA ROSA BEACH 32459

Inspection Date: 11/02/2009 Inspection Number: 1881646 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: VINCENT, STACEY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-30-1	No Class K portable fire extinguisher provided for high hazard cooking area (for suppression system/equipment installed after June 30, 1998). For reporting purposes only.	NFPA 10, 4.3.2. and 4.3.2.1:: Class K Fire Extinguishers for Cooking Oil Fires. Fire extinguishers provided for the protection of cooking appliances that use combustible cooking media (vegetable or animal oils and fats) shall be listed and labeled for Class K fires. Class K fire extinguishers manufactured after January 1, 2002, shall not be equipped with extended wand-type discharge devices. Fire extinguishers installed specifically for the protection of cooking appliances that use combustible cooking media (animal, vegetable oils and fats) prior to June 30, 1998, shall not be required to comply with 4.3.2. (Also see 4.3.2.3.)

License Number: 7601783 MCDONALDS OF EAST DESTIN
 License Type: Permanent Food Service 12830 EMERALD COAST PKWY, DESTIN 32550

Inspection Date: 11/03/2009 Inspection Number: 1881638 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: VINCENT, STACEY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-07-1	Observed uncapped hood suppression system nozzles. Corrected On Site.	NFPA 96, 10.2.: Automatic fire-extinguishing systems shall be installed in accordance with the terms of their listing, the manufacturer's instructions, and the following standards where applicable. (1) NFPA 12, Standard on Carbon Dioxide Extinguishing Systems (2) NFPA 13, Standard for the Installation of Sprinkler Systems (3) NFPA 17, Standard for Dry Chemical Extinguishing Systems (4) NFPA 17A, Standard for Wet Chemical Extinguishing Systems

License Number: 7601889 CIAO BELLA PIZZA DA GUGLIELMO
 License Type: Permanent Food Service 10676 W EMERALD COASTPWY#146, SANDESTIN 32550

Inspection Date: 10/12/2009 Inspection Number: 1902150 Inspection Type: Routine - Food Inspection Disposition: Inspection Completed - No Further Action
 Inspector Name: VINCENT, STACEY

<u>Violation Code</u>	<u>Observation</u>	<u>Violation Citation</u>
45-02-1	Out of compliance: Unacceptable obstructions to spray patterns shall be corrected.	NFPA 25, 5.2.1.2.: Unacceptable obstructions to spray patterns shall be corrected.